Remington Arms Co., Inc. **Product Service** Legal Case #:1926

Case Information

RE# Date Opened Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

12/28/2007 1/3/2008 1/3/2008 138816

Customer Information

City State Zip Age Contact Type Business First Name Last Name Street

H 636-433-2580

Engemann 15401 Engemann Lane Marthasville MO 63357 Reporter Doug

W 314-234-0137 E douglas.g.engemann@boeing.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

Cause: 4006 Altered Adjustments or Components

PD

Unknown

S fires on safe release Concern: 1007 Fired on Safe Release

1/9/08-correspondence from repair-cust lightened trigger to help with accuracy. Rifle fired on safe release. Wants x mark pro.lw

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

CF/BA

700/300 WIN MA

27313

S6585150 RA

11/6/2006 8:08:28

Date

Where Purchased

SPORT

Accessories

Original Owner

AM

Purchased

GLENN ZANDERS FUR &

TWO PIECE SCOPE

BASE, RINGS

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA Release Date

Reimbursement

Cash Settlement Reim. Date APV

Cash Date APV

Settlement Replace TA at discount

Repair/Replacement

Cost

Release of Claims

Repair/Replacement Date

1/9/08-Replace TA at discount.lw


Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/3/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	SET SCREWS ALTERED
	Description		26" 300 WIN MAG FL SS
	Date Code		RA
	Bore Plugged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=1926&Type=Case

1/9/2008

	Bulged	False	i
Barrel	Fired	False	
	Fired while Obstructed	raise	J.
	Muzzle/Crown Condition	Tiles and Tiles and	ר
Bolt		Like new; Functioning	<u>]</u>
	Firing Pin	Like new; Functioning	<u>]</u>
	Shroud	Like new; Functioning	<u></u>
	Face	Like new; Functioning	
	Handle	Like new; Functioning	
Extractor	Stop	Like new; Functioning	
	Condition	Like new; Functioning	
	Cut Condition	Like new; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Like new; Functioning	
	Notch Condition	Select	
	Exterior Condition	Like new; Functioning	
Overall	Stock Condition	Like new; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Like new; Functioning	
Received	Bulged	False	
	Description		STANDARD M/700 X-MARK PRO
Safety	Function	Like new; Functioning	
Sear	Sub-Assembly	Non-ISS	
	Lift	Select	.012
	Notch	Like new; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Like new; Functioning	
	Pull	Select	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	X-Mark Pro	
Non-Remington Components	Description]	TWO PIECE SCOPE BASE,RINGS



Remington Arms Attention: Arm Services 14 Hoefler Avenue Ilion, NY 13357 December 12, 2007 7 2 26'

3th 26'

,012

To Whom It May Concern:

Enclosed please find the Remington 700 Sendero 300 Win Mag that I purchased last year. I ordered the gun in July and didn't get it until December, after our deer season had past here in Missouri.

I was not completely satisfied with the accuracy I was getting from the gun so my brother-in-law recommended I get the trigger lightened. A gunsmith in Ruston, LA lightened the trigger to about 2.5 pounds, which seemed to help.

During this deer season while I was hunting, I saw a deer and flipped the safety to the fire position. The gun immediately discharged! I was able to bolt the gun and shoot the deer as well as another one which came after it. After I got down from the tree stand, I unloaded the gun and adjusted the safety to the safe position. When I flipped it to the fire position, it dry fired. I did this probably ten times in a row and every time the gun would dry fire.

I spoke to your Customer Service department today, and they suggested that I send it to you. I am asking that you do the following:

- 1) Assess what is wrong with the trigger mechanism of the gun.
- 2) Notify me of the results of your investigation at the following contact information: Work 314-234-0137, Home 636-433-2580, E-mail douglas.g.engemann@boeing.com
- 3) Provide me an estimate of the cost of putting in a new X-Mark Pro Trigger. Please note that if I decide to put in the X-Mark Pro Trigger, I would want it lightened to the <u>minimum</u> of factory specifications.

Please advise me of your findings as soon as you can and thank you for your attention in this matter.

Doug Engemann

15401 Engemann Lane

Marthasville, MO 63357

COULD NOT Duplicate concern

TRIG. Set Schews ALTERED,

Mer Mer TAP, check over, clear

AT 1/2 NONWAL CHANGES, Set

TRIG. pull TO Min Ructory Specs.

Sincerely yours

S6585150

Model: 700

RE00138816