ì

Remington Arms Co., Inc. Product Service Legal Case #:4948

Case Inform	mation											
RE#	RE# Date Opened		Date Opene	d(PS) Date Clos	Date Closed		Incident Date		re Lit	Lit	Obsolete	
213152	12/8	3/2010	12/9/201	0 12/9/201	0							
Customer I	Information											
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age		Cont		
Incident		Eric	Wert	1648 Forest Hills Dr	Hatfield	PA	19440				2-3032 Jycos.com	
Incident In	formation											
Claims		•	Codes		Repair Est.		. Medical Treatment Me		edical Status			
PI												
PD			use:4038 Coul	ı Unknown								
S Fired on bolt closing Cor		oncern:1008 Fired on Bolt Closing		OTENIO WIT								
С												

11/3/10 Per email sent to Remington.com, incident # 101028-000061, "I recently purchased a Remington 700 CDL (left hand) in 30-06 from Cabela's. During my first trip to the range, I experienced what I have heard described as a "slam fire." Essentially, the rifle fired when I was closed the bolt when neither of my hands was near the trigger nor the trigger guard. Please let me know how I can send the rifle back to Remington to have it examined and repaired. I want to ensure that this never happens again."cm

Firearm Information Mfg. Remington Date Purchased CONCERN:FBC	Type CF/BA Where Purchased CABELA S WHEELING DC / #	Model/Ga. 700/30-06 SPR Accessories	SKU n/a Driginal Owner U	Serial G6907475	Bbl. ED	DOM 10/7/2009 4:12	
Ammunition Informatio	n - None Defined	angen Anhar berther redamer - 1 fan i anderen hit yr radioneth yn radioneth					
Other Products Informat	tion - None Defined						
Settlement							
		Remington/700/CF/	BA ⁻				
Settlement	Release of Claims	Release Date	Reimburs	omont	Cash ttlement	Reim. Date APV	Cash Date APV
Per Ilion, replace TPA no charge to restore cor							
	Repair/Replacement Cost	Repair/Replacem Date	ent				
	134.94	12/13/2010					
11/3/10 Emailing ARS a	and letter.cm 12/13/10 Per Ilion, co	ould not duplicate cor	cern. Replace TF	A, check ov	er and te	st fire at no cha	rge to

11/3/10 Emailing ARS and letter.cm 12/13/10 Per Ilion, could not duplicate concern. Replace TPA, check over and test fire at no charge to restore confidence in rifle. Emailed Wert inspection results and the no charge repair info.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/9/2010
Examination	Product Type		RF
	Action Type		Α
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
	Description		24" 30-06 SPR
Barrel	Date Code		ED
	Bore Plugged	False	
	Bulged	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4948&Type=Case

12/13/2010

PrintDisplay

•

Page 2 of 2

•	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Extractor Locking Overall Receiver Safety Sear	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	SCRATCHES
	Fore End Condition	Select	
Baasiyan	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.011
Receiver Safety Sear	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Like new; Functioning	
Triccor	Pull	Select	2#
ringger	Altered	False	
	Sub-Assembly	X-Mark Pro	

•

12/13/2010

ile A		air Est frmREI r		lepair Exp Repair Inc	edite Repair uiry	Inquiry	Repair Tools	CSR Tool	s Reports	Table Maintenance	System	Location
	64	Repair Nur - Verity Re - ADORE \$ - Addres - Addres - Addres 	bber: F pair SINFOR SINFOR 2 SINFOR 2 SINFOR 2 SINFOR 3 SINFOR 3 SINFOR 4 SINFOR 4 SINFOR 4 SINFOR 4 SINFOR 4 SINFOR 4 SINFOR 4 SINFOR 5 SIN 5 SINFOR 5 SIN 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SINFOR 5 SIN 5 S	ATFIELD ATFIELD ATFIELD A Zp Cod n Problems Expedite EmailSent Maint	2 Seriat (06 SPF) ILLS DR Estimate / Hist User ID schultscm ArmEmail	FPO Box (Country: my / Status)	FFL Shipping / Billing ded ck In ceived	m Peturn I ERIC WE 1648 FOI HATFIEL PA 2 Desc2 A FOI ERICFWI ERICFWI	Status o RT REST HILLS DR	PD.Box Country US Country US Country US Current S Repair 12/9/2010 Syst 12/9/2010 Syst Repair Repair Repair U Current I2 Courter I2	ceived from.	
		Rëpa	kolije in Kolije in	11 12 13 18 19					Internal Repai			
Stal	1-ILW/Pr	nd 🧐 🖓 frm	Rep	frmR 9 Mic	palman û ▼ <u>C</u> 21n 3 ₁] DM5	NAGLETJ		Thursday, Dec 9	2010 M24A2	9:54 AM

.

• •

DEC 1 0 2010 BY: 655-165

Zimbra: ericfwert@lycos.com

1648 Forest Hills Drive

Hatfield, PA 19440

EricFWert@lycos.comEricFWert@lycos.com>

215-872-3032

Question Reference #101028-000061

Product Level 1: Firearms Date Created: 10/28/2010 02:26 PM Last Updated: 11/03/2010 08:30 AM Status: Waiting



Could not duplicate conceRN. Rephree TPA, checkourn + Test fike at N/C to restore confidence IN Rifle

monowhy

Zimbra: ericfwert@lycos.com

4948-

2011

Zimbra Collaboration Suite

ericfwert@lycos.com

Page 1 of 2

Remington 700 [Incident: 101028-000061] 1 Messages

Remington 700 [Incident: 101028-000061]

Wednesday, November 03, 2010 8:30:55 AM

From: info@remington.com To: ericfwert@lycos.com

Reply To: info@remington.com

Recently you requested personal assistance from our on-line support center. Below is our response.

We will assume your issue has been resolved if we do not hear from you within 72 hours.

Thank you for allowing us to be of service to you.

To access your guestion from our support site, click here.

Subject Remington 700

Discussion Thread

Response (Chris)

Mr. Wert, I apologize for the delay in responding. I will email a prepaid UPS ground shipping label to you i the next 24-48 hours. Please print it and tape it to your rifle box. Take it to a UPS terminal or UPS driver an shipping is paid. I will also email a letter with my contact information. Please print a copy and insert it insid the rifle box before shipping. We will inspect the rifle at no charge and contact you with the results and how we can resolve.

If you would like to contact me directly, following is my direct information.

Thank you again for your patience.

Christy Mitchell <u>christy.mitchell@remington.com</u> 800-342-9700, ext 8684

Customer (1 ericfwert@lycos.com)

10/28/2010 02:26 P

11/03/2010 08:30 A

I recently purchased a Remington 700 CDL (left hand) in 30-06 from Cabela's. During my first trip to the range, I experienced what I have heard described as a "slam fire." Essentially, the rifle fired when I was closed the bolt when neither of my hands was near the trigger nor the trigger guard. Please let me know how can send the rifle back to Remington to have it examined and repaired. I want to ensure that this never happens again.

I own and enjoy other Remington firearms and trust that the company will help me resolve this problem. Thank you for your prompt response.

Eric Wert







