


Results Summary

The Model 710 and Model 700 behaved similarly during this test. The mode of failure and the force level at which it occurred were approximately the same. In all four test runs a high enough load was reached that caused the firing pin head to over-ride the sear safety cam. When this occurred the firing pin assembly was bound or trapped in this condition. In the authors opinion in no case would this mode of failure result in an unsafe condition that would result in an unintentional discharge of the firearm. The following table summarizes the peak load recorded at the instant the over-ride occurred.

	<u>Model 710</u>	Model 700 <u>Control</u>
Test #1	33.7	394
Test #2	128	
Test #3 (24 hr. Solvent South)	377	
Labl	<u>e 1. – Maximum</u>	Load (lbs.)

In order to cause an over-ride like this some part movement and deformation must occur. In the 710's case it appears that deformation of the synthetic insert resulted in the override. In the 700's case the fire control mounting pins were bent. The loads required to cause this situation are far in excess of normal service loads. In the 710's case the firing pin spring load is in the 23 fb – 26 lb. range. The lowest load recorded above (337 lbs.) is about 13 times that of the high end service load (26 lbs.). This Factor of Safety (FS) is far in excess of accepted engineering safety levels. This coupled with comparison to the 700 validates the robustness of the 710 design in this area.



BARBER - 5.30.060007002