đ.

				Produ	Arms Co., Inc. ct Service Case #:8245						
Case Inform	nation										
RE# 295116	Date C 1/4/2)pened 2013	Date Opened(H 11/29/2012	rs) I	Date Closed 2/14/2013		ident D 1/29/201		Pre Lit	Lit	Obsolete
Customer I	nformation										
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age		Conta	ct
Incident		Sid	Wilson	357 30 Rd	Ponca City	OK	74604		E osage	1954@	yahoo.com
Incident In	formation										
	Clain	15		Codes Repair Est.		st. Med	edical Treatment Medical Status				
	f thumb rough floorb ission	oard and	Cause:4038 Concern:10		t Duplicate Con Bolt Opening	cern			U		

11/29/12 Per call from Wilson, his 700 SPS Tactical fired when he went to unload it. He was standing outside his pick-up and it fired through the floorboard and transmission. He has about \$3000 damage to his truck.cm

	PI	<u>,</u>				
	PD	Cause:			Unkne	own
	S C	Concern:				
						<u></u>
Firearm Information	on					
Mfg.	Туре	Model/Ga.	SKU	Serial	Bbi.	DOM
Remington	CF/BA	700/308 WIN	84207	G6702647	ĒΒ	10/26/2007 8:32:57 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRY S SPORT CENTER NOP	۲T	Y			
CONCERN: FBC						
Mfg.	Туре	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/308 WIN	84207	G6702647		10/26/2007 8:32:57 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	JERRY S SPORT CENTER NO	RT	U			
	mation - None Defined formation - None Defined	Remington/700/0	7E/BA			
0 (4)		-		. (Cash	Reim. Date Cash
Settlement	Release of Claims	Release Date	Reimburseme	nt Sett	lement	APV Date APV
Return as received						
	Repair/Replacement Cost Repa	ir/Replacement Date	e			
He said the safety He had not pulled wrong. I gave ther day air cm 2/7 Red told his wife that I	ARS.cm 1/10/13 Emailed S. Earl to was on, and he touched the safety to a the trigger prior to that while the safe n the correct address for E-town and a cd 2nd inspection info from Watkins. would send an email with inspection for I shipped it back.cm 2/14 Spoke v	move to fire and just ity was on.cm 1/24 Tl asked them to ship it. The claimed defect of info.cm 2/13 Emaile	the touch caused it the firearm was return On 1/28 it still had could not be duplicated d Wilson letting him	o fire. It had ned to Ilion not shipped ted.cm 2/8/1 1 know the r	l not mo since th so I ask 3 Calle ifle was	wed to the fire position. c address they listed was ted that they ship it one d but Wilson not home. I c on hold as I waiting to
Examination[Rem	ington/CF/BA]					
		<u>, , , , , , , , , , , , , , , , , , , </u>				

Part	Sub-Part	Code	Comment
			Comment

.

	Examiner	1	B.TRAVIS
1	Exam Date	Í	1/7/2013
Examination	Product Type	1	RF
	Action Type	1	A
	Assigned To	1	J.BALIO
Cause	4038	Could Not Duplicate Concern	THE SEAR SPRING IS NOT POSITIONED CORRECTLY UNDER THE SEAR. SEE PHOTO
	Description]	20" 308 HB
	Date Code	1	EB
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	DIRTY
	Fore End Condition	Select	ļ
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	J
Safety	Description		XMP SAFETY
	Function	Like new; Functioning	
	Lift	Select	.011
Sear	Notch	Slightly Worn; Functioning	
	<u> </u>	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
Trigger	Pull	Select	4.5#
	Altered	False]
	Sub-Assembly	X-Mark Pro]

2/15/2013

.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		Derek Watkins
	Exam Date	1	2/7/2013
Examination	Product Type	ĺ	RF
	Action Type	Í	A
	Assigned To	1	
Cause	4038	Could Not Duplicate Concern	The rifle passed 5 function tests and 5 trick tests. The rifle was then soaked in a freezer at -20F for three house with the bolt cocked and the safety in the on position. When the rifle was moved to the "Fire" position and the rifle did not fire. Th
	Description	i	slightly worn, functioning
	Date Code	ĺ	
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		• •
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
LATIACIO	Cut Condition	Select	n/a
	Ext/Eject Test	False	
Magazine	Condition	Slightly Worn; Functioning	
	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Slightly Worn; Functioning	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		Slightly worn, functioning
Safety	Function	Slightly Worn; Functioning	
Tests	Test Fired	False	
1 0515	Feeding Test	False]
	Condition	Slightly Worn; Functioning	Sear spring was slightly out of position but was functioning properly
Trigger	Pull	Select	no measured
	Altered	False	Indeterminate: The safety block screw had very little tamper evidence sealant on it and may have be

2/15/2013

Name: Sid Wilson

 Firearm: M700 SPS Tactical with Hogue Stock (84207)

 Caliber:
 .308 Win

 Serial Number:
 G6702647

 DOM:
 10-26-2007

 Owner: Sid Wilson

Description of Incident: 11/29/12 Per call from Wilson, his 700 SPS Tactical fired when he went to unload it. He was standing outside his pick-up and it fired through the floorboard and transmission. He said the safety was on, and he touched the safety to move to fire and just the touch caused it to fire. It had not moved to the fire position. He had not pulled the trigger prior to that while the safety was on.

Items supplied for examination: The incident M700 SPS Tactical rifle.

Present for the examination: Derek Watkins

General Condition: Overall the condition of the rifle was good, with some signs of slight wear on the barrel and bolt.

Conclusion: The claimed failure of the incident rifle discharging without a trigger pull could not be duplicated. The rifle was subjected to function testing at 75F and -29F, with the rifle only discharging when the safety was in the "Fire" position and the trigger was fully pulled. The rifle was disassembled and inspected; no manufacturing or design defects were found. The incident rifle was found to be in specification and functioning properly.

Ammunition Used: N/A

Respectfully submitted: 15 February, 2013

By: Derek L Watkins Director, Product Technology Integration Remington Arms Co. LLC. 315 W Ring Rd. Elizabethtown, KY 42701

Customer Name		Case# 8245	G6702647
Part	Sub-Part	Code	Comment
Examination	Examiner	Derek Watkins	
	Exam Date	2/7/2013	
	Product Type	M700	
	Action Type	Bolt	
	Assigned To		
			The rifle passed 5 function tests and 5 trick tests. The rifle was then soaked in a freezer at -20F for three hours with the bolt cocked and the safety in the on position. When the rifle was removed the safety was moved to the "Fire" position and the rifle did not fire. The
Cause		Claimed fire with out a trigger pull.	rifle was then subjected to 5 function tests and it passed each test. The claimed defect could not be duplicated.
Barrel	Description	slightly worn, functioning	
Daller	Date Code	anging worn, functioning	
		No	
	Bore Plugged		
	Bulged	No	
	Fired	Yes	
	Fired while Obstructed	No	
	Condition	slightly worn, functioning	
Bolt	Firing Pin	slightly worn, functioning	
BOIL	Shroud	slightly worn, functioning	
	Face	slightly worn, functioning	
	Handle	slightly worn, functioning	
	Stop	slightly worn, functioning	
	Ejector	slightly worn, functioning	
Extractor	Condition	slightly worn, functioning	
	Cut Condition	N/A	
	Ext/Eject Test	No	
Magazine	Condition	slightly worn, functioning	
	Box Condition	slightly worn, functioning	
Overall	Exterior Condition	slightly worn, functioning	
	Stock Condition	slightly worn, functioning	
	Fore End Condition	slightly worn, functioning	
Receiver	Condition	slightly worn, functioning	
I COGIVEI	Bulged	No	
Cofati		<u> </u>	
Safety	Description	slightly worn, functioning	
1	Function	slightly worn, functioning	
	Sub-Assembly	slightly worn, functioning	
Tests	Test Fired	No	
	Feeding Test	No	
Trigger	Condition	clightly worn functioning	Sear spring was slightly out of position but was functioning properly.
Trigger		slightly worn, functioning	nunctioning propeny.
	Pull	not measured	The safety block screw had very little tamper evidence sealant on it and may have been altered, but was indeterminate. All other adjustment screws were
1	Altered	indeterminate	unaltered.
	Sub-Assembly	slightly worn, functioning	
	1		L

Print:Screen 2001 *freewa		An owners where the second state of the	S -						
St File 78 Add Repair	Estimate R	epair Expedite R	epair Inquiry	Repair Tools	CSR Tools Re	ports Table Maintena	ince ince		
	a din kara ar								
	frmREInqui	y Repair Inquiry	S. M. S. M.		1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	vites - as even a sublimation			
	Repair Number:	RE00295116	Serial: G6702647 WIN Produced: 1	Model 700 RIFLE (0/26/2007 SKU: 8420)	aliber: 308	Repairman:			
	Verify Repair			83		Status: New 11/30/20	12 9:46:31 AM	·	
	-ADDRESS INF	ORMATION		Received from		a – an - an a' denistra - an a' - canan ann dhan a dhadha adhadh adhadh an dhadh dhadh an dhadh dhadh an a	C Received from		
	Name	SID WILSON		 Received from 	SID WILSON	an a	< Received from	n	
	Address 1:	2			357 30 RD				20
	Address 2:	ſ <u>.</u>	PO Box:			PO Box:			ESUIU
		PONCA CITY			PONCA CITY		gelation a sala of a state of		4.5
	State:	OK Zip Code: 7	1604 Count	ry: JUS	OK Zip Co	ode: 74604 Countr	r: JUS		• • • • • •
				FFL:			01011900		
	Contact / Cond	ition Problems Estima	ate History / Statu	s Shipping / Billing				\$ 1	
	Contact Info	rmation		Received Condition	n	Accessories Recei	· · · · ·	-	
	Phone:	· · · · · · · · · · · · · · · · · · ·	و معاون مواد و مار و مار و معان معالمات المراجع الماري الم	Good		AD07	c Qty Stud 2	2	
	Fax:		than stalled de south des berefester de selfenter southe dette	Condition Notes					
	Email: Comments:	osage1954@yahoo.co	m			and a state of the second			
	Comments.			CSR Prod Se Notes:	rv #8245				
		· · · · · · · · · · · · · · · · · · ·		1	ран на артон Артон Мак, амбаларан ал албан артон арт			<u>-</u>	
		na fallan ika ana kana kanaka bara da ka		<u> </u>		R	lefresh	Close	
G6702	617								
			1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1						
(Model: 70	0			ارتی ہے۔ اور ایک					ан
			1						
			α. * ετ≊στα τι				DE	CEIV	EM
RE0	0295	5116					L L	N 0 9 2013	, U
			Paul Barry No. Aurilia	opro la Field	LASRPR 11 8	Monday, 1	lan 7 2013	3:37 AM	· · · · · · · · · · · · · · · · · · ·
							-۱۰ پ		

•

:

Service Request

.

Remington Service PO Box 700

Madison, NC 27025-0700 ATTN

ATTN: Prod Serv #8245

Parts and Repairs: P:800-243-9700/F:336-548-7801

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

www.Remington.com

SR00036958 Customer: SID WILSON 357 30 RD PONCA CITY, OK 7 Email: osage1954@ya Your request for service on th		Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 Email: ne if it is covered under our warranty po		11/30/2012 11/30/2012
Reason For Return M123 - FORWARD TO Service Request Section Prod Serv #8245	PRODUCT SERVICE FOR INSPECTION	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Parts And Service Detai Material Type	ls Description	Qty Warranty Needed	Price	Disc Amount
	. This is a pre-estimate to repair, recondition, or replace ersation with our representative.	the item(s)	Sub Total: Est Sales Tax Grand Total:	

Service Request

Parts and Repairs: P:800-243-9700/F:336-548-7801

.

Remington Service PO Box 700

Madison, NC 27025-0700

ATTN: Prod Serv #8245

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number SR00036958 Customer: SID WILSON 357 30 RD PONCA CITY, OK 74 Email: osage1954@yah Your request for service on the returned. If not, you will be co	G6702647 Model 700 RIFLE Caliber: 308	Destination: Arms Services 14 Hoefler Ave Ilion, NY 133 Email: te if it is covered under our warranty	57 US	1 1/30/20 12 1 1/30/20 12 n will be repaired and
	PRODUCT SERVICE FOR INSPECTION			
Service Request Section Prod Serv #8245				
Parts And Service Details Material Type	s Description	Qty Warranty Needed	Price	Disc Amount
	This is a pre-estimate to repair, recondition, or replace trsation with our representative.	the item(s)	Sub Total: Est Sales Tar Grand Total:	

Please send your firearm back via a traceable method of shipping to the address below.

This Service Request number is only valid for this return.

Please follow these guidelines:

- Include a copy of your proof of purchase to assist in the evaluation of your repair
- Record your serial number for future reference
- Remove <u>any</u> accessories (sling, scope, scope mounts, case, etc.) unless these items are needed to assist in the evaluation.
- Properly package your <u>unloaded</u> firearm. Do not ship in your hard case (note: Original boxes are not returned with repair)
- Do not send live/loaded or spent ammunition with your firearm.
- Please package the ammunition in a secure carton or box.
- The package should be stuffed to prevent movement.
- Include service request number.
- Shipment of live ammo must be via U.P.S. only.
- Please advise your local U.P.S. mailing center of the contents so that a special Other Regulated Materials-Domestic (ORM-D) label can be applied.

Please let us know of any address change requests by email or phone. Our returns process will take approximately 2-3 weeks to complete and a confirmation email will be sent once we have shipped your firearm.

Should you have any further questions or concerns please don't hesitate to contact us via email (<u>info@remington.com <<mailto:info@remington.com>></u>) or by phone at 800-243-9700, M-F 9am - 5pm, EST. We look forward to helping you resolve this issue!

Mailing Label:

(cut here)

Arms Services SR# SR00036958 14 Hoefler Ave Ilion, NY 13357 US

Email: Attn: Prod Serv #8245

ARS LABEL REQUEST FORM

DATE:	11/30/2012	Service Request #	SR00036958	
QUANTITY:	1	WEIGHT PER PACKAGE:	10 LBS	
REQUESTED BY:	mitchelles	email address:		
				<u> </u>

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:

SID WILSON 357 30 RD PONCA CITY, OK 74604 US SR00036958

Email: osage1954@yahoo.com

RETURN ITEM TO:

ILN

Arms Services

TOT PUB CHG 11.38

ATTN: Prod Serv #8245

4XX596 NOV 30, 2012 ALL CURR USD SVC GNDCOM ACT WT 10.0 LBS TRACKINC# 124XX5969065594599 1 OF 1 REF 1:SR00036958 REF 2: HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 DC 0.00
 DV
 0.00
 COD
 0.00

 DC
 0.00
 DGD
 0.00

 AH
 0.00
 PR
 0.00
 RS 1.00 SD 0.00

PUB+HANDLING

SP 0.00

11.38

ARS LABEL REQUEST FORM

DATE:	12/03/2012	Service Request #	SR00036958	
QUANTITY:]	WEIGHT PER PACKAGE:	10 LBS	
REQUESTED BY:	mitchellcs	email address:		
<u> </u>				

Business:

Remington Service PO Box 700 Madison, NC 27025-0700 www.Remington.com

LABEL INFORMATION

MAIL LABEL TO:	SID WILSON 357 30 RD PONCA CITY, OK 74604 US SR00036958 Email: osage1954@yahoo.com
RETURN ITEM TO:	ILN Arms Services

	AXX595 DEC 3, 2017 SVC GNDCOM TRACKINGH 1Z4XX55 ACT WT 10.0 LBS REF 1:SR0003F_358 REF 2:
ATTN: Prod Serv #8245	HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD V 0.00 COD 0.00 RS 1.00 DC 0.00 DGD 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 11.38 PUB+HANDLING 11.38







