Remington Arms Co., Inc. Product Service Legal Case #:9568

Case Information Pre Lit Lit Obsolete RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date 328695 11/25/2013 12/2/2013 12/2/2013 Х Customer Information First Last Type Business Street City State Zip Age Contact Name Name H 478-588-1312 1603 Racket Sharpe Incident Harold Lyons GA 30436 Ε Town Rd. sharpe@mclendonenterprises.com Incident Information Claims Codes Repair Est. Medical Treatment **Medical Status** PI PD Cause:4015 Improper Maintenance Unknown Concern:1028 Fired With Safe ON S FSO С Service Request # 67652 - "smp = gun went off while on safety according to consumer. no injuries / no damages. 1975 gun". df Firearm Information Mfg. SKU Model/Ga. Serial Bbl. DOM Туре 788/308 WIN Remington CF/BA n/a A6071283 DZ 9/25/1975 Accessories Original Owner **Date Purchased** Where Purchased ACE HDWE CONYERS GEORGIA U CONCERN: FSO Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/788/CF/BA Reim. Cash Cash Settlement **Release of Claims Release Date** Reimbursement Date Date Settlement APV APV Per Ilion - Quote to repair @ a discount Repair/Replacement Repair/Replacement Date Cost 12/4/13: Per Ilion - Trigger assembly very loose on receiver & trigger spring out of position. Can offer to repair as needed at 1/2 cost - quote. df 12/13/13: I called customer concerning quote. He apprvd & paid w/CC#. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
		·····	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9568&Type... 12/13/2013

	Examiner		B.TRAVIS
Examination	Exam Date		12/2/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4015	Improper Maintenance	
	Description		22" 308 WIN
	Date Code		DZ
	Bore Plugged	False	
Barrel	Bulged	False	
Danei	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
DOIL	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Missing	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Worn; Functioning	
	Fore End Condition	Select	
n	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
T	Condition	Slightly Worn; Not Functioning	VERY LOOSE ON REC TRIG SPR OUT OF POSITION
Trigger	Pull	Select	4#
	Altered	False	

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9568&Type... 12/13/2013

:

ł

PrintDisplay

1			2	
1			1	
- [Sub Accombly	Other Remington		
	1340-ASSCIIUIV	Other Remington		

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9568&Type... 12/13/2013

ł

Quota	ition	Remington Serv PO Box 700 Modison NG 2				Estir R	natir epor	ng t	
n	n.000	Madison, NC 2)		-	- 6	-	
		243-9700/F:336-548-7801 www.Reming IN EXCHANGE FOR REPLACED PARTS.		a the state		•~		· .	
THIS IS NOT AN PLEASE APPRO	I INVOICE. THIS IS OVE BY SIGNING	IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE TH BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RE	IE ITEM(S) D R TO TAKE /	ESCRIBED BELO	W. IF THIS IS S.	ATISFACTO	RY.	PROVAL.	
 Repair Numb)er	Serial Number / Description			Date Re	ceived:	11/25/2	2013	_
RE00328695		A6071283			Estimate		12/03/2		
		Model 788 Center Fire Caliber: 308 WIN			Date Pri	nted:	12/13/2	2013	
Customer:				irn To:	·				
) SHARPE CKET TOWN I	חס		HAROLD SH 1603 RACKET					
	GA 30436 U			LYONS, GA					
Please Circle		IFD Card Na		E.	Data				
Open Acc	AC DISCOV	VER Card No PO Number:		CA	(p.Date				
0.000									
Approval Sign	nature:) Time to Call			Date:				
						<u></u>			
	esire any chang	ge, please use the reverse side for your comments and t Problems					-		
Reported									
			23 - FORV	WARD TO PRO	ODUCT SERV	VICE FOR	INSPE	CTION	
M240 - DU	LI LUCK SAI	FETY MODIFICATION							
_		Technician Com	mante	· · · · · · · · · · · · · · · · · · ·					
trigger assemb		on receiver and trigger spring is out of position. can of	ffer to repa	ir ans needed a	ind test fire at	1/2 norma	l cost.		
Material	Туре	ESTIMATE (note: C.O.D./Shipping and Handling Description	Charges a Qty Needed	Warranty	ded in this Q Qty From Inv	uote.) Price	Disc	Amount	
4000114	Service	GR-SHIPPING & HANDLING (GUN REPAIR)		Billable	1	17.00		17.00	
4000116	Service	GR-LABOR	35	Billable	35	1.00		17.50	
4000119	Service	GR-TEST	1	Billable	1	23.00	50	11.50	
					_				l
			D,	$\frac{\mathbb{A}}{2 13 13}$)				
			ЦL)				
			V	2/13/13	· d+				
					Sub	Total:		46.00	
						Sales Tay	•	00	

Grand Total:

\$46.00

Service Request

*

Remington Service PO Box 700

Madison, NC 27025-0700



.

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number Serial Number / Description SR00067652 A6071283 Smp	Date of Request: 11/14/2013 Date Printed: 11/14/2013
Smp Customer: HAROLD SHARPE 1603 RACKET TOWN RD LYONS, GA 30436 US	Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 US
Email:	Email:
Your request for service on the item(s) will be evaluated by our repairman to determine if it is returned. If not, you will be contacted with an estimate before work is performed.	covered under our warranty policy. If it is your firearm will be repaired and
	·
Reason For Return M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M240 - BOLT LOCK SAFETY MODIFICATION	
Service Request Section smp = gun went off while on safety according to consumer no injuries / no damages	
1975 gun	
Parts And Service Details Material - Type Description	Qty Warranty Price Disc Amount leeded
A6071283	
Model: 788 Transmin and the cash and the liter of the and the state and the state of the state o	DECEIVE
	UL DEC 0 4 2013
RE00328695	B Y:
	Tiziq, ASSM, VERY loose on Tiziq, ASSM, VERY loose on
	CAN offer to pep. As well del mit
	1/2 20 St.
THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(being sent based on the conversation with our representative.) Sub Total: .00 Est Sales Tax: .00
	Grand Total: \$.00