TON ARMS COMPANY, INC.

Remington

WIND

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

October 16, 1980

Centerfire "Hammer Mark" Meeting

Present:

A.R. Baszczuk H.J. Baylor J.W. Bower

G.E. Fletcher W.R. Globig J.A. Harter G.J. Hill

A. Huffman

P.G. Johnson

W.W. Cook

K.R. Couchman

C.S. Poore G.E. Schineller

A meeting was held on October 15, 1980; at 2:00 in the P.E. & C. Conference Room to discuss the problem of hammer marks on M/700, 7400 and 7600 barrels.

The fellowing was established:

- 1. All barrels with hammer marks were produced on the new Upsetter.
- New Upsetter places barrels in Verson type tubs and they do not cool for 18-24 hours. were placed in H-frame and and the
- Hammer marks showed up after Harper Buff operations were introduced.
- 4. Only "No Finish Turn" barrels have hammer marks.

Questions to be answered:

3. Is the Black Oxide process not coloring properly?

Deedrate test 8,9,11,13 IPM - 55 Walled

Centerfire "Hammer Mark" Meeting

Kevin Couchman and Carla Poore will follow a load of barrels with hammer marks (already through color) through strip, re-polish, re-harper and color in Dept. 79. They will also have a microstructure done of a barrel with hammer marks.

J.A. Harter, Supervisor Centerfire Bbl. Mfg. Area

dcw