

Revised comments on 1/20/09

#	Item or Observation	Further Action(s) Required	Responsibility	Date
1	Sear lift measured .005 - .006" in Mayfield on early assemblies via sear lift gage. Another 6-pc sample measured .002 - .006" in E-town via comparator. A third sample built w/ latest versions of safety arm and receiver insert measured .006 - .008". The results are different from the current M770 and historical M710 measurements.	Go through scenarios for possible bad effects of new sear lift. Respond to Mayfield with recommendation. Recommended to correct modify safety arm to bring sear lift for new assembly in line with current product (.012 to .015")	Vince Norton	12/9/08
2	Side plate galling was found on (2) early assemblies; the effect was increasingly difficult operation (forces) of the safety arm; a 6-sample test conducted in E-town showed the safety "on" forces increased on 3 of the samples.	Dry cycle the new assembly and measure how safety forces change over time.	Vince Norton	12/19/08
		Done – Safety forces creep up slightly on average but no significant increase	Vince Norton	12/19/08
		Continue previous safety forces test up to higher cycle count.		
		Done – Safety forces creep up slightly on average but no significant increase		
3	The new safety is more difficult to translate in either direction than the current safety. How do the safety on/off forces compare to the current forces? Is the condition likely to be objectionable to the customer?	Verify inside radius on trigger block.	Mayfield	12/9/08
		Investigate new material for sideplate.	Mayfield	?
		Measure safety forces on current receiver insert assemblies. Compare to new assembly.	Vince Norton	12/19/08
		Done – Safety forces on current assemblies measure an average of 4.27 lbs. (5 assemblies)		
		Investigate lighter safety detent spring.		
		In process		
		Other work:		
		Inspect DAT trigger blocks and production trigger blocks to compare dimensions that could affect safety forces.		
		Done on 1/20. Data is available for review.		

		<p>Install the X-mark pro safety arm on the production insert assembly and compare forces to new, 770 safety arm. Done on 1/20. Safety forces with X-mark pro arm are on average 1.1 lbs. lighter.</p> <p>Remeasure safety forces on DAT insert assemblies. In Process</p>		
4	Method of setting trigger motion on safe (TMOS) is relatively uncertain. Overtravel checked in "fire" is thought to be the result of successful TMOS setting, rather than attempting to set both OT and TMOS. Consider applying a known force against the trigger if the results prove to be operator dependent.	Experiment with fire control adjustment process and develop a process for setting and checking TMOS	Mayfield	When available
5	Identify an alternative coating (color) for the shorter safety pivot pin to avoid mix-up with the 300464 pin (longer by .050").	<p>Select Coating and color</p> <p>Add finish spec to print Waiting for determination of coating by Mayfield</p>	<p>Mayfield</p> <p>Vince Norton</p>	12/19/08
6	The new assembly requires (3) different adhesives. If possible, reduce the # by at least (1). If the black max cure time is greater than a few minutes, there is a higher likelihood of chipping the <u>slotted</u> screw heads. Care must be exercised when applying Duco to the trigger block screw head to prevent seepage into the trigger block.	<p>Spec out Loctite for trigger block screw Done – Loctite 660</p> <p>Apply Black Max thread sealer to all other adjustment screws and as tamper evident coating</p> <p>Prepare samples and test</p>	<p>Vince Norton</p> <p>Mayfield</p> <p>Mayfield</p>	<p>12/19/08</p> <p>When available</p> <p>When available</p>
7	Reverse the direction of safety pivot pin installation, if there are no ill effects, to simplify the assembly process. All (3) retaining clips could be installed on the same side at the same time.	<p>Use current samples to compare safety forces with pin inserted from either direction. Done – It is OK to assemble safety pin from the right side and put the clip on the left side</p>	Vince Norton	12/19/08
8	What is the purpose of the .060" hole on the side plate?	<p>Leave hole for now. Possibly remove it or move it applying black max to threads post setting. Hole moved and another one added for application</p>		

		of black max to the threads after setting.		
9	Issues with tamper evident material applied to the trigger block screw.	Look at shortening the trigger block screw to recess the head in the trigger block and provide a pocket for black max. On hold	Vince Norton	12/19/08