Remington.

CITPIND

bcc: C. G. Dekanek B-87-10907

HOLD FOR REPLY

REMINGTON ARMS COMPANY, I

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357 TELEPHONE 13159 894-9961

Mr. Douglas Hamann 5551 Townline Rd. Wisconsin Rapids, WI 54494 June 4, 1987

Dear Mr. Hamann:

Examination has been completed on the Model 700 BDL 270 Win. caliber rifle, serial number B5282052, which you returned to us because of the accidental firings you experienced.

The returned firearm, which was produced in November of 1981, was found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had passed all necessary tests and inspections prior to shipment from our factory.

The general condition of the gun appeared to be excellent, and in going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal. It was noted that scope bases had been added to the rifle after it originally left our factory.

Examination of the rifle and trigger assembly could not duplicate the malfunction that was reported. All tolerances and dimensions were found to be normal. Also, factory seals were intact on the trigger adjustment screws, indicating no alterations were made to trigger adjustments outside our factory. Trigger pull was measured to be 5 1/2 pounds, and sear left with the safety in the "on-safe" position was well within our specifications at .010". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed. Inadvertent contact with the trigger while releasing the safety could cause a rifle to fire, which will pocur with all popular bolt action rifles.

Since we found your firearm to function properly in every respect, we are prepared to return it in its present condition. However, if you so desire, we offer the following alternatives: (1) Install a new trigger assembly with the present safety lever for \$35.00; (2) Install a trigger assembly without a bolt-lock which allows raising the bolt handle while the safety lever is in the "on-safe" position for \$35.00.