GTON ARMS COMPANY, INC.

Reminston

DETERS

Xc. J.P. Linde

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY".

October 16, 1960

Centerfire "Hammer Mark" Meeting

Present:

A.R. Baszczuk H.J. Baylor J.W. Bower W.W. Cook K.R. Couchman

G.E. Fletcher

A. Huffman

W.R. Globig J.A. Harter G.J. Hill

P.G. Johnson C.S. Poore G.E. Schineller

A meeting was held on October 15, 1980; at 2:00 in the P.E. & C. Conference Room to discuss the problem of hammer marks on M/700, 7400 and 7600 barrels.

The fellowing was established:

- 1. All barrels with hammer marks were produced on the new Upsetter.
- New Upsetter places bearels in Verson type tube and they do not cool for 18-24 hours were placed in H-frame and control
- 3. Hammer marks showed up after Harper Buff operations were introduced.
- 4. Only "No Finish Turn" barrels have hammer marks.

Questions to be answered:

barrels for affect the steel

Is the Black Oxide process not coloring properly?

Deedrate test 8,9,11,13 IPM - 55 ptal Bel

Centerfire "Hammer Mark" Meeting

Kevin Couchman and Carla Poore will follow a load of barrels with hammer marks (already through color) through strip, re-polish, re-harper and color in Dept. 79. They will also have a microstructure done of a barrel with hammer marks.

J.A. Harter, Supervisor Centerfire Bbl. Mfg. Area

dcw