

BOLT ACTION CALL BACKS

MODEL XP-100

DATE OF CALL BACKS

Set. 1992 To Aug. 1994

PROBLEMS

Possible miss-cut in stock inletting, the Pistol may discharge if Dropped on the Muzzle with the safety off (in the fire Position)

Return to: Remington

Attn: Dept. XPSC
Ilion, NY 13357

Set. 1989 To Dec. 1989

Firing pin head with below specification Heat treatment. Premature wear may show in this part which could eventually cause harder than normal bolt lifting, and in time could lead to an accidental firing.

Return to: Remington Arms Co., Inc.

Attn: Dept. FP
Ilion, NY 13357

Jan. 1987 To Oct. 1988

the Front guard screw may position it self in a manner that could promote Unintentional firing upon release or the safety or upon closing the bolt.

Return to: Remington Arms Co., Inc.

Attn: Dept. XP
Ilion, NY 13357

All SN under 7507984
*Except those with a
Prefix of "A" or "B"

Under cretin unusual circumstance, the safety selector and trigger of these firearms could be manipulated in a way That could result in accidental discharge.

Model

7

DATE OF CALL BACKS

Sep. To Dec. 1989

PROBLEMS

The firing pin head had a below Spec. heat treatment. Premature wear may show in this part, which could eventually cause harder than normal bolt lift, and in time could lead to an accidental firing.

Return to: Remington Arms Co., Inc.

Attn: Dept. FP

July to Dec. 1987

Trigger connectors were re-bent after they were heat treated because of this change the possibility of connector breakage was introduced.

Return to: Remington Arms Co., Inc.

Dec. 1993 to Jan. 1994

One of the parts in the trigger assem. may be out of specifications.

Return to: Remington Arms Co., Inc.

Serial number between

If the firearm is disassembled out side of the factory, it is possible to reassemble incorrectly producing off-center trigger alignment that may cause subsequent malfunction and accidental firing of the rifle.

7600000 To 7604000

Return to: Remington Arms Co., Inc.
or an RARC

Jan. to March 1990

The sear safety cam in a limited quantity of rifles made between March 6th 1990 and Jan. 10th '90 may have been softer than our specification. The "soft" part may show premature wear and may eventually cause harder than normal safety switch force. Return to:

Remington Arms Co., Inc.

MODEL
700

DATE OF CALL BACKS

Aug. 7th To Aug. 15th '90

PROBLEMS

The firing pin head had a below Spec. heat treatment. Premature wear may show in this part, which could eventually cause harder than normal bolt lift, and in time could lead to an accidental firing.

Return to: Remington Arms Co., Inc.
Attn: Dept. FP
Ilion, NY 13357

July 1987 to Dec. 1987

Trigger connectors were re-bent after they were heat treated because of this change the possibility of connector breakage was introduced.

Return to: Remington Arms Co., Inc.
14 Hoefler Ave.
Ilion, NY 13357

Dec. 1993 to Jan 1994

One of the parts in the trigger assem. may be out of specifications.

Return to: Remington Arms Co., Inc.
14 Hoefler Ave.
Ilion, NY 13357

Jan. to March 1990

The sear safety cam in a limited quantity of rifles made between March 6th 1990 and Jan. 10th '90 may have been softer than our specification. The "soft" part may show premature wear and may eventually cause harder than normal safety switch force. Return to:
Remington Arms Co., Inc.

MODEL

700

DATE OF CALL BACKS

700 17 Rem. Cal. Only
all serial number with
"C" and "Q" prefixes
Serial numbers starting
A658000 to B6302402 &
B6302403 to C6354486
Also V6291911 to V6292802
V6292831 to V6292869

700 SS

Only with catalog numbers
6080,9714,9725,9723
and serial numbers starting
with S670, S671 and S620.
In the Month of June 1992

PROBLEMS

Some of the .17 cal Rem. Barrels could
develop cracks and eventually split due to
unique combination of characteristics
present only in barrels chambered for .17
Rem. Return to: Remington Arms

Some trigger connector missed washing &
de-burring process which could make the
gun go off when closing the bolt.

Return to: Remington Arms

MODEL
600,660, AND MOHAWK 600

DATE OF CALL BACKS

All 600, 660 and Mohawk 600
*Except those serial numbers
that start with "A" and 660 that
have serial numbers starting with
"B".

All gold triggers and trigger with-
Out a "V" stamp.

PROBLEMS

Under certain unusual circumstance, the
safety selector and trigger of these
firearms could be manipulated in a way
That could result in accidental discharge.
Return to: Remington Arms Co., Inc.

If the trigger and safety switch of these
600, 660, Mohawk 600 series guns were
Manipulated in an abnormal fashion, the
rifle might accidental discharge.
Return to: Remington Arms Co., Inc.
Or an RARC