

To whom it may concern:

Enclosed you will find a Remington XP-100 .35 REM serial number B7520484. The gun was purchased 3/17/88 from Shooters Supply Holcomb, NY.

The gun had been fired approximately 35 times before it blew out on 4/30/88.

Of the 35 rounds fired thru the gun the last 10 rounds were handloads. These handloads had been carefully researched and fired in 3 different Thompson Contenders

previously with no adverse results. The load consisted of 43 grains of H322 with

a 180 grain Speer flat point bullet and large rifle magnum primers. The brass used was

once fired Remington brass which had each been checked for length. The individual charges had

each been carefully weighed. The resulting charges produced a high loading density with

the charge filling right up into the case neck thereby making it impossible to overcharge a

case. Enclosed you will find 2 of the spent cartridges. The loading data was taken from

a Sierra Manual. The firing was done on a range with all previous rounds observed on the target.

As you can imagine I am quite concerned about what happened as it could have resulted in serious injury. I would greatly appreciate any information you can supply me as to what may have happened and why, along with information about either repairing or replacing the gun.

Sincerely,
[Signature]