

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: USED R #: 006153
OUTSIDE WORK: TRIGGER ADJUSTING SCREWS RE-ADJUSTED, SCOPE MOUNTED, & SIGHTS REMOVED. DATE: 3-10-72
FIRED AMMO TYPE: _____ FROM: GIBSON PRODUCTS CO.
& CONDITION: _____ MISSOULA, MONTANA.
PROOF: R.F.P.-D INSP.: 9 TEST: 41 GUN #: 6325677
HEADING: _____ CODE: CT = 4/70
BREECH OPENING: _____ GA./CAL.: 2506
RECOIL SHOULDERS: O.K. CHECKED BY: PROSSER
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN-DAMAGED COMPONENTS. CONNECTOR CLEARANCE ON TRIGGER 1.070 ($\frac{MID = 1.0796}{1.0796}$) TRIGGER CLEARANCE IN CONNECTOR 1.091 ($\frac{MID = 1.093}{1.093}$) ADJUSTMENTS HAVING BEEN ALTERED MAKES IT IMPOSSIBLE TO DETERMIN CONDITION AFTER FINAL ASSEMBLY. AS RECEIVED, SEAR, CONNECTOR ENGAGEMENT = .005 MIN. IS .020.

COMPLAINT: "SAFETY DEFECTIVE"

INCIDENT: MAY HAVE BEEN FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION: COULD HAVE BEEN THE RESULT OF LIGHT TRIGGER PULL, 3LBS. AND UNDER MIN. SEAR, CONNECTOR ENGAGEMENT THIS WOULD PERMIT JAR OFF. IT COULD ALSO HAVE BEEN THE RESULT OF THE DIA EXCESS CLEARANCE BETWEEN TRIGGER & CONNECTOR WHICH PERMITS CONNECTOR-SEAR INTERFERENCE PREVENTING PROPER TRIGGER-CONNECTOR RETRACTION.