


Based on our findings, Remington Arms Company, Inc cannot accept any responsibility for the incident. It is possible that while the safety lever was being moved from the "safe" to the "fire" position, the trigger was inadvertently contacted. When the safety lever reached the "fire" position, the gun then discharged - as it is designed to do - because the trigger was being pulled with the gun no longer on "safe".

31



CONSIGNEE RECEIPT

<b>C.O.D.</b>	
<b>AMOUNT</b>	
<b>TOTAL</b>	<b>CASH</b>
400	

☐ — ONCE HERE  
IF CASH ONLY  
SEE INSTRUCTIONS

NUMBER TWO

<b>DATE RECEIVED</b>
<b>RECEIVED BY</b>

Rep Trace Trigger  
for the Assen  
Down