Remington Arms Co., Inc. Product Service Legal Case #:5498

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete Lit 12/17/2010 12/28/2010 12/28/2010 215210

Customer Information

First Name Last Name Street City State **Business** Zip Contact Type Age 610 S Connor Incident Don Hamilton Odessa MO 64076 H 816-807-9844

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status**

ΡI

PD Cause: 4038 Could Not Duplicate Concern

Unknown

C

1/10/11 Per letter with rifle, pushed safety to fire and gun fired without pulling trigger.cm

Concern: 1007 Fired on Safe Release

Firearm Information

S Fired on safety release

Model/Ga. SKU Serial Bbl. DOM Mfg. Type CF/BA 700/3006 SPR A6881526 LA 2/1/1980 Remington n/a

Date Where Purchased Purchased

Accessories Owner BOTTOM HALF OF SEE THRU

SIMMONS GUN SPEC OLATHE KS

MOUNTS

Y

Original

CONCERN:FSR

Ammunition Information

SKU Cal./Ga. **UPC DOM** Mfg. Type Mfg. Code Remington CL/180 Reload Other **Factory** Concern 0: Y N

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Cash Reim. Settlement Release of Claims Release Date Reimbursement Date Settlement Date APV APV

Per Ilion, replace TPA, clean, test at BLSM program price

> Repair/Replacement Repair/Replacement Cost Date 60.40 1/10/2011

1/10/11 Per Ilion, could not duplicate concern. Trigger assm very dirty. Replace TPA, clean, test fire under BLSM program price of \$20 + shipping and tax.cm 1/11/10 Left voice message for Hamilton with quote/inspect info. Awaiting reply.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/28/2010
Examination	Product Type		RF
	Action Type		A
_	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
			<u></u>

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5498&Type=Case

1/11/2011

	Description		22" 3006 SPR
	Date Code		LA
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D :	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS]
	Lift	Select	.011
Sear	Notch	Slightly Worn; Functioning	SLUGGISH
	Tests	Test Fired	False
Feeding Test	10313	False	
	Condition	Slightly Worn; Functioning	VERY DIRTY
Trigger	Puli	Select	7#
111660	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		BOTTOM HALF OF SEE THRU MOUNTS

Remington

	ir Instructions rm, and then include it with your firearm.)
Model Number: 700	Serial Number: A 688 1526
Are you the original owner?:	
Name: DAN HAMILTON	Date of Purchase: 1976
Address (no PO Boxes):	
1010 SCONNOR	1
City:	State: M 0 Zip: 64076
Phone (Daytime): 816-807-9844	Fax:
E-mail Address: Would like to receive future e-mail updates from R	
Please describe your problem: PUShed	SAFty to Fire t
Please describe your problem: PUShed GUN Fired without P	Mins Trigger
<u> </u>	
· · · · · · · · · · · · · · · · · · ·	
Ammunition Information:	
	Type: CoreLoK
Other (i.e. bullet weight/type, shot size, powder):	180 GIAIN
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used:	j
How often do you clean the bore? (Months or Number of	
How often do you clean the action? (Months or Number of	
How often do you clean the trigger assembly? (Months o	
Total de you count the digger assembly. (Pontils o	1 1111 70 988
Brand of lubricant used: 1+0 PPS	
1/-1	كرات دران المالية
	₩ 5= @ 5= 4 W -
	₩ JAN 0 4 2011 ₩

How often do you lubricate the bore? (Months or Number of rounds) How often do you lubricate the action? (Months or Number of rounds) How often do you lubricate the trigger assembly? (Months or Number of rounds reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? Comments: When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith? What were the services performed? Ship your INSURED firearm by either UPS or Parcel Post to: REMINGTON ARMS CO., INC **ATTN: Arms Service Divison** fler Ave Y 13357 ₿A6881526 N YOUR FIREARM OR IN THE SAME BOX WITH THE IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND mage in shipping and handling. Preferably,

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

- :: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)
- :: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

could not diplicate concern.

T.A. very DIINTY. Rephace TOA,
clear to Test fine under BLP

Con & Zo.oo + sain

e returned.)
oss or damage.

le the box. Shipments without a proper

Quite

QUOTATION

Remington Arms Company, Inc.

870 Remington Dr. P.O. Box 700 Madison, NC 27025-0700 ESTIMATING REPORT

Parts/Repairs Fax 800-243-9700 336-548-7801

www.remington.com info@remington.com

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPEACED PARTS

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order	Number	Description/Serial Nu	mber		Date R	eceived -	12/17/2010
RE00215210	RE00215210 A6881526 Account # - R-					te Date - it Date -	1/4/2011 1/10/2011
Customer DON HAMI 610 S CON	LTON			Return To DON HA 610 S CC	o MILTOÌ		1/10/2011
ODESSA. M	1O 64076 US			ODESSA	MO 64	076 US	
Phone (H) (816)-807-9844 Fax Phone (W) Email							
l .	ne MEX DISCOVER Card N	o		Exp. l	Date		
Daytime Phone	tomer Signature			Оре	n Acct. <u>R</u>		
1 	Desire Any Change Please Use				his Box	Date_	
10,35-01,550		•		-	inal river		servetti (i i
Reported		Probler	<u>Found</u>				
M123	FORWARD TO PRODI	UCT SERVICE	M123	FORW	ARD TO	PRODUCT	Γ SERVICE F
		Technician's C	omments	To the time.			
ProblemNote	could not duplicate con bolt lock program for\$	ncern,trigger assem very 20 + shpg	dirty.Repla	ace trigger a	ssembly,c	lean and tes	t fire under
	Estimate **C.O.D.	Shipping and Handling (Charges are	NOT Include	ed in this ()uote 🔆	
Material #	Material Description		<u>Oty</u>	Warranty <u>Y/N</u>	Price/ Unit	Discount Percent	Extended Amt
Part							
F305570B Service	X-MARK PRO 700 TRIG	ASSB RH BLACK (O	Ī	Y	\$94.00	0%	\$0.00
4000114	GR-SHIPPING & HANDI	ING (GUN REPAIR)	1	N	\$17.00	0%	\$17.00
4000116	GR-LABOR		1	N	\$20.00	0%	\$20.00
4000119	GR-TEST		Ť	Y	\$23.00	0%	\$0.00
4000294	GR-CHECK TPA		1	Y	\$17.00	0%	\$0.00
					Sub Total	:	\$37.00
				I	Est. Sales T	Гах:	
					Grand To	tal:	\$37.00







