Remington Arms Co., Inc. Product Service Legal Case #:4780

Case Information

RE# **Date Opened** Date Opened(PS)

Date Closed

Incident Date

Pre Lit Lit Obsolete

205793

Type

10/11/2010

Business

10/12/2010

10/12/2010

Street

10/3/2010

Reporter Gander Mountain

Gander Mountain 1313 Paul Bunyan Dr Bemidji MN 56601

City State Zip Age Contact

W 218-755-6150

Incident Information

Customer Information

Claims

Codes

Last Name

Repair Est.

Medical Treatment Medical Status

ΡI

PD

Cause:4006

Components

Altered Adjustments or

Unknown

fires on safe S release

Concern: 1007 Fired on Safe Release

10/19/10 Per note with firearm, discharges when safety turned off.cm

First Name

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl.

DOM

Remington

CF/BA

700/7MM REM MA

27271

S6697267 KD 5/27/2009 6:56:24 PM

Date Purchased

Where Purchased **BILL HICKS & COLTD** Accessories

Original Owner

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement

Cash Reim. Date Date

APV

APV

Per Ilion, replace rifle at no charge under

warranty

Repair/Replacement

Repair/Replacement

Cost

Date

222.00

10/19/2010

10/19/10 Per Ilion, the sear spring is out of position and it is unknown if this happened at the factory or if someone removed the trigger assembly and assembled it incorrectly. Replace rifle at no charge under warranty.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
 	Exam Date		10/12/2010	
Examination	Product Type		RF	
	Action Type		A	

	Assigned To	j	F.SUPRY
Cause	4006	Altered Adjustments or Components	
	Description		26" 7MM REM MAG SS
	Date Code		KD
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		STANDARD XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.012
Sear	Notch	Like new; Functioning	<u> </u>
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Like new; Not	SEAR SPRING IS OUT OF POSITION.IT IS UNDER THE REAR PART OF THE SEAR NOT THE FRONT

		Functioning	(MISSASSM ?)	
T	Pull	Select	2.5#	
Trigger	Altered	False		
	Sub-Assembly	X-Mark Pro		

Add Repair Est	imate Repair	Expedite Repair I	nquiry Re	epair Tools	CSR Tools	Reports	Table Maintenanc	e System			
						in the state					
			15000				•				
											politica de la companya della companya della companya de la companya de la companya della compan
,											
	Á			4000	and the second	6.4			Mary Hair		•
	2 GW 6-1	REInquiry - Re	77874			1 14					Max.
٠		1909), 1900 (1900)	(K.454, #42, 6)	arown nyddi							
		lumber: RE002057	33 Sena MM I	L S669/26/ M REM MAG Prod	odel 700 Cente uced: 05/27/20	r Fire Caliber 19 SKU: 27271		Bruce Travis			
7,4	48 K	Repair ESS INFORMATION :					Status.	Parked 10/12/2010	8 15:29 AM		
		Custamer			€ Received h	om Retu	ın Ta	, c	Received from		
1 W	68 7.41 5 S . 3 S . 3 S . 3	Name: GANDER MOU				27 P. C.	OER MOUNATIN		= 1 to deside de d	TEXAS (
	2 3 32 5 4	tiess 1: ATTN CINDY K tiess 2: 180 E 5TH ST		PO Box		1313	PAUL BUNYAN DRIV	PO Box			
		City SAINT PAUL				BEMI	THE PART AND PARTY OF THE PARTY				
		State: MN Zip Co	le: 55101	, Country:	US	МИ	Zip Code: 56601	Country US			(A) 1351
<i>j</i>	ueeu (FFL						
14	Contac	t / Condition Problems	Estimate : H	istory / Stalus	Shipping / Billin	ol		4.0			
	E Contract	e Code	User ID.	Desc1	***************************************	Desc2 🔺	Shipping Hold	F	nt Status () Paiked ()		
	23333	17/2010 11 New 11/2010 11 Expedite	bordenia bordenia	Repair Add		To:	Interface Hold Estimate Sent	Committee of the Commit	10 8:15:29 AM		
	331861	12/2010 6: Maint	travisbw	Repair Ma	······································	Status: F	Rats Received	A CONTRACTOR	acements Location		
	-2.6	12/2010 7: Estimate	travisbw	Estimate U		Status: F	Passed Inspecti	Side Spirit Block Sec.	ILN Location		
	10/	12/2010 8: ParkedExt	pencerl	2012	ent on arder	(. Has Been Appro		ILN er Number		fl. so.
			W. 13.12				Exclude TATC				
	Rec	air Search				X ()		Refre	sh Clo	se .	
• "		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							**************************************		
	*					* -	4.				
	77										
	•	4	100	Diame							
						100	1.00				
					40.00						
		•			S. 10 July 19			1 A 4			

I wanted to keep this gun in tact so I askro Bruce to order a new gun instead of replacing the TA.

The SEAR Spring was on the wrong 5, de of the trigger causing the sear to move as the safety was released. Unknown where this improper assembly occurred either at the tockery or some one removed the TA and

DECELY Empled it incorrectly,

FRED Supey 10/12/10

4780

Hello,

Enclosed is a Remington 700 Serial # S6697267, 7mm Rem Mag. It has a faulty Safety on it, or trigger not sure which but this is what happens.

Randy (owner) brought this gun in very visibly shaken yesterday 10/3/10. Asked him what had happened and he said, "I almost shot my buddy." So I asked for a little more detail. He was at the range sighting it in getting ready for deer season. The gun was purchased about a year ago but hasn't been taken out of the box until this last weekend. He was shooting it and they decided to change out targets. Gun was in a rest on a table and Randy flipped on the safety to head down range. Firearm discharged missing the gentleman's leg by a matter of inches he felt the muzzle gasses hit his leg and thought he was hit. Upon inspection he was very narrowly missed. They brought the gun into me right after this. I said I would talk to you folks on Monday and see what there was to do. Just to try out the gun for myself I put the safety on worked the action and flipped off the safety and sure enough it dry fired in my hands. It doesn't do it every time, but it has done it pretty consistently. Also noted that despite numerous ammo changes he was unable to get groups of less than 5 or so inches.

I know Randy really likes his Remington's he has bought a ton of them from me. He is unhappy with this particular one. Fixed or not he isn't comfortable with this gun. He would like to know what options he has.

Thank you for your time,
Josh Breyfogle
Hunting Manager
Gander Mountain #484
Bemidji, Mn
218-755-6150
Gm484ops@gandermountain.com

Sean Spr. out of Position. check over replace TPA, Splety check + Test fine At N/C

marrianty

S6697267 Model: 700

RF00205792

Ship to Reminston X4th Droduct Service



Service Request

Service Order # 4195

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726 14 Hoefler Ave

Ilion, NY 13357

Attn:

Date Shipped: 10/05/2010

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 3-41-007-01-7B-01210

Attn: Gun Parts Dept. 1313 Paul Bunyan Drive

Bemidji, MN 56601

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Rifle Туре:

Serial Number: S6697267

Model: 700

Cal/Ga.: .7 Rem Mag

Cased?:

DESCRIPTION OF ITEM RETURNED:

Remington 700 SPS Stainless 7 Rem Mag

REASON FOR RETURN:

Firearm Discharges when safety turned off.

ATTENTION VENDOR

Please contact me with any questions or concerns.

Mark Davis (218) 755-6150

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain

Attn: Cindy Kilbride

180 E. Fifth Street Suite 1300

St. Paul, MN 55101