۹.

			Prod	n Arms Co., I uct Service Case #:6282	nc.							
233591 6/13	Opened /2011	Date Opened(6/14/2011	PS)	Date Closed 6/14/2011		Incide	nt Date		Pre Li	t	Lit	Obsolete
Customer Information Type Business	First Name	Last Name	Street		lity	State	Zip	Age		I	Conta	ct
Incident	Martin	Tremethick	145 Johnson	n Rd. Neg	aunee	MI	49866)6-475 ieth@c	-7966 harter.net
Incident Information Claims		Codes		Repair	Est.	Me	dical T	reatm	ent		Medic	al Status
PI PD S C FBO	Cause:4015 -Concern:1020	Improper Mainte Fired on Bolt Op					Unkn	own				
Customer sent rifle in	with his email.	He stated that the	rifle will fire	when the bol	t is ope	ned. He	would	like th	e bolt lo	ock n	nodific	ation. df
Firearm Information												
Mfg.		Туре		Model/Ga.		SKU		Serial A6785030			Bbl.	DOM
		CF/BA ere Purchased ART LAWRENCE KS		700/3006 SPRG Accessories		n/a A67 Original Owner U		A0/830	30	PV	6/14/1979	
CONCERN:FBO												
Ammunition Informat	on - None Def	ined										
Other Products Inform	ation - None D	efined										
Settlement												
			Remingt	ton/700/CF/B.	4			Ca	h	Dair	m Dof	e Cash Dat
Settlement	Release	e of Claims	Release	e Date	Reim	bursem	ent	Settle			n, Dai APV	APV
Per Ilion - Quote to repair under BLM												
		blacement Cost F 30.40	Repair/Repla 6/23/2									
6/23/11: Per Ilion - TA	has a partially	v dried & sticky lu	be residue ca	using part to	work sh	uggish. I	Replace	TA, c	lean &	test f	ire und	ler BLM. df

6/23/11: Per Ilion - TA has a partially dried & sticky lube residue causing part to work sluggish. Replace TA, clean & test fire under BLM. df 6/23/11: I left msg for customer to call regarding the quote. df 6/23/11: Customer apprvd quote & paid by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/14/2011
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4015	Improper Maintenance	
Barrel	Description		22" 3006 SPRG
	Date Code]	PV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown	Slightly Worn;	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6282&Type=Case

۰.

L	Condition	Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description]	M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	011
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	STICKY LUBE RESIDUE CAUSING PARTS TO WORK SLUGGISH WILL FOLLOW DOWN
	Pull	Select	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	7

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=6282&Type=Case

,01

Martin



From:"Remington Information" <info@remington.com>Date:Friday, May 20, 2011.7:57 AMTo:<mtremeth@charter.net>Subject:700 BDL [Incident: 110515-000016]

Recently you requested personal assistance from our on-line support center. Below is our response.

We will assume your issue has been resolved if we do not hear from you within 72 hours.

Thank you for allowing us to be of service to you.

To access your question from our support site, click her-

T.A. has A partially divided a sticky lube residue causing

Subject 700 BDL

BDL PARts to WORK Sluggish. No mee TPA, cleAN + TOSS fike UNDERBLP FOR \$ 20.0045 htp

Discussion Thread

Response (Ron)

A6785030 Model: 700 RE00233591

Dear martin,

Under the program you are responsible to get the gun to the factory through a UPS Hub or Distribution Center, you do not have to go through a dealer.

You can send directly to the factory and we can send it back to you!

() wat

Customer (1 Martin)

05/19/2011 07:26 PM

05/19/2011 08:07 AM

05/15/2011 08:27 AM

How do I go about getting my rifle to the factory? Will I have to send it through a FFL dealer? Can you issue a UPS pick up authorization?

From: Remington Information Sent: Thursday, May 19, 2011 8:07 AM To: <u>mtremeth@charter.net</u> Subject: 700 BDL [Incident: 110515-000016]

Response (Ron)

Dear Martin,

Your gun was made in 1979 and is part of a Safety Modification Program, were you get your gun to the factory. We clean and inspect your gun and remove the bolt lock mechanism for a \$20.00 charge plus shipping and handling. In the event the trigger needs to be replaced this is also included.

Customer (1 Martin)

I have a 30-06 700 BDL #A6785030 that has the following problem. When I switch from safety to fire, the rifle will not fire. It's as if the safety is still on. When I move the bolt handle to open the bolt the rifle fires. How can I get this problem corrected? Sincerely, $\square E C E U - \square$

Martin Tremethick

BY:

145 Johnson Road Negaunee, MI 49866 906 475 7966

Question Reference #110515-000016

Product Level 1: Firearms Date Created: 05/15/2011 08:27 AM Last Updated: 05/20/2011 07:57 AM Status: Waiting







