Remington Arms Co., Inc. Product Service Legal Case #:7651

Cas	se Info	rmation													
1	RE#	Date (Opened		Date O	pened(P	S) Date C	losed	Incide	ent	Date	Pr	e Lit	Lit	Obsolete
20	66897	5/8/2	2012		5/	9/2012	5/9/2	012							
Cu	stomer	Informatio	n												
I	ype	Business	First N	Name	Last N	Name	Street	City	Stat	te	Zip	Age		Cor	itact
Inc	ident		Ra	у	Stol	kes	161 S. 200 West	Wellsville	e UI	ſ	84339		E ray	y.stoke	s@atk.com
Inc	ident I	nformation													
		Claims				С	odes	F	lepair	Es	st.	Med Treat			Medical Status
PI													-		
PD	I			Cause:	4006	Altered	Adjustments or								
S	Fired	while worl		Causo.	.4000	Compor	nents					Unkn	own		
3	the bo	olt	, i	Conce	rn:1008	Fired on	Bolt Closing								
С															
5/1	8/12 P	er letter wit	th rifle,	this fir	earm ha	as never t	fed cartridges ver	y well since	the ti	me	it was	new.]	Remin	ngton s	ent some

new parts but it did not solve the problem. After talking to a gunsmith he decided to polish the feed rails a little. After he put it back together the first 2 cartridges cycled through fine but still did not feed cleanly. He cycled the last cartridge from the magazine and as he closed the bolt the cartridge fired in his garage. Since that time he has cycled the bolt over 100 times without a reoccurrence. He has also fired a 1/2 dozen cartridges with no problems. He has pulled the external trigger screw on the trigger in and out, this trigger is not as light as some of my other firearms.cm

Firearm Information

Mfg.	Туре	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/300 RUM	27140	S6717753	BE	1/22/2010 2:54:22 PM
Date Purchased	Where Purchased	Accessories	Original Owner			
	AL S SPORTING GOODS, INC.		U			
CONCERN: FBC						

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion, as a good-will gesture, will repair as needed at no charge						
	Repair/Replacement	Repair/Replacement				
	Cost	Date				
	50.39	5/18/2012				
5/18/12 Per Ilion, trigger pu at no charge.cm	Ill set below minimum s	pecs. Trigger is not retu	ming. As a good-w	vill gesture, wi	ll repair a	s needed

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7651&Type=Case

5/18/2012

	Exam Date		5/9/2012
Examination Product Type RF Action Type A Action Type A Assigned To T.NAGLE Cause 4006 Altered Adjustments or Components Description 26" 300 RUM Date Code BE Bore Plugged False Bore Plugged False Fired False Fired while Obstructed Muzzle/Crown Condition Muzzle/Crown Condition Slightly Worn; Functioning Shroud Slightly Worn; Functioning Bolt Face Face Slightly Worn; Functioning Bolt Face Mandle Slightly Worn; Functioning Condition Slightly Worn; Functioning Extractor Condition Cut Condition Select Locking Lug Condition Bock Condition Select Description Slightly Worn; Functioning Receiver Condition Slightly Worn; Functioning Receiver Condition Slightly Worn; Functioning Fore End Condition Select-	RF		
Examination	Action Type		A
			T.NAGLE
Cause		Altered Adjustments or Components	
	Description	<u>h</u>	26" 300 RUM
		False	
Barrel		False	
		False	
	Fired while Obstructed	······································	1
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning Slightly Worn; Functioning Slightly Worn; Functioning Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	BRAKE HAS BEEN REMOVED/MISSING
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Deseiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.013
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	10303	False	
	Condition	Slightly Worn; Not Functioning	IRIG NOT RETURNING
Trigger	Pull		2.5#
	Altered		PULL SCREW ALTERED
	Sub-Assembly	X-Mark Pro	

Service Request

Parts and Repairs: P:800-243-9700/F:336-548-7801

.

Remington Service PO Box 700

This document is a summary of your request for service. Please review the document for securacy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service.PLIASE

Madison, NC 27025-0700 www.Remington.com ATTN: ATTN product services

ZU" BE1/10 2.5[±] ,013

	Serial Number / Description	7651	· •	10/2012
SR00018636	S6717753 Model 700 RIFLE Caliber 300	10	Date Printed: 043	0/2012
Customer:	Model AVO RIFLE Calloer 300	Destination:		
RAY STOKES		Arms Services		
151 S 200 W WELLSVILLE, UT 84	730 TIC	14 Hoefler Av Ilion, NY 13		
WELLSVILLE, UI 84	239 465	lindi, N I 13.	557 05	
Email: ray stokes@atk.co	om he item(s) will be evaluated by our repairman to det:	Email:	motor policy If it is more firmers	
	, you will be contacted with an estimate before work		fairty policy. If it is your meanin	сш be
		قو		
· ·				
Reason For Return	NONLOT SERVICE FOR DEDECTION			
MI25 - FOKWARD IOF	RODUCT SERVICE FOR INSPECTION			. [
apprend D an mant Castler		an a		THE CALL THE THE
ustomer had round go off	while working the bolt and once while gun was en	npty and working bolt.		and the second secon
Parts And Service Details laterial Type		Oty Warranty	Price Dis	
laterial Type	Description	Qty Warranty Needed	TIRE DE	c Amount
67177	′53			
67177 ^{odel:} 700	_			
odel: 700	_	T	t = t + b = b	W MIN SI
odel: 700		TRig. pu	ull set be lo	w min SI
odel: 700		TR19. pu TR19.1	ull set be lo s not return	w MINSI
odel: 700		TR19. po TR19. 1	111 set be lo s not return 1.11 Gisturio u	w min SI VINQ. AS II MARIN
odel: 700		TR19. po TR19.1 Good-4	111 set be lo s not return s 11 Gesture u	w mins VINQ. AS II MPRIN
odel: 700 RE00	0266897	Meede	d at (Y/C	w min si unq. As II MPHin
odel: 700 RE00		Meede	111 set be lo s not return s 11 Gesture u d ot 14/c ware only	w min s ung. As 11 (MpAin
odel: 700 RE00	0266897	Meede	d of (Y/C WARBANKy Sub Total:	.00
odel: 700 RE00	0266897	Meede	d D+ (Y/C WAAQAA hy Sub Total: Est Sales Tax:	. 00 . 00
odel: 700 RE00	0266897	Meede	d D+ (Y/C WAAQAA hy Sub Total: Est Sales Tax: Grand Total:	.00 .00 \$.00
odel: 700 RE00	0266897	Meede	d D+ (Y/C WAAQAA hy Sub Total: Est Sales Tax: Grand Total:	.00 .00 \$.00
odel: 700 RE00	0266897	Meede	d D+ (Y/C WAAQAA hy Sub Total: Est Sales Tax: Grand Total:	.00

May 1, 2012 To whom it may concern,

Yes, this firearm scared the jeepers out of me. I have been around firearms and used them for many years. I am 53 years old and until now never had anything like this happen. I promise this is true (I just had to add that last bit).

This firearm has never fed cartridges very well since the time it was new. I contacted Remington and was sent a new follower, spring, and magazine. This did not solve the problem. Most of the 300 or so cartridges fired through this firearm have been loaded one at a time while at the range.

After talking to a gunsmith I decided to polish the feed rails a little. On April 28th I removed the bolt, took the barreled action out of the stock, put it upside down in a holder, did a little polish, and put the firearm back together to see if it would feed any better. The first two cartridges cycled through were uneventful, but still not feeding cleanly. I cycled the last cartridge from the magazine, and as the bolt closed the cartridge fired – in my garage!

I placed the firearm on the bench and then took some time to clear my head while waiting for the ringing in my ears to calm down. I ejected the spent case and did a visual examination of both the case and action. There was nothing unusual. I moved the bolt forward, closed it, and as it closed the firearm again released the firing pin - a very distinct click just before the bolt was fully closed. This time there was no cartridge in it though. Once again I examined the firearm, and still found nothing unusual. Since that time I have cycled the bolt over 100 times without a reoccurrence. I have also fired half a dozen cartridges. Everything operates as expected. As you can imagine, I no longer have any trust in this firearm.

As to the pull weight of the trigger, I have turned the external screw on the trigger in and out. While I do not have a trigger scale to measure the weight, this trigger is not as light as some of my other firearms. This one is for hunting and field use, so I do not want an extra light trigger on it. No modifications have been made to any part of the trigger assembly other than turning the external screw located on the trigger.

I sincerely hope you can find an explanation for an involuntary, unintentional, unplanned, dangerous discharge. Please contact me before shipping it back so I can be updated on what was found and what was done to insure it will not happen again.

Sincerely, Stokes

435-764-5409 Cell 435-245-4627 Home

161 S. 200 W. Wellsville, Utah 84339





