Remington Arms Co., Inc. Product Service Legal Case #:8007

Case Information

Date Opened RE# Date Opened(PS) Date Closed **Incident Date** Pre Lit Lit Obsolete 10/5/2012 10/5/2012 284515 10/4/2012

Customer Information

Business First Name Last Name Street City Zip Contact Type State Age Cronkhite 670 West Hill Rd. 13808 H 607-263-2016 Incident Donald Morris NY

Incident Information

Claims Codes Repair Est. **Medical Status** Medical Treatment

ΡI PD

Cause: 4006 Altered Adjustments or Components Concern: 1007 Fired on Safe Release

Unknown

S FSR

SR# 29593: Reason for Return - Perform safety checks on trigger assembly. Service Request Section - 3 incidents of trigger going off when removing the safety. df

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl. DOM

Remington

CF/BA

7/7MM-08 REM

24741

S7632101 KS 5/5/1998

Date Purchased

Where Purchased

Accessories

Original Owner

HORTON DIST CO INC * LEW REAR BASE, BOTTOM HALF OF RING

U

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/7/CF/BA

Settlement Release of Claims Release Date

Reimbursement

Cash Settlement Reim. Date Cash Date APV

APV

Per Ilion - Quote to repair

@ a discount

Repair/Replacement Cost

Repair/Replacement

Date

10/10/12: Per Ilion - TA dirty & set screws altered. Trigger not releasing properly. Replace TA, clean & test at 1/2 normal cost - quote. Customer approved & paid quote on 10/9/12. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		10/5/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		20" 7MM-08 REM SS
	Date Code		KS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	ACTION DIRTY
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.012
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	Select	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		REAR BASE,BOTTOM HALF OF RING

Service Request

Remington Service PO Box 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

ኢଟ 1012

SR00029593

Service Request Number

DONALD CRONKHITE

MORRIS, NY 13808 US

670 WEST HILL RD

Serial Number / Description

S7632101

Date of Request:

Date

09/19/2012

Printed: 09/19/2012

Customer:

Destination:

Arms Services

14 Hoefler Ave

Ilion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if i returned. If not, you will be contacted with an estimate before work is performed.

S7632101

Reason For Return

M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

Service Request Section

3 INCIDENTS OF TRIGGER GOPING OFF WHEN REMOVEING THE SAFETY WILL EMAIL DELL / FS

Parts And Service Details Material

Type

Description

Needed

Warranty

Disc

BUINGTON FOLKS: I COULD NOT GET THE REMR SCOPE MOUNT OFF THE ENCLUSED GUN. IF YOU COULD REMOVE IT IN ADDITION TO CHECKING THE GUNS SAFETY IR WOULD GREATLY HPRECIATE IT. IF THERE IS A CHARGE FOR THAT STELLICE I WILL GLADLY PAY IT.

I AM 70 YMARS OLD AND I LOVE THIS GUN, ALONG WITH MY OTHER ZINE POLIDETON GULS. I JUST WANT TO BE IT'S SAFE TO SHOUT WITHOUT FEAR 11'S GOING TO GO OFF WHEN I PUSH THE SAFETY OFF-

(Per request to remove reprement) T.A. dinty + set screws Altered. TRA, clear repost of 1/2 rion was

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Continte CCT 1 0 2012

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00







