Remington Arms Co., Inc. Product Service Legal Case #:7558

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 263751 4/3/2012 4/4/2012 4/4/2012

Customer Information

City **Business** Last Name Street Contact Type First Name State Zip 7721 Moreland Rd. Theodore H 228-475-6885 Incident Mike Graham AL36582

Incident Information

Repair Est. Claims Medical Status Codes **Medical Treatment**

ΡI

PD Cause: 4038 Could Not Duplicate Concern

Concern:1007 Fired on Safe Release

Unknown

S FSR C

SR# 15137 - Service Request Section: Claims rifle fires when going from safe to fire - was bought 2nd hand. df

Firearm Information

Mfg. Remington

Type CF/BA

Model/Ga. 700/270 WIN SKU n/a

Bbl. DOM Serial

Date Purchased

Where Purchased

Accessories

Original Owner

A6361329 9/29/1976 DI

AMARILLO HDWE AMARILLO TX

Reimbursement

N

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Cash Settlement Reim. Date Cash Date

APV APV

Per Ilion - Quote to repair under BLM

> Repair/Replacement Cost

Repair/Replacement

Date

\$29

4/9/12: Per Ilion - Could not duplicate concern. TA dirty & set screws altered. Replace TA, clean & test under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		4/4/2012
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	
Ватеі	Description		22" 270 WIN
	Date Code		DI
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7558&Type=Case

4/24/2012

ı	1		
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	DENTS,MARS,SCRATCHES
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	.009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	T csts	False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY,TRIG HAS MIN RETURN
	Pull	Select	3.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Service Request

Remington Service PO Box 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

OLANI ation 3.5[±] TENT 009

Service Request Number

Serial Number / Description

SR00015137

A6361329

Model 770

Customer: MIKE GRAHAM

7721 MORELAND RD THEODORE, AL 36582 US 1220

Date of Request:

03/13/2012

te Printed: 03/13/2012

Destination: Arms Ser

Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

CLAIMS RIFLE FIRES WHEN GOING FROM SAFE TO FIRE. RIFLE WAS BOUGHT SECOND HAND.

Parts And Service Do

Time

Description

Qty War Needed

Price

Disc Amount

5A6361329

Model:

700



RF0026375

ECEIVET APR 0 9 2012

BY: ..

could not displicate concern.

T.A. disty + set screws aftered.

TUP ACE TOA, CLEARY NOST UNDER

BCP for \$ 20.+

Quote

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00







