**PrintDisplay** Page 1 of 2

> Remington Arms Co., Inc. Product Service Legal Case #:8325

1 256	INTOFF	nation

RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit Obsolete 12/10/2012 292144 12/11/2012 12/11/2012

Customer Information

First Name Zip Type Business Last Name Street City State Contact Age H 423-646-6164 Incident Chris Scher 287 Hamilton Lane **Bluff City** TN 37618 E scherc 1@earthlink.net

Incident Information

Claims Codes Repair Est. **Medical Treatment Medical Status** 

ΡI

PD Cause:4015 Improper Maintenance S FBC

Unknown Concern:1008 Fired on Bolt Closing

SR# 36428 - Service Request Section: Firearm went off as the consumer closed the bolt. df

Firearm Information

Model/Ga. SKU Serial Bbl. DOM Mfg. Type CF/BA 700/3006 SPRG 29712 S6206871 OM 7/14/1992 Remington **Date Purchased** Where Purchased

Original Owner Accessories

HICKS INC SCOPE BASE, BOTTOM HALF FRT RING U

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Reim. Date Cash Date Cash Release of Claims Release Date Settlement Reimbursement Settlement APV APV

Per Ilion - Quote to repair @ 1/2 normal cost

> Repair/Replacement Repair/Replacement Cost Date

12/13/12: Per Ilion - TA has a dried & sticky lube residue causing parts to work sluggish. Replace TA, clean & test at 1/2 normal cost - quote.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/11/2012
	Product Type	]	RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4015	Improper Maintenance	
Barrel	Description	]	22" 3006 SPRG SS MR
	Date Code		OM
	Bore Plugged	False	
	Buiged	False	
	Fired	False	•
	Fired while Obstructed	]	
	Muzzle/Crown Condition	Slightly Worn; Functioning	

PrintDisplay Page 2 of 2

	Firing Pin	Slightly Worn; Functioning	SLUGGISH
Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	DIRTY,DRIED LUBE RESIDUE
Overall	Stock Condition	Slightly Worn; Functioning	DIRTY
	Fore End Condition	Select	
	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
C C .	Description		STANDARD SAFETY
Safety	Function	Like new; Functioning	
Sear	Lift	Select	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY PARTS WORK SLUGGISH WILL FOLLOW DOWN
	Pull	Select	6#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,BOTTOM HALF FRT RING

Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number

Serial Number / Description

SR00036428

\$6206\$71

Model 700S RIFLÉ

Customer: CHRIS SCHER

287 HAMILTON LANE

BLUFF CITY. TN 37618 US

Date of Request:

Printed:

11 27 2012

11 27 2012

Destination: Arms Services 14 Hoefler Ave

Bion, NY 13357 US

Email: scherc! @earthlink net

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

Service Request Section

irearm went off as the consumer closed the bolt. Issue seems to be in trigger itself or the cocking mechanisms in the bolt action.

Kept in a safe and only used

Parts And Service Details Material

Disc Amount

<sup>2</sup>856206871

Model:

T.A. has A dried + Sticky lube rusidue cousing parts to WORK Slugger. Ry. TOA, CLEAR TOST At 1/2 Normal

THIS IS NOT AN ENVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: Est Sales Tax: . 00 .00

Grand Total:

\$.00

SHIPPED DEC 13 PAID

This Service Request number is only valid for this return.

## Please follow these guidelines:

- Include a copy of your proof of purchase to assist in the evaluation of your repair \_ G.++
- Record your serial number for future reference
- Remove any accessories (sling, scope, scope mounts, case, etc.) COM of not remove mon? unless these items are needed to assist in the evaluation.
- Properly package your unloaded firearm. Do not ship in your hard case (note: Original boxes are not returned with repair)
- Do not send live/loaded or spent ammunition with your firearm.
- Please package the ammunition in a secure carton or box.
- The package should be stuffed to prevent movement.
- Include service request number.
- Shipment of live ammo must be via U.P.S. only.
- Please advise your local U.P.S. mailing center of the contents so that a special Other Regulated Materials-Domestic (ORM-D) label can be applied.

Please let us know of any address change requests by email or phone. Our returns process will take approximately 2-3 weeks to complete and a confirmation email will be sent once we have shipped your firearm.

Should you have any further questions or concerns please don't hesitate to contact us via email (info@remington.com << mailto info@remington.com>>) or by phone at 800-243-9700, M-F 9am - 5pm, EST. We look forward to helping you resolve this issue!

Mailing Label:	
cut here):	
~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	

**Arms Services** SR# SR00036428 14 Hoefler Ave Ilion, NY 13357 US

Email:







