Page 1 of 3

Remington Arms Co., Inc. Product Service Legal Case #:9434

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 328960
 11/27/2013
 11/6/2013
 12/2/2013
 10/26/2013
 X

**Customer Information** 

Type Business First Name Last Name Street City State Zip Age Contact H 337-344-9730 102 Bear Creek Ct. Broussard LA 70518 Reporter Robert Roger Sr. E rroger 104@aol.com Incident Gerard Roger 609 S. State St. Abbeville LA 70510 H 337-296-7282

Incident Information

Claims Codes Repair Medical Medical Est. Treatment Status

PΙ

PD Shot a hole in 4- Cause:4006 Altered Adjustments or Components

Components Unknown

S FSR Concern:1007 Fired on Safe Release

C

11/6/13: Gerard called in. He stated he was using Robert's rifle on 10/26/13 and it fired on safe release. Gerard said he shot a hole in his 4-wheeler and said he is not worried about that at all. He stated that he read online about the recall on this rifle but the trigger does have the "V" stamped on it. He said that Robert wants the trigger replaced & the bolt lock removed. df

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM
Remington CF/BA Mohawk 600/243 WIN n/a 6743141 KY 5/1/1974

Date Purchased Where Purchased Accessories Original Owner

U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/Mohawk 600/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Date Date APV APV

Per Ilion -Repair @ n/c goodwill

Repair/Replacement Repair/Replacement Cost Date

\$44

11/7/13: Mailed ARS, letter, SR paperwork. Box order# 1560351. df 12/4/13: Per Ilion - TA dirty & set screws altered. Trigger not returning properly. Per request to replace TA, check over & test at n/c - goodwill. df

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9434&Type... 12/26/2013

Page 2 of 3

#### Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/2/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	
	Description		18.5" 243 WIN
	Date Code		KY
	Bore Plugged	False	
Barrel	Bulged	False	
Darrei	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
Duit	Handle	Slightly Worn; Functioning	ALTERED
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Worn; Functioning	MARS,SCRATCHES,DENTS
	Fore End Condition	Select	
D '	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
Sear	Lift	Select	.008
	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9434&Type... 12/26/2013


Trigger	Condition	Functioning	PROPERLY	
	Pull	Select	2#	
	Altered	True	SET SCREWS ALTERED	
	Sub-Assembly	Other Remington		

# Remington

18.6" 245/ 247

November 7, 2013

9434





Robert Roger Sr. 102 Bear Creek Ct. Broussard, LA 70518 Phone: 337-344-9730


Ref # 9434, Model Mohawk 600, Serial # 6743141

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory. This shipping label is for a UPS Hub or UPS Terminal. A box will arrive separately.

Please include a copy of this letter and service request to put inside the shipping container. The letter and service request inside are important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm.

Sincerely, Dell Fulcher Consumer Affairs Administrator Remington Arms Co, LLC Phone: 1-800-243-9700 ext 8686

Fax: 336-548-7872





T. A. dinty + Set screws All.

Trig Not put properly. Per

Request to up T. A. cleckouer

+ resturd. BLP Con . M/C

Good-Will.

#260974

Remington Arms Company, LLC • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

### Service Request

## Remington Service PO Box 700

Madison, NC 27025-0700 ATTN: Product Service

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

SR00066888  Customer: ROBERT ROGER SR. 102 BEAR CREEK CT BROUSSARD, LA 70 Email:		Destination: Arms Services 14 Hoefler Ave Ilion, NY 13357 Email:		11/07/2013 11/07/2013
Reason For Return M123 - FORWARD TO I	PRODUCT SERVICE FOR INSPECTION			
Product Service # 9434. dn  Parts And Service Details  Material Type		Oty Warranty Needed	Price	Disc Amount
THIS IS NOT AN INVOICE. Theing sent based on the conver-	This is a pre-estimate to repair, recondition, or replace the ite sation with our representative.	em(s)	Sub Total: Est Sales Tax: Grand Total:	.00 .00 \$.00

#### ARS LABEL REQUEST FORM

DATE: 11/07/2013	***************************************	Service Request *	\$8,300,608.
QEANIDY	***************************************	WEIGHT PER PACKAGE:	19 (388
REQUESTED BY: Galdenin		email address;	I WILL MAIL LABEL:
Business:	Remington Servi PO Box 700 Modison, NC 27 www. <b>Reming</b> to	101.5-9700	
	LABEL IN	IFORMATION	
MAIL LABEL TO:	ROMERT ROCK ICT BEAR CRE OROUSSAND, SECREMANN Consider	EN CT.	
RETURN ITEM TO:	ILN Anns Services		
	1890 840	196	all Curr uso 1 of 1 8.8 CSS
ATTN: Product Service	884 338 27 28 88	0.186 CHARSE 8.00 AE-PIECE PUB PATE CHROS: 0.00 0.8 0.00 0.00 0.8 0.00 PR 0.8	9 SD 8 99
ATTIV. FTUUUCLORIVICE			





