Remington Arms Co., Inc. Product Service Legal Case #:9339

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 325070 10/23/2013 10/24/2013 10/24/2013

Customer Information

Type Business First Last Street City State Zip Age Contact

Incident David Lesley Way Greer SC 29650 E davidlesley@charter.net

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡĪ

PD Cause:4038 Could Not Duplicate Concern

Unknown

S FBO Concern:1020 Fired on Bolt Opening

C

Per SR00064355 Service Request Section, consumer states the gun will go off when opening the bolt handle. jbi

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial
 Bbl.
 DOM

 Remington
 CF/BA
 700/270 WIN
 N/A
 A6645024 OQ 7/26/1978

Date Purchased Where Purchased Accessories Original Owner

KEI % K MART NEWNAN GA TWO PIECE BASE U

CONCERN:FBO

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Date Date APV APV

Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.

Repair/Replacement Repair/Replacement

Cost Date

\$29

10/25/13: Per Ilion, could not duplicate concern. Replace trigger assembly, check over, and test under BLP for \$20 plus shipping. jbi 10/29/13: Customer sent letter to consumer service approving quote with a credit card. jbi

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9339&Type... 10/29/2013

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		10/24/2013
Examination	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
	Description	,	22" 270 WIN
	Date Code		OQ
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False]
	Fired while Obstructed	\cdot	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning]
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning]
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	REC'D UNASSM
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.010
	Notch	Slightly Worn; Functioning	
	-	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	1
	Pull	Select	5.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Bolt Lock	1
Non-Remington Components			TWO PIECE BASE

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=9339&Type... 10/29/2013

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00325070	A6	A6645024			Date Received: Estimate Date: Date Printed:			
Customer: DAVID LESI 320 NEW TA GREER, SC	RLETON WA	Return To: DAVID LESLEY WAY 320 NEW TARLETON WAY						
Please Circle One VISA MC Open Account	DISCOVER		,	Ex ₁	o.Date			
Approval Signatur		Time	e to Call:		_ Date:			
If you desire	any change, p	please use the reverse side for your comme	nts and mark this b oblems Found M123 - FOR				ÍŃSPE	CTION
		Technici	an Comments					
could not duplicat	e concern.repl	lace trigger assembly, check over and test fi	re under bolt lock	program for \$20).00 + shippi	ng		
Material	Type ES	TIMATE (note: C.O.D./Shipping and Ha Description	andling Charges a Qty Needed	re NOT Includ Warranty	ed in this Q Qty From Inv	uote.) Price	Disc	Amount
F305570B 4000114 4000116 4000119	Part Service Service Service	X-MARK PRO 700 TRIG ASSB RH BL GR-SHIPPING & HANDLING (GUN RI GR-LABOR GR-TEST	ACK (OS) 1	Warranty Billable Billable Warranty	1 1 20	.00 17.00 1.00 .00	0 0 0	.00 17.00 20.00 .00
		•						
					Est	o Total: Sales Tax: and Total:		37.00 .00 \$37.00

Service Request

Remington Service PO Box 100



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number | Serial Number / Description A6645024 SR00064355

Model RJ 770

Customer: DAVID LESLEY 320 NEW TARLETON WAY GREER SC 29650 US

David Lesley 320 New Tarleton Way Greer SC 29650-3249

Arms Services 14 Hoeder Ave Hion, NY 13357 US

Email: davidlesley@charter.net Your request for service on the item(s) will be evaluated by our repaintan to betermine if it is covered under our warranty policy. If it is your firearm will be repaired and relumed. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section

THE CONSUMER STATES THAT THE GUN WILL GO OFF WHEN OPENING THE BOLT HANDLE.

Qtv Needed

Warranty

Disc


Pupe T. A. chick over + test UND. BLP CON ZU+

THIS IS NOT AN DIVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: Est Sales Tax:

.00 .00

RCH 700 SN A 664502



Date of Request: Date Printed: 10/14/2013

010



