Remington Arms Co., Inc. **Product Service** Legal Case #:9498

Case Information

RE# **Date Opened** 327997 11/18/2013

Date Opened(PS) 11/20/2013

**Date Closed** 11/20/2013

**Incident Date** Pre Lit Lit Obsolete

Customer Information

First Type Business Name

Last Name

Lowman

Street

City State Zip Age Contact

Incident

James

16 Caldwell St.

Brookville PA 15825

H 814-849-8161 C 814-952-1901

E jlowman16@comcast.net

Incident Information

Claims

Codes

Repair Est. Medical Treatment Medical Status

ΡI

PD Cause:4006

Altered Adjustments or Components

Unknown

Concern:1007 Fired on Safe Release S FSR

C

Service Request # 67561 - Customer wrote a note - "Gun has fired when taking off Safe also several times the Safety would not release and the gun had to be taken out of stock to release the Safety". df

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl. DOM

Remington

CF/BA

700/7MM REM MA

n/a

A6899838 CA 4/2/1980

Date Purchased Where Purchased

Accessories

**Original** 

HORNICKS HDWE JOHNSTOWN PA

Owner

U

CONCERN: FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash Settlement Reim. Date

Cash Date APV

Per Ilion - Quote to repair under BLM

> Repair/Replacement Repair/Replacement Cost

Date

\$29

11/22/13: Per Ilion - TA dirty & sticky. Set screws altered. Replace TA, check over & test under BLM - quote. df 11/22/13: Customer spoke w/a CSR, apprvd & pd quote. df

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9498&Type=... 12/4/2013

PrintDisplay Page 2 of 3

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		11/20/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
	Description		24" 7MM REM MAG
	Date Code	]	CA
	Bore Plugged	False	
	Bulged	False	
Barrel	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
	Description		BOLT LOCK SAFETY

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9498&Type=... 12/4/2013

Safety	Function	Like new; Functioning	
	Lift	Select	.008
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Not Functioning	DIRTY,STICKY TRIG NOT RETURNING WILL FOLLOW DOWN
Trigger	Pull	Select	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

## Quotation

## Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Numb RE00327997	er	Serial Number / Description A6899838 Model 700 Center Fire Caliber: 7 mm rem mag			Date Re Estimate Date Pri	e Date:	013 013 013	
Customer: JAMES LO 16 CALDO BROOKV		5825 US		Irn To: JAMES LOWN 16 CALDWELI BROOKVILLE	LST	US		
Please Circle (		VED Card No.	<del></del>	Fv	n Date			
Open Acco	ount: R	VER Card No PO Number:			p			
Approval Sign	ature:	) Time t	o Call:		_ Date:			
		ge, please use the reverse side for your comments						
	<u> </u>		blems					
		PRODUCT SERVICE FOR INSPECTION FETY MODIFICATION		WARD TO PRO T LOCK SAFET			INSPE	CTION
			Comments					-
trigger assemb	ly dirty and s	ticky.set screws altered.replace trigger assembly,	check over and t	test fire under be	olt lock prog	ram for \$20	0.00 + s	hipping
Material	Туре	ESTIMATE (note: C.O.D./Shipping and Han Description	dling Charges a Qty Needed	are NOT Includ Warranty	led in this Q Qty From Inv	uote.) Price	Disc	Amount
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLAG		Warranty	1	.00	0	.00
4000114	Service	GR-SHIPPING & HANDLING (GUN REF		Billable	1	17.00	0	17.00
4000116	Service	GR-LABOR	20	Billable	20	1.00	0	20.00
4000119	Service	GR-TEST	1	Warranty	1	.00	0	.00
		11/2 P	22/13 aid					
					Sut	) Total:		37.00
						Sales Tax	:	2.22 \$39.22

## Service Request

Remington Service PO Box 700

Madison, NC 27025-0700



Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service PLEASE.

11 15 2013

11/13/2013

RETAIN THIS COPY FOR YOUR RECORDS. Service Request Number Serial Number / Description Date of Request: SR00067561 A6899839 Date Printed: Model 5872 Customer: JAMES LOWMAN 16 CALDWELL ST 14 Hoefler Ave Ilien. NY 13357 US BROOKVILLE, PA 15825 US Email: flowman16@comcast.net -Your request for service on the item(t) will be evaluated by our repairman to determine if it is covered under our marranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed. Reason For Return . .

Service Request Section

CUSTOMER STATES THAT WHEN THE FIREARM WAS PLACED ON SAFE, IT FIRED.

Parts And Service Details Material Description Type

Qty Needed

Warranty

Price Disc Amount

Model:

M249 - BOLT LOCK SAFETY MODIFICATION

T.A. dinty+Sticky. Set screws Alt. Apr. T.A. who heckover + Mest und de PRou 20 t

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: Est Sales Tax: .00 .00

Grand Total:

\$.00

Phise See Attached

· .	
	11/14/2013
	*
	Re: Service Request# 00067561
	Ren 700 Classic Sept A68 99838 7mm Ran Mag
	1 100 (1331C See " 1760 17038 MM 119
1	Re: Gus has fixed when taking off safe Also
	South of the Salaha would and Palice And
· · · · · · · · · · · · · · · · · · ·	Several times the 5-kety would not Referre AND
	the Gan had to be taken out of Stock to Release
	the silety
· · · · · · · · · · · · · · · · · · ·	
	Return Address
	JAMES S. LOWMAN
	16 CA/dwell St
>.	Brookuille, PAISE25
The second secon	The state of the s
an Amelica de La capação de Carresta de Ca	Phone 814 849-8161
	Cell 814 952-1901
	(1) (1) 732-140
State and the state of the stat	
······································	
And the second s	







