Remington Arms Co., Inc.
Product Service
Legal Case #:9507

Legal Case #:9507 Case Information Date Opened(PS) Pre Lit Lit Obsolete RE# **Date Opened Date Closed Incident Date** 11/18/2013 11/20/2013 11/20/2013 327964 Customer Information Street State Zip Age Contact Type Business First Name Last Name City 12135 Shannon Rd. Shannon NC 28386 H 910-843-5024 Incident Adam Oxendine Incident Information Claims Codes Repair Est. Medical Treatment Medical Status ΡI PD Cause: 4038 Could Not Duplicate Concern Unknown S **FBC** Concern:1008 Fired on Bolt Closing C Service Request # 66679 - "THE CONSUMER STATED THAT THE GUN FIRED WHEN THE BOLT WAS BEING CLOSED". df Firearm Information Model/Ga. SKU Serial Bbl. DOM Mfg. Type 700/7MM REM CF/BA n/a A6737605 AV 3/25/1979 Remington MA Date Original Where Purchased Accessories Purchased Owner PAUL BUNYAN MINNEAPOLIS U MN CONCERN: FBC Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA Cash Reim. Reimbursement Settlement Cash Settlement Release of Claims Release Date Date Date APV APV Per Ilion - Quote to repair under BLM Repair/Replacement Repair/Replacement Date Cost \$29 11/22/13: Per Ilion - Could not duplicate concern. Replace TA, check over & test fire under BLM - quote. df 11/27/13: Customer mailed quote w/apprv. & payment. df Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington PSA/PrintDisplay.aspx?ID=9507&Type=... 12/4/2013

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/20/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7MM REM MAG
	Date Code		AV
	Bore Plugged	False	
	Bulged ·	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn, Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.010
	Notch	Slightly Worn; Functioning	
	Tooto	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	4.5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M/700 Bolt Lock	

Quotation

Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

Repair Number RE00327964		Serial Number / Description A6737605 Model 700 Center Fire Caliber: 7 MM REM N	Estimate	te Received: 11/18/2013 imate Date: 11/21/2013 te Printed: 12/04/2013									
Customore			Date	urn To-									
Customer: ADAM OXENDINE 12135 SHANNON ROAD SHANNON, NC 28386 US			Return To: ADAM OXENDINE 12135 SHANNON ROAD SHANNON, NC 28386 US										
Please Circle One													
VISA MC DISCOVER Card No													
Open Accoun	Open Account: K PO Number:												
Approval Signature: Daytime Phone: () Time to G				Date:									
Daytime Phon	ic: () Time	to Call:										
If you desire any change, please use the reverse side for your comments and mark this box.													
Problems Found													
Reported M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M240 - BOLT LOCK SAFETY MODIFICATION M240 - BOLT LOCK SAFETY MODIFICATION Found M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION M240 - BOLT LOCK SAFETY MODIFICATION													
		Technicia	1 Comments										
could not duplica	ile concern	replace trigger assembly, check over and test fir	e under bolt lock	program for \$20	.00 + shippi	ing							
Material	Type	ESTIMATE (note: C.O.D./Shipping and Har Description	idling Charges a Qty Needed	Warranty	d in this Qu Qty From Inv	uote.) Price	Disc	Amount					
F305570B	Part	X-MARK PRO 700 TRIG ASSB RH BLA	CK (OS) 1	Warranty	1	.00	0	.00					
4000114	Service	GR-SHIPPING & HANDLING (GUN RE	PAIR) 1	Billable	1	17.00	0	17.00					
4000116	Service	GR-LABOR	20	Billable	20	1.00	0	20.00					
4000119	Service	GR-TEST	1	Warranty	1	.00	0	.00					
			11/27/ Paic	(3									
					Est	Total: Sales Tax	:	37.00 .00 \$37.00					

Service Request

Remington Service PO Box 700



Madison, NC 27025-0700e

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

1014

SR00066679

Service Request Number | Serial Number | Description

A6737605

Date of Request: 11/06/2013 Date Printed: 11/06/2013

Customer:

ADAM OXENDINE 12135 SHANNON ROAD SHANNON, NC 28386 US Destination: Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section ...

THE CONSUMER STATED THAT THE GUN FIRED WHEN THE BOLT WAS BEING CLOSED.

Parts And Service Details Type

Description

Qtý Needed Warranty

Price Disc Amount

Could Not dip CONCERN Rep T. A. checkount PLET Fine UND BLP for 20 +

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00







