PrintDisplay Page 1 of 2

Remington Arms Co., Inc. Product Service Legal Case #:8414

Case Informat	ion							
RE# 294132	Date Open 12/26/2011		1/2/2013	Date Closed 1/2/2013	Incident Date	Pre Lit	Lit	Obsolete
Customer Info	rmation							
Туре	Business	First Name	Last Name	Street	City	State Zip	Age	Contact
Incident		Thomas	White	204 Overlook	Coffeyville	KS 6733	7	
Incident Infor	mation							
Claims			Codes		Repair Est.			Medical Status
PI PD S Rifle fires when switched from safe to fire C 1/9/13 Per note on SR, consumer complain.		Cause: 4006 Altered Adjustments of Components Concern: 1007 Fired on Safe Release as rifle fires when switched from safe to		Unknown				
						- v		
Firearm Information Mfg. Remington Date Purchased		Type CF/BA 70 Where Purchased		Model/Ga. D/7MM REM MA Accessories	SKU n/a Original Owner U	Serial 372310	Bbl. ER	DOM 10/1/1968
CONCERN: F	rsr				Ü			
	nformation - N s Information	lone Defined - None Defined		.emington/700/CF/BA				
Settlement Rel		ease of Claims Release Date		Reimbursement	Cash Reim. Settlement Date AP			
	olace TPA, clea SM program p	rice	ir/Replacement Cost	Repair/Replacemer Date	nt			
1/9/13 Per Ilio	n, trigger assn	set screws alt	ered. Trigger not	eturning properly. Re	place TPA, clean and t	est at BLSM	rogram p	orice.cm
Examination[]	Remington/CF	/BA]						
Part	Sub	-Part		Code		Comment	-	1
	Examiner				B.TRAVIS			
Examination	Exam Date				1/2/2013			
	Product Type	;			RF			
	Action Type				A			
	Assigned To			•	J.BALIO			
Cause	4006		Altered Adjustme	ents or Components				
	Description				24" 7MM REM MA	G		

ER

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8414&Type=Case

False

False

False

Muzzle/Crown Condition | Slightly Worn; Functioning

Date Code

Bulged

Fired

Barrel

Bore Plugged

Fired while Obstructed

1/9/2013

PrintDisplay Page 2 of 2

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	Select	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	Select	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	I csts	False	
Trigger	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN
	Pull	Select	4#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	

Service Request

Remington Service PO Box 700

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

1015

,00

SR00038281

Service:Request Number | Serial Number | Description

372310

Date of Request:

12/11/2012

Printed:

12/11/2012

Customer: THOMAS WHITE 204 OVERLOOK

COFFEYVILLE, KS 67337 US

Destination:

Arms Services 14 Hoefler Ave

Ilion, NY 13357 US

Email:

Email:

Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return
M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION
M240 - BOLT LOCK SAFETY MODIFICATION

M240 - BOLT LOCK SAFETY MODIFICATION

Service Request Section CONSUMER COMPLAINS RIFLE FIRES WHEN SWITCHED FROM SAFE TO FIRE.

Parts And Service Details

Material

Description

Qty V Needed

Warranty

Price Disc Amount

Model:



E00294132

T.A. set screws Altered, Tilly. Notret prop. rup. TOR, CLAR Test UNZ. JCP CONK ZO.T

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the item(s) being sent based on the conversation with our representative.

Sub Total:

. 00

Est Sales Tax:

.00

Grand Total:

\$.00

Gold & Silver Exchange 219 W. 9th Coffeyville, Ks 67337 254-6710 70204 293806 11/30/2012 12:08:56 PM AT Sold to: WHITE, HIGHAS 204 OVERLOOK - COFFEYUILLE, KS 67337 1.00 103242-1 430.00 430.00 MAN, PENINGTON, H-700, 7, RIFLE, S/N-37231 U 1.00 Subtotal: 430.00

34.99 lax: iotala 469.99 Amount lendered: 480.00 10.01 Change : **装货车单乘** 主的行行 2部 两种销售 191 部上1950

HERCHAROUSE - - NO CASH REFUNUS Thank You have a rice day





