

# Status Report

## Product Development

(1)

### Model 700 LT-20 Limited

Mail & Relat guns were tested satisfactory. A special field test with 8 boys and girls was successfully completed. The guns were accepted.

### Model 7400 - 7600

Final Production model 7400 rifled consisting of a selection of 30-06, 270, and 7mm Exp. Rem. caliber were successfully tested for ball velocity verification.

Receiver marking drawings are being prepared for the designation of Model 4 and 6. Drawing transmittals will be made once location has been approved by Marketing.

Satisfactory production samples of the bore grip cap have been made on a single cavity die.

### M/870 Competition Trap

Production of this new model is in delay as a result of failure of the action bar and fore end tube assembly. Three design modification have been tested.

The first design <sup>tested was</sup> ~~used~~ the present production site.

②

with the thread changed <sup>design</sup> to increase the area thru the threaded section by approximately 40%. The complete action bar is copper seized together, microcarbed and heat treated. Using ~~an~~ accelerated firing tests, one assembly went to 13,000 rounds with the tube failing next to the action bars. Two assemblies went up to 25,000 rounds without failure. A slow rate of fire test <sup>also</sup> was conducted to determine if the rate of firing was a factor. Two assemblies went to 25,000 without failure.

The second design tested was the same as the first with the exception of a shock ring added to the test gun between the fore end nut and the gas cylinder. Using the accelerated firing test method one assembly went to 25,000 rounds without failure.

The third design tested was fore end tubes of heavier wall thickness, <sup>copper seized together, microcarbed and heat treated.</sup> Five assemblies went 25,000 rounds <sup>with</sup> failure under the accelerated mode of testing.

Test results indicated that the first design using the standard production tube is satisfactory. Process Engineering feels that for sake of assembly the heavier wall tube be pursued.

(3)

During the intensive testing of the new fore end tube designs the premature cracking of the receiver was detected. Initial endurance testing of the prototype guns shows cracks developing at the rear of the ejection port at 37,000, 35,000 and 30,000 rounds. Cracking of receivers on production guns began to show after 5,000 rounds. Two M/870 control went to 25,000 rounds without cracking the receivers.

To further investigate the problem strain analysis tests were conducted on the M/870 completion trap gun receiver using CT barrels and a standard M/870 barrel. Test results showed similar stress levels. Tests on a standard M/870 receiver showed similar results.

Further strain analysis measurements are being made to the locking block area. ~~and~~ ~~the~~ ~~magazine~~ ~~cap~~ ~~effect~~ ~~the~~ ~~strain~~ ~~gauge~~ ~~reading~~. Two production guns are currently in test to determine the ~~relationship~~ ~~of~~ ~~the~~ ~~magazine~~ ~~cap~~ ~~and~~ ~~stress~~.