

Remington Arms Company, Inc.
200

REMINGTON ARMS COMPANY, INC.

U.S. Patent
I. Kearns

Pitts
200

SPORTING FIREARMS
TRAPS
POWDER METAL PARTS
100% NEW YORK
AMMUNITION, BRIDGEPORT, CONNECTICUT
LONGER, ARKANSAS

MANUFACTURED BY
SPORTING FIREARMS AMMUNITION
TRAPS TARGETS
ILION, NEW YORK 13357

REPS CARTRIDGE DIVISION
BRIDGEPORT, CONNECTICUT
TARGETS, ADA, OKLAHOMA
ATHENS, GEORGIA
INDIAN, OHIO
CARE - HARTLEY, BRIDGEPORT

May 12, 1980

Acher Arms
3295 "A" St.
Lincoln, Nebraska 68510

Gentlemen:

Examination has been completed on your customer's, Mr. George Kearnes, Model 700 BDL 6mm Rem. caliber rifle, serial number A6464840, which you returned to us when it allegedly fired on two (2) separate occasions when the safety was moved to the "off" position.

The returned firearm, which was produced in June of 1977, has been examined by our firearms experts, who report that it contained our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all our necessary tests prior to shipment.

The general condition of the gun appeared to be good and it was noted that the rear sight blade had been removed and a scope base had been added after it originally left our factory. In addition, it was noted that there were slight marks on the stock. In going over the individual parts, we found the headspace normal, recoil shoulders normal, and chamber normal.

Examination of the rifle and trigger assembly could not duplicate the incident that was described. All parts tolerances and dimensions were found to be normal, including sear-connector engagement. Also, factory seals were intact on the trigger adjusting screws, indicating no alterations were made on the trigger outside our company. Trigger pull was well within our specifications at 4 3/4 pounds.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the incidents. When the safety is in the "on safe" position, the sear is lifted off of the trigger connector. At this time, very little effort is required to pull the trigger rearward, allowing the connector to be moved away from under the sear and, in this condition, on moving the safety to the "fire" position, the rifle will fire if the trigger is touched.

June 6/10/80