## (742) Improvements vs. Current 740

- Reduction in Fail to Fire Complaint
  - a. Additional firing pin clearance in bolt.
- Filminate Damaged Threads on Bolt and Barrel Extension. (A process improvement)
- 8. Fore End Improvements
  - a. Addition of spacer tube.
  - b. New design fore end bushing.
  - c. Redesigned fore end lines.
  - d. Redesigned fore end screw 5 - 120°
- Reduced Operating Randle Locseness .

- Loseness handle and bolt carrier.
- b. Increased diameter of operating handle retaining pin.
- c. New shear proof pins from vendor.
- 10. Improved Extractor Breakage. Redimensioned seating radius or extractor rivet to agree with countersink of rivet hole in extractor.
- 11. Improved Action Tube Support
  - 4. Redimensioned hole spacing in bracket.
  - b. Reduced pin hole diameter in bracket.

## Benefits and Improvements

This complaint can be caused by hard preservative greases and foreign matter lodged in between firing pin and its guide dinmeter of the carrier and bolt assembly as described under Improvement No. 1. However, analysis of the current design indicates possible interference and hydraulic snubbing of the firing pin. Additional clearances have been provided to overcome both interference and hydraulic effect.

This process improvement will will to improve lock up and unlock both manually and auto syele

83 Improved fore end design will eliminate current premature liner deformation at front end leading to loose and cracked fore ends. Also accuracy (point of impact) should be improved by new screw and bushing design which automatically insures no interference (free floating) between fore end and rear of receiver.

These modifications will improve endurance of gun, eliminate presature loosening of operating handle causing hard manual opening of action.

Reduced premature breakage of extractors across the rivet hole,

This mudification assures better alignment with sleeve.