

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: FAIR R #: 006152
 OUTSIDE WORK: SCOPE MOUNTED; SIGHTS DATE: 3-8-72
REMOVED. FROM: GIBSON PRODUCTS CO.
 FIRED AMMO TYPE: _____ MISSOULA, MONTANA.
 & CONDITION: _____ GUN #: 6222426
 PROOF: RE.P. ASSEMBLER 30 INSP.: 13 TEST: 49 CODE: PS-6/69
 HEADING: — GA./CAL.: 3006
 BREECH OPENING: _____ CHECKED BY: PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN, DAMAGED COMPONENTS. SEAR, CONNECTOR
ENGAGEMENT .06 (MIN. IS .020) TRIGGER CLEARANCE IN
CONNECTOR = 1.091 (M/D = 1.083, 1.089); CONNECTOR CLEARANCE ON
TRIGGER = 1.071 (M/D = 1.079) CONNECTOR IS WARPED AND
TRIGGER HAS EXCESSIVE RADIUS UNDER CONNECTOR ON TOP.

COMPLAINT: DEFECTIVE SAFETY

INCIDENT: FOLLOW DOWN IS POSSIBLE

COMMENTS: THE EXCESS CLEARANCE BETWEEN THE CONNECTOR
AND TRIGGER (.013 EXCESS) COULD ALLOW THE CONNECTOR
TO WORK UP TO INTERFERE WITH THE SEAR PREVENTING
RETRACTION WITH THE SAFETY ON. PUSHING THE
SAFETY OFF THEN, WOULD RESULT IN A FOLLOW DOWN;