

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: USED R #: 000153
 OUTSIDE WORK: TRIGGER ADJUSTING SCREWS RE- DATE: 3-10-72
ADJUSTED, SCOPE MOUNTED, & SIGHTS REMOVED. FROM: GIBSON PRODUCTS CO.
 FIRED AMMO TYPE: _____ MISSOULA, MONTANA.
 & CONDITION: _____ GUN #: 6325677
 PROOF: R.F.P.-D INSP.: 9 TEST: 41 CODE: CT = 4/70
 HEADING: _____ GA./CAL.: 2506
 BREECH OPENING: _____ CHECKED BY: PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN-DAMAGED COMPONENTS. CONNECTOR CLEARANCE
ON TRIGGER 1.070 ($\frac{1.110}{1.070}$) TRIGGER CLEARANCE IN CONNECTOR
1.091 ($\frac{1.093}{1.091}$) ADJUSTMENTS HAVING BEEN ALTERED MAKES IT
IMPOSSIBLE TO DETERMIN CONDITION AFTER FINAL ASSEMBLY.
AS RECEIVED, SEAR CONNECTOR ENGAGEMENT = .005 MIN. IS .020.

COMPLAINT: "SAFETY DEFECTIVE"

INCIDENT: MAY HAVE BEEN FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION: COULD HAVE BEEN THE
RESULT OF LIGHT TRIGGER PULL, 3LBS. AND UNDER MIN.
SEAR, CONNECTOR ENGAGEMENT THIS WOULD PERMIT THE
OFF. IT COULD ALSO HAVE BEEN THE RESULT OF THE
.014 EXCESS CLEARANCE BETWEEN TRIGGER & CONNECTOR
WHICH PERMITS CONNECTOR-SEAR INTERFERENCE PREVENT-
ING PROPER TRIGGER-CONNECTOR RETRACTION.