Xr. Joseph L. Morris Route 3, Bex 37A Pouhatan, Virginia Dear Mr. Morris: Emmination has been completed on the Model 700 ADI, 243 Win. caliber rifle, serial number 86265592, which you returned to us when it allegedly fired as the safety lever was moved to the "fire" position. The raturned firearm, which was produced in Movember of 1980, has been examined by our firearms experts who report that it contained our high-pressure proof test, gallary test, and final inspection stampings, in-dicating that it had successfully passed all our necessary tests prior to shimment. The general condition of the gum appeared to be good and, in going over the individual parts, we found the headspace, recoil shoulders and chamber all to be normal. Examination of the rifle and trigger assembly could not duplicate the reported condition. All parts tolerances and dimensions were found to be normal, including sear-connector engagement. Also, factory seals were intact on the trigger adjustment scraws, indicating no alterations were made on the trigger outside our company. Trigger pull was within our specifications at Jy pounds. Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the incident. It is possible that while you were moving the safety lever from the "safe" position to the "fire" position, you at the same time were inadvertantly applying finger pressure to the trigger. When the safety lever reached the "fire" position, the gun them discharged - as it is designed to do - because the trigger and the safety lever reached the "fire" position, the gun them discharged - as it is designed to do - because the trigger was being pulled with the rifle no longer on "safe". We trust that we have clarified the circumstances that could possibly have caused the accidental fixing and, as a gesture of good wil', even though there is nothing wrong with the present trigger assembly, we can