

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-23953

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/19/91

11/22/91

00 7-77

A6488854

700 270

BDL

ACCESSORIES

W/STUDS

L/SIGHTS

FROM:

SHIP TO:

SHOWKER, SKIP
157 GREENVILLE AVE
P O BOX 2573
STAUNTON
USA

VA 24401

SHOWKER, SKIP
157 GREENVILLE AVE
P O BOX 2573
STAUNTON
USAVA
24401

CUST NO: 053411 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

11/22/91

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

Above malfunctions could not be duplicated, after many attempts. Trigger and safety consistently operate properly. However, trigger assembly has been improperly adjusted outside factory (evident missing from screws). 1) Trigger pull is below our min spec - measured at 2 1/2 pounds. 2) Over travel is excessive.

Sear lift - .010"

PARTS

COMMENTS

Offer to properly re-adjust present trigger assembly; or, we can install a new trigger assembly at a normal cost as a gesture of good-will, if it will better restore confidence in the rifle.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/91