






850
3025
PLAINTIFF'S EXHIBIT

- Bolt Action Fire Controls



DON'T SAY IT - WRITE IT

File copy

To

From

Joe Glas
Clark Jorkman

Date

5/22/80

Attached are a series of memos, reports, letters etc that will give you a feel for our Bolt Action Rifle Fire Control Status. You will note that there is a wide variety of opinions and philosophies expressed. We will be prepared to discuss our present position with you in the near future.

SAFETY IS A WISE INVESTMENT

S
I
C
H

AL 0016386

7 of 80

DON'T SAY IT-WRITE IT

To C.B. WORKMAN ✓
From J.P. GLAS
Subject _____

location
location

Phone No. _____
Date S-16-80

There is no record of a policy statement re fire control design goals in the Product Safety file. I have requested a search of the Operations Committee minutes. If you have any records of documentation, please advise.

JPG:j1


REMININGTON ARMS CO.
RECEIVED

MAY 20 1980

ILION RESEARCH DIVISION

RD 778

STOP, LOOK, AND LIVE



AL 0016387

3 of 80

000

REMINGTON ARMS COMPANY, INC.
Research Department

xc: R.A. Partnoy
J.E. Preiser
C.B. Workman

Bridgeport, Connecticut
May 16, 1980

E.F. BARRETT

POLICY DIRECTION FOR RESEARCH PROGRAMS
BOLT ACTION FIRE CONTROL IMPROVEMENT

The subject research programs are guided by the following policy guidelines.

1. Design the operation of the bolt lock to operate independently from that of the fire control.
2. Design the fire control so that the bolt can be operated, subject to (1), above, independently from the position of the safety mechanism.
3. Design the fire control mechanisms to be retrofittable.

Point two would allow the user to unload the gun with the safety mechanism in the "ON SAFE" position. It would also allow the user to reload the gun with the safety mechanism in the "FIRE" position.

Please advise of your agreement, with, or suggestions for modifications to the policy.

Joseph P. Glas

JPGlas:jl

RECEIVED
REMININGTON ARMS CO.

MAY 20 1980

ILION RESEARCH DIVISION

AL 0016388

4 of 80

REMINGTON ARMS COMPANY, INC.
Research Department

cc: J.P. McAndrews
E. Sparre
R.A. Partnay
E.G. Larson
T.J. Sharpe
J.G. Williams

TO: R.L. HALL J.P. LINDE
C.B. WORKMAN J.S. MARTIN
R.B. SPERLING A.A. HUGICK
W.E. LEEK

FROM: E.P. Bennett

SUBJECT: PRODUCT SAFETY MEETING - BOLT ACTION FIRE CONTROLS
APRIL 23, 1975

This meeting was held to develop plans to conduct a safety analysis of bolt action fire controls.

The following is a summary of the status reports given by each Department and their plans for further action.

RESEARCH

The investigation to date has been largely confined to the Model 600. An investigation has also been made of the M/788 and the M/580 series fire controls. Research has completed an analysis of the design of the M/600 fire control and has -

1. Changed part dimensioning to insure adequate lift of the sear by the safety cam.
2. Specified hardening the fire control housing to minimize wear between the detents.
3. Increased the length of the safety lever cam.

These modifications are being tested to evaluate their effectiveness and to insure there is no interaction with the other aspects of fire control performance.

Research has concluded that the present design for a 3-position safety is inadequate and plans to begin a study during the second half of 1975 to develop a new safety mechanism.

MARKETING

Approximately 600 Model 600 rifles are expected to be returned to the Plant as the result of the special quality audit.

AL 0016389

50F80

Marketing will review the available information on all bolt action rifles as it relates to the safety performance of bolt action fire controls. This will include gunsmith reports, arms repair data, parts usage, etc.

PRODUCTION

Inspection of 147 Model 600 rifles returned for the safety audit show the following.

1. Safety cannot be "tricked" - 103
2. Safety can be "tricked" but movement of safety lever to full "safe" position clears trigger connector and sear and gun will not fire when moved to "off" position - 40
3. Safety can be "tricked"; trigger connector remains disengaged from sear when moved to "safe" position and gun will fire when the lever is moved to "off" position - 4
4. Trigger can be set in unsafe condition when safety lever is in "safe" position - 0

Production is rejecting guns which fall in the #2, #3 and #4 categories. Indications are that this provides an ample safety factor that wear will not lead to the category #4 situation during the life of the gun.

A gauge is being developed that will permit checking for sear lift at assembly.

Production is analyzing variations in purchased and internally manufactured parts and reviewing quality control procedures and limits. A list of recommendations for improving quality performance will be developed and reviewed by the Product Safety Committee.

A follow-up meeting is scheduled for the week of May 19.

EFB/ab
4/25/75

AL 0016390

6 of 80

LIMITED DISTRIBUTION

RD-41-B

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
SPORTING

PETERS
S

Xc: E.P. Everett
A.A. Hugick

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

Ilion, New York
May 7, 1975

TO: W. E. LEEK

FROM: J. P. LINDE

SUBJECT: EVALUATION OF THE BOLT ACTION RIFLE SAFETY MECHANISMS
M/580s, 788, 600 and 700

This investigation was instituted when a Model 600 was returned from Texas by a customer who in the process of unloading his gun moved the safety lever from the on safe to off safe position (so the bolt could be actuated) and the gun discharged. Upon further investigation of the incident it was determined that he had pulled the trigger with the safe in the on position. It was also determined that some Model 600s could be tricked by putting the safety lever in an intermediate position half way between on safe and off safe, pulling the trigger, releasing the trigger, push the lever to the off safe position and the gun will fire.

Model 600

The M/600 safety is a blocked sear design. The safety lever rotates a cam under the sear, lifting the sear off its contact with the trigger-connector. The trigger then can be pulled with no effect to the sear or firing pin assembly. In the guns in question it was found that they had inadequate sear lift on both the on safe and intermediate positions. The sear lift is the amount of clearance generated between the trigger-connector and the sear. The lifting action of the cam on the safety lever takes place when the safety lever is rotated to the on safe position. On the guns in question there was very little clearance between the sear and trigger-connector. Thus when the trigger was pulled in a certain way when the gun was on safe, the connector would not return with the trigger. In this case the safety cam is preventing the gun from firing, thus when the safety is moved to the fire position the gun will discharge.

The initial production remedy was to swage the cam on the safety lever to provide greater lift on the sear. The greater lift provides a bigger clearance between the trigger connector and sear when the gun is in the on safe condition. The trigger can be pulled without any fear of the connector failing to return due to inadequate lift. The final inspectors, assemblers and customer repair people were retrained on what to look for. A test has been added at assembly to check for the sear lift from the safety actuation by use of a shim stock.

AL 0016391
70f 80

To:
From:

W.E. Leek
J. P. Linde

5-7-75

-2-

Evaluation of the Bolt Action Rifle Safety Mechanisms - M/500, 738, 500 & 700

The guns are being checked to give at least .008 inches min. lift between the trigger-connector surface and the sear.

The holes on the fire control housing on some of the samples tested were out of control. Corrective action is being taken.

Proposed Design and Process Changes

Design

1. The safety levers have been redimensioned to give better manufacturing control of critical dimensions.
2. The dimensions on the safety lever cam were changed to give greater lift on the sear and maintain the lift longer when the safety is moved from "on safe" to "off safe".
3. The fire control housing will be changed to be common with the Model 700. It has two separate side plates which are riveted together, while the 600 has a folded assembly. The M/700 housing has a heat treated side plate with the detent hole, which gives more positive safety. The folded assembly is not heat treated and the detent holes wear and become less positive.
4. The sear has to be altered to eliminate a potential interference with the rear housing assembly pin.

Process

1. A production gage has been designed and is being built which will measure the sear lift due to the safety lever operation before the fire controls are assembled to the gun.
2. An inspection hole has been added to the new design safety lever so the cam form and its position on the safety lever can be readily inspected in purchase parts inspection.

To: W. E. Leek 5-7-75
From: J. P. Linde -3-
Evaluation of the Bolt Action Rifle Safety Mechanisms - M/580, 788, 600 & 700

Test Program - M/600

The current M/600 being manufactured with the swaged safety levers are being tested. They are shot with live ammunition at the start of the test to check their function. The amount of sear lift from the safety operation is measured before the start of the test as well as the force to put safe on and off. The guns are being dry cycled safe on-safe off and cock and dry fire to 50,000 cycles each. The sear lift is being measured every 5,000 cycles to determine how wear affects the sear lift over the life of the gun. The wear on the detent system, trigger connector and sear surfaces also will be checked. The test is being duplicated in a dry and oiled (WD40) condition on the trigger mechanism.

The testing will be duplicated for the redesigned fire control. From this and the original testing it is being determined the minimum safe sear lift for new guns. This report will be followed by the test report.

Status of Design Change

The design has been determined and all drawings have been completed. Design test confirmation is under way. The new drawings have been submitted to P.E. & C. for estimating purposes and the appropriate vendors contacted. As soon as the design test is satisfactorily completed the drawings will be transmitted.

Proposed Future Plans - M/600 & 700

A design investigation will be started to determine the feasibility of changing the safety design from a blocked sear system to a blocked firing pin system. The benefits of a three position safety also are being investigated.

The spring force on the detent system on the M/600 & 700 varies due to the leaf spring design, which can vary the safety operating force. The design will be reviewed to see if the system can be altered to give a more constant operating force.

Model 788 and 580 Series

The problem came to light in February when the design was changed from a blocked trigger system to a blocked sear system similar to the 600 and 700 design. This design change was instituted to standardize parts in these guns with the 540 Series, to eliminate a high scrap operation, and to obtain a more positive safety.

To:

W.E. Leek

5-7-75

From:

J. P. Linde

-4-

Evaluation of the Bolt Action Rifle Safety Mechanisms - M/580, 783, 600 & 700

Model 788 and 580 Series Continued

When the problem appeared all the parts involved in the safety mechanism were measured to determine why there was insufficient sear lift. The following items were found:

1. The powder metal trigger was out of tolerance. Powder Metal has been contacted.
2. The safety lever dimensioning did not tie the critical dimensions together.
3. The holes in the trigger housing were not to locational dimension.

Corrective Action Taken to Maintain Production

1. The triggers were ground to provide more clearance when the safety was operated.
2. The gaging technique was established to measure the sear lift with the safety operation when the gun is assembled.
3. All the assemblers were retrained on what to look for -- proper lift and can the gun be tricked.

Corrective Action Being Taken

1. Correct the parts out of gage and establish controls.
2. Redimension safety levers for both the 580 Series and 788 to tie the critical surfaces together. The vendor has been contacted on what surfaces are critical and how they can best be maintained.
3. The dimensions on the safety lever were altered to give greater lift to insure in all tolerance conditions there is adequate lift with an allowance for wear.
4. Process Engineering is designing a gage to measure the sear lift from the safety lever operation to insure that the fire control will have adequate lift before it is assembled to the gun.

AL 0016394

10 of 80

To: W. E. Leek 5-7-73
From: J. P. Linde -5-
Evaluation of the Bolt Action Rifle Safety Mechanisms - M/580, 788, 500 & 700

Corrective Action Being Taken Continued

5. The assemblers will use a feeler gage to measure sear lift to make sure a minimum lift is maintained.
6. The safety lever hold down screw has been deleted. The pin with the retaining ring presently used in the pivot pin will be used instead of the screw. The alteration was made after it was determined under some conditions the screw could back out and bind the safety operation.
7. The cut in the bottom of the M/788 receiver for safety lever clearance has been altered in the proposed design to eliminate any potential interference with the safety lever which could block the safety operation.
8. An inspection hole will be added to the M/788 fire control housing so the sear lift can be visually checked.

Test Program - M/580 Series and 788

Production guns with ground triggers are being tested to make sure there will be no field problems with the powder metal surfaces wearing down with usage. These guns are being tested in the following way.

1. The 580 Series are being shot to 20,000 rounds and dry cycled safe on - safe off to 400 cycles.
2. Another gun will be dry cycled to 50,000 safe on - safe off cycles and 50,000 cock and fire cycles.

The new design is being tested by swaging out and recutting the safety lever to the new dimension. The gun test will include;

1. One gun will be shot 2,000 times, with 500 safe on - safe off cycles, the sear lift being measured every 500 rounds as well as the safe on - safe off actuation load.
2. One gun will be cycled to 50,000 safe on - safe off cycles, and 50,000 cock and dry fire cycles.

These tests will be repeated with the design changes as they become available.

To:
From:

W. E. Leek
J. P. Linde

5-7-75

-6-

Evaluation of the Bolt Action Rifle Safety Mechanisms - M/580, 738, 600 & 700

Future Program

1. The 540 Series fire controls will be altered to reflect the changes made in the M/580 and 788 fire controls.
2. ~~The sear pin will be looked into as one backed out in testing. This is presently a substitute pin and will be changed to a spiral pin as soon as the testing can be completed on the new pin. When the solid pin backed out after about 20,000 cycles it resulted in a fire on safe condition. The pin slipped out of one side of the housing, letting the sear slip down. When the safety was positioned to the on safe position there was inadequate lift, so if the trigger is pulled it will become trapped ahead of the sear. When the safety is moved to the fire position the gun will discharge.~~

JPLinde:T
illion Research Division

AL 0016396

12 of 80

BOLT ACTION SAFETY SYSTEM ANALYSIS

This report is a summary of the information accumulated in a design analysis of the popular current bolt action safety systems. The systems are listed as to how they function, with a description of the design advantages and disadvantages.


Blocked Trigger Safety

This safety works on the principle of employing a mechanical means to block the rotation of the trigger. The trigger is the only element in the triggering mechanism which is blocked. This type of safety has been utilized extensively in hunting type rifles and shotguns. The M/1100, M/870, and M/742 utilize this type of safety.

The blocked trigger safety has the following advantages:

1. It is easy to determine how the mechanism operates even by a novice shooter.
2. The safety operation is not dependent on the position of the striker or some other integral part. The safety can be operated with the bolt open, bolt closed, or striker cocked or fired on all of our current models which use the common fire control such as the M/742. With all the bolt action rifles which use the blocked trigger safety, the safety can only be put in the "On Safe" position when the striker is cocked. The bolt can be either in the open or locked position. The bolt lock feature normally inhibits the operation of the safety if the bolt is in the open position.

AL 0016397



Blocked Trigger Safety - Cont'd.

- The blocked sear safety can normally not be moved to the "On Safe" position when the striker has fallen. The blocked striker type safety cannot be actuated unless the rifle is cocked and the bolt locked closed.
3. The blocked trigger safety locks the trigger in position; if the shooter fidgets with the rifle while he is waiting for a big trophy deer the trigger will remain locked unless the safety is repositioned. With a safety system where the trigger is free to move if the hunter fidgets with the rifle and pulls the trigger with the safety in the "On Safe" position, the trigger could possibly bind on the trigger guard, stock, or trigger housing. If this happened, the rifle would fire "off safe".
4. The designer has much greater freedom on where the physical position of the safety can be located with this type of safety. With the blocked striker or blocked trigger safety, the physical position of the safety mechanism is determined by where the force has to be applied to cam the striker or sear.

The blocked trigger safety has the following disadvantages:

1. In firearms where the trigger directly supports the sear (trigger surface engages sear surface to inhibit rotation), the tolerances and clearances in the trigger block (safety) allow movement when the trigger is pulled with the firearm in the "On Safe" position, decreasing the amount of sear trigger engagement.

Blocked Trigger Safety - Cont'd.

1.A. In the common fire control, as used on the M/1100 and M/870, and M/742, there is a connecting link between the trigger and sear.

The design calls for a clearance between the link and sear engagement surface which, when the trigger is pulled with the firearm in the "On Safe" position, allows the trigger to move slightly taking up the tolerances and clearances in the safety block without moving the sear.


The trigger is allowed to retract when released which allows the safety to be actuated regardless of the position of the sear.

S

I

C

H




The blocked trigger design does not lend itself to target triggers as a target trigger demands a minimum preplay or initial clearance and a minimum engagement. If the trigger has a connecting link the trigger would normally have preplay. If the trigger connects directly to the sear the engagement cannot be decreased to target specifications as the safety tolerances and clearances are such as not to insure an adequate engagement if the trigger were pulled with the firearm in the "On Safe" position.

Blocked Sear Safety

This type of safety functions by having a mechanical means block the sear or cam the sear clear of the trigger. In this type of mechanism where the sear is disconnected from the trigger a mechanical cam is actuated against the sear, lifting the sear away from the trigger by actuation of the safety lever. The M/700 rifle uses a safety mechanism of this design. In the M/700 system when the sear is cammed free of the trigger the sear cams the striker assembly, retracting the firing pin slightly.






The blocked sear safety has the following advantages:

1. The system can be used successfully with either a hunting rifle or a target rifle. Because the system lifts the sear clear of the trigger, the system is not as sensitive to the amount of sear engagement as the blocked trigger safety.
2. The system blocks the striker, camming it rearward slightly.
3. The safety can be operated with the bolt in the open position or in the closed and cocked position.



-4-

4. The safety lever can be positioned in a convenient location.
5. The system is positive -- mechanical actuating means physically disconnecting sear from trigger. The trigger can be pulled with high force levels not affecting the safety operation.
6. The striker is blocked by the sear and will take a large amount of abuse without firing.
7. The sear, trigger and safety cam all are attached to the same housing making the system less tolerance sensitive.
8. Can be designed either as a two position or three position safety.
The blocked sear safety has the following disadvantages:
 1. If the customer fidgets with the trigger when the gun is in the "On Safe" position and the trigger fails to return to position, the safety mechanism (can) will be holding the striker and when it is switched to the fire position the striker will fall. The trigger could be bound by the stock, trigger housing, trigger guard, or insufficient clearance between trigger and sear.
 2. The rifle cannot be put in the "On Safe" position when the striker is forward.



Blocked Striker System

The system is actuated by camming the striker rearward with a mechanism located on the bolt plug. The M/70 Winchester utilizes this type of system.

Advantages of blocked striker system:

1. Can be designed as a two or three position safety system.
2. This type of safety holds or retains the last link in the firing mechanism. This could possibly be an advantage under drop test circumstances and for advertising or sales appeal.

Disadvantages of the blocked striker system:

1. Located in a position which interferes with scope mounted rifles.
2. The system is very tolerance sensitive as the mechanism parameters are determined by the sear position located in the receiver assembly and the camming mechanism located in the bolt assembly.
3. - The mechanism can only be actuated when the bolt is closed and cocked. To load the rifle with the safe in the "On Safe" position requires closing the rifle, putting the safe in the "On Safe" position, opening the bolt and loading the rifle. If one shot is fired and the following shot fed from the magazine, the bolt must be locked in the fire position before the safety can be actuated.
4. If the hunter fidgets with his rifle, squeezing the trigger while the rifle is in the "On Safe" condition, the trigger could possibly lock back from binding on the trigger housing, stock, trigger guard, or excessive dry lubrication and cause the rifle to fire when the safe is moved to the "On Safe" position.

SAFETY LEVER LOCATION

The safeties located on the bolt plug normally are difficult to actuate with scoped rifles.

The safety buttons located on the top center of the tang are very difficult to operate when the bolt is in the rear open position. If the hunter carries his rifle with his hand around the grip he could inadvertently reposition the safety without realizing it, with the safety positioned on the top tang.

AL 0016402

18 of 80

The safety buttons located on the trigger bow are easy to actuate but tend to be confusing as to which is the safe position.

The safeties located along the side of the receiver are easy to actuate, do not interfere with the gun operation, but normally work in the same direction as the trigger. This could cause a problem if the customer previously operated a Winchester M/94 lever action where to put the gun on half cock he has to pull the trigger while retarding the fall of the hammer with his thumb. If the customer pulls the trigger while releasing the safety with a blocked sear safety the rifle will naturally fire.

Safety Design

The safety should have two clearly defined positive positions; "ON SAFE" and "OFF SAFE". The safety should require 3 to 10 pounds to move to the "Off Safe" position. The safety mechanism should not be overly sensitive to lubrication; that is, the actuation forces should not vary dramatically due to lubrication.

The safety mechanism should have an endurance life such that it will not wear to create a dangerous condition. The safety clearances and checks performed at the plant should allow for wear.

The operation of the safety mechanism should be easily understood by the customer without consulting the owner's manual.

The safety lever or button should not protrude in such a manner where it can be easily knocked out of position. The safety should not be positioned such that operation of the bolt or some other member is in line with the safety such that it could be repositioned by said mechanism operation. An example would be having the safety lever project up on the right rear tang such that operating the bolt handle back and forth by the customer could reposition the safety.

AL 0016403

19 of 80

A The safety operation should not be noisy such that its operation will scare off game animals.

If a clearance or interference is required in the mechanism it should be in a place where it can be readily inspected and understood by the people servicing the firearm.


With the safety in the "On Safe" position the rifle should tolerate a 30 pound pull on the trigger without firing.

The safety mechanism should be able to withstand a drop test without repositioning itself in all six planes.

The safety should allow the rifle to be loaded and unloaded with the safety in the "On Safe" position.





Three position safeties can be confusing to a new shooter. What does the center or middle position mean? 1/2 safe. The motion required on a three position safety to go from the fire to the middle position is the same as the total motion in a two position safety to obtain an equivalent mechanical advantage. The motion required on the three position safety from the second to third position must be substantial to allow for a positive central detent position. It is easier to develop and manufacture a two position detent system which goes from stop to stop than it is to develop a three position system where the mechanism is supposed to stop in an intermediate position.

People who own three position safeties leave them in the intermediate position so they can operate them quicker.



Bolt locks

A bolt lock is important to insure proper function of a bolt action rifle. The bolt lock holds the bolt in the ready position to insure that the protruding bolt does not catch on some object and partially unlock the action. If the action becomes partially unlocked the rifle will not fire when the trigger is pulled as the firing pin head will bottom on the cam surface on the bolt before the tip can impinge on the shell primer. To insure the rifle is ready to fire, particularly when hunting dangerous game, it is important to incorporate a bolt lock into a bolt action rifle. If the bolt catches on an obstacle it can unlock the rifle, unloading the action.



AL 0016405

21 of 80

January 19, 1977

FIRE CONTROL DESIGN CONSIDERATIONS

- BOLT ACTION RIFLES -

Tolerances

Fire Controls have many interacting parts. And their function requires minimum part movement. Because of this, tolerance buildup is the key problem in designing Fire Controls for mass production. This tolerance buildup problem can be solved in a variety of ways:

- Adjust tolerance buildup out by screw adjustment, bending, swaging, or filing.
- Have several parts sizes in inventory for a selective fit.
- Eliminate the tolerance buildup by performing a manufacturing operation during final assembly. For instance, a critical hole could be drilled during assembly using the assembly up to that point as a fixture.
- Design parts which can move a lot, to move even more to take up tolerance buildups.
- Parts whose function is not critical to safety can be toleranced statistically.

Safeties

Block Trigger Safety

This Safety blocks the movement of the Trigger. The Trigger, in turn, blocks the movement of the Sear which blocks the Firing Pin. When the Safety is disengaged the Trigger may be pulled to fire the rifle. In my opinion this is the ultimate Safety because it blocks all of the functions required to fire the rifle.

This type of Safety will not work on a target type Trigger because the Sear engagement might be adjusted too fine for the tolerances in the Safety. Then the rifle could be shot with the Safety on.

AL 0016406

Safeties - Contd.

Lift Sear Safety

This Safety lifts the Sear clear of the Trigger and blocks it so that, when the Trigger is pulled, it can not release the Sear. This Safety is used on rifles where the Trigger movement is too small to effectively block. It is especially useful on target rifles.

Problems can occur with this Safety if the Trigger binds. Foreign material in the Fire Control, or a bad trigger fit, can cause the Trigger to stick in the "pulled" position. When the Safety is released, there is nothing to support the Sear, so the rifle fires off safe.

This Safety requires more throw than a block trigger safety. This is because it has to do considerable work to lift the Sear against the mainspring force.

A Lift Sear Safety must have constant force camming between the Safety and the Sear. So that the Safety "on" force will be consistent in all tolerance situations.

Bolt Safety or Block Firing Pin Safety

This Safety lifts the Firing Pin from the Sear and blocks it. A binding Trigger will also cause a rifle with this type of Safety to fire "off" safe.

Safety Detents

Safety detents provide the following functions:

- Controls Safety "on" and "off" forces
- Provides positive position stops for Safety "on" and "off"
- Insures no "dead" positions between "on" and "off" where the Safety might otherwise hang up.

The force required to initiate movement of the Safety depends upon the detent spring thrust and the "contact" angle of the detent head. These work together

Safety Detents - Contd.

to create the "feel" of the Safety. The "contact" angle is the angle of the surface that the Safety Lever has to work against to retract the detent. It is defined by 1/2 the included angle of a conical detent head. It can also be defined by the tangent angle where a ball detent contacts the hole it is sitting in.

I have successfully tested detents with conical heads whose included angle was 60° (contact angle of 30°). I found that these detents should be supported at both sides of the Fire Control Housing to eliminate binding.

The contact angle can be varied between the "on" and "off" positions. This is done by having two different size detent holes with a ball detent or a conical detent with a hemispherical tip.

Trigger

The Trigger should have the following characteristics:

- Balanced so that it cannot be jarred off
- Pull 3 - 5# or adjustable 1 - 5# for target Triggers
- Sear engagement adjustable for target rifles
- Over travel minimum or adjustable for target rifles
- An optional 3-bar system can be designed for target rifles to minimize Trigger movement.

Sear

- Engagement with Trigger - .015" Min. (except for target rifles)
- Engagement with Cocking Piece - .010" Min. (worst tolerance condition)

A
Fire Control Design Considerations
Bolt Action Rifles

- 4 -

January 19, 1977

Bolt Release

The Bolt Release can sometimes be operated by the Safety.

On some rifles the Sear can also serve as a bolt stop.

Fire Control Mounting

The Fire Control must be strongly attached to the Receiver. This joint should not yield when Fire Control parts are being changed while the Fire Control is attached to the Receiver.

Critical Dimensions

After the Fire Control is designed the following dimensions have to be checked. They should be checked by drawing and/or calculation to ensure safe operation under all tolerance conditions:

- Sear-Cocking Piece engagement .010" minimum
- Sear Lift * (on sear lift type safety) -.008" minimum

* Be sure to include sear rotation allowed by sear pivot pin fit! This happens if the Sear is lifted from the side so that it can become cocked.

E. J. YOUNG/nl
Ulion Research Division
Manual Firearms Design

AL 0016409

25 of 80

A

M/600 FIRE CONTROL

In January 1975 R&D was advised of a problem existing with the M/600 Fire Control. Initial investigation of the fire control and components showed several out of tolerance conditions existing. The parts found to be out of tolerance are:

SEAR SAFETY CAM - Safety cam surface.

.534 / .539 dim. and connector contact area

.341 / .346 dim. over max.

TRIGGER - Pivot hole in trigger

.991 / .973 dim. was found to be out of position over max.

TRIGGER CONNECTOR - This part was found to have a blow in the long leg of the part.

TRIGGER HOUSING - The following holes were found out of position -

Safety Pivot hole .649 / .651 & 1.305 / 1.307

Safety Detent Holes

Trigger Pivot holes .839 / .841 & 1.239 / 1.241

Holes were out of position also had variations from side to side.

Correction of these tolerance conditions was easily accomplished as two of the four parts are made here.

SEAR SAFETY CAM - Is manufactured by Hi-Dense. It was found that by exercising more care in pressing and sintering this part could be made to model drawing tolerance.

TRIGGER - Also made by Hi-Dense with final machining by Rem. This part was brought back into tolerance by minor alteration of fixturing and reinstruction of the operator.

TRIGGER CONNECTOR - Manufactured outside - this part was brought back into tolerance by having the vendor make alteration on die.

AL 0016410

26 of 80

A

TRIGGER HOUSING - This part was found to have the most out of tolerance conditions.

This part can be controlled but it is necessary for both Rem. and vendor to screen and check all parts. Doing this increases piece price. Parts are also checked at Sub-Assembly to insure proper sear connector separation with safe in "ON SAFE" position.

Reason for change to M/700 Style Fire Control Housing.

Hardened low wear housing

More Positive safety

Eliminate trigger housing rejects at safety clearance inspection.

Common Housing - (M/600, M/700 M/40X)

PARTS CHANGED OR REDESIGNED

Housing - Altered to fit M/600 and M/700 receivers.

Safety Lever and Sear Safety Cam - Altered to provide a longer duration of safety and more lift - sear and connector separation.

Future plans for this Fire Control, the XP-100 Fire Control and the M/700 Fire Control are:

Continue to upgrade and improve them, include a unload on safe feature, a three position safe or both. This will probably be dictated by Marketing.

FEMartin:bd

4/5/77


S

C

H

AL 0016411

27 of 80



m/700 Bolt Lock (New Design)

3/18/81

ERO

ESTIMATION OF ADDED OPERATIONAL COST.

NEW COMPONENTS:

	EQUIPMENT	COST / KUN
BOLT PLUG (ADDED COST TO PRESENT PROCESS) —	* 118,120.00	.168
BOLT LATCH (P/M COST)	4,400.00	.150 1.540
PLUNGER —	—	** .030
SPRING —	—	** .010
PIN —	—	** .005

ADDED OPERATIONS TO EXISTING


COMPONENTS:

BOLT ASSEMBLY — — — — — 3920.00 .028

FIRING PIN ASSEMBLY

ASSEMBLE LATCH IN BOLT PLUG

785.00 .072
 * 127225.00 + .853
 * .467



AL 0016412

* INCLUDES 71% EQUIPMENT COST ** BASED ON SIMILAR PART COSTS

2006

3/12/81
ERG

101790 Boat Lock (New Design)

Boat Plug (New)

OPERATION-26 (ADDED TO PRESENT PROCESS)

8-STATION DIAL TYPE TRANSFER MACHINE

BASIC MACHINE WITH HYDRAULICS AND ALL CONTROLS	40,000.00
8- DRILLING HEADS @ \$5,000.00 EACH *	40,000.00
2- MILLING HEADS @ \$7,500.00 EACH *	15,000.00
8-FIXTURES AND TOOLING	<u>\$17,000.00</u>
	\$112,000.00

GAGES

3-PLUG GAGEE @ \$40.00 EACH	120.00
1-PINNING GAGE (HAVE LOCATIONS)	2000.00
1-RACE GAGE (MILLING CUTS)	<u>4000.00</u>
	\$6120.00

TOTAL CAPITAL -- \$118,120.00

MACHINE CYCLE TIME --- 20 SEC. **

PRODUCTION RATE @ 80% 144 PARTS/Hr.

EMPLOYEE RATE /hr. 7.90 + 45% (FRINGE) = 11.455

(Operator (Keeps Part While Waiting)) 11.455 / 144 = .0795 / PART

7 1/2% OF \$118,120.00 = \$8859.00

\$8859.00 / 100,000 = .0886 / PART

TOTAL = .1681 / PART


Note: DESIGN COST INCLUDED

* INCLUDES MOUNTS

** INCLUDES LEAD TIME

AL 0016413

29 of 80



M/700 Bolt Lock (New Design)


3/12/61
EES

Bolt Plug (New)



OPERATION - ZIG - DESCRIPTION

8-STATION DIAL TYPE TRANSFER MACHINE. (LOAD AT STA. 1)



STA. 2 - ① Butt Drill Back LATCH Pivot Hole & ② Rough Drill LATCH SLOT (Center)




STA. 3 - ③ Drill B.L. P.H & ④ Rough Drill LATCH Slot (Front)



STA 4 - ⑤ Mill Right Side (M/600 B.A.C.) & ⑥ Rough Drill LATCH Slot (REAR)



4-2-6




M700 Door Lock (New Design)

3/10/81
ECD


Bolt Plug (New)

OPERATION 26 - DESCRIPTION CONT'D.


STA. 5 - ⑨ ~~Alum~~ LATCH SCOT





STA. 6 - ⑩ Bolt Drive SPRING PLUNGE Hole



STA. 7 - ⑪ Drive SPRING PLUNGE Hole



STA. 8 - ⑫ REAM B.L.P.H.



AL 0016415

31 of 80

32 of 80

AL 0016416

TOTAL - .0279

$$294.00 / 100,000 =$$

$$71\% \text{ of } 3920.00 = \$294.00$$

$$\frac{3600 / 11.455}{3600} = 8/x \quad x = 8(11.455)$$

Base Cu & Sec. Employee Time Address Cost = .025/Rate



Employee Rate /hr. $7.90 + 45\% (\text{base}) = 11.455$

Position Rate @ 80% = 144 Pairs/Hr Cost

Load Time - - - - - 8 Sec.

Machine Cycle Time - - - - - 12 Sec

20 Sec.

Total Cost = \$3920.00

400.00

950.00

1 - Depth Gauge - Flushing Pin Type

1 - Position Gauge (Functional Co - Negs)

Gages

2500.00

70.00

Fixture - Vertical Vice Block

Tooling - Special Fixture

Machining - O-12 CMM

Operator N-2 38

Bolt Ass'y (Added Operation)


n/700 Bolt Lock (New Design)

500

3/18/81

50=6

6006



Bolt Lock (NEW DESIGN)

3/19/81

ERD

FIRING PIN ASSEMBLY (ASSM. LATCH IN BOLT PLATE)
OPERATION - 100 (NEW)

Fixture - Locate On FIRING PIN HEAD Hole ..

650.00

PART HANDLING TOOLS - (MAGNETIC)

125.00

HAND HELD DRILL - CLEAN OUT SPRING HUNGER HOLE

10.00

Total Capital - 785.00

CYCLE TIME —————— — 18 SEC

PRODUCTION RATE @ 80% = 160 PARTS/Hr.

EMPLOYEE RATE / Hr. 7.90 + 45% (FRINCE) = 11.455


BASED ON 18SEC. EMPLOYEE TIME Added Cost = .0716 / PART

$$11.455 / 160 = .0716$$

$$7\frac{1}{2}\% \text{ OF } \$785.00 = 58,875$$

$$\frac{58,875}{100,000} = .0006 / PART$$

TOTAL = .0722 / PART



AL 0016417

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
DEPTPETERS
DEPT

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

RESEARCH MEETING

November 1, 1978

S U B J E C T:

BOLT ACTION FIRE CONTROL

A meeting was held on the above subject with the following people in attendance:

C. B. Workman
A. A. Hugick
J. S. Martin

E. J. Young
D. E. Bullis
G. D. Bailey

T. P. Powers
P. Nasypany
J. W. Brooks

An explanation of the M/600 recall program was given by Clark Workman.

The present fire control was discussed using a diagram to explain its operation.

The various safeties, their positions on rifles and how they operated (what they blocked) were discussed. This included competitive models. The discussion then proceeded to what our future thinking should be on our fire controls. Is our present system satisfactory? Can we make a better system?

The outcome of the ensuing discussion produced the following criteria as a start for looking at future designs:

1. The mechanical lock type "ON SAFE" - "OFF SAFE" safety control should be retained.
2. Trigger must be pulled to fire rifle - pulling trigger is only way rifle will fire - rifle will fire immediately when trigger is pulled.

AL 0016418

34 of 80

3. Rifle (can - must) be unloaded with the mechanical safety (No. 1 above) in the "ON SAFE" position.
4. Bolt handle must be locked down with safety in "ON SAFE" position with round in chamber.


An example of No. 2 above that was discussed was to have a second trigger that had to be pulled before the primary trigger could be pulled. The secondary trigger would block the sear or other mechanism until pulled with a predetermined force through a specific distance and then continued movement would pull the primary trigger to fire the rifle.

In No. 3 above the discussion covered whether the rifle "can" or "must" be unloaded in the "ON SAFE" position. At the meeting of the Design Group on Nov. 7, opinions will be given for reaching a decision.

J. W. Brooks:T
Manual Firearms Design
Illiion Research Division

AL 0016419

35 of 80



Remington
INTER-DEPARTMENTAL CORRESPONDENCE

Present: C.B. Workman
J. S. Martin
S.J. Young
D.F. Bullis
G.D. Bailey
F.E. Martin

T.P. Powers
P. Nasipany
J.W. Brooks
D.R. Lewis

PETERS
INTER-DEPARTMENTAL CORRESPONDENCE

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

RESEARCH MEETING

November 7, 1978

SUBJECT: BOLT ACTION FIRE CONTROL

Observations

1. "Can" or "Must" condition on unloading a rifle in "ON SAFE" position. Majority feel a "Must".
2. Unload magazine box without cycling thru chamber?
3. Gun must be safe when unloaded!

Further Criteria

1. Bolt handle must be locked down with round chamber and safe on.
2. Rifle must be unloaded with safe on.
3. Trigger feel safely adjustable by customer.

JW Brooks:T
Manual Firearms Design
Illiion Research Division

AL 0016420

36 of 80

Bridgeport, Connecticut
November 16, 1978

C.B. WORKMAN ✓
M.H. WALKER
J.P. LINDE
H.D. ALBAUGH-W.H. FURSON

BOLT ACTION FIRE CONTROL - DESIGN REVIEW 11-14-78

- A gauge is being designed to check sear lift. The gauge is expected to be positive and simple enough to be used in the field. Completion of a prototype gauge is scheduled for mid-December.
- The following design requirements for a new fire control for bolt action rifles were tentatively established -
 - OK 1. Eliminate the "trick" condition. At this point the best solution appears to be adding a trigger block to the safety cam mechanism. This would prevent the trigger from moving in the "safe" position - eliminating the "fail to reset" possibility.
 - ? 2. The new fire control should be retrofittable.
 - OK 3. A bolt lock arrangement should be provided. At this point a locking device separate from the fire control appears most desirable.
 - OK 4. Adjustment for the trigger pull force should be provided for the user. Access to the adjustment should not require stock removal. Other adjustments - sear-connector engagement - should be eliminated.
- Program
 - 1. Marketing will conduct consumer tests of the fire control designs now in hand during December and January. These include a three position and a two position safety with an external bolt lock. A sample with the present fire control with the bolt lock removed will be included.

2. Research will complete the design investigation and select a design approach by February 1, 1979.
 3. Consideration will be given to introducing the new design in a limited quantity of restyled M/600s in 1980.
- M.H. Walker will prepare a letter with his views on renaming the "safety" mechanism.

E.F. Barrett

EFFBarrett:jl

C

H

AL 0016422



38 of 80







DON'T SAY IT—WRITE IT

72 25 ft

	<u>W/C Back</u>	<u>W/B Back</u>	<u>A</u>
Std. 1012 -	25.17	25.81	.64
Std. 1076 -	39.49	39.92	.43
			<u>1.07</u>



"SAFETY RULES ARE PERFECT TOOLS"



AL 0016423

39 of 80

L. D. W. - 11/78

Copies to: R. L. Hall J. P. Linde
R. A. Morris L. B. Bosquet
H. K. Boyle Z. J. Kowalski
G. E. Fletcher Est. No. 4197
J. H. Sweeney

Jill

October 24, 1980

G. D. CAMPBELL

M/700 Bolt Latch Mechanism

Evaluation of the proposed Bolt Latch mechanism for M/700 rifles indicates it will result in a \$3.00 increase in unit factory cost (full allocation basis) in its first year (1982). For comparison purposes, a 1982 M/700 "Line Before" and three alternative "Line After" results were developed based on M/700 cost performance during the first six months of 1979. These alternatives were:

1. Adding of the Bolt Latch mechanism without adjusting prices.
2. Adding the Bolt Latch mechanism and adjusting prices to maintain the percent pretax margin.
3. Adding the Bolt Latch mechanism without adjusting prices, but deleting the sling and swivels from the BDL grade to compensate for the increased cost.

The results of these evaluations are summarized in the attached table which shows weighted average unit prices, costs, and pretax earnings and the project results. This data has been adjusted to anticipated 1982 price and cost levels.

As shown in this table, Alternative III is the most attractive in % margin, earnings, and net return on investment because it results in a net reduction in costs and working capital requirements. One disadvantage of this alternative is that ADL and Classic grade earnings are adversely affected, and the results shown depend on maintaining current product mix.

Alternative II also results in increased earnings, however, its net return on investment is substantially lower because of additional working capital requirements resulting from increased costs and sales.

All alternatives require project expenditures of \$249M construction and \$83M in operations charges. Detailed data for the line before and each alternative are attached.

J. C. Hutton

J. C. Hutton, Superintendent
INDUSTRIAL ENGINEERING SECTION

by T. R. Andrews
TRA/mc
Att.

AL 0016424

40 of 80

41 of 80

	1982 Line After			
	1982 Line Before	Alternative I Without Price Adjustment	Alternative II With Price Adjustment	Alternative III With String Deleted From BDL
Retail Selling Price	\$ 411.28	\$ 411.28	\$ 419.09	\$ 411.28
Net Selling Price	220.55	220.55	224.74	220.55
Factory Cost	158.05	161.05	161.05	155.89
Total Cost	183.75	186.62	187.23	181.68
Pretax Earnings - Unit Line	36.80 \$ 5,123 M	33.93 \$ 4,723 M	37.51 \$ 5,221 M	38.87 \$ 5,410 M
% of Net Selling	16.7%	15.4%	16.7%	17.6%

Project Results

Pretax Earnings

	Full Allocation Incremental	Net	Full Allocation Incremental	Net
Full Allocation Incremental	\$ 98M \$223M	\$ 287 M \$ 275 M	\$ 52M \$117M	\$ 150 M \$ 144 M
Net Earnings	(-\$100M) (\$310M)		(-\$204M) (\$158M)	
Net Return on Investment	8.6% 19.7%	202.7% 187.0%		

Net Earnings

Net Return on Investment

AL 0016425

	M/700 ADL	M/700 BDL	M/700	LINE BEFORE (MS)	WEIGHTS
QUANTITY	24,536	98,398	4,176	139,210	139,210
RETAIL SELLING PRICE	\$358.14	\$239.73	\$402.55	57,284	6411.28
NET SELLING PRICE	\$192.05	235.80	215.97	30,702	30,702 \$220.55
STANDARD MATERIAL	\$31.46	\$39.49	\$32.99	5,096	5,096
MATERIAL VARIANCE	3.93	4.88	4.08	637	627
STANDARD LABOR	22.23	25.17	23.53	3,366	3,366
LABOR VARIANCE	13.27	15.12	13.21	2,011	2,011
DIRECT EXPENSE	2.44	25.60	25.24		
GAS & POWER	2.24	2.52	2.36		
INDUSTRIAL RELATIONS	17.00	19.30	17.61		
GRATUITY REPAIRS	1.85	1.91	1.85		
TOTAL DIRECT CHGS.	\$62.59	\$48.83	\$46.06	6,451	6,451
SUPERVISION	2.16	2.42	2.30		
INDUSTRIAL RELATIONS	1.03	1.15	1.09		
FACTORY CLERKS	.27	.30	.29		
INDUSTRIAL ENGINEERING	.30	.33	.32		
DEPRECIATION	3.16	3.59	3.35		
PE & C DIRECT	.20	.22	.21		
FLOOR SPACE	2.34	2.62	2.48		
PROJECT COST	.90	1.01	.95		
OTHER DIRECT	.28	.31	.29		
TOTAL MFG O/H	\$10.64	\$11.94	\$11.28	11,593	-
Sub - Total	\$124.14	\$144.93	\$131.11	19,150	
PLANT OVERHEAD	21.87	25.35	23.60	3,353	-
UNAMORTIZED FACTORY COST	\$146.01	\$170.38	\$154.77	22,509	17,551
FACTORY COST (Gross Prof.)	\$142.73	\$166.43	\$151.29	20,062	17,156 158.05
SELLING & ADMINISTRATIVE	14.60	17.92	16.41	2,334	321 16.76
TECHNICAL	2.69	3.30	3.02	430	154 3.09
DISTRIBUTION	3.65	4.48	4.10	583	736.8 4.19
COST BEFORE ADMIN. EXP.	163.67	192.15	174.82		181.593
TOTAL COST	\$164.85	\$194.03	\$176.59	25,579	19,119 \$183.75
EARNING BEFORE Admin. Exp.	29.38	42.63	41.05		12,103
Less: Admin. Exp.	1.22	1.88	1.77	230	520 1.66
Pre-Tax Earnings	\$27.16	\$41.77	\$39.28	5,123	11,583 36.80
Less: Tax					
plus: AMORTIZED ITC					
Net Earnings					AL 0016426
Pre-Tax Margin	14.1%	17.7%	18.2%		16.7%

Single Line - 2000 units
Bout-Latum - 1932

2.5% ADJUSTED TO MAINTAIN 7% MARGIN

	MFG ADL M/200 EDL M/200	LINE A METER (M.S.) WEIGHTED
BURNT	44.635 30.398	4.176 210 139 210
BETWEEN Selling Price	5335.95	5447.53
NET Selling Price	\$1961.74	2351.93
	2201.56	31.285 311.285 \$224.74

STANDARD MATERIAL

MATERIAL VARIANCE

STANDARD LABOR

LABOR VARIANCE

DIRECT EXPENSE

GAS & POWER

INDUSTRIAL RELATIONS

GEARBOX REPAIRS

TOTAL DIRECT COST

SUPERVISION

INDUSTRIAL RELATIONS

FACTORY CLEANES

INDUSTRIAL ENGINEERING

DEPRECIATION

PE & C DIRECT

FLOOR SPACE

PROJECT COST

OTHER DIRECT

TOTAL MFG OH

Sub - Total

PLANT OVERHEAD

UNADJUSTED FACTORY COST

FACTORY COST (NET OF 20%)

SELLING & ADMINISTRATIVE

TECHNICAL

DISTRIBUTION

COST BEFORE ADMIN. EXP.

TOTAL COST

EARNING BEFORE Admin. Exp.

Less: Admin. Exp.

PRE-TAX EARNINGS

Less: TAX

plus: AMORTIZED ITC

Net Earnings

PRE-TAX MARGIN (%) OR NET SELLING (%)

Total

AL-0016428

16.7%

44 of 80

SAME AS LINE AFTER
WITHOUT PRICE ADJUSTMENT

()

DEPRECATION

PE & C DIRECT

FLOOR SPACE

PROJECT COST

OTHER DIRECT

TOTAL MFG OH

Sub - Total

PLANT OVERHEAD

UNADJUSTED FACTORY COST

FACTORY COST (NET OF 20%)

SELLING & ADMINISTRATIVE

TECHNICAL

DISTRIBUTION

COST BEFORE ADMIN. EXP.

TOTAL COST

EARNING BEFORE Admin. Exp.

Less: Admin. Exp.

PRE-TAX EARNINGS

Less: TAX

plus: AMORTIZED ITC

Net Earnings

PRE-TAX MARGIN (%) OR NET SELLING (%)

Total

AL-0016428

16.7%

Copies to: R. L. Hall J. P. Winda
R. A. Morris L. B. Bosquet
H. K. Boyle L. J. Kowalski
G. E. Fletcher Est. No. 4197
J. H. Sweeney

October 24, 1980

G. D. CAMPBELL

M/700 Bolt Latch Mechanism

Evaluation of the proposed Bolt Latch mechanism for M/700 rifles indicates it will result in a \$3.00 increase in unit factory cost (full allocation basis) in its first year (1982). For comparison purposes, a 1982 M/700 "Line Before" and three alternative "Line After" results were developed based on M/700 cost performance during the first six months of 1979. These alternatives were:

1. Adding of the Bolt Latch mechanism without adjusting prices.
2. Adding the Bolt Latch mechanism and adjusting prices to maintain the percent pretax margin.
3. Adding the Bolt Latch mechanism without adjusting prices, but deleting the sling and swivels from the BDL grade to compensate for the increased cost.

The results of these evaluations are summarized in the attached table which shows weighted average unit prices, costs, and pretax earnings and the project results. This data has been adjusted to anticipated 1982 price and cost levels.

As shown in this table, Alternative III is the most attractive in % margin, earnings, and net return on investment because it results in a net reduction in costs and working capital requirements. One disadvantage of this alternative is that ABL and Classic grade earnings are adversely affected, and the results shown depend on maintaining current product mix.

Alternative II also results in increased earnings, however, its net return on investment is substantially lower because of additional working capital requirements resulting from increased costs and sales.

All alternatives require project expenditures of \$249M construction and \$83M in operations charges. Detailed data for the line before and each alternative are attached.

J. C. Hutton

J. C. Hutton, Superintendent
INDUSTRIAL ENGINEERING SECTION

by T. R. Andrews
TRA/mc
Att.

AL 0016430

46 of 80

1982 Line After

	1982 Line Before	Alternative I Without Price Adjustment	Alternative II With Price Adjustment	Alternative III With Sling Deleted From HDL
Retail Selling Price	\$ 411.28	\$ 411.28	\$ 419.69	\$ 411.28
Net Selling Price	220.55	220.55	224.74	220.55
Factory Coat	158.05	161.05	161.05	155.89
Total Cost	183.75	186.62	187.23	181.68
Pretax Earnings - Unit Line	36.80 \$ 5,123 M	33.93 \$ 4,723 M	37.51 \$ 5,221 M	38.07 \$ 5,410 M
% of Net Selling	16.7%	15.4%	16.7%	17.6%
<u>Project Results</u>				
<u>Pretax Earnings</u>				
Full Allocation Incremental		(\$400M) (\$310M)	\$ 90M \$223M	\$ 287 M \$ 275 M
<u>Net Earnings</u>				
Full Allocation Incremental		(\$201M) (\$150M)	\$ 52M \$117M	\$ 150 M \$ 144 M
<u>Net Return on Investment</u>				
Full Allocation Incremental	--	Negative Negative	8.6% 19.7%	202.7% 187.0%

08 39 44

GENERAL INFORMATION						
NAME - LINE A - 22 W-12	NAME - 34A - 22	NAME - 34B - 22	NAME - 34C - 22	NAME - 34D - 22	NAME - 34E - 22	NAME - 34F - 22
M/700 ADL M/700 BDL	M/700	LH-4 ADL (M.G.)	W3162-22			
SURFACE & SWIVELS DELTED SPOOL BDL SPARE	C-1232-E	3000ft	129.210	129.210	129.210	129.210
BETAIL SURFACE Pipe	750A, 140	430A, 92	420A, 58	371.25H	371.25H	371.25H
NEL - GELLING Pipe	5192.05	5225.80	5215.90	301.702	2230.35	
STABOARD MATERIAL	531.89	533.65	533.42	44.601	44.601	44.601
MASTHEAD MATERIAL	3.88	4.16	4.13	3.365	3.365	3.365
STARBOARD LASHES	22.00	23.91	24.20	3.456	3.456	3.456
LADEER VARIANCE	13.52	15.37	13.46	2.046	2.046	2.046
DIALECT EXPEND	22.15	23.69	23.54			
GAS & POWER	21.30	22.58	22.42			
STARBOARD RELEASERS	17.49	19.72	18.04			
GATEAU'S RELEASERS	18.87	19.93	18.87			
TACKLESTAR RELEASERS	17.49	19.72	18.04			
TACKLE STAR TACKLES	3.29	3.31	3.30			
FACTOORY CLIPS	28					
DRILLING CIRCUMSTANCES	3.29	3.17	3.24			
DRILLING CIRCUMSTANCES	3.29	3.23	3.24			
OTHER DRILLING	1.93	1.04	0.98			
ROD TIE-UP COST	2.41	2.69	2.55			
FACSIMILE SPLICER	2.41	2.23	2.22			
DRILLING CIRCUMSTANCES	3.29	3.17	3.24			
DRILLING CIRCUMSTANCES	3.29	3.23	3.24			
OTHER DRILLING	1.93	1.04	0.98			
TOTAL MFG O/A	11.00	12.30	11.44	1.400	1.400	1.400
SUS - TOTAL	126.69	140.41	133.72	8.580	17.216	9.216
DRILLING OPERATIONS	22.32	24.56	24.05			
TOTAL MFG O/A	11.00	12.30	11.44	1.400	1.400	1.400
SEPARATING COST (Cost BPS)	145.73	161.33	154.29	21.708	16.565	15.599
EXCAVATOR COST (Cost BPS)	145.73	161.33	154.29	21.708	16.565	15.599
SEPARATING & EXCAVATOR COSTS	14.60	17.92	16.41	2.356	9.211	16.716
DISMANTLING	2.69	3.30	3.02	4.320	4.320	3.009
DISMANTLING	3.55	4.08	4.16	5.013	3.68	4.119
COAL BREAKING & MINING	166.67	184.67	177.62	187.03	177.62	177.62
DEE-1A EQUINOS	824.29	844.67	836.41	91.056	836.41	836.41
DEE-1A EQUINOS	1.09	2.10	1.64	2.023	0.958	1.095
EXCAVATING EQUIPMENT	25.38	43.97	38.05	12.291		
EXCAVATING EQUIPMENT	25.38	43.97	38.05	12.291		
NET EARNINGS						
ALL 0016435						

(E) 12.2% - Net Income (Excl. Div.)
 (E) 12.2% - Net Income (Excl. Div.)
 (E) 12.2% - Net Income (Excl. Div.)

St-and-and L&L 8.53
 M-Subsidy 1.05
 L&L 0.75
 Indus-tial Exports 1.13
 Other-Direct Exports 0.08
 Direct Charge 0.30
 Indus-tial Exports 1.13
 Other-Direct Exports 0.08
 Other-Manufac-turing 0.23
 S&b-T&t 2.55
 Plant Over-head 0.45
 Total Cost \$3.00

M190 Bolt-Latch Mechanism

Cost by Component

T.B Andrews
12/11/80

Component	Standard Material	Standard Labor	Direct Charges
Bolt Latch (new part + 2 drill + 2 operations heat treat & color)	\$.168	\$.115	\$.028
Bolt Plug (existing part + 3 special machine operations no burrs)	-	.377	.169
Bolt Assembly (existing part + 1 mill oper.)	-	.253	.101
Firing Pin Assembly (existing part + assm. oper.)	-	.092	.0001
Detent Plunger (new part, heat treat & color)	.234	.0004	.0004
Detent Plunger Spring (new part)	.013	-	-
Detent Retaining Pin (new part)	.011	-	-
Final Assembly (added inspection elements)	-	.014	-
Total	\$.426	\$.6514	\$.2985

AL 0016437



REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
ARMED

PETERS

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

cc: C. B. Workman
J. S. Martin
F. E. Martin
E. R. Owens

April 8, 1981

To: T. L. Capeletti

From: L. W. Bower *jwb*

Re: M/700 Bolt Lock - Manufacturing Costs

In October, 1980, Industrial Engineering issued a report on the cost of the M/700 Bolt Lock based on a PE & C estimate. Because of the seemingly high cost to manufacture this feature, the Research Process Development Group was asked to review. Exhibit 1 shows a comparison of costs based on estimates prepared by PE & C, Research, and a hypothetical best case.

The major difference between the Research and PE & C estimate is the labor cost to make the extra cuts in the Bolt Plug. PE & C estimated two special machines, the Research estimate provides for 1 machine, and, therefore, less labor input. This \$.21 difference is multiplied when labor variance, industrial relations, and overhead are added to it.

The "best case" condition assumes that the pin hole in the Bolt Latch can be moved so that the powder metal blank can be made to include the hole. This \$.11 savings in the direct cost to drill the hole is again multiplied by the various overhead accounts.

Two other approaches are possible. If a high strength plastic could be substituted for powder metal in the Bolt Latch, it may be possible to reduce the total cost of the feature by an additional \$.20 below the "best case". Finally, the possibility of an investment cast Bolt Plug could be investigated. It would be necessary to eliminate all of the added cuts in the investment cast blank, however, to show any significant savings.

JWB:ws
Firearms Research Division
Attach.

AL 0016438


53 of 80

M/700 BOLT LOCKMANUFACTURING COSTS

	<u>PE&C</u>	<u>R&D</u>	<u>BEST CASE</u>
Standard Material			
Bolt Latch	.17	.15	.15
Detent Plunger	.02	.02	.02
Detent Plunger Spr.	.01	.01	.01
Detent Retaining Pin	.01	.01	.01
Total	.21	.19	.19
Material Variance (12.2%)	.03	.02	.02
Standard Labor			
Bolt Latch	.12	.12	.01
Bolt Plug	.38	.17	.17
Bolt Assembly	.05	.03	.03
Firing Pin Assembly	.09	.07	.07
Final Assembly	.01	.01	.01
Total	.65	.40	.29
Labor Variance (38.6%)	.25	.15	.11
Industrial Relations (47.9%)	.43	.26	.19
Misc. Direct Exp (3.8%)	.06	.04	.03
Depreciation (7.5% Capital)	.13	.07	.07
Manufacturing Overhead (10%)	.18	.12	.09
Plant Overhead (17.5%)	.34	.22	.17
Price/Gun	\$ 2.28	\$ 1.47	\$ 1.16

AL 0016439

54 of 80



DON'T SAY IT—WRITE IT

To: T.L. CAMPBELL


From: G.D. CAMPBELL *bc*

Date: 12/22/80

RE: M/700 BOLT LATCH MECHANISM - Costs

Attached are I.E. worksheets detailing the cost of adding this feature. If you have questions or wish to discuss this further, please contact me.

GDC:js
Attach.



K

S

I

C

H

"SAFETY RULES ARE PERFECT TOOLS"

AL 0016440

55 of 80

Component						Comments
B.04 Hatch	B.04 Plugs	B.04 Assembly	B.04 Existing part + 3 specific	B.04 Existing part + 1 mill open	B.04 Assembly	Firing Bn Assembly (existing part + 1 mill open)
0001	093	093	-	-	053	(existing part + 1 mill open)
0004	.0004	.0004	.034	.013	.011	D Detent Plugs - Spacing (new part)
0005	-	-	-	-	-	D Detent Retaining Bn (new part)
0114	-	-	-	-	-	Total Assembly (existing part + 1 mill open)
0115	0115	0115	0115	0115	0115	Total
0116	0116	0116	0116	0116	0116	
0117	0117	0117	-	-	-	
0118	0118	0118	-	-	-	
0119	0119	0119	-	-	-	
0120	0120	0120	-	-	-	
0121	0121	0121	-	-	-	
0122	0122	0122	-	-	-	
0123	0123	0123	.013	.013	.011	D Detent Plugs - Spacing (new part)
0124	0124	0124	.034	.011	.011	D Detent Retaining Bn (new part)
0125	0125	0125	-	-	-	Total
0126	0126	0126	-	-	-	
0127	0127	0127	-	-	-	
0128	0128	0128	-	-	-	
0129	0129	0129	-	-	-	
0130	0130	0130	-	-	-	
0131	0131	0131	-	-	-	
0132	0132	0132	-	-	-	
0133	0133	0133	-	-	-	
0134	0134	0134	-	-	-	
0135	0135	0135	-	-	-	
0136	0136	0136	-	-	-	
0137	0137	0137	-	-	-	
0138	0138	0138	-	-	-	
0139	0139	0139	-	-	-	
0140	0140	0140	-	-	-	
0141	0141	0141	-	-	-	
0142	0142	0142	-	-	-	
0143	0143	0143	-	-	-	
0144	0144	0144	-	-	-	
0145	0145	0145	-	-	-	
0146	0146	0146	-	-	-	
0147	0147	0147	-	-	-	
0148	0148	0148	-	-	-	
0149	0149	0149	-	-	-	
0150	0150	0150	-	-	-	
0151	0151	0151	-	-	-	
0152	0152	0152	-	-	-	
0153	0153	0153	-	-	-	
0154	0154	0154	-	-	-	
0155	0155	0155	-	-	-	
0156	0156	0156	-	-	-	
0157	0157	0157	-	-	-	
0158	0158	0158	-	-	-	
0159	0159	0159	-	-	-	
0160	0160	0160	-	-	-	
0161	0161	0161	-	-	-	
0162	0162	0162	-	-	-	
0163	0163	0163	-	-	-	
0164	0164	0164	-	-	-	
0165	0165	0165	-	-	-	
0166	0166	0166	-	-	-	
0167	0167	0167	-	-	-	
0168	0168	0168	-	-	-	
0169	0169	0169	-	-	-	
0170	0170	0170	-	-	-	
0171	0171	0171	-	-	-	
0172	0172	0172	-	-	-	
0173	0173	0173	-	-	-	
0174	0174	0174	-	-	-	
0175	0175	0175	-	-	-	
0176	0176	0176	-	-	-	
0177	0177	0177	-	-	-	
0178	0178	0178	-	-	-	
0179	0179	0179	-	-	-	
0180	0180	0180	-	-	-	
0181	0181	0181	-	-	-	
0182	0182	0182	-	-	-	
0183	0183	0183	-	-	-	
0184	0184	0184	-	-	-	
0185	0185	0185	-	-	-	
0186	0186	0186	-	-	-	
0187	0187	0187	-	-	-	
0188	0188	0188	-	-	-	
0189	0189	0189	-	-	-	
0190	0190	0190	-	-	-	
0191	0191	0191	-	-	-	
0192	0192	0192	-	-	-	
0193	0193	0193	-	-	-	
0194	0194	0194	-	-	-	
0195	0195	0195	-	-	-	
0196	0196	0196	-	-	-	
0197	0197	0197	-	-	-	
0198	0198	0198	-	-	-	
0199	0199	0199	-	-	-	
0200	0200	0200	-	-	-	
0201	0201	0201	-	-	-	
0202	0202	0202	-	-	-	
0203	0203	0203	-	-	-	
0204	0204	0204	-	-	-	
0205	0205	0205	-	-	-	
0206	0206	0206	-	-	-	
0207	0207	0207	-	-	-	
0208	0208	0208	-	-	-	
0209	0209	0209	-	-	-	
0210	0210	0210	-	-	-	
0211	0211	0211	-	-	-	
0212	0212	0212	-	-	-	
0213	0213	0213	-	-	-	
0214	0214	0214	-	-	-	
0215	0215	0215	-	-	-	
0216	0216	0216	-	-	-	
0217	0217	0217	-	-	-	
0218	0218	0218	-	-	-	
0219	0219	0219	-	-	-	
0220	0220	0220	-	-	-	
0221	0221	0221	-	-	-	
0222	0222	0222	-	-	-	
0223	0223	0223	-	-	-	
0224	0224	0224	-	-	-	
0225	0225	0225	-	-	-	
0226	0226	0226	-	-	-	
0227	0227	0227	-	-	-	
0228	0228	0228	-	-	-	
0229	0229	0229	-	-	-	
0230	0230	0230	-	-	-	
0231	0231	0231	-	-	-	
0232	0232	0232	-	-	-	
0233	0233	0233	-	-	-	
0234	0234	0234	-	-	-	
0235	0235	0235	-	-	-	
0236	0236	0236	-	-	-	
0237	0237	0237	-	-	-	
0238	0238	0238	-	-	-	
0239	0239	0239	-	-	-	
0240	0240	0240	-	-	-	
0241	0241	0241	-	-	-	
0242	0242	0242	-	-	-	
0243	0243	0243	-	-	-	
0244	0244	0244	-	-	-	
0245	0245	0245	-	-	-	
0246	0246	0246	-	-	-	
0247	0247	0247	-	-	-	
0248	0248	0248	-	-	-	
0249	0249	0249	-	-	-	
0250	0250	0250	-	-	-	
0251	0251	0251	-	-	-	
0252	0252	0252	-	-	-	
0253	0253	0253	-	-	-	
0254	0254	0254	-	-	-	
0255	0255	0255	-	-	-	
0256	0256	0256	-	-	-	
0257	0257	0257	-	-	-	
0258	0258	0258	-	-	-	
0259	0259	0259	-	-	-	
0260	0260	0260	-	-	-	
0261	0261	0261	-	-	-	
0262	0262	0262	-	-	-	
0263	0263	0263	-	-	-	
0264	0264	0264	-	-	-	
0265	0265	0265	-	-	-	
0266	0266	0266	-	-	-	
0267	0267	0267	-	-	-	
0268	0268	0268	-	-	-	
0269	0269	0269	-	-	-	
0270	0270	0270	-	-	-	
0271	0271	0271	-	-	-	
0272	0272	0272	-	-	-	
0273	0273	0273	-	-	-	
0274	0274	0274	-	-	-	
0275	0275	0275	-	-	-	
0276	0276	0276	-	-	-	
0277	0277	0277	-	-	-	
0278	0278	0278	-	-	-	
0279	0279	0279	-	-	-	
0280	0280	0280	-	-	-	
0281	0281	0281	-	-	-	
0282	0282	0282	-	-	-	
0283	0283	0283	-	-	-	
0284	0284	0284	-	-	-	
0285	0285	0285	-	-	-	
0286	0286	0286	-	-	-	
0287	0287	0287	-	-	-	
0288	0288	0288	-	-	-	
0289	0289	0289	-	-	-	
0290	0290	0290	-	-	-	
0291	0291	0291	-	-	-	
0292	0292	0292	-	-	-	
0293	0293	0293	-	-	-	
0294	0294	0294	-	-	-	
0295	0295	0295	-	-	-	
0296	0296	0296	-	-	-	
0297	0297	0297	-	-	-	
0298	0298	0298	-	-	-	
0299	0299	0299	-	-	-	
0300	0300	0300	-	-	-	
0301	0301	0301	-	-	-	
0302	0302	0302	-	-	-	
0303	0303	0303	-	-	-	
0304	0304	0304	-	-	-	
0305	0305	0305	-	-	-	
0306	0306	0306	-	-	-	
0307	0307	0307	-	-	-	
0308	0308	0308	-	-	-	
0309	0309	0309	-	-	-	
0310	0310	0310	-	-	-	
0311	0311	0311	-	-	-	
0312	0312	0312	-	-	-	
0313	0313	0313	-	-	-	
0314	0314	0314	-	-	-	
0315	0315	0315	-	-	-	
0316	0316	0316	-	-	-	
0317	0317	0317	-	-	-	
0318	0318	0318	-	-	-	
0319	0319	0319	-	-	-	
0320	0320	0320	-	-	-	
0321	0321	0321	-	-	-	
0322	0322	0322	-	-	-	
0323	0323	0323	-	-	-	
0324	0324	0324	-	-	-	
0325	0325	0325	-	-	-	
0326	0326	0326	-	-	-	
0327	0327	0327	-	-	-	
0328	0328	0328	-	-	-	
0329	0329	0329	-	-	-	
0330	0330	0330	-	-	-	
0331	0331	0331	-	-	-	
0332	0332	0332	-	-	-	
0333	0333	0333	-	-	-	
0334	0334	0334	-	-	-	
0335	0335	0335	-	-	-	
0336	0336	0336	-	-	-	
0337	0337	0337	-	-	-	
0338	0338	0338	-	-	-	
0339	0339	0339	-	-	-	
0340	0340	0340	-	-	-	
0341	0341	0341	-	-	-	
0342	0342	0342	-	-	-	
0343	0343	0343	-	-	-	
0344	0344	0344	-	-	-	
0345	0345	0345	-	-	-	
0346	0346	0346	-	-	-	
0347</						


M/1900 120L - ATC-4 METAHANISM
M/1900 120L - ATC-4 METAHANISM

4/700 Bow Latch Mechanism
Cost Breakdown

T.R. Andrews
2/1/60

Standard Material	\$.43	(Estimated)
Material Variance	.05	(@ 12.3% - historical ratio)
Standard Labor	.65	(Estimated)
Labor Variance	.25	(38.4% calculated by department based on 1919 experience)
Direct Charges	.30	(Estimated)
Industrial Relations	.43	(@ 47.9% of Labor + Labor Variance)
Other-Direct Expense	.08	(Calculated based on historical ratios repair and gas & power ratios)
Additional Depreciation	.13	(@ 7.5% of project estimate)
Other Manufacturing Overhead	.23	(Calculated based on historical ratios)
Sub-Total	2.55	
Plant Overhead	.45	(@ 17.5% of subtotal - historical ratio)
Total Cost	\$ 3.00	

AL 0016442



DON'T SAY IT—WRITE IT

To T.L. CAPELETTI

Date 12/22/80

From G.D. CAMPBELL *bc*

RE: M/700 BOLT LATCH MECHANISM - Costs

Attached are I.E. worksheets detailing the cost of adding this feature. If you have questions or wish to discuss this further, please contact me.

GDC:js.
Attach.

"SAFETY RULES ARE PERFECT TOOLS"



AL 0016443

58 of 80

Mar 11 - 1970

4/100 Foot Hatch Mechanism
Cost Breakdown

T.R. Andrews
2/17/70

Standard Material	\$.43	(Estimated)
Material Variance	.05	(@ 12.2% - historical ratio)
Standard Labor	.65	(Estimated)
Labor Variance	.75	(38.4% - calculated by department based on 1970 experience)
Direct Charges	.30	(Estimated)
Industrial Relations	.43	(@ 47.9% of Labor + Labor Variance)
Other Direct Expense	.08	(Calculated based on historical ratios repair and gas & power ratios)
Additional Depreciation	.13	(@ 7.5% of project estimate)
Other Manufacturing Overhead	.22	(Calculated based on historical ratios)
Sub-Total	2.55	
Plant Overhead	.45	(@ 17.5% of subtotal - historical ratio)
Total Cost	\$ 3.00	

AL 0016445

	SAC	BOLT LOCK	DATE	AL 0016446
2023	3-2-80		by	2-20-80
Estimator	Z. KOWALESKI		2023	2-20-80
				2-20-80
ALL FIGURES IN \$		CAP.	OPR.	
1. DESIGNATION				
Investigation				
Design				
Model Making				
Design Casting				
Model, Form, Tools				
Tooling - Castings				
Tooling - Parts				
Tooling - Production				
2. PRODUCTION				
Process Eng. & Trial Run				
Pilot lot forming				
3. TOOLING				
Design	2000-	14000-		
Planned & Used	7000-	144000-		
Holds				
Reusable tools		1000-		
Tool revisions		18000-		
Reusable tooling		6000-		
4. SPECIAL MATERIALS				
Construction	100000-			
Design				
Quality				
Reusable materials				
Revisions				
5. EQUIPMENT				
Construction				
Design				
Quality				
Reusable materials				
Revisions				
6. STANDARD MACHINES & TOOLS				
Construction				
Design				
Quality				
Reusable materials				
Revisions				
7. REPAIRS				
Machining alterations				
Paint job add		4000-		
Welding repairment		10000-		
Some obsolescence				
General job for maintenance				
Welds & general repairs				
etc. etc.				
etc. etc.	10900-	8700-		
Total	119900-	95700-		
GRAND TOTAL		215600-		


AL 0016446

		ESTIMATE		G.E. FLETCHER J.C. MOTTORI S. BURDICK J.C. GARDNER N. KARASCOVICH T. L. HARRIS J. L. LINDSAY D. COOK C. CLEVANT J. T. JENNISON L. WALL R. COYLE H. COYLE	
Date	Model	Review	Estimator	Design	Process
1983-84	AMERICAN-AT-LAKE	Y1	G. CAMPBELL		
Estimated by	J. C. MOTTORI				
ALL FIGURES IN \$		CAP	OPR.		
1. DEVELOPMENT					
Investigation					
Design					
Model Making					
Design Testing					
Models, 1st lot					
Normal - Production Model					
Development Units					
Process Holders, 6 sets \$ 500					
2. PROCESSING					
Process Eng. & tooling					
First lot testing					
3. TOOLING					
Design	10000-	10000-			
Fixtures & Gages	10000-	10000-			
Molds		X			
Reusable tools			10000-		
Tool revisions			50000-		
Vendors tooling			5000-		
4. SPECIAL MACHINES					
Construction	212,000-				
Design	12,000-				
Testing					
Reusable tooling					
Operations					
5. CONSTRUCTION MACHINES					
Construction					
Design					
Testing					
Reusable tooling					
Operations					
6. STARTUP MACHINES & EQUIPMENT					
ROUTINE USE					
Construction					
Operations					
7. OTHER EXPENSES					
Machine alterations					
First lot mix		3000-			
Machining requirements		2000-			
Com. obsolescence		3000-			
Printers for advertising					
Vehicle & material moves					
etc etc					
etc etc					
etc etc					
etc etc					
etc etc					
etc etc					
TOTAL	365,000-	83,000-			
Grand Total		277,000			

AL 0016447

63 of 80

AL 0016448



100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100

100




100

100

100

100

100



SK-D-3551

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

||

M1700 Gear-Latch Mechanism
Cost Breakdown

T.B. Andrews
April 1960

Standard Material	\$.43	.25	(Estimated)
Material Variance	.05	.03	(@ 12.2% - historical ratio)
Standard Labor	.62	.46	(Estimated)
Labor Variance	.25	.13	(38.6% calculated by department based on 1979 experience)
Direct Charges	.30	.30	(Estimated)
Industrial Relations	.13	.10	(@ 47.9% of Labor-Labor Variance)
Other-Direct Expense	.28	.07	(Calculated based on historical rates repair and fast power ratios)
Additional Depreciation	.13	.14	(@ 7.5% of project estimate)
Other Manufacturing Overhead	.23	.15	(Calculated based on historical ratio)
Sub-Total	2.55	2.23	
Plant Overhead	.45	.30	(@ 17.5% of subtotal - historical ratio)
Total Cost	\$3.00	2.62	
		2.62	
		2.62	

AL 0016449

WILCOX B80 - 4-2-1 MESSAURISM

(Bolt Lock)

PROCESS ENGINEERING ESTIMATE - TRIAL AND PILOT SHEET

~~5720~~ #
5720

Digitized by srujanika@gmail.com

MODEL F-84B COMPONENT FINAL ASSEMBLY
DATE 5-28-62 COMPUTER KOMALSKI

PART NO.

SHEET 1 OF 1

TOTAL

AL 0016451



ESTIMATE - TRIAL AND BILLET

→ *Aeros*

• SEQUENCE OF OPERATIONS •

卷之三

MODEL BCB-4E COMPONENT FLYING PI ASSEMBLY
DATE 5/7/83 COMPUTER KOWALSKA

卷之三

COMMITTEE **KOVALSKY**

PART NO.

Sheet 1 of 1

80-6566 1-18-83

TOTAL

AL 0016452



(Bolt Lock)

PROCCESS ESTIMATE INIZIATIVA

• SEQUENCE OF OPERATIONS •

Model Name: COMPONENT DET-100 PUNGER SPRING Part No:
Date: 3-14-89 Computer: KOWALSKI Sheet 1 of 1

RD-6566 145-63

AL 0016453

68 of 80

ପ୍ରକାଶକ

PROCESS ENGINEERING ESTIMATE - TRIAL AND PILOT SHEET

Digitized by srujanika@gmail.com

* SEQUENCE OF OPERATIONS *

304-A-010
MODEL MA-10 COMPONENT DOOR PLATE RETAINING PART NO.
DATE 3-12-83 COMPUTER KOMALSKII SHEET 1 OF 1

3D-4548 1-18-62

TOTAL

AL 0016454

69 of 80

(Bob-Lock Special Machines)

PROCESS ENGINEERING ESTIMATE - TRIAL AND PILOT SHEET

* SEQUENCE OF OPERATIONS *

MODEL A-10
DATE 0-26-50

COMPONENT BOLT PLUG
COMPUTER KOWALSKI

SK 0.5004
PART NO. 0.5004
SHEET 2 OF 2

OPER. NO.	OPERATION NAME	MACHINE	DEPT. (NO.)	HOURS DESIGN	HOURS BUILD
25-8	LOAD WORK	6 STA. SPEC. MACHINE			
	DEAL STAKING HOLE - 1/8" POS	INDEX TAPS			
	Burr Deal " - 1/8"				
	Dent " " 2x8	MACHINE	WELD	—	1120.000
	Rough Mill Slot (2 Depth)	(Fix-Holder-Cut-Weld)			
	Finish Mill Slot (2 Depth)	(AGES)		*	761 200
	MACHINE CYCLE - 36 SEC (APPROX)				
	DELIVERY - 30-34 WKS				
26	Burr - Deal to Depth	WELD. LINE MACHINE			
	DETENT PUNCHER HOLE				
	NO. 100-2125 - 40 SEC (APPROX)	MACHINE		4000	720.000
		FIXTURE	WELD	50	1000
	DELIVERY - 30-34 WKS	TOOL	STL WELD	2	150
	(APPROX)	BOSS	WELD	40	110
27-2	DEBURR	FRENCH			
28	SURFACE	SAND A - M1700			
31	DEBURR	" "	" "	" "	" "
32	NOTE BLACK SPACE IN TRAVS	" "	" "	" "	" "
33	INSPECT FOR COVERS				
34	INSPECT INSULAT.				
	TOTAL				



PROCESS ENGINEERING ESTIMATE - TRIAL AND PILOT SHEET

44-100-4 - Act 9

* SEQUENCE OF OPERATIONS *

SEARCHED - INDEXED
SERIALIZED - FILED

Model Name

COMPONENT Bolt-Plug

2021-20

卷之三

COMPUTED X 22 APR 51

卷之三

2025 RELEASE UNDER E.O. 14176

Digitized by srujanika@gmail.com

卷之三

Bolt Lock
PROCESS ENGINEERING ESTIMATE - TRIAL AND PILOT SHEET

41700
Bolt Action Parts
MODEL 300
COMPONENT Bolt PWR
DATE 5/27-80 COMPUTER KOWAH AX.

SEQUENCE OF OPERATIONS

SK-3
PART NO. 3551
SHEET 2 OF 3

OPER. NO.	OPERATION NAME	MACHINE	DEPT. NO.	HOURS DESIGN	HOURS BUILD
(new) 25	LOAD & UNLOAD	75" Spec MACHINE			
	MILL PROBLEMS OF Bolt Lock SWR				
	Perforate Retainer " " "	MACHINING COST	NEW	100,000 ²	
	Dein 1/2" Starting Hole	FIXTURE (72000)	"	70	7000
	" " "	PERMANENT TOOLS	"	6	\$533
	Mill Small Slit	TOOL HOUSES	"	20	3750
	Mill Form in Center Section	GAGES	"	180	550
	Cycle Time - 15 SEC (approx)				
(new) 26	Burr & Drill to Depth DETENT PLUNGER HOLE	25" DIA DRILL PRESS			
		DRILL JIG	60	120	
		TOOLS	6	250 ²	
		GAGES	35	95	
(new) 27	Burr Root Drill - REM ESTABLISH D.J. HOLE	4" SCALES	PRESS		
		DRILL JIG	JAW	60	120
		TOOLS	6	250 ²	
		GAGES	35	95	
(new) 28	DEBURR	BENCH			
(new) 29	SURFACE HOLE	(same as 41700)			
	TOTAL				

AL 0016458

PROCEDURES WHICH ESTIMATE TRIAL ATTRIBUTION

*** SEQUENCE OF OPERATIONS ***

MODEL Passive COMPONENT Dot Plus
DATE 5/27-92 COMPUTER Kowalski

SK-D.
PART NO. 1551

SHEET 1 OF 2

AL 0016459

Bolt Lock - Powder Metal

PROCESS ENGINEERING ESTIMATE - TRIAL AND PILOT SHEET

SEQUENCE OF OPERATIONS

MODEL 100	COMPONENT BOLT LATCH	PART NO. SK-C. 3200
DATE 10-17-80	COMPUTER KWALSKI	SHEET 1 OF 1
OPER. NO.	OPERATION NAME	MACHINE
		DEPT. HOURS NO. DESIGN BUILD
PURCHASE FROM HI-DEUSE DIVISION		
	POWDER METAL BLANK	QUOTATION # - 1523 (C-3-40)
	153.51M - 25,000 QTY	
	\$143.91M - 50,000	
	Tooling 4400 ⁰⁰	
20	DRILL CROSS PIN HOLE	1 APOLLO Drill Press
	Drill Jig NEW 40	120
	PS2 (0.035 Dia) Drill ISO -	
	GAGES NEW 31	35
30	CUT IN TO DEGREE HOLE (BOTH SIDES)	2000 Drill Press
	CUT - 30° - 3200	
40	CROWNING HAMMER	
50	LINDBERG DRILL	
60	INSPECT FOR ROCKWELL	
70	BURN ON WIRE COATINGS	
80	TO MRP CBB TOTAL	
		AL 0016460

RD-6568 118-63

Bout Loun

PROCESS ENGINEERING ESTIMATE - TRIAL AND PILOT PLANT

~~130~~ ~~2~~ Doc Action)

• SEQUENCE OF OPERATIONS •

~~MODELLING~~
DATE 5-13-80

COMPONENT BOLT LATCH
COMPUTER KONIALESKY

~~PA 21 ZO X~~

STREET 1 OF 1

(Bolt Lock)

PROCESS ENGINEERING ESTIMATE, TRIAL AND PILOT SYSTEMS

* SEQUENCE OF OPERATIONS *

MODIFICATION DATE 3/1/20 COMPONENT Defect Plumber Schematic PART NO. _____
DATE 3/1/20 COMPUTER KOWALSKI SHEET 1 OF 1

AL 0016462

2020-08-20 2020-08-22

77 of 80

A

Salt Clay

L

E

K

S

I

C

6

H

Rec Acct
4/11/61

17012 } 11.957 labor } 69.357
57.400 material }
129.885 full factory

AL 0016463

78 of 80

RE-1-8
REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
OUPORT

PETERS
OUPORT

Xc: C. B. Workman
T. L. Capeletti

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

February 8, 1982

TO: J. S. Martin
FROM: F. E. Martin
SUBJECT: M/700 Fire Control Program

The program to complete this project beginning now could be completed by 1 September 1982:

- The completion of the testing of fire controls already in the Test Lab. These fire controls contain:
 - hardened triggers
 - trigger block plunger of 8640 material
- Fabrication and testing of fire controls having:
 - skeletonized housing
 - relieved sear
 - relieved triggers - design permitting
 - no trigger connector
- Research-Marketing agreement on implementation of change
- Design acceptance and transmittal

FEM:ws

AL 0016464

A
L
E

G-88

DON'T SAY IT-WRITE IT

cc: Fred Martin

To: Tim Martin

Date:

2/10/82

From: Toni C.

re: M/1700 Fire Control Program

We should schedule a early review of our plans with warehouse, Marketing, and Legal (+ Production ?) to make sure they are aware of our direction for this design. To be completed by Sept. 1, 1982 means that we must have a specific design concept in mind by March 1st with at least one configuration. Therefore, we should begin the review by mid-March.

"SAFETY RULES ARE PERFECT TOOLS"

H

AL 0016465

80 of 80