

GUN EXAMINATION REPORT NUMBER: 700 BDL
 GENERAL CONDITION: NEW R #: 002678
 OUTSIDE WORK: NO DATE: 2-2-72
 FIRED AMMO TYPE: DECATUR, ILL.
 & CONDITION: 6294075
 PROOF: R.E.P.-A INSP.: 9 TEST: 13 CODE: X5-12/69
 HEADING: O.K. GA./CAL.: 270 WIN.
 BREACH OPENING: — CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER PULL 6 LBS., ENGAGEMENT 0.20. TRIGGER
 BIND IS NOTICEABLE. IN DIS-ASSEMBLING THE TRIGGER
 HAS WHAT APPEARS TO BE DRIED STEEL BURR ON
 THE SIDES CAUSING IT TO BIND.

COMPLAINT: WHEN BOLT IS PUT IN ALL THE WAY THE GUN WILL
GO OFF?
 INCIDENT: FOLLOW DOWN

COMMENTS: THE SLOTTED TRIGGER PROBABLY FAILED TO
RETRACT RESULTING IN A FOLLOW DOWN MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3257

AL 0029789

P.I. NO GUN EXAMINATION REPORT NUMBER: _____GENERAL CONDITION: GOODOUTSIDE WORK: SCOPE MOUNTEDFIRED AMMO TYPE: F

& CONDITION: _____

PROOF: R.E.P.INSP. DTEST: ?HEADLINE: O.K.BREACH OPENING: -RECOIL SHOULDERS: O.K.CHAMBER: O.K.

TEST: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700ADLR# : 000972DATE: 1-15-73FROM: COOPER'S
SPORTING GOODSMANFIELD, PA.GUN # : 300043CODE: NP = 8/67GA./CAL.: 270WIN.CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

BOLT HANDLE BROKEN OFF. TRIGGER BINDING -
HEAVY LUBRICANT - CONNECTOR. STUCK TO
TRIGGER. CORNER OF SEAR BROKEN DOWN.

COMPLAINT: FIRES WHEN SAFETY IS TAKEN OFF.INCIDENT: FOLLOW DOWNPLAINTIFF'S
EXHIBIT3181

REMARKS: THE TRIGGER BINDING AS A RESULT OF THE
DRIED OUT LUBRICANT FAILED TO RETRACT,
REMAINING IN FIRED POSITION, CAUSED THE
FOLLOW DOWN.

Cust. Complaint

NO GUN EXAMINATION REPORT NUMBER: MODEL: 700 ADL
 GENERAL CONDITION: GOOD R#: 002805
 OUTSIDE WORK: SWIVELS AND SCOPE MOUNT- DATE: 2-1-73
 ED. FROM: FULKS SPORTING
 FIRED AMMO TYPE: CLACKS BURG, N.V.A.
 & CONDITION: GUN #: 6247427
 PROOF: R.E.P.-A INSP. 73 TEST: 87 CODE: K5 = 5/69
 HEADING: O.K. SA./CAL.: 270 N.H.
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED:
 CHAMBER: O.K. APPROVED:
 TEST: NO APPROVED:
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. IS .020)

CONNECTOR CLEARANCE ON TRIGGER = .0069 (MODEL = 1.076
DRAWING = 1.074)4 OF TRIGGER PIN HOLE TO TOP OF TRIGGER = .974 (.973
.971)

COMPLAINT: FIRES WHEN SAFETY IS MOVED TO FIRE POSITION.

INCIDENT: FOLLOW DOWN

COMMENTS: THE EXCESSIVE MOVEMENT BETWEEN TRIGGER &
 TRIGGER CONNECTOR WILL ALLOW INTERFERENCE
 BETWEEN THE SEAR AND CONNECTOR WHICH PREVENTS
 RETRACTION INTO COCKED POSITION. THE PRESENCE
 OF HARDENED LUBRICANT INCREASES THE POSSIBILITY
 OF A MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3176

AL 0029706