

WAW
10/15

CUSTOMER

POINT OF VIEW

HIGH

"EASE OF USE"

- QUICK TO FIND
- EASY TO OPERATE
- EASY TO UNDERSTAND
- RELIABLE TO OPERATE
- EASY TO USE WITH 'SCOPE
- CRISP TRIGGER PULL
- MINIMUM CREEP
- HIS OWN PERCEPTION OF "WHAT IS"

MEDIUM

- QUIET OPERATION
- MINIMUM BACKLASH (feed back)
- SINGLE STAGE PULL
- EASILY KNOWN STATUS ("S" OR "F")
- PLEASING APPEARANCE
- ADJUSTABLE FOR WEIGHT OF PULL

LOW

- LOCATION OF SAFETY (CONSISTENT WITH EASE OF USE)
- HOW MECHANISM PREVENTS UNINTENDED FIRING-WHAT IT BLOCKS
- MINIMUM TRIGGER OVER-TRAVEL

PLAINTIFF'S
EXHIBIT

3122

10f6
AL 0023960

MARKETING

POINT OF VIEW

HIGH

- RESPONSIVE TO THEIR ASSESSMENT OF WRITERS' & CUSTOMERS' PERCEPTIONS OF REALITY.
- AVOID MULTIPLE FEATURE OPTIONS WHICH WOULD COMPOUND/CONFUSE SALES INVENTORIES
- PRESERVE PRODUCTION CAPABILITY TO SATISFY TOO DEMAND
- EASY TO UNDERSTAND AND USE
- USER ABLE TO OPEN [AND CLOSE] BOLT IN A SAFE CONDITION ("3-POSITION SAFETY")
- BOLT LOCKED DOWN IN "S" CONDITION

MEDIUM

- CUSTOMER-ADJUSTABLE TRIGGER PULL FORCE ONLY DOWN TO MINIMUM SATISFACTORY LEVEL
- NOT ADJUSTABLE EXTERNALLY
- BOLT STOP RELEASE AWAY FROM "IN FRONT OF TRIGGER"
- NO SAFETY ON TANG
- LEFT-HAND VERSION (12-15% OF MARKET)

LOW

- FIELD-CONVERTIBLE FOR OPERATIONS WITH OR WITHOUT BOLT LOCK

NOT

- MAGAZINE-BOX DISCONNECT SYSTEM

WAW
10-15-93

MANUFACTURING

POINT OF VIEW

HIGH

- INTERCHANGEABILITY OF COMPONENTS AT SUB-ASSEMBLY AND FINAL ASSEMBLY.
- SATISFACTORY PERFORMANCE WITH NORMALLY-ACHIEVED TOLERANCES
- ONLY NORMAL TRAINING AND DEXTERITY REQUIRED TO PROCESS

MEDIUM

- READY-TO-ASSEMBLE SUB-ASSEMBLIES AT FINAL ASSEMBLY
- DESIGNED TO PREVENT INCORRECT ASSEMBLY OF COMPONENTS

LOW

- READILY REWORKABLE/SALVAGEABLE

3 of 6

AL 0023962

10-15-93
WAW

LIABILITY

POINT OF VIEW

HIGH

- AVOID PATENT INFRINGEMENT
- NOT INTERCHANGEABLE OR RETROFITTABLE TO M700
- TWO POSITION "S" & "F"
- SEALED UNIT REQUIRING NO ORIGINAL OR FIELD LUBRICATION
- ROBUST AGAINST IMPACT - EXCEED SAAMI/AUSI RECOMMENDATIONS BY WIDE MARGIN
- USER OPERATION CONSISTENT WITH PRECEDENT AND CONVENTION.
- ROBUST AGAINST EFFECTS OF TAMPERING/ADJUSTING
- HIGHLY INTUITIVE OPERATION

MEDIUM

- READILY DEFENSIBLE REASONS FOR DEPARTURE FROM CURRENT DESIGN
- ? • CONVERTIBLE & REVERSIBLE BOLT LOCK
- ? • INTERLOCK: WILL NOT FIRE IF TRIGGER IS PULVED AND HELD AS SAFETY

AL 0023963

4 of 6

10-15-93

WAW

POINT OF VIEW

ENGINEERING PROCESSING

HIGH

- SHORT RECEIVER
- MACHINES, TOOLS, PROCESSES CONSISTENT WITH EXPECTED VOLUME
- HIGH-YIELD OPERATIONS
- MAINTAIN 11200 PRODUCTION CAPACITY

MEDIUM

- DESIGN TO INHIBIT/PREVENT INCORRECT ASSEMBLY OF COMPONENTS
- DESIGN TO PERMIT REWORK/SALVAGE

ENGINEERING DESIGN


10.15.93
WAW
POINT OF VIEW

HIGH

- SHORT DIMENSIONS PARALLEL TO C/B/L
- AVOID ANY REASON TO PUT FINGER WITHIN TRIGGER GUARD EXCEPT TO INTENTIONALLY FIRE
- EASY TO UNDERSTAND - HIGHLY INTUITIVE OPERATION
- REALITY VS PERCEPTION RECONCILED THRU ACTUAL TESTING / PERFORMANCE
- PRESERVE ADVANTAGES OF RESILIENT (CONNECTOR) FUNCTION
- DO NOT USE SEAR AS BOLT STOP OR APPLY BOLT STOP IMPACT TO ASSEMBLY
- REDUCED LOCK TIME
- ACTUATE SAFETY WITH BOLT OPEN

MEDIUM

- QUIET OPERATION
- ENHANCED CORROSION RESISTANCE
- COMPEL TRIGGER TO SUPPORT POSITION IN MOVING SAFETY F → S
- FULL TRIGGER RETRACTION UPON PARTIAL PULL
- MEANS TO PREVENT INCORRECT ASSEMBLY / RE-ASSEMBLY OF COMPONENTS



AL 0023965

6 of 6

OCT 23

WAW
10/15

CUSTOMER

POINT OF VIEW

HIGH

"EASE OF USE"

- QUICK TO FIND
- EASY TO OPERATE
- EASY TO UNDERSTAND
- RELIABLE TO OPERATE
- EASY TO USE WITH 'SCOPE
- CRISP TRIGGER PULL
- MINIMUM CREEP
- HIS OWN PERCEPTION OF "WHAT IS"

→ BASICALLY

USER FRIENDLY

= DESIGN OBJECTIVES

MEDIUM

- QUIET OPERATION
- MINIMUM BACKLASH (feedback)
- SINGLE STAGE PULL
- EASILY KNOWN STATUS ("S" OR "F")
- PLEASING APPEARANCE
- ADJUSTABLE (Especially WEIGHT OF ROLL)

LOW

- LOCATION OF SAFETY (CONSISTENT WITH EASE OF USE)
- HOW MECHANISM PREVENTS UNINTENDED FIRING-WHAT IT BLOCKS
- MINIMUM TRIGGER OVER-TRAVEL

improved MATHIE REEL OF TRIGGER
" " " OF SAFETY

PLAINTIFF'S
EXHIBIT

3123

1 of 01

AL 0023977

10.15.93
WAW

MARKETING POINT OF VIEW

HIGH

- RESPONSIVE TO THEIR ASSESSMENT OF WRITERS' & CUSTOMERS' PERCEPTIONS OF REALITY.
- AVOID MULTIPLE FEATURE OPTIONS WHICH WOULD COMPOUND/CONFUSE SALES INVENTORIES
- PRESERVE PRODUCTION CAPABILITY TO SATISFY M700 DEMAND
- EASY TO UNDERSTAND AND USE
- USER ABLE TO OPEN [AND CLOSE] BOLT IN A SAFE CONDITION ("3-POSITION SAFETY")
- BOLT LOCKED DOWN IN "S" CONDITION

MEDIUM

- CUSTOMER-ADJUSTABLE TRIGGER PULL FORCE ONLY DOWN TO MINIMUM SATISFACTORY LEVEL
- NOT ADJUSTABLE EXTERNALLY
- BOLT STOP RELEASE ~~AWAY FROM~~ ^{REGULATED} ~~THE FRONT~~ ~~OF TRIGGER~~ WITH IMPROVED ~~MILK~~ ~~FUEL~~
- NO SAFETY ON TANG
- LEFT-HAND VERSION (12-75% OF MARKET)

LOW

- FIELD-CONVERTIBLE FOR OPERATION WITH OR WITHOUT BOLT LOCK

NOT

- MAGAZINE-BOX DISCONNECT SYSTEM

MANUFACTURING

POINT OF VIEW

HIGH

- INTERCHANGEABILITY OF COMPONENTS AT SUB-ASSEMBLY AND FINAL ASSEMBLY.
- SATISFACTORY PERFORMANCE WITH NORMALLY-ACHIEVED TOLERANCES
- FINAL ASSEMBLY WITH READY-TO-ASSEMBLE SUB-ASSEMBLIES

MEDIUM

- ONLY NORMAL TRAINING AND DEXTERITY TO PROCESS
- DESIGNED TO PREVENT INCORRECT ASSEMBLY OF COMPONENTS

LOW

- READILY REWORKABLE / SALVAGEABLE

DESIGN FOR MANUFACTURABILITY PRINCIPLES
DESIGN FOR ASSEMBLY PRINCIPLES

10.15.93
WAW

LIABILITY

POINT OF VIEW

HIGH

- AVOID PATENT INFRINGEMENT *NO WRITING*
- NOT INTERCHANGEABLE OR RETROFITTABLE TO M706
- TWO POSITION "S" & "F"
- ROBUST AGAINST IN APPROPRIATE LUBRICATION
- ROBUST AGAINST IMPACT - ~~EXCEED~~ ^{MUST PASS A MIN 8'} ~~RECOMMENDATIONS BY UNDERMARGIN DRAP~~ ^{SAAMI/AUSI}
- USER OPERATION CONSISTENT WITH PRECEDENT AND CONVENTION.
- ROBUST AGAINST EFFECTS OF TAMPERING/ADJUSTING
- HIGHLY INTUITIVE OPERATION

MEDIUM

- READILY DEFENSIBLE REASONS FOR DEPARTURE FROM CURRENT DESIGN
- ? • CONVERTIBLE & REVERSIBLE BOLT LOCK
- ? • INTERLOCK: WILL NOT FIRE IF TRIGGER IS PULLED AND HELD AS SAFETY $S \rightarrow F$

"SAFETY" DESIGN

4 of 7
AL 0023980

10.15.93

WAW

ENGINEERING DESIGN

POINT OF VIEW

HIGH

- SHORT DIMENSIONS PARALLEL TO C/B/L
- AVOID ANY REASON TO PUT FINGER WITHIN TRIGGER GUARD EXCEPT TO INTENTIONALLY FIRE
- EASY TO UNDERSTAND - HIGHLY INTUITIVE OPERATION
- REALITY VS. PERCEPTION RECONCILED THRU ACTUAL TESTING / PERFORMANCE
- PRESERVE ADVANTAGES OF RESILIENT (CONNECTOR) FUNCTION
- DO NOT USE SEAR AS BOLT STOP OR APPLY BOLT STOP IMPACT TO ASSEMBLY
- NO LUBC "~~LUBRICANT~~" DESIGN ←
 - REDUCED LOCK TIME
- ACTIVATE SAFETY WITH BOLT OPEN

MEDIUM

- QUIET OPERATIONS
- ENHANCED CORROSION RESISTANCE
- COMPEL TRIGGER TO SUPPORT POSITION IN MOVING SAFETY F → S
- FULL TRIGGER RETRACTION UPON PARTIAL PULL
- MEANS TO PREVENT INCORRECT ASSEMBLY / RE-ASSEMBLY OF COMPONENTS

10.15.93
WAW

ENGINEERING PROCESSING POINT OF VIEW

HIGH

- SHORT RECEIVER
- MACHINES, TOOLING, PROCESSES CONSISTENT WITH EXPECTED VOLUME
- HIGH-YIELD OPERATIONS
- MAINTAIN 1M200 PRODUCTION CAPACITY

MEDIUM

- DESIGN TO INHIBIT/PREVENT INCORRECT ASSEMBLY OF COMPONENTS
- DESIGN TO PERMIT REWORK/SALVAGE

leaf 27

AL 0023982

NBAR FIRECONTROL DESIGN OBJECTIVES

- USER "FRIENDLY" DESIGN
- IMPROVED TACTILE FEEL OF THE TRIGGER
- IMPROVED TACTILE FEEL OF THE SAFETY
- CUSTOMER ABLE TO OPEN AND CLOSE BOLT WITH SAFETY "ON"
- BOLT LOCKED DOWN IN A "S" CONDITION
- CUSTOMER ADJUSTABLE TRIGGER PULL FORCE ONLY WITHIN
PRESCRIBED LIMITS
- BOLT STOP-RELEASE RELOCATED WITH IMPROVE TACTILE FEEL
- LEFT HANDED VERSION TO BE DESIGNED
- DESIGN FOR MANUFACTURABILITY PRINCIPLES UTILIZED
- DESIGN FOR ASSEMBLY PRINCIPLES UTILIZED
- "SEALED" DESIGN
- RIFLE WILL NOT FIRE IF TRIGGER PULLED AND HELD AS
SAFETY IS MOVED FROM "S" TO "F"
- ROBUST AGAINST IMPACT
- COMPEL TRIGGER TO SUPPORT POSITION IN MOVING SAFETY
FROM "F" TO "S"
- "NO LUBRICATION" DESIGN
- ENHANCED CORROSION RESISTANCE

*Orig.
Draft*

10-22-93
FROM D.S.F.

NBAR FIRECONTROL DESIGN OBJECTIVES

"TACTILE FEEL - ?
DON'T UNDERSTAND
THE INTENTION
HERE."

- USER "FRIENDLY" DESIGN
- "IMPROVED TACTILE FEEL OF THE TRIGGER
- "IMPROVED TACTILE FEEL OF THE SAFETY
- CUSTOMER ABLE TO OPEN AND CLOSE BOLT WITH SAFETY "ON"
- BOLT LOCKED DOWN IN A "S" CONDITION
- CUSTOMER ADJUSTABLE TRIGGER PULL FORCE ONLY WITHIN PRESCRIBED LIMITS
- "BOLT STOP RELEASE RELOCATED WITH IMPROVE TACTILE FEEL
- LEFT HANDED VERSION TO BE DESIGNED
- DESIGN FOR MANUFACTURABILITY PRINCIPLES UTILIZED
- DESIGN FOR ASSEMBLY PRINCIPLES UTILIZED
- "SEALED" DESIGN
- RIFLE WILL NOT FIRE IF TRIGGER PULLED AND HELD AS SAFETY IS MOVED FROM "S" TO "F"
- ROBUST AGAINST IMPACT
- COMPEL TRIGGER TO SUPPORT POSITION IN MOVING SAFETY FROM "F" TO "S"
- "NO LUBRICATION" DESIGN
- ENHANCED CORROSION RESISTANCE

ADDITIONAL DESIGN CRITERIA:

- TWO-POSITION SAFETY
- NOT INTERCHANGEABLE OR RETROFITABLE WITH M700
- SHORT AS PRACTICAL TO FACILITATE INTEGRAL DTL/REC'R INTERNAL PROCESSING.
- ROBUST AGAINST TAMPERING
- QUIET OPERATION

COMMENT
SOME USEFUL INFORMATION HAS BEEN
LOST IN CONSOLIDATION TO ONE PAGE.

Bill W 10-25-93

PLAINTIFF'S
EXHIBIT

3124

AL 0023984

1 of 1

FIREARMS RESEARCH DIVISION

Origination Date Jan. '82

Update(s) _____

Project Title: Center Fire Rifle System Research

Project No.: C-7500

Objective: This program provides for development in new center fire rifles such as one common rec. design for bolt actions and auto/pumps, new concepts in locking systems, also, new fire controls and bolt lock systems.

Commitment: Investigate ideas.
Layout & detail drawings.
Make prototypes or mockup models.
Artist rendering.
Investigate new calibers, etc.

Personnel Assigned: Martin

Design/Engineers .75 Man Years

Budget: Operating Expenses 1982 \$ 125M (including testing)
Research Capital Project/Expenses \$ -

Uncertainties:

- Can a two piece stock and fore-end be made that will be acceptable for a bolt action rifle?
- Can a new system be set up that will lock the bolt handle and still allow the full safety operation?

PLAINTIFF'S
EXHIBIT

3125

1082
AL 0024003

FIREARMS RESEARCH DIVISION

Program Steps and Timing

Responsibility

Completion Date

1.	Investigation	Martin	2-1-82
2.	Layouts/design for mockups.	Martin	4-1-82
3.	Complete look/ see types.	Martin	6-1-82
4.	Investigate new locking/extractors, etc.	Martin	3-1-82
5.	Layout/design and detail.	Martin	5-1-82
6.	Make prototypes	Martin	7-1-82
7.	Design test.	Martin	9-1-82

AL 0024004

FIREARMS RESEARCH DIVISION

CATEGORY II

Jan.
Origination Date 1982

Update(s) _____

Project Title: Bolt Action Rifle Development Program

Project No.: Q-5000

Objective: To investigate and design a new concept bolt action rifle and assure our position in the market place for the dollar value. This project is to include a new receiver and stock design, new fire control, review of the bolt lock system, new scope mounts/sights, and review of the feed system (such as detachable box, etc.). Other concepts to be investigated include expendable case, electronic ignition, and light weight designs. The gun will retain the M/700 lock up and extractor design.

Commitment: The program will be in three parts. Part I, to be completed by January 1983, will include a new receiver/stock design, minor changes to the fire control, revised sights, and the addition of scope mounts. Part II, to be completed by June 1983, will add the feed system, bolt lock system, and light weight concept. Part III, to be completed in 1984, will include the investigation of expendable case ammunition and electronic ignition.

Personnel Assigned: Martin

Designers/Engineers 4 Man Years

Test Lab and N/C Support .5 Man Years

Budget: Operating Expenses 1982 \$ 430 M (including testing)
Research Capital Project/Expenses \$ _____

Uncertainties:

- Can a receiver be restyled and still be cost effective?
- Can a stock be manufactured on a production basis that meets the needs of the customer and marketing?
- Will expendable case ammunition be the answer for future gun designs?

PLAINTIFF'S
EXHIBIT

3126

AL 0024005

10f2

FIREARMS RESEARCH DIVISION

Program Steps and Timing

Responsibility

Completion Date

Part I

- Design new receiver and stock
- Design scope mounts and sights
- Design new fire control

Martin

July '82

Martin

Nov. '82

Martin

Jan. '83

Part II

- Design bolt lock system
- Design weight reduction
- Design feed system, box, etc.

Martin

Sept. '82

Martin

Jan. '83

Martin

June '83

Part III

- Design system for expendable case ammunition
- Design electronic ignition system

Martin

Jan. '84

Martin

June '84

Note: These dates are only for design and do not establish any production or announcement dates.

AL 0024006

GUNSMITH CALL REPORT

44-241-82

Reporter Donald McIlwaine

Shop Name Sportswest-Div of Ray's Save Corp Gunsmith's Name Daniel Cowen

No. & Street 502 South Third City Renton State Washington Zip 98055

Gunsmith on Premises? YES If not, give address below:

Gunsmith's Address No. & Street City State Zip

Recommended List (X) Open Acct. (X) % Disc. 30% Dealer (X) Large (X) Small ()
New Gun Repair

PERSONS INTERVIEWED and POSITION:

1. Daniel Cowen Gunsmith (2)
3. (4)

SPECIFIC PROBLEMS ENCOUNTERED:

1. M700 still very heavy trigger pulls from factory.

GENERAL DISCUSSION

No special problems. Lots of rebluing work, again because of the geographic location.

Dan did bring up the point that we are still sending out M700's with very heavy trigger pulls, 7-7½ pounds or heavier. This shop performs all the repair work for the chain of Sportswest stores in the north west area. Since the volume of stores sell a large number of M700's Dan receives several sent in from the other stores just to have the trigger pull lightened to the 3-4 pound range. This fact disturbs me because I wonder how many do it yourselves adjust their own triggers and do it improperly perhaps by reducing the sear engagement.

PLAINTIFF'S
EXHIBIT

3127

AL 0024034

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

NEW YORK

PETERS

NEW YORK

XC: A. A. Hugick
F. E. Martin

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

Ilion, New York
September 27, 1977

TO: J. P. LINDE
FROM: C. J. MILLER / R. E. NIGHTINGALE
SUBJECT: 17 REM. PRIMER BLANKING

Work Order: C 1803

OBJECTIVE:

To confirm that primer blanking in the Model 700 rifle chambered for 17 Rem. would cause the trigger connector to break.

PROCEDURE:

The 17 Rem. ammunition was heated to 140° to increase the pressure to approximately 57,000 C.U.P. The heated ammunition was shot in three (3) Model 700 rifles, with sharp edges on the firing pin hole. Each fired case was observed for primer blanking.

RESULTS:

Rifle No. 6395444 was shot first and thirty three (33) out of the sixty one (61) rounds, had blanked primers. The trigger connector broke after the sixtieth round. The sixty first (61) round fired when the bolt was closed.

PLAINTIFF'S
EXHIBIT

3128

AL 0024072

1 of 2

To: J. P. Linde
From: C. J. Miller/R. E. Nightingale
17 Rem. Primer Blanking

September 27, 1977
Page 2

RESULTS: (Cont'd)

Rifle No. 6713463 was shot forty eight (48) rounds with twenty (20) of the primers blanking before the bolt started following down. The trigger connector was broken.

Rifle No. 6394666 was shot thirty three (33) rounds with twenty (20) of the primers blanking before the bolt started following down. The edge of the sear was rounded. The sear connector engagement was increased to allow to continue the test. Seventeen (17) more rounds were shot with twelve of the primers blanking, then again the gun followed down. The trigger connector was broken.

C.J.Miller/R.E.Nightingale:bd
Measurement/Test Lab
Illion Research Division

AL 0024073

cc: J.H. Chisnall

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
SUPERPETERS
SUPER

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

July 21, 1977

JUL 25 1977

OFFICE - E. F. SIENKIEWICZ

TO: E. G. LARSON

FROM: E. F. SIENKIEWICZ

SUBJECT: MODEL 700, .17 CALIBER RIFLES

We have a potential primer blanking problem in our .17 caliber rifles due to an improper radius being performed on the firing pin hole in the bolt face.

This primer blanking condition can break the trigger connector by allowing gas to escape rearward through the firing pin hole, causing the striker to move rearward and hitting the sear down onto the trigger connector. With the trigger connector broken, a rifle could fire upon closing the bolt.

After receiving two primer blanking complaints in May, I examined the production drawings on the .17 caliber bolt and found that the .010" firing pin hole radius was not included on the drawings. This matter was brought to the attention of John Linde, who took immediate action and this was added in a DCR (Design Change Request) drawing, along with a tool drawing to perform this operation.

I met with Jim Conover, Foreman of the Model 700 Assembly, and instructed their bolt assembler how to use the tool supplied to obtain the proper radius, as he was only bumping the firing pin hole, causing a ridge to form, which would increase the blanking problem. Also, Arms Service personnel were instructed how to use the tool and a bolt with the proper radius on the firing pin hole was shown.

All of the corrective measures have now been implimented and production has been made aware of this potentially dangerous condition. However, several thousand of these rifles are now in the field and all can experience a primer blanking problem.

Sincerely,

E. F. Sienkiewicz

EFS:tpg

RECEIVED

JUL 22 1977

E. G. LARSON

PLAINTIFF'S
EXHIBIT

3129

AL 0024076

MODEL 700 PROBLEM

A Small quantity of Model 700, 7 and 40X rifles may have been made with an out of specification part. The sear safety cam in a limited quantity of rifles made between January 10 and March 6 may have been softer than our specification. This "soft" part may show premature wear and may eventually cause harder than normal safety switch forces.

Remington has checked the guns in our inventory and is taking steps to check all guns that were shipped. Teams of employees have been dispatched to the field to check and repair, if necessary, guns at our major accounts. Since the rifles in question were made quite recently, we feel that this will be effective in achieving the repairs of all rifles that may be involved.

10f1

PLAINTIFF'S
EXHIBIT

3130

AL 002446Z

cc: J. A. Stekl

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington



January 23, 1980

To: D. J. Sanita

From: E. G. Larson

Dennis:

In our Safety Meeting review of the 600 recall yesterday, E. F. Barrett asked for a tabulation of safety related complaints received in the past six months on all bolt action centerfire rifles.

Would you please have your files reviewed, and list the model (either current or obsolete), and the number returned.

All complaints should be included, and if we have found some to be unjustified because owner changed screws, altered parts, etc., please note.

Many thanks.

E. G. Larson

EGL:lb

*Jerry Burns
supplying info. to Earl
per phone with Earl Jerry
1/24/80*

AL 0024608

PLAINTIFF'S
EXHIBIT

3131

1 of 1

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
SUPERPETERS
SUPER

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

February 22, 1979

TO: E.G. LARSON

FROM: E.F. SIENKIEWICZ

SUBJECT: RIFLES RETURNED FOR FIRE ON SAFE RELEASE

Since the Model 600 recall, hundreds of people owning Model 700 and other model firearms have contacted Remington alleging that their guns have fired when pushing the safety from on safe to off safe position without touching the trigger.

To date, all such inquiries have been handled by requesting the rifle be returned to Ilion for examination and repair at no charge.

Examinations of the returned guns received at Ilion have revealed no factory defects. All problems that have been found are due to customers tampering with the trigger adjusting screws, over oiling, (I.E. motor oil, salad oil, etc.) and other unauthorized alterations.

Several models returned are old obsolete Models 721, 722 rifles, some being 30 years old, that are worn from hard use, including the trigger assemblies. We do not have any replacement assemblies for these models; therefore, requiring extensive alterations to present Model 700 trigger assemblies for installation at no charge.

Each firearm returned requires 20 minutes examination time for each of three (3) engineers and \$25.00 to \$30.00 Arms Service charges for time and parts to make the repairs, totaling approximately \$50.00 to \$55.00 per gun on a no charge basis.

I believe that we should review this problem with our Legal Department and, if possible, reword our letters to customers on these alleged incidences to read: "Return your rifle for our examination and, if the rifle is found to be factory defective, the repairs will be made at no charge." If these guns have been tampered with, neglected, or parts are worn because of long usage, the customer should be responsible for the repairs.

In order to put this problem into proper prospective, 500 guns returned, examined and repaired on a no charge basis, is costing our Company between \$25,000 and \$27,000.

PLAINTIFF'S
EXHIBIT

3132

EFS:tpg

AL 0024651

10f1

bcc: R.B. Sperling
J.H. Chisnall
E.G. Larson
F.D. Cole
D.C. Brooks

February 26, 1979

Mrs. Susan McGinnis
Star Route, Box A-8 I.H.
Cuba, Missouri 65453

Dear Mrs. McGinnis:

Examination has been completed on your Model 660, .243 Win. caliber rifle, serial number 108687, which allegedly fired when the safety was pushed to the off position.

Our experts thoroughly examined the rifle and trigger assembly and found that the safety selector and trigger could be manipulated in such a way that subsequently moving the selector to the fire position did result in accidental discharge.

In view of our findings, we will have our Accounting section issue a check in the amount of \$73.90 for damages that occurred from the incident. This will be sent under separate cover and should be received within three (3) weeks.

Our Arms Service section will install a replacement trigger on your rifle, at no charge, and the rifle will be returned to you in the very near future. Once the rifle is again in your hands, we are sure you will find it satisfactory in every respect.

Thank you for bringing this matter to our attention, and for having afforded us the opportunity to be of service.

Sincerely,

J.A. Stekl, Supervisor
Firearms Product Service

JAS:tpg

PLAINTIFF'S
EXHIBIT

3133

AL 0024694

DO NOT REMOVE CARBONS OR COPIES

Remington®



REMINGTON ARMS COMPANY, INC.

ILION, N. Y. 13357

ORIGINAL

RD-8538

3-1-79

INFORMATION FOR WHICH SPACES
HERE PROVIDED MUST BE SUPPLIED
BY SHIPPER OR INVOICE WILL BE
RETURNED AND DISCOUNT CALCUL-
ATED FROM DATE CORRECT INVOICE
IS RECEIVED

REMINGTON ORDER NO. _____
CONSIGNEE TO _____
SHIPPED VIA _____
CAR NO. & INITIAL _____
ORIGINATING POINT _____
SHIPPING WEIGHT _____ LBS.
PREPAID OR COLLECT _____

TERMS

PER CENT _____ DAYS _____ DAYS NET _____
DELIVERY _____

F. O. B.

NET CASH

RECEIPTED EXPENSE BILL MUST ACCOMP. _____
ANY ALL CHARGES FOR TRANSPORTATION _____

SELLER'S NO. _____ DATE 3-1-79

REMIT TO: Mrs. Susan McGinnis

ADDRESS TO WHICH REMITTANCE IS TO BE MAILED

STREET AND NO. Star Route, Box A-8 I.H.

CITY AND STATE Cuba, Missouri 65453

ORIGINAL BILL OF LADING MUST ACCOMPANY THIS INVOICE

QUANTITY	DESCRIPTION	PRICE PER UNIT	AMOUNT	TOTAL
	To Cover Damages Resulting from Defective		73.90	
	Safety Selector and Trigger.			

PRICES AND
TERMS
CORRECT

APPROVED

APPROVED FOR PAYMENT ONLY

ABOVE MATERIAL RECEIVED

AND SAME IS SATISFACTORY

AMOUNT
OF
INVOICE

73 90

DO NOT WRITE BELOW THIS LINE

CASH
DISCOUNT

FREIGHT

NET

73 90

CHARGE

5300 - ILION

EXTENSIONS
CORRECT

PURCHASE
ORDER
CHECK

ENTERED

AUDITED

CHECK NO. AND DATE PAID

51075

AL 0024695

2 of 5

Form 100-100

Ref. #

45513
2787

REMINGTON ARMS COMPANY, INC. **Trigger Assembly Special Replacement Program**

(A)

GUNSMITH

GUN OWNER

Name _____
Street _____
City, State Zip _____
Telephone _____
(Area Code) _____
Control No. _____
(For Rem. Use Only)

Name _____
Street _____
City, State, Zip _____
Telephone _____
(Area Code) _____
Control No. _____
(For Rem. Use Only)

(B) FIREARMS INFORMATION

Model (Check One)

- ☐ 1. Rem 600
- ☐ 2. Rem 660
- ☐ 3. Mohawk 600
- ☐ 4. XP-100

Caliber (Check One)

- ☐ 1. 222 Rem.
- ☐ 2. 6mm Rem.
- ☐ 3. 243 Win.
- ☐ 4. 308 Win.
- ☐ 5. 6.5mm Rem. Mag.

Caliber (Check One)

- ☐ 6. 350 Rem. Mag.
- ☐ 7. 35 Rem.
- ☐ 8. 223 Rem.
- ☐ 9. 221 Rem. "Fireball"
- ☐ 10. Rechambered

Serial No.

1	2	3	4	5	6	7	8	9	0
---	---	---	---	---	---	---	---	---	---

(C) MODIFICATION INFORMATION

Method Gun Received From Owner:

(Check One)

- ☐ Hand Delivered
- ☐ UPS
- ☐ U.S. Mail
- ☐ Other _____
(Specify)

Date Gun Received From Owner

Month	Day	Year
1	2	9

Estimated Completion Date

1	2	9
---	---	---

(D) INVOICE DATA

Date Work Completed

1	2	9
---	---	---

Charges: Modification Charge
Transportation
Other (Detail Below)

\$5.00

Gunsmith Signature _____

Date _____

Total

\$

GUNSMITH'S COPY
(to be retained by gunsmith)

30f5

AL 0024697

RE-CHARGE: YES 65

GENERAL: Good

OUTSIDE: FRONT & REAR SIGHTS AND SCOPE

SCREWS MISSING RECOIL PAD ADDED

FIRED AMMO TYPE: UNKNOWN

& CONDITION: Good

PROF: YES INSP: 9 TEST: 57

HEADING: OK

BREACH OPENING: OK

RECOIL SHOULDERS: OK

CHAMBER: Good

TEST: OK

COMPONENT CONDITION: (Damaged, Broken, Old Style)

SLIGHT DENTS IN WOOD

BOLT SHOWS COLOR WORN OFF

BOL BRIGHT AT MUZZEL

COMPLAINT: IF TRIG. IS DEPRESSED WHILE SAFETY IS

ON GUN WILL DISCHARGE WHEN SAFE IS MANIPULATED

INCIDENT: SHOOT HOLE IN FLOOR OF PICK UP TRUCK

COMMENTS: Gun involved in recall program. Gun

can be fired when safety triggers are

manipulated.

MODEL: 660

R #: 02787

DATE: 1-18-79

MASS. SGT. W. MCGINNIS

FROM: STAR AT BAX 18

I.H. CUBA NO.

GUN #: 108687

CODE: LR-2-68

QA/CAL.: 243

CHECKED BY: M. HARDY

APPROVED: 9/11/79

APPROVED: 2/14/79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

APPROVED: 2-16-79

4085

AL 0024698

A

U-24

DON'T SAY IT — WRITE IT

To

From

Date

J. H. Carter
R. J. Smith

3/6/79

1. m/660 received 1/18/79 to Ed. Sunkiewicz
attention
2. Customer letter dated 12/2/78 +
3. Arms Service held for Personal or Property Damages
Examination - copy attached
4. Returned to Arms Service for storage
5. Examination report to Jack Chumal 2/22/79
6. Feb 26, 1979 instruction for J. H. Still to replace *Filing*
Control

SAFETY IS A WISE INVESTMENT

5 of 5

AL 0024699

H

cc: E.F. Sienkiewicz
J.E. Preiser
E.G. Larson
R.G. Sherman
J.H. Chisnall

December 11, 1978

Mr. O.K. Baxley
Vice President for Finance
Lamar University
P.O. Box 10003
Beaumont, Texas 77710

Dear Mr. Baxley:

Examination has been completed on your returned Model 700 ADL 6mm caliber rifle, serial number 307270.

We found the trigger assembly to be well within manufacturing specifications and we could not duplicate the problem that you had experienced. However, we did find excessive oil within the trigger assembly and strongly recommend that oil be used sparingly on the rifle with no lubrication added to the trigger mechanism.

In most of our investigations, concerning the problem that was experienced, we have found that the safety was pushed to the fire position with a finger on the trigger.

As a gesture of good will, we are replacing the entire trigger assembly, at no charge, and the rifle will be returned via Blue Label U.P.S.

Thank you for having afforded us this opportunity to be of service.

Sincerely,

E.F. Sienkiewicz, Supervisor
Firearms Product Service


EFS:tpf

PLAINTIFF'S
EXHIBIT

3134

AL 0024700

10f1



cc: C.B. Workman
J.P. Glas
J.H. Garner
D.J. Sanita

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

Ilion, New York
May 2, 1980

P. H. HOLMBERG
Bridgeport

NEW FORMAT INSTRUCTION BOOK

Forwarded for review, comments and Marketing/Legal approval are printed versions of the proposed Model 700 Instruction Book. Ten printed copies are enclosed for distribution to Bridgeport personnel. Minor art and verbiage errors have been already detected.

Also forwarded are, copies of the instruction book in three different paper stock size: 60 lb., 70 lbs. and 80 lbs. It is recommended that the 80 lb. paper stock be used for the new style instruction book. This stock paper size would provide more rigidity. Cost of the new style book is 8.5¢ vs 4¢ for our present Model 700 manual.

It has been suggested that the new format booklet be used with the introduction of the Model 7400-7600 Rifles. Expediting the review and legal approval of the new Model 700 instruction book is required if we are to meet scheduled warehouse date for the new models.

A meeting should be scheduled to review comments, and required changes, additions or deletions.

R. L. Sassone
R. L. Sassone, Supervisor
Project Control & Admin. Services

RLS:sse
Enc.

PLAINTIFF'S
EXHIBIT

3135

AL 0025065

1 of 1

CALE

TO

Mr. Duane Ricci
Remington Arms Inc.
Ilion, New York 13357

DATE February 3, 1983

SUBJECT rejected trigger connect
I-80600; I-80550

(Rejected at Vendor)

4,500 rejected trigger connectors, undersized stock,

both processes completed (before & after heattreat)@163.24/M \$734.58

8,000 rejected for excessive radius on 075 short leg (inside) *(B)*

both processes completed (before & after heattreat)@163.24/M \$1305.92

8,000 rejected for excessive radius on 075 short leg (inside)

first process completed (before heattreat)@65.92/M \$ 527.36

☒ PLEASE REPLY ☐ NO REPLY NECESSARY

SIGNED

Ronald Crass

PLAINTIFF'S
EXHIBIT

3136

AL 0025181

1 of 1

~~John~~
A

11/200 Sea Safety Cam

Potential customer complaints from insufficient charge
material analyzed from 6/13/78 - 1/31/80

Possible complaint

11/1
2/10 5

- 1) Delayed firing
- 2) Discharge when bolt handle raised
- 3) Discharge without pulling trigger
- 4) Accidental discharge
- 5) Trigger - Safety malfunction
- 6) Misfire

7

7

2

9

1

2

28 Total

PLAINTIFF'S
EXHIBIT

3137

AL 0025778

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

cc: P. H. Holmberg
J. E. PreiserBridgeport, CT
October 19, 1981

TO: E. F. BARRETT
E. B. BEATTIE
H. K. BOYLE
J. P. GLAS
R. L. HALL

E. HOOTON, JR.
J. P. LINDE
J. P. McANDREWS
J. G. WILLIAMS
C. B. WORKMAN

FROM: T. W. RAWSON *twr*

SUBJECT: SUMMARY EXECUTIVE BOLT ACTION RIFLE COMPETITIVE AUDIT

On 10/15/81 the second Annual Executive Firearms Competitive Audit was held. Because of the competitive situation, bolt action rifles were chosen as the subject. Observations and discussion at this audit were limited to product. Once again the evaluation was restricted to visual impressions as would be typical in a store environment. Technical evaluation will be presented by R & D in November.

Attached is a matrix similar to the one filled out which summarizes the scoring. Following are observations on that scoring and a summary of the discussion.

- First, second and third place without price consideration went to 700 BDL, M70 Featherweight and Ruger M77 respectively.
- The overall scores did differ from the cumulative individual item scores indicating that overall impression and other factors than those cited contributed to ranking.
- The addition of pricing information (copy attached) did change the ranking. Ruger M77 went from third to a first place tie with the 700 BDL in this analysis. The M70 FWT fell from 2nd to 3rd reflecting the negative reaction to its higher price.
- Stock appearance honors went to M70 FWT, 700 BDL and Ruger M77 in that order suggesting some combination of the 3 might prove most desirable. While the 700 Classic was not audited a sample was reviewed. An oral consensus seemed to indicate our classic was the favorite style. The narrow forend, open styled pistol grip and straight comb of the M70 FWT received special mention.

PLAINTIFF'S
EXHIBIT

3138

AL0025561

10f5

• Action smoothness, a characteristic discussed in market research panel studies, ranked Remington entries rather low. This ranking suggests the work being done on the recessed follower is in the right direction.

• Browning, known for its high quality appearance, ranked first in metal finish. Dropping back down the price scale the auditors seemed to agree, there was little difference between the major three contenders. Remington did outrank both WW and Ruger in this characteristic on the sample guns. Some auditors expressed surprise at this but warehouse audits and in store checks confirm, generally, this situation.

• Remington's BDL and ADL took the honors in the extractor, ejector, locking system category. It was mentioned that our design yields the cleaner, neater appearance as a system. Objectivity may have been compromised here as well because of what we believe to be true of the strength and safety of our system. While more bulky and less streamlined the Ruger extractor (Mauser type) does get a lot of play in the press and trade as the more impressive looking mechanism. It was noted that our extractor appears less than impressive and this is partly due to the crudely ground off rivet used to hold the extractor in place.

• The panel was asked to judge the safety not so much from its "safeness" which is difficult to judge in this environment, but from the point of view of convenience, quietness and quality of appearance. The Browning and Ruger took 1st and 2nd place respectively. Both rifles feature sliding, "shotgun type" tang safeties. Remington safety which is functionally similar to Ruger's was relegated to 4th place because of the side tang position which necessitates an elongated hole in the stock and yields relatively poor appearance.

• Ruger took first place for accessory parts (sights, scope mounts, grip caps, etc). Their combination of clean barrel (no sights, no holes) and scope mount plus absence of white line spacers at grip cap and butt seemed to be most preferred. The Ruger scope mount system is respected functionally but was described as rather bulky - visually. Negative comment was recorded regarding the safety message on Ruger's barrel. (cosmetic reaction).

Summary:

Within our price segment there was little to choose from an execution point of view between the big 3. (Rem., WW, Ruger).

2 of 5

AL 0025562

Remington's wood finish, fits and metal finish were at least as good as competition. Small details, like the previously mentioned white extractor rivet head were jarring footnotes.

While the functional analysis has yet to be heard there was little apparent, in the visual audit phase to suggest Remington's functional quality suffers by comparison.

Confining the conversation to product then, it appears that we suffer in the competitive comparison with design cosmetics. In the absolute sense our styling left something to be desired. The panels interest in the 700 Classic, M70 Featherweight and Ruger M77 all fairly well follow a documentable trend in bolt action rifle styling in evidence today. Considering the M700 in current form is basically 20 years old while the movement toward pre 64 M70 - classic styling started by Ruger with the M77 is but 10 years down the product life cycle, this is not surprising. More subtle however is the apparent visual quality of mechanical design from which people imply overall product quality. The M700 safety while functionally similar to the Ruger 77 suffers by comparison in the visual sense. The quality of our design from a styling point of view needs some upgrade as well as styling in the absolute.

Finally the audit also raises a more significant question relevant to quality. Our execution is acceptable and functional design adequate to superior. The styling differences seem short of a total explanation for slipping sales. The price value relationship is the key and as can be seen by the summary matrix the price does effect peoples opinion of gun desirability. Ruger with price added represents the significant threat to M700 sales. Price-cost relationships are the rub. Significant improvement in productivity through better management control of scrap, rework and warranty repair are the benefits of an improved quality system outlined in the quality plan. The changes called for in that plan are essential to improving the cost situation.

TWR:fd

attachment

30f5 AL 0025563

After inspecting all samples, please fill in matrix below. Best score = 1; Worst score = 7.
 Duplicates are acceptable.

	REM. 700-BDL	RUGER M/77	REM. 700-ADL	W-W 70-XTR	W-W 70-FWT	BROWNING BBR	S&W 1500
Stock Appearance	2	3	6	4	1	5	7
Action Smoothness	5	3	6	4	2	1	7
Metal Finish	2	5	3	6	4	1	7
Extractor, Ejector, Locking System	1	4	2	5	5	3	6
Safety	4	2	4	3	3	1	5
* Accessory Parts (Grip Caps, Sights)	2 (2)	1 (3)	6 (5)	5 (5)	4 (4)	3 (1)	7 (6)
Best Overall w/o Price	1	3	6	4	2	5	7
Best Overall with Price	1	1	2	4	3	5	6

* Number in Parenthesis is placement based on individual item scores above. Best overall W.O.
 and W. price reflect overall impression and other factors not identified as individual items.

COMMENTS:

40FSAL 0025564

COMPETITIVE BOLT ACTION RIFLE AUDIT 1981

PRICING INFORMATION

	<u>M/700 BDL</u>	<u>RUGER M/77</u>	<u>M/700 ADL</u>	<u>W-W 70-XTR</u>	<u>W-W 70FWT</u>	<u>BROWNING BBR</u>	<u>S & W 1500</u>
uggested etail tart '81	399.95	325.**	334.95	412.	433.	429.95	334.95 Std. 379.95 Deluxe
etail Median elling Price 6/81	315.	269.	250.	385.	433.*	400.*	255. Std 305. Deluxe

* Estimated
** 340. as of 6/1/81

AL 0025565



5 of 5

10/81

REMINGTON ARMS COMPANY, INC.
ENGINEERING DEPARTMENT
SUBJECT: M/100 ADL & BOL UPGRADE
COMPUTATION SHEET
DATE: 10/81

math for design release

Nov. 1 Dec. 1



PLAINTIFF'S
EXHIBIT
8139

A

Green Valley, AZ

Jan. 25, 1982.

To Clark Workman

From Wayne E. Leek

Subject: Jan. 1982 report on Silhouette activities in

Arizona, matches attended, and repairs to

Remington products. Also a more detailed report

on suggestions supporting a new line of rifles

and shotguns.

Matches attended:

Cochise Gun Club Jan. 16, 82 Match winner Leek 27/40

Nogales Rifle Club Jan. 17, 82 Match 1 winner Leek 30/40

Match 2 winner Leek 30/40

Black Canyon Range Jan. 24, 82

Arizona Rifle and Pistol Assn. Championships

Match winner Yehl 32/40

1st. AAA Leek 31/40

Repairs to Remington Product:

A customer's M700 /30'8 Silhouette rifle would fail to fire about 30% of the time. Examination revealed an improper nose shape on the firing pin. After replacing with one of correct design consistent ignition was restored. Instead of having a radius for the nose it was flat. There was no indication of tampering. This firing pin will be sent upon your request.

PLAINTIFF'S
EXHIBIT

3140

AL 0026166

1 of 26

A

SUGGESTIONS SUPPORTING A NEW LINE OF BOLT ACTION RIFLES AND SHOTGUNS.

Introduction.

This program reviews the favorable and undesirable features of the M700 rifle with suggestions to support an improved M700, elevating it to a higher quality level of customer acceptance. The development will not be too expensive or time consuming and would provide a base rifle allowing time to accommodate the more innovative ideas.

A proposed foundation for a new bolt action shotgun follows the rifle program.

Program for the improved rifle.

The M700 action exceeds the strength of every known bolt action ~~GP~~ rifle by a substantial margin. Supporting the exposed head of the cartridge case by reinforcing it with the bolt shroud, barrel recess and receiver, prevents case rupture and a damaging amount of gas from escaping rearward during high pressure firing. The ring extractor used in the M700 eliminated the need for expensive qualification threading an and extractor cut in the ~~barreled~~ receiver assembly so commonly used in previous bolt action rifles. The superior strength was a fortuitous spin-off of this design and not known until severe strength testing revealed the secret. Any future development should include the integrity of this principle and must be jealously guarded. This is not to say that the ring extractor is mandatory to protect the strength principle but the support of the cartridge case without rupture under high pressure is extremely important.

The M700 extractor has undergone a series of design changes to guarantee reliability and the latest is believed to be superior to previous attempts. Unfortunately a bad reputation of breakage, malfunctions, and difficult repairs

AL 0026167

20726

A

has plagued the principle to the point that future customer acceptance is severely questioned.

During an Ordnance development of a tank machine gun by Remington, an improvement to the ring extractor was found in a German WWI machine gun resulting in a successful design for our program. This extractor was a claw type, small but efficient in nature housed in a cut in the bolt shroud. Its main feature, an ever-tightening grip as the load was increased, left little to be desired. The outside surface of this extractor replaced the cut-out portion of the shroud and was thoroughly supported by the barrel recess. Strength tests revealed that this combination provided all the strength of the ring-extractor design. It is suggested that this principle be used in the improved rifle.

In general the accuracy of the M700 is adequate for hunting, varmit, silhouette and target shooting. Special orders for bench-rest type rifles produced by the custom shop have proven accuracy superior to all but the finest match rifles. Modern barrel manufacturing methods such as used in Remington are to be credited for this achievement. Remington, however, is not in the league of competition for the position match shooter, dominated by Anschutz.

There are several areas where accuracy can and should be enhanced by changes in the basic design such as the barrel bracket. The cross-sectional area of the bracket adjacent to the barrel is considered weak by many gunsmiths and has now gained a bad reputation for lack of recoil support especially when using heavy-calibered ammunition. This situation is

AL0026168

3826

A

aggravated by improper bedding in the stock, especially if the bedding support contacts the bottom of the bracket.

Any shifting or bending of the bracket can cause accuracy problems. One made of powder metal or other means of greater rigidity as used in the M 788 would be of benefit.

A round surface on the bottom of the receiver as presented by the M700 has always been questioned by many gunsmiths, designers, and match shooters as a possible area of non-stability during the torquing of the receiver during firing. If true, and I believe the torque problem does exist, a conventional flat surface should be provided for proper bedding. The new barrel bracket design could be extended with a mating flat surface to fit the receiver.

Research is needed to explore the areas of bedding actions in an effort to determine the magnitude of advantages in barrel-dampening devices. Although some investigation in the past has shown advantages by using dampening methods inconsistencies have prevailed. I believe the results of past efforts were clouded by barrels which had varied wall thicknesses. Modern manufacture such as practiced by Remington virtually guarantee centralized bores in the barrels. Reliability in the use of bedding devices would be enhanced with these barrels. Such methods as electric bedding, 2-point and 3-point bedding, pre-determined muzzle pressure, free-floating barrels and other means should be explored.

There is some indication that accuracy is improved when accompanied by faster lock time in rimfire rifles and the same should be true in center fire rifles. It is believed that

AL 0026169

4826

A

the fall of the firing pin sets up pre-vibrations in the barrel prior to ignition which disrupt accuracy. There also may be a more uniform ignition advantage.

Accuracy testing of thousands of production rifles has revealed that the M788 is superior to the M700. This fact was observed during the development of the M788 when compared to the M700. Using the same barrel process, stock bedding principles and the same lots of ammunition have ruled out most of the variables between the two rifles, the exception being the receiver (front vs rear lockup), heavy vs light barrel bracket, and the difference in lock time. M700 lock time is approximately 5.5ms and the M788 is 2.7ms. The shooters are also observing the accuracy advantage of the M788. It is believed that the faster lock time in the M788 gives this model accuracy advantage. Re-design of the M700 should involve reduced lock time to improve its accuracy and give the off hand competitor the advantage of this principle.

There are numerous ideas to achieve faster lock time. Such a design is a flat-type formed pin with rotary swaged nose as used in the M788. Other ideas include the use of lighter weight metals, ie, aluminum, titanium, tubular construction, carbide or alloy steel-tipped light weight pins, etc. It will be found that a nose diameter of .060" is necessary when using the lighter weight pin for proper ignition. Faster lock time approaching zero should be our objective.

Reliable accuracy is no more secure than the rigidity of the scope base mounting screws and in the M700 6/48 screws are

AL 0026170

5826

A

not adequate. The use of 8/40 screws as used in the M788 or a fixed scope base of Ruger design is recommended.

Glass bedding methods are excellent to insure a perfect fit of the action to the stock. Also recent developments in custom designs provide extruded aluminum bedding elements which precisely fit the barreled action and are securely epoxied to the recesses of the stock. Fiber glass and other plastic materials are now appearing on the market, impervious to the elements and strikingly attractive. These items certainly suggest improvements in accuracy.

Accuracy is always enhanced by fine trigger mechanisms. Remington's M700 has a reasonable trigger which when properly adjusted, allowed a spread of pull weight from 1 1/2# to 8# with a crisp let off. However one must rely on the factory adjustment which is anchored with loc-tite cement plus staking with a center punch. The latter ruins the threads and side plates of the mechanism and the former fills the screw slots, all of which makes it virtually impossible to adjust by anyone, including gunsmiths. The excuse for this is in the name of safety to prevent the customer from making adjustments. However the shooters are attempting to make adjustments and often ruin the reager adjusting means that has been damaged in assembly.

A more substantial approach is the Canjar design which in essence is a copy of Remington's principle but improved and of course more expensive. This assembly allows more contact area for the screws. The main adjustment of over travel is retained by a nylon pin. Canjar provides instruction for adjustment and a warning statement, which apparently relieves him of responsibility in case of accidental discharge due

AL 0026171

6826

A to faulty adjustment. The screws are Allen-headed which eliminates the slot problem. Two-link and three-link systems are available-the latter can be adjusted down to a 2 oz. pull. Most match shooters resort to the Canjar or Kenyon design. It is suggested that before improvement to our trigger mechanism be made that we analyze Canjar, Anschutz, Kenyon and Feinwerkbau designs.

Remington's manual safety blocks the sear mechanism. The manual motion is in the same plane as the trigger movement and allows a dangerous condition to exist. Pulling the trigger at the same time the manual safe is moved to off, fires the rifle! This motion is not unlike taking the hammer off safe in a M94 Winchester or a revolver.

A manual safety should never be allowed to function in the same plane with the trigger unless a disconnecter is provided preventing firing if movement of the safety takes place while the trigger is pulled! A safer and more reliable manual safety is a 3-position type located on the cocking piece. It is recommended that these ideas be considered.

The stock design of the M700 is excellent, presenting good balance and symmetry. The PKW finish is appealing to those who desire a glossy shiny finish but has little appeal to the experienced sportsman who is accustomed to European walnut and hand-rubbed oil finishes.

AL 0026172

7226

A

The effect of pressed checkering has down graded cut checkering and has led some shooters to search for stocks with other decorative designs. One attractive procedure is to use a grained ^{grained} stippling pattern as found on fine German-made firearms. Also there is a slight trend toward hunting scenes cut or impressed or transferred on the stock.

Approximately 13% of the population are left-handed and I believe it is prudent to continue providing these models for the left handed shooters.

For many years Remington was very aggressive in developing and promoting new calibers, leading the competition in the market place. Such successful developments as the 7MM Magnum -25-06, 222, 22-250 are examples. Naturally not all of our cartridge developments were a huge success and the inability to analyze a future market such as was done on the military 308 has in some degree hurt our posture. To keep our product alive new developments in cartridge design which provide a substantial improvement over the common place is needed. The 7/308 and the Remington 7MM Express are good examples of a policy to keep new cartridge development in the forefront.

A peen-hammered barrel presents desired effects of something special being done to high grade rifles. This process was used for years on the surface of a sterling silver bell on slide trombones manufactured by the Old's musical instrument company. They claimed exceptional tone qualities from this process due to the relief of surface tensions.

AL 0026173

8226

A

on the bell, and this feature became an appearance of excellence among musicians.

We achieve this appearance in our rotary swaging of barrels and then remove the surface by grinding. The idea of providing a super-grade barrel with this aesthetic effect was weekly presented to the operations committee several years ago. This lacked technical support of what might be desirable mechanical improvements in accuracy. Certainly the aesthetics of something special was there. Since then the fine custom Mauser rifles display their product with this appearance. I believe the surface condition if left might indeed support improved accuracy performance along with a desirable appearance and certainly would be obtainable at no extra expense.

PROPOSED IDEAS FOR FUTURE DEVELOPMENT.

Several ideas were suggested in my Sept. 81 report that would improve the performance of the match shooter in his quest for perfection in accuracy and these are repeated in this report.

Recoilless principles used in fine match-grade air rifles, (nullifying recoil caused by movement of the compression piston.)

Movement of a large mass prior to release of a bullet or pellet tends to throw the shooter's aim off target before exit of the projectile. This problem exists in such open-bolt centerfire rifles as the BAR, M3 and Thompson Sub machine guns and others. To nullify this unwanted problem in match grade air rifles four approaches have been taken as follows:

AL 0026174

9826

A

1. Anschutz match air rifle uses an oil-filled hydraulic cylinder, an action similar to car-type shock absorbers to compensate for the forward motion of the compression piston.

2. Walther's match air rifle uses a single stroke pneumatic system which allows a piston to compress air into a chamber only a few times larger than the pellet. Movement of the trigger sear allows a heavy spring-loaded hammer to hit a striking lever which in turn pushes open an exhaust valve.

3. Beeman's match air rifle involves double-acting pistons which results in a smooth recoilless and vibration-free firing action.

4. Feinwerkbau's match air rifle uses a principle where movement of the compression piston at the moment of firing trips a sear which releases the entire barrelled receiver assembly to ride on a pair of hidden, hardened rails. The necessary "equal and opposite" reaction causes this heavy metal mass to slide back about $\frac{1}{2}$ " on the rails while the shooter holds the motionless stock and trigger. The shooter feels almost nothing and his sighting picture is undisturbed. The mechanism must be returned to its locked-forward position for the next shot.

Eliminating the disturbing recoil sensation caused by the moving piston prior to pellet movement in these excellent match air rifles allows the shooter to concentrate on all the fine points of shooting affecting his performance such as sight picture, hold, trigger pull and follow-through.

Remington's patented recoilless principle.

Developed during bench rest shooting competition around 1947-1950, this system applied to powder-actuated fire arms. The objective was to eliminate the variable offered by the shooter's shoulder from shot to shot in an effort to improve accuracy. The principle was sound and was instrumental in winning bench rest matches in Johnstown, New York. It was also a factor in the development of the several accuracy devices now in use in gallery testing at the Ilion plant.

Basically the system allowed the barreled action with scope to move $3/4$ " rearwardly on bearings before being retarded. In other words the bullet would exit before rearward resistance could affect the shifting of the point of impact.

Remington's method is quite similar and preceded that used by Feinwerkbau.

A recommendation for consideration in future rimfire match rifle design.

Two variations in accommodating the movement of barreled actions until bullet exit were used in Remington's recoilless design.

1. The preliminary design allowed the action to float on lubricated lead bearings sliding rearwardly in a metal track.
2. In the final design the action was allowed to recoil on a series of cam followers until the bullet had exited.

The principle is sound, and now is being used successfully by Feinwerkbau in their championship winning air rifles. I used this system successfully in winning bench rest matches. Remington accuracy devices have proven successful.

AL 0026176

11/8/26

A

in millions of rounds fired. Therefore I believe the method could be introduced into a rimfire match rifle where the principle would nullify errors in the major problems associated with follow-through.

SUMMARY

Air rifle shooting has emphasized the need for follow-through in precision off hand shooting making one aware of the need for uniform resistance to recoil.

Olympic class air rifles have built-in designs to nullify any unnecessary movement of mass which would aggravate consistent resistance to recoil.

Remington's patented recoilless system provides a secure method of eliminating this effect in powder-actuated firearms.

It is recommended Remington consider incorporating this principle in future match rifle development.

Recoil reduction is uppermost in every shooter's mind and numerous ideas have been promoted to solve this disturbing element. Some ideas have been moderately successful such as the Cutts Compensator, a protruding device located ahead of the muzzle, where jetting gas following the bullet impinges upon flat metal surfaces pulling the gun forward. In use the result is an ear-splitting but reasonable recoil reduction of about 10% of the total recoil. However, the effect appears late during the recoil cycle and aids some shooters more than others depending upon how tightly they hold the gun to the shoulder. Many innovations to this principle less effective but possibly more attractive have been used such as providing drilled holes or cut slots in the barrel.

AL 0026177

12826

A

Other ideas such as used in Remington's M1100 wherein a portion of gas energy is stored in a moving mass and then later transferred back into the gun has been successful and acceptable as a recoil reducer to the hunter, skeet and trap shooter.

Moving butt stocks which store energy in a spring or hydraulic absorbing means such as the so-called hydro-coil have been attempted but with questionable success. This principle allows the shooter's grip hand to recoil into his cheek with an unpleasant effect as the stock pull length is decreased. Naturally if used with a scope on a high recoil rifle this would result in eye injury.

The most common lowest cost and least effective method is the provision of rubber recoil pads designed with collapsing internal rubber fins. This device made of rubber stores recoil similar to a spring allowing an undesirable fast recovery. An analogy is the motion of suspension springs in automobiles which require shock absorbers to subdue the rebound of stored energy.

An ideal butt pad would be the type that resists compression up to a predetermined pre-load level, then absorbs the recoil without a spring-like action recovering gradually back to normal.

Such a device was developed by Remington with the assistance of DuPont-made of polyurethane foam. Tests of this device produced outstanding recoil absorbing characteristics and met the principles previously mentioned.

There were problems of color, matching surface to wood, and if sanded, water absorption. These problems I believe can be solved and if produced correctly would perform superbly far

AL 0026178

13826

A

beyond any butt pad now produced.

A standard 30'06 caliber requires a 36" barrel to obtain maximum velocity. Therefore it is obvious that a considerable amount of gas energy is being wasted when using barrels of shorter lengths. The escaping gas from a 24" barrel in this caliber generates a muzzle pressure of 10,000#sq" and is escaping at velocities in excess of 2700 ft/sec. This escape produces a rearward jet effect which is approximately 1/3 of the total recoil energy, and is so significant that if prevented from happening would be one of the more important advances in gun design and recoil reduction in history. An adequate solution would stir the very foundation of the sporting and military gun industry and would provide a powerful edge of leadership. When achieved safely the principle has far-reaching implications in the commercial and military areas. For example with fully automatic rifles recoil would become nearly stabilized during firing, a feat long sought by the military. Reducing recoil in this magnitude could provide the hunter with potential big caliber performance and a recoil of a 223.

The idea is not a myth. A laboratory model was constructed by Remington personnel using a M760 in 30'06 caliber with the resulting measured recoil of a 223! It is conceivable that this principle could be used on shotguns as well and combined with the recoil-reducing principle in the M1100 could approach a recoil-free shotgun.

Initially some reliable means must be used to trip a

AL 0026179

14726

A

valve mechanism closing the escape of gas. The most logical means is the bullet. Therefore it is assumed that the various suggestions of valve mechanisms discussed will be programmed to be activated by the bullet. Inertial problems are a big factor and careful calculations, computer analysis, and measurements are necessary. If the nose of the bullet activates a valve mechanism in sufficient time a difficult problem in timing is overcome. Conversely if more delay is needed earlier programming by the bullet in some selected area of the barrel is needed and careful analysis and design must be instigated to prevent dangerous premature muzzle closure before bullet exit.

The following suggestions are without calculation or measured foundation and are ideas only, to be examined and reviewed by design and laboratory personnel. It is hoped that they may cause an hedonic reaction by the readers to further enlarge the spectrum of thought.

Suggestion 1

Utilize a 3-section barrel. The first section is held rigid containing the chamber and is smooth bored. Being the longer of the three lengths allows the bullet to obtain maximum velocity. The second or middle section rotates like a nut in a threaded tube. This portion is relatively short and contains gain twist rifling. The rear portion of the barrel works like a collet closing a sphinter valve when rotated by the bullet trapping the expanding gas. The bullet continues into and thru the third rifled muzzle section

AL 0026180

15726

A

finalizing its spin and accuracy. This section is held rigid. The middle section when rotated loads a spring which is programmed to open the valve, gradually releasing the stored gas by counter rotation at a later period.

L

E

K

S

I

C

H

AL 0026181

16226

A

Suggestion II

Use a bullet design of two diameters.

Fig. 1

The front section, for example, could be .284" in diameter and the rear section .375" in diameter. The first 20" of 24" of the barrel is smooth bore to accommodate the .375" rear cylinder of the bullet and the last 4" a .284" rifled bore. The juncture of the two sections of bullet are sharp, creating an intentional stressed area. The bore provides a sharp shoulder from .375" to .284" to shear off the rear slug which acts as a plug preventing any further forward movement of gas.

Fig. 2

Fig. 3

The sheared .284" diameter forward section is allowed to enter the 4" of rifled barrel, spin stabilize, and exit from the muzzle. The remaining slug must be removed. If the front section of the barrel is allowed to slide forward due to the force generated by the forward motion of the bullet, an escape vent could be provided to discharge the slug and the pent-up lower velocity residual gas. It is believed that because of inertia in actuating the mechanism sufficient time to release the stored gas could be programmed to discharge at a gradual reduced rate with negligible effect on recoil reduction.

Fig. 4

AL 0026182

17226

TITLE OF PROJ.

PROJ. NO.

SUBJECT

WORKS

COMPUTER

DATE

19




Fig. 1




Fig. 2




Fig. 3




Fig. 4

AL 0026183

18226

A

Suggestion III

This method has the appearance of petals on a tulip. In this system a series of metal petals surrounded by a very strong spring seals the exit of gas after the projectile forces its way through the petals. The projectile should have a long gradually-tapered section starting just back of the ogive, quite similar to a tapered heel except having a longer taper.

E
K

Fig. 5
Fig. 6
Fig. 7
Fig. 8

The entire action is as follows: The petals, perhaps 8 in number, are closed tightly over the forward section of the muzzle surrounded by a strong circular spring. They must be completely tight, capable of preventing gas from leaking at a pressure of 10,000#sq". As the projectile passes past the muzzle and into the valve area the petals are forced open by the ogive of the bullet and start closing as the rear taper passes through the seals. Trapped residual gas could be allowed to escape through a valve at a later period somewhere in the barrel or by actually using the extraction of the cartridge case as a valve. It is also possible that a delayed blow back unlocking system could be designed wherein the residual gas would thrust the cartridge case rearward using the jet effect in reverse thus forcing the rifle forward. The result would be additional recoil reduction. In this case alteration to the locking mechanism

TITLE OF PROJ. _____

PROJ. NO. _____

SUBJECT _____

WORKS _____

COMPUTER _____

DATE _____

19__

FIG. 5




FIG. 6




FIG. 7





FIG. 8



and safe handling of the ^{rearward} exhaust gas would be in order.

The petal design must be so well engineered that accuracy is not impaired. If the long taper in the rear of the bullet doesn't allow enough working area for the gas, a driving band exposing a sharp shoulder of substantial working area followed by a long taper allows closing of the petals.

Ultra high velocity can be obtained by several means. One of the most successful, the Gerlich principle, was used by the Germans in large bore cannons during WWII. This principle used a tapered bore from breech to near the muzzle. The projectile contained one or more circular fins much larger in diameter than the main body exposing a large working area to the expanding gas.

Fig. 9

As the projectile moved toward the muzzle thru the tapered bore the fins folded into recesses attaining a finished bore dimension. During this movement down the tapered bore an exceedingly high velocity was obtained in the neighborhood

Fig. 10

Fig. 11

AL 0026186

21826

REMINGTON ARMS COMPANY, INC.

ENGINEERING DEPARTMENT



COMPUTATION SHEET

DES. NO.

FIG. NO.

DATE

BY

19




Fig. 9




Fig. 10




Fig. 11

AL 0026187

22826

A of 5000 ft. per second. Naturally, with this velocity and projectile construction of high hardness and toughness qualities, penetration of armor was achieved with devastating results.

A bullet of 6mm size with two fins of .375" dia. could be used for the initial test of the Gerlich principle. The barrel should be approximately 26" in length with an initial smooth bore diameter of .375" gradually tapering to .240" in 20". The last 6" contains a gain twist rifling to achieve stability.

It seems possible that a projectile, if properly designed, could provide its own power supply. The core would be the actual projectile surrounded by the igniting material safe enough under normal handling to be of no concern. When initiated forward by the thrust of a base percussion type primer the friction caused by contact with the tapered bore would provide combustion. Because of the large working area extra thrust would be attained as the eroding bullet approached muzzle bore dimensions. At a point approximately 6" from the muzzle ignition would be complete and a gain twist would stabilize the projectile. In this design no ejection or extraction is needed and the design of the receiver could be shorter in length, thus lighter in weight, lower cost and would provide a faster lock time.

Fig. 12
Fig. 13
Fig. 14

AL 0026188

23826

REMINGTON ARMS COMPANY, INC.

ENGINEERING DEPARTMENT ANALYSIS COMPUTATION SHEET

SHEET NO.

TITLE OF PROJ.

PROJ. NO.

SUBJECT

Eroding bullet

DESIGN

DATE

19




Fig. 12




Fig. 13




Fig. 14

AL 0026189

24726

Processed foundation for a new bolt action shotgun.

I believe this program can be achieved easily at low development and production cost, because the ground work for such a design was thoroughly covered during the M788 and M540 period.

The effort of simultaneous design to process concept was almost a success in the M788 development, and was attempted to eliminate the costly redesign to process that always occurred in previous attempts. The big problem was to nail down process engineering at the early design stage instead of after the model was tested and accepted for production.

We did achieve a measure of success with this approach by making our layouts of all essential cuts in the receiver the same whether they were for the M788-M540 or the proposed bolt action shotgun. This included the receiver lengths, diameters, ejection ports, feed opening and fire control slots, etc. The drawings of these similarities were presented to process in this manner.

Thus the bolt action shotgun concept was logical and simple for we needed 3 sizes of receivers for the various M788 cartridges and these sizes were ideal for the shotgun if we were to cover all the gauges from 410-12 ga.

I believe, because of this process design effort, that production machinery as now used for the M788-M540 receivers will accommodate the requirements for the shotgun.

The rear locking system was more than adequate in strength and proper for feeding shot shells. The design did not include a tubular feed system which was adverse to

A the X788 but that doesn't mean it couldn't be accomplished.

I do not recall whether a model was made but I remember that strength testing of the competitive bolt action shotguns revealed weaknesses in their bolt handle lock up which would not be acceptable. Therefore our rear multiple lock method was superior. The trigger mechanism of the X788 was a natural for the shotgun and provided a clean crisp let off with very fast lock time of around 2.7 ms.

The reason we did not pursue the program further was because of Mr. Coleman's reluctance in lieu of a bad image for Remington which he thought would lower the status of the M1100.

At that time marketing speculated we would sell 50,000 units a year.

AL (X)26191

26826

Green Valley, Ariz.
Jan. 4, 1982

Mr. Rogers S. White
1426 Ute Ave. Box 2344
Grand Junction, Colo. 81501

Dear Mr. White:

Please excuse the delay in answering your letter. I wanted to give your questions careful thought.

Your list of manufacturing facilities and experience is certainly impressive and be-speaks of a quality organization. However, if you will pardon the constructive criticism, the experience outlined is lacking in several areas when it comes to producing a product for the market place that is considered in the dangerous category, such as a firearm. Your third sentence pertaining to product liability obligations should and has prompted your hesitation in the pursuit of the design and manufacture of trigger assemblies for they are definitely in the dangerous category. This item is especially critical when the design must function precisely in a product that is under the control of another company.

Canjar has been relatively successful with his product, but if the truth was known there is no question he has had problems. Imagine his frustrations in trying to keep abreast of design and dimensional changes after the fact in the various rifles he is trying to fit. It took many years of trial and error by his company to determine the mean dimensions of another product. During those early years product liability was not as serious as it is now, but it gave him time at least to determine the dimensional trends. I must admit he did very well but I certainly wouldn't have the fortitude to attempt such an effort in light of today's legal situation.

Liability suits, involving injury and death, are not in the magnitude of a mere hundred thousand dollars but in the millions. Often the one who pays is not at fault as in the case against Remington concerned with the alleged safety mechanism on the M600 rifle.

In the design and manufacture of a trigger mechanism there are so many dimensional variables and tolerances that testing of all the combinations requires hundreds and thousands of parts, several hundred thousand rounds of test firing*, and thousands of precise measurements. This is needed to detect dimensional variations in the manufacture and wear and damage during testing.

Within the last ten years computer analysis, coupled with automated drafting techniques allowing enlarged examination of dimensional variations, has been added to the designer's kit of tools to allow further examination in depth into the areas of critical control of parts in the dangerous category.

* In semiautomatic mechanisms this could approach one half million rounds.

PLAINTIFF'S
EXHIBIT

3141

AL 0026195

182

Therefore this leaves the small company, no matter how dedicated with limited capital, facilities, experience, and equipment, to the mercy of chance--a very dangerous place to be and does not provide a secure base for product development such as you are suggesting. Such a program would be fraught with costly problems and liability suits.

In the area of trigger guards, sights and accessories, the liability problems are of no concern.

In the design and manufacture of an entire rifle especially by a small company the problems previously described involving the trigger mechanism are compounded by the additional necessity of dimensional control over the locking mechanism, strength of the action, and gas flow, another dangerous category. The only advantage one would have is the opportunity of complete control over the entire product.

To justify the design, testing, permanent or temporary tooling, and production requires a considerable amount of working capital and as problems arise, and they will, costs can soar. Also consider the cost of recall as this can happen in the best of circumstances.

Then there is the problem of advertising, sales promotion, and the establishing of marketing outlets. If there is a weakness in this area failure in the market is assured regardless of the sterling qualities of the product.

Venture-analysis into the market of a new concept or product is an excellent safeguard to be established before progressing beyond the model stage of development.

To support a rifle design that you mentioned I would estimate that 25,000 units a year would be necessary to break even on your costs. I doubt the market would support that volume.

In producing items in the low-volume category, production methods using investment castings and numerical control are ideal, with the individual parts at high cost but the tooling investment held at the minimum level.

In reviewing the history of success of new arms development over the past 20 years there have been numerous starts by small companies with almost 100% failures. These results should be seriously reviewed before undertaking a new venture in this area.

I suggest to you that these ventures are very risky.

Very truly yours,

Wayne E. Leek
Wayne E. Leek

AL 0026196

292

A

Model XP-100 Test Results
December 14, 1962

Test No. 1

ENDURANCE AND FUNCTION TEST

During the week of October 14 thru 20, 1962, an endurance and function test was run on one Model XP-100, Caliber .221 Fireball. This test was conducted by personnel of the R&D Test Unit. All firing was conducted indoors from mechanical shooting devices.

The ammunition used in the test was loaded at Bridgeport earlier in the year for Ilion R&D testing. The loading specifications were 15.8 grains of 4227 powder with a 50 grain Remington bullet.

The test gun was assembled completely with production parts and no alterations of any kind were made on any of the components. The gun was assembled and adjusted by R&D personnel.

No cleaning of any kind was conducted throughout the test.

Prior to commencing the test, the gun was reviewed by the author and members of the R&D Test Unit. Function and operation of the gun were explained at that time, and a pre-fire check was conducted on the weapon.

At frequent intervals during the test a series of 11 - 5-round groups were fired at 100 yards in an experimental accuracy device. It was the purpose of this targeting to determine the effect of wear on the accuracy of the gun.

Data from these and other checks are indicated on the attached test form. Results of the test have been interpreted by the author as follows:

1. No major change in headspace.
2. Trigger pull increased slightly during test. Probably caused by foreign matter in fire control.
3. Group size decreased from zero to about 2500 rounds, where it commenced to open slightly.
4. No looseness of trigger housing throughout test.
5. Firing pin protrusion and indent constant.
6. No development of trigger creep.
7. Rib and sight screws have tendency to loosen slightly after prolonged shooting.
8. Receiver - Stock bedding OK.
9. Feeding OK with gun horizontal.

HLC:T

AL 0027816

PLAINTIFF'S
EXHIBIT

3142

12/10

A

Model XP-100 Test Results
December 14, 1962

Case No. 2

TRIGGER PULL TEST

This investigation consisted of checking trigger pull weight on the first 84 completely assembled production guns to determine whether or not production specifications of 1.5# to 2.75# trigger pull could be met.

Results of the check are as follows:

a.	Total number of guns checked	84
b.	Average trigger pull	2.143 lbs.
c.	Max. trigger pull	3 lbs.
d.	Min. trigger pull	1.75 lbs.
e.	Number over 2 3/4 lb. limit	2
f.	Number under 1 1/2 lb. limit	0

SECRET

AL 0027817

2210

Model XP-100 Test Results
December 14, 1962

Test No. 3

ACCURACY TEST

This test consisted of firing from the XP-100 accuracy device two 5-shot groups at 100 yds. from each of 38 production guns. All ammunition used in the test was Rem. 50 grain factory loads. Groups were measured inside to inside, extreme spread.

Data and test results are as follows:

<u>Gun Serial No.</u>	<u>Group Size (in.)</u>	<u>Avg. Group Size</u>
1015	1.25 - 1.0	1.13
1018	3.0 - 1.0	2.0
1019	2.5 - 2.0	2.25
1024	2.8 - 1.0	1.9
1025	1.5 - 1.0	1.25
1028	1.0 - .75	.88
1029	3.5 - 3.0	3.25
1034	2.0 - 2.5	2.25
1043	1.5 - .75	1.13
1044	2.0 - 1.5	1.75
1050	3.5 - 3.0	3.25
1051	1.0 - 1.5	1.25
1052	2.0 - 1.8	1.9
1054	1.5 - 2.0	1.75
1065	3.5 - 3.0	3.25
1074	2.0 - 1.25	1.63
1082	1.0 - 1.2	1.1
1086	1.5 - 1.5	1.5
1089	1.0 - .75	.88
1091	2.5 - 3.0	2.75
1101	1.0 - .75	.88
1115	2.0 - 1.0	1.5
1119	2.0 - 2.5	2.25
1122	1.25 - 1.7	1.48
1125	1.5 - 1.0	1.25
1126	1.5 - 4.0	2.75
1132	2.5 - 3.0	2.75
1134	3.0 - 1.5	2.25
1136	2.0 - 1.5	1.75
1139	3.0 - 3.0	3.0
1140	1.0 - 1.3	1.15
1153	2.7 - 1.0	1.85
1155	1.5 - 1.0	1.25
1157	2.0 - 1.5	1.75
1162	1.8 - 1.0	1.4
1165	1.5 - 1.25	1.38
1171	1.8 - 1.0	1.4
1176	1.5 - 1.3	1.14

AL 0027818

3010

A

Local XP-100 Test Results
December 14, 1962

Test No. 3
Sheet 2

ACCURACY TEST

Total guns tested	38
Average Group Size	1.802
No. of Guns with over 3" Group Percentage	3 7.9%
No. of Guns with Average over 3" Group Percentage	3 7.9%

E

K

S

I

C

H

HLC:T

AL 0027819

4810

Model XP-100 Test Results
December 14, 1962

Test No. 4

EFFECT OF STOCK INTERCHANBEABILITY
ON
ACCURACY and POINT OF IMPACT

Several guns were fired by W.E. Leek and H.L. Chambers to determine the effect of interchanging stocks on accuracy and point of impact.

All shooting in this test was done off hand, out of doors.

Guns were fired by both shooters with common stocks to determine shootability and point of impact. Stocks were then interchanged and the guns were refired. No change in grouping or point of impact was noted.

It should be brought out at this point that production guns are targeted without stocks, and the effect of stock interchangeability on accuracy and point of impact becomes extremely critical.

HLC:T

AL 0027820

5810

Model XP-100 Test Results
December 14, 1962

Test No. 5

FIRING PIN INDENT

The purpose of this test was to determine the amount of firing pin indent attained with production guns. Indents were checked with standard copper crushers supported by a crusher holder. A total of 36 guns were tested, each gun being checked five times.

The following data indicate the average of the five readings for each gun. In no case was there a variation in crusher indents greater than .001 in. for one gun.

<u>Gun Serial No.</u>	<u>Avg. of 5 Indents</u>	<u>Gun Serial No.</u>	<u>Avg. of 5 Indents</u>
1065	.0183	1173	.0180
1028	.0186	1026	.0193
1138	.0186	1044	.0166
1074	.0186	1167	.0186
1038	.0193	1151	.0190
1155	.0186	1171	.0173
1018	.0180	1146	.0176
1057	.0173	1133	.0176
1129	.0170	1122	.0206
1086	.0180	1126	.0186
1183	.0190	1043	.0185
1141	.0213	1082	.0200
1090	.0206	1041	.0190
1050	.0180	1154	.0196
1175	.0176	1139	.0203
1019	.0200	1140	.0200
1162	.0183	1071	.0176
1056	.0186	1174	.0180

Total Guns Checked	36
Max. Avg. Indent for 1 Gun	.0213
Avg. Indent for 36 Guns	.0187
Min. Avg. Indent for 1 Gun	.0166

HLC:T

AL 0027821

6810

Model XP-100 Test Results
December 14, 1962

Test No. 6

PACKAGING RUST TEST

The purpose of this test was to determine whether or not the proposed plastic zipper case for the XP-100 would induce or retard rusting.

Sections of scrap barrels from the XP-100 were prepared for various treatments including color and no color, Steelgard, and also proprietary material called Rig, for the coating. These were sealed in a plastic zipper case and then the proposed paperboard guter wrap before being placed in the Research weatherometer. The equipment was cycled to provide some 90% humidity and also heated to prescribed temperatures. For control, a duplicate group of the same experimental barrel sections were packed in our regular paperboard gun box, sealed and submitted to the same test.

The packages were opened after 23 days in the weatherometer and conclusions were significantly favorable towards the plastic zipper case. Parts, which included one powder metal component, were very well preserved when colored to provide at least normal treatment. Those in the standard paperboard carton were considerably more rusted. The "Rig" was observed to be better than any other coating used. The samples which were treated with another proprietary oil marketed by Stoeger seemed to give little, if any, protection.

These results relieve any immediate concern; however, arrangements are being made to store one of the XP-100 Pistols in a case for long time exposure under natural conditions.

HLC:T

AL 0027822

7210

Model XP-100 Test Results
December 14, 1962

Test No. 7

LOCK TIME

One production Model XP-100 was checked by the Research Measurements Lab to determine lock time. A series of thirty readings was made. Results of the test are as follows:

Max. Lock Time	3.56 milliseconds
Avg. Lock Time (30 readings)	3.505 "
Min. Lock Time	3.45 "

An investigation is being carried on at the present time to determine an economical way to decrease lock time without weakening the firing system.

HLC:T

AL 0027823

8210

Model XP-100 Test Results
December 14, 1962

Test No. 8

GROUP SIZE COMPARISON
12" Twist vs. 14" Twist

On recommendation of the Ammunition Research Department at Bridgeport, the bore twist of the XP-100 was changed from 1 turn in 14 inches to 1 turn in 12 inches. The purpose of this change was to provide proper stability for a faster, lighter weight bullet. Until now, all XP-100 barrels have been made with the 14 inch twist. Recently, however, a limited number of barrels with 12 inch twist have been made, and it was the purpose of this test to compare group sizes fired in the two barrel types with various bullet weights.

Test data and results are shown below:

1. Group Measurement --
5 shot groups - 100 yds. - measured inside to inside.
2. All shooting done in accuracy device.
3. Ammunition Data
50 gr. - Rem. Factory Ammo. 15.8 gr. 4227
35 gr. - Handloads - Rem. Bullets - 16.6 gr. 4227
60 gr. - Handloads - Morse-Watkins Bullets - 15.0 gr. 4227
4. Guns - XP-100 Production Models

Gun Serial No.	Twist - 1 Turn in 12 in.		
	Group Size		
	35 gr.	50 gr.	60 gr.
1200	2.25	2.25	2.25
1219	1.75	2.25	2.25
1226	3	2.25	1
1197	3	1.5	1.5
1199	1.9	2.25	1.25
1217	2.13	1.75	1
1177	4.5	2.75	1.75
Average Group Size	2.647	2.143	1.571
No. of Groups Over 3 in.	1	0	0

AL 0027824

9810

A

Model XP-100 Test Results
December 14, 1962

Test No. 8
Sheet 2

Gun Serial No.	Twist - 1 Turn in 14 in		
	Group Size		
	35 gr.	50 gr.	60 gr.
1192	2.75	1.25	2.25
1185	3	1.75	3
1072	2.25	2.75	2.75
1206	1.75	2.5	2
1201	3.25	2	3.13
1220	2	2.75	2.25
1180	2.75	2	2.25
Average Group Size	2.536	2.143	2.519
No. of Groups Over 3 in.	1	0	1

RESULTS

Average Group Sizes

	12" Twist	14" Twist
35 gr.	2.647	2.536
50 gr.	2.143	2.143
60 gr.	1.571	2.519
Overall Avg. Group Size	2.120	2.399

HLC:T

AL 0027825

H

10 B/10

REMINGTON ARMS COMPANY, INC.

INTERDEPARTMENTAL CORRESPONDENCE

Remington

SPORT

PETERS

SPORT

Distribution: C. B. Workman
J. S. Martin
C. E. Ritchie
F. S. Martin

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

RESEARCH TEST and MEASUREMENT REPORT - Report No. 812441

NEW DESIGN M/700 TRIGGER/SEAR BLOCK EVALUATION

Prepared by: Ron Williams

Date Prepared: 9/10/82

Proofread and Cleared By:

J.H. Hemmings, / R.E. Nightingale,
Foreman-Test Lab / Foreman-Measurement Lab

Signature

Date

C.E. Ritchie,
Sr. Supervisor - Testing,
Mech. & Mech. Analysis Lab

Signature

Date

PLAINTIFF'S
EXHIBIT

3143

AL 0027889

10211

TEST & MEASUREMENT LAB REPORT

REPORT NUMBER: 812441
REPORT TITLE: New Design Trigger/Sear Block Evaluation
MODEL(S): 700 ADL
GAUGE OR CALIBER: 6MM Remington
DATE: 9/10/82
WORK ORDER NO.: C-1803-000
PART NAME: Trigger Assembly
DESIGNER/ENGINEER: F. Martin

TEST TYPE:

1. PHOTO LAB
2. STRENGTH TEST - NO. OF GUNS TESTED _____
3. FUNCTION TEST - NO. OF GUNS TESTED _____
4. ACCURACY TEST - NO. OF GUNS TESTED _____
5. MEASUREMENTS - TYPE: Static
6. ENVIRONMENTAL TEST
7. AMMUNITION TESTING & EVALUATION - TYPE: _____
8. VISUAL EVALUATION - _____ OUT OF _____ GUN SAMPLE
9. ENDURANCE - NO. OF GUNS TESTED: 5

NO. OF ROUNDS PER GUN 2,500

TOTAL ROUNDS FIRED IN TEST: 12,500

AMMO TYPE: MAGS. _____; TARGET: _____

RIM FIRE _____ CENTER FIRE 6mm

September 10, 1982

TO: J. H. Hanning

FROM: R. Williams

REPORT TITLE: NEW DESIGN M/700 TRIGGER/SEAR BLOCK EVALUATION

ABSTRACT:

A total of (5) M/700 Fire control assemblies with the New Design safety assemblies, were delivered to the Test Lab by Fred Martin for testing. This safety assembly blocks the trigger and the sear so that the firing pin won't fall when the trigger is held back while the safety switch is pushed from the safe to fire position. Both dry cycle and live fire endurance tests were used to test the assemblies. A M/700 fire control assembly (Current Production) was used as a control and (4) out of the (5) New Design assemblies were used in the test.

SCOPE OF TEST

To evaluate the functional performance of the New Design safety assembly, in the M/700 Rifle during lab testing.

TEST RESULTS

No functional problems arose during testing. Both the New Design safety and the control functioned normally. There was no significant change in the safe On/Off forces measured before, during and after testing, on all the assemblies, including the control.

REPORT TEXT

All four (4) new trigger assemblies were subjected to the following trick test:

- o Place Safety Switch in the Safe "On" position.
- o Close the bolt.
- o Put constant pressure on the trigger attempting to fire the rifle.
- o Push the Safety Switch from the "On" position to the "Off" position.
- o Does the firing pin fall?

All four (4) New Design Trigger Assemblies with the trigger /sear blocked passed this test. In all four (4) guns the firing pin did not fall.

NOTE: The measurements recorded for the Safe On/Off forces are questionable. There is no way to determine if they are within Remington Standards, because there are no standards written for these forces with this fire control assembly. The only Remington Standards written for Safe On/Off forces, pertain to the common fire control. That Standard is:

4 - 8 lbs. - One sharp click
Double click not allowed

The Safe On/Off forces measured in this test range from 5.25 lbs. to 10.2 lbs. - almost a 5 lb. difference. (Refer to Appendix A, Data Sheets No. 1 - 5 for all Safe On/Off measurements).

TEST PROCEDUREA. MEASUREMENTS

The following measurements were taken on the five rifles used in this test:

- o Headspace
- o Firing Pin Indent
- o Trigger Pull
- o Sear Lift
- o Sear Engagement
- o Safe On/Off Forces

B. TEST CONDITIONS

1. After every 20 rounds fired, the safety was checked. This was done by holding the trigger and pushing the safety switch from safe to fire.
2. After 1,000 rds. of live fire all the rifles were cleaned and they were remeasured. (Jack Shooting).
3. The rifles were then subjected to Safe On/Off dry cycle. Each rifle was cycled for 2,500 cycles, with Safe On/Off measurements taken every 500 cycles and Sear Lift and Engagement at the 2500 cycle level.
4. The rifles were then live-fired to the 2,000 round level. (Jack Shooting) Measurements were taken at this level.

AL 0027892

4211

TEST PROCEDURE - CONT'D.

5. The rifles were then subjected to another Safe On/Off dry cycle test. They were brought to the 5,000 cycle level. (2,500 additional cycles) Safe on/off measurements were taken every 500 cycles and sear lift and engagement wear measured at the 5,000 cycle level.

These same procedures were followed until live fire totaled 2,500 rounds per rifle and safe On/Off dry cycle totaled 7500 cycles per rifle.

C. AMMUNITION

Remington 80 grain Pointed Soft Point.

A

L

E

APPENDIX

" A "

K

S

I

C

H

M-700 TRIGGER/SEAR BLOCK EVALUATION

No. 1

A 31/1982

R. Williams

M-700 / 6MM CAL # A675273	Sample No. 1	HEADSPACE	FIRING P-N INDENT	SAFE (lb)		TRIGGER PULL (lbs)	SEAR LIFT	SEAR ENGAGEMENT
				ON	OFF			
START OF TEST	MIN. +.004"	.025"	6.2	6.0	4.0	.0105"	.035"	
LIVE FIRE								
after 1000 rds.	MIN. +.004"	.025"	6.2	6.8	4.25			
DRY CYCLE								
500 cyc				5.5	9.6			
1000 cyc				5.8	9.7			
1500 cyc				5.9	9.5			
2000 cyc				5.5	9.7			
2500 cyc				5.7	9.8		.0105"	.035"
LIVE FIRE								
after 2000 rds.	MIN. +.004"	.025"	5.6	7.3	4.0	.0165"	.027"	
DRY CYCLE								
3000 cyc.				6.2	9.8			
3500 cyc.				6.5	10.3			
4000 cyc.				5.7	9.2			
4500 cyc.				6.2	9.5			
5000 cyc.				6.2	9.2		.0165"	.027"
LIVE FIRE								
after 2500 rds HL	MIN. +.004"	.025"	6.3	7.5	4.5			
DRY CYCLE								
5500 cyc				6.2	10.5	4.8		
6000 cyc				6.2	10.0	4.6		
6500 cyc				6.2	8.8	4.6		
7000 cyc				6.0	7.8	4.8		
7500 cyc				6.2	9.8	4.6		
AL 0027895 7/27/11								

AL 0027895

7/27/82

M-700 TRIGGER/SEAR BLACK EVALUATION

No. 2

R. Williams

3/19/82

M-700	Serial No. 296744789	HEADSPACE	FIRING PIN INDENT	SAFE		TRIGGER	SEAR		SEAR ENGAGEMENT
				ON	OFF		PULL	IFT	
Sample No. 2						(in lbs)			
START OF TEST	MIN+.003"	.023"	6.5	5.3	4.3	.0135"	.026"		
LIVE FIRE	MIN+.004"	.024"	6.4	5.2	4.4				
Dry Cycle									
500 cyc			5.9	7.8					
1000 cyc			6.0	6.8					
1500 cyc			6.0	7.0					
2000 cyc			5.5	6.7					
2500 cyc			5.3	7.7		.015"	.025"		
LIVE FIRE									
after 2000 cyc	MIN+.004"	.023"	5.7	4.8	4.2	.014"	.029"		
Dry Cycle									
3000 cyc			6.5	9.0					
3500 cyc			5.5	7.8					
4000 cyc			5.8	7.2					
4500 cyc			6.2	7.7					
5000 cyc			7.8	8.0		.018"	.0285"		
LIVE FIRE									
after 2500+ H.	MIN+.004"	.023"	5.8	4.5	4.7				
Dry Cycle									
5500 cyc			7.0	9.5	4.8				
6000 cyc			6.7	8.7	4.5				
6500 cyc			6.7	7.8	4.5				
7000 cyc			7.2	7.8	4.8				
7500 cyc			6.6	8.5	4.5				

AL 0027896 *8/2/11*

AL 0027896

3/31/1982

M-700 TRIGGER / SEAR BLOCK EVALUATION

No. 3

R. Williams

M-700	GMMed. # A6744915 Sample No. 3	HEADSPACE	FIRING		SAFE		TRIGGER PULL (lb)	SEAR LIFT	SEAR ENGAGEMENT
			PEN	INDENT	(in lbs)	ON	OFF		
1									
2	START OF TEST	Min. +.004"		.025"	9.	6.4	4.7	.015"	.025"
3									
4	LIVE FIRE								
5	after 100 bds.	Min. +.004"		.026"	9.7	6.7	4.1		
6									
7	DRY CYCLE								
8	500 cyc.				8.2	6.9			
9	1000 cyc.				8.3	7.0			
10	1500 cyc.				8.8	6.3			
11	2000 cyc.				9.2	7.0			
12	2500 cyc.				9.9	6.0		.012"	.032"
13									
14	LIVE FIRE								
15	after 2000 bds.	Min. +.005"		.026"	10.2	5.2		.013"	.033"
16									
17	DRY CYCLE								
18	3000 cyc.				8.5	8.5			
19	3500 cyc.				9.2	7.2			
20	4000 cyc.				9.2	9.0			
21	4500 cyc.				8.7	8.7			
22	5000 cyc.				9.5	12.2		.015"	.032"
23									
24									
25	LIVE FIRE								
26	after 2500 bds. HL	Min. +.005"		.025"	9.8	5.2			
27									
28	DRY CYCLE								
29	5500 cyc.				8.3	8.3			
30	6000 cyc.				9.2	8.8			
31	6500 cyc.				9.7	9.3			
32	7000 cyc.				8.5	12.0			
33	7500 cyc.				9.5	12.0			
34									
35									
36									
37									
38									
39									
40									

AL 0027897

9/8/82

M-700 TRIGGER / SEAR BLOCK EVALUATION No 4

31/1982

R. Williams

M-700	GMMCAL #6745544	HEADSPACE	FERRING		SAFE (lbs)		TRIGGER	SEAR	SEAR
			PIN INDENT		PULL (lbs)	LIFT	ENGAGEMENT		
				ON	OFF				
START OF TEST			MINT 002	.022	83	5.4	3.8	.018	.034
LIVE FIRE									
after 1,000 cys			MINT 002	.022	68	5.2	4.0		
DRY CYCLE									
500 cys					77	77			
1000 cys					78	75			
1500 cys					68	73			
2,000 cys					78	72			
2500 cys					72	77		.017	.035
LIVE FIRE									
after 2,000 cys			MINT 003	.022	73	4.5	3.8	.0155	.035
DRY CYCLE									
3000 cys					67	87			
3500 cys					75	77			
4000 cys					77	67			
4500 cys					75	77			
5000 cys					77	68		.017	.036
LIVE FIRE									
after 2,500 cys			MINT 003	.022	88	4.3	4.3		
DRY CYCLE									
5500 cys					82	9.0	4.5		
6000 cys					73	9.0	4.1		
6500 cys					75	9.3	4.2		
7000 cys					83	9.2	4.3		
7500 cys					87	8.3	4.3		
AL 0027898 1084									

AL 0027898

1024

M-700 TRIGGER / SEAR BLOCK EVALUATION

ASPC 110 01077

g. 31, 1982

No. 5

R. Williams

M-700	MMMA #1747525	HEADSPACE	FIRING		SAFE (lbs)		TIMER	SEAR	
			PIN	INDENT	ON	OFF	PULL (lbs)	LIFT	SEAR ENGAGEMENT
	Sample No. 5								
	CONTROL BAR								
1									
2	START OF TEST	MINT 003	.025		5.2	5.2	4.2	.019	.020
3									
4	LIVE FIRE								
5	after 1,000 rds	MINT 003	.025		5.5	5.2	4.0		
6									
7	DRY CYCLE								
8	500 cyc				6.3	7.6			
9	1000 cyc				5.6	8.3			
10	1500 cyc				5.8	7.8			
11	2000 cyc				6.1	8.5			
12	2500 cyc				5.1	8.3		.021	.0205
13									
14	LIVE FIRE								
15	after 2,000 rds	MINT 003	.025		5.5	5.1	4.5	.020	.020
16									
17	DRY CYCLE								
18	3,000 cyc				6.6	8.1			
19	3,500 cyc				6.8	8.1			
20	4,000 cyc				6.1	7.6			
21	4,500 cyc				6.1	7.3			
22	5,000 cyc				6.0	6.5		.020	.020
23									
24									
25	LIVE FIRE								
26	after 2,500 rds th	MINT 003	.025		5.1	4.8	5.0		
27									
28	DRY CYCLE								
29	5,500 cyc				6.1	8.0	4.7		
30	6,000 cyc				6.1	8.0	4.6		
31	6,500 cyc				7.0	8.5	4.6		
32	7,000 cyc				6.8	8.1	4.7		
33	7,500 cyc				6.3	7.6	4.8		
34									
35									
36									
37									
38									
39									
40									

AL 0027899

11/2/82

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

Bridgeport, Connecticut
April 16, 1982

TO: T. L. CAPELETTI
FROM: T. W. RAWSON *WR*
SUBJECT: LONGER RANGE M700 REFORM PLANS

Per our phone conversation, I would very much like to be included in the planning sessions for the M700 rifle upgrade.

The research that I have done suggests an enumeration of features, which follows, should be helpful to identify the basic scope of work.

1. Barrel contour
2. Recoil bracket
3. Receiver shape
4. Bolt release
5. Safety
6. Bolt handle
7. Ejector/extractor
8. Trigger guard floor plate
9. Stock
 - a. Cheekpiece
 - b. Comb
 - c. Pistol grip shape
 - d. grip cap
 - e. Forend tip

PLAINTIFF'S
EXHIBIT

3144

AL 0027925

123

- A
- f. Butt pad
 - g. Checkering
 - h. Finish

I too believe there are some basically very desirable features of the 700 with a few less desirable details that can be upgraded to surpass competitive offerings.

While the committee will need to confront each of these items, I have suggestions which might speed up some of our evaluation.

It is believed the safety is a significant place for improvement. This is being called out here, however, only because an opportunity exists to evaluate an alternative. We have asked Bob Emmons to have Pete Grisel install a tang safety on our 4th prototype gun under contract. The tang safety is probably more desirable than our current mechanism because it will eliminate the appearance of a stamped part and the hole in the stock alongside the tang. The tang safety, however, is still a trigger lock safety and does not address the theoretical advantage of a striker lock safety. The Ken Jantz bolt sleeve safety that you and I viewed at the NRA show is seen as an alternative with appeal in several areas.

- It eliminates the stamped lever and hole in stock by virtue of bolt sleeve location.
- Is a striker lock system.
- Can provide the choice of two position or three position with the three position giving a choice of bolt lock and striker lock or blocked striker (only) for safe unloading.

This particular option is being mentioned now because Pete Grisel's work is going on - he may be able to replace or add the bolt sleeve safety to his barreled action work. While we would never produce a gun with both a tang and bolt sleeve safety the presence of both safety's on one gun does not cancel out the other and will provide a chance for instant comparison.

TWR/df

4/21/82

10

A

Check Piece Options as per Tom Revision

L

E

K

L

K

S

L

I

L

C

H

11/11

But Action Program

1-5-82

Chapter 83

1. Scope - alignment / new concept - what R III

2. Scope units - for Centers -

3. 11/700 ADL - BDL -
we can see change

4. 11/700 ADL

K

Bob Emmons - 84

Get a schedule for revised stock

- 1984

-
-
-

11/700 ADL - new - also - standard

11/700 BDL new - also - standard

11/700 Classic - new - also - standard

11/700 Detachable Box -

11/100 Box and Store -

S

C

H

PLAINTIFF'S
EXHIBIT
3145

AL 0027940 182

A

1st Fire Control - Present
Connector-Less Trigger

L

2nd Fire Control - Proposed
Connector-Less Trigger - For Bucked
TRIC SAFETY

E

3rd Triggers - Streamlined - For Bucked
TRIC SAFETY

K

Test Cells - Fire Controls with
Bucked TRIC & SEAR
* Low Volt. To Comm.
Puncher Prefs
* Heat Treat Trials

S

I

C

H

December 21, 1981

Bolt Action Program
1984 Introduction
Fire Control Revision & Redesign

Add to Fire Control

- Trigger Block
- Housing Clearance
Skeletonize
- Sear Clearance
Relieve
- Remove Connector
- Restyle Trigger

Extractor - M-1911-A1 Style

New Receiver Configuration
Barrel Bracket - .250 thick
Lighten Barrel
Ruger Patent on Action Screw - Diagonal Tension
Detachable Magazine - Mag Con
Sights - Rear P.E. & C.
Safety On Bolt Plug
Safety On Tang
Feeding
Restyle Trigger

Add caliber to short action line to be based on 7mm BR case .25 caliber.

F. E. Martin:ws

PLAINTIFF'S
EXHIBIT

3146

AL 0027947 121



xc: J. P. Glas
J. W. Brooks
J. S. Martin
A. A. Hugick
F. E. Martin
S. A. Fanelli

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY" _____

Ilion, New York
March 2, 1981

TO: C. B. WORKMAN
FROM: T. L. CAPELETTI *TC*
SUBJECT: POTENTIAL IMPROVEMENTS TO BOLT ACTION RIFLES

Attached is a copy of my December 11, 1980 memorandum to J. P. Glas summarizing our suggestions concerning potential improvements to bolt action rifles. On February 19, 1981, I discussed these improvements again with John Brooks, Jim Martin, Adam Hugick, Fred Martin and Sal Fanelli. The December 11, 1980 memorandum remains a good summary of what we feel is needed or can be done to improve our market position with the bolt action rifles. In addition to our suggestions in the previous memorandum, I have summarized below our comments from our February 19, 1981 meeting. In general, we feel that our rifles are better than any competitively priced bolt actions on the market. However, there are some changes we can make in basic design, chamberings and styling features that would provide new offerings for our dealers to use in promotional campaigns. Furthermore, our marketing philosophy needs to center around a more aggressive advertising campaign based on the strengths of our designs (eg. strongest locking system on the market - we have test data).

Design

1.) Common receiver for all centerfire rifles

- We have a conceptual drawing of a common receiver design, but have not pursued to the engineering stage. The advantage would be use of a common magazine box and fire control for bolt actions, pumps, and autoloaders with no sacrifice in accuracy or durability of our current bolt actions.

PLAINTIFF'S
EXHIBIT

3147

AL 0028064

182

2.) Model 700 Limited Edition (Model 7)

A special edition bolt action rifle (M/700 LE or M/7) would be a natural extension of our Limited Edition line beyond the M/870 LE currently planned. We have built a prototype Model 7 with the following features:

- Octagon receiver
- Hammer forged barrel
- Lightweight firing pin (Gives a 25% reduction in lock time).
- 6 1/2 lb. total weight
- Redesigned fire control with blocked trigger and sear
- Redesigned follower for smoother action
- 22 inch barrel
- Fully enclosed bolt plug
- Cooking indicator

3.) Modify caliber offerings

— Due to overlap in our current offerings, we recommend the following changes in calibers:

- Delete the 223, 243, and 270
- Add the 220 Swift, 7mm Mauser and 358 Win.

4.) Redesign feed system

- Modify the magazine box to easily accommodate 3 magnum or 4 regular rounds
- Modify the follower to reduce feeding malfunction rates

5.) Redesign the fire control

- Implement new design with blocked trigger and sear
- "Skeletonize" the design to make components more visible and easier to keep clean

6.) Left handed rifles

- Expand line to include smaller calibers (eg. 243)

7.) Offer synthetic stocks in target rifles

Appearance

1.) Bolt handle

- A variety of designs were prepared for use on the bolt action carbine.

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
OUTLINE

PETERS
OUTLINE

cc: C. B. Workman
J. S. Martin
F. E. Martin
S. A. Fanelli

"CONFINE YOUR LETTER TO ONE SUBJECT. ONLY" _____

Ilion, New York
December 11, 1980

TO: J. P. GLAS

FROM: T. L. CAPELETTI

SUBJECT: POTENTIAL IMPROVEMENTS TO BOLT ACTION RIFLES

I have discussed potential improvements to our bolt action rifles with Fred Martin and Sal Fanelli in response to your inquiries concerning why Remington may be losing position in that market and what we might do to regain that position. In view of the new Winchester Model 70 light weight, this is an opportune time to review results of those discussions for you. Fred and Sal's suggestions, summarized below, fall into three general categories: Improvements in a.) Design, b.) Appearance, and c.) Marketing Philosophy. These suggestions have not been fully reviewed with either Jim Martin or Clark Workman. However, I feel they merit further consideration. Significant change in our market position will probably require focused attention on a complete redesign of the firearms combined with a more aggressive marketing approach.

Design

Areas where design changes may be beneficial are in the receiver, feeding, and fire control systems. It may be possible to design a bolt action with enough commonality in the receiver to permit use of one magazine box and fire control system with all of our centerfire rifles (autoload, pump, and bolt action). Commonality would have obvious cost improvement advantages and is worth serious consideration. However, our bolt actions have an excellent reputation for accuracy and durability and one of the program objectives would certainly be to maintain that performance and reputation.

Short of complete redesign of the line, improvements are possible in the feeding and fire control systems of the current designs. The magazine in the M/700 ADL 7mm magnum can only accommodate

PLAINTIFF'S
EXHIBIT

3148

AL 0028067

182

two (2) rounds with ease; holding three (3) rounds sometimes requires special adjustments. Magazines should be designed to easily accommodate three (3) magnum rounds or four (4) standard rounds. In fact, we need focused attention on the feeding systems on all our bolt actions, including the rimfires. Regarding the fire controls, we already have a program to develop improved systems. Those improvements should be aggressively pursued and implemented.

Appearance

When properly cleaned and displayed, our bolt action centerfires have an excellent appearance and give an impression of rugged dependability. However, out-of-the-box appearance is generally not as favorable due to salt bleedout problems, use of oil coatings for rust prevention, and dull sights. Salt bleedout is not a new problem and we have taken steps to eliminate bleedout where we have a known recurring problem. Oil coating for rust prevention is a standard Remington procedure which is not used by some of our competitors. We should investigate alternative protective coatings, such as dry lubricants. Our powder metallurgy sites have a dull appearance due to porosity even when polished. We should consider a complete change in our sight line.

Marketing Philosophy

Our marketing approach for bolt actions has been unchanged for many years. We need some innovations in design combined with more emphasis on strengths of our current line. The M/700 has the strongest locking system and is the most accurate bolt action centerfire rifle on the market. While our extractors are stronger than those of our competitors, they do not have the same massive appearance. We need to take advantage of existing test data to counter the implication that massive appearance correlates with strength. Finally, we should advertise availability of special calibers on custom orders or make special calibers available to preferred dealers or customers. One possibility is to introduce a special edition 35 Whelen caliber rifle as a commemorative to Col. Townsend Whalen.

CURRENT REMINGTON BOLT ACTION FIRE CONTROLS

1. M600
2. M700
3. M788
4. XP-100
5. 541-S
6. 540 XR
7. 580-81-82
8. 40XB
9. 40XB-20Z

ALTERNATIVE DESIGNS

1. 3 POSITION
2. BOLT PLUG LOCK
3. BUTTON LOCK
4. FIXED ENG. & O.T.
5. REVISED 788-580
6. NEW DESIGN A
7. NEW DESIGN B

TYPE OF SAFE	UNLOAD WITH SAFE ON	ADJUSTMENT				BOLT LOCK	INDEPENDENT BOLT LOCK	ON SAFE - STRIKER DOWN	INTERCHANGEABLE WITH M700	FITABLE - Field	FITABLE - PLANT
		OVERTRAVEL	ENGAGEMENT	PULL	PRE PLAY						
SB	NO	YES	YES	YES	NO	YES	NO	NO			
SB	NO	YES	YES	YES	NO	YES	NO	NO	YES	YES	YES
SB	YES	NO	NO	NO	NO	NO	NO	NO			
SB	YES	YES	YES	NO	NO	NO	NO	NO			
SB	YES	YES	YES	YES	NO	NO	NO	NO			
SB	YES	YES	YES	YES	NO	NO	NO	NO			
SB	YES	NO	NO	NO	NO	NO	NO	NO			
SB	NO	YES	YES	YES	NO	YES	NO	NO			
NO	NO	YES	YES	YES	NO	NO	NO	NO			
SB	YES	YES	YES	YES	NO	YES	YES	NO	NO	NO	YES
SB	YES	YES	YES	YES	NO	YES	YES	NO	NO	NO	YES
SB	YES	YES	YES	YES	NO	YES	YES	NO	NO	NO	YES
SB	NO	NO	NO	YES	NO	YES	NO	NO	YES	YES	YES
SB	YES	NO	NO	NO	NO	NO	NO	NO			
SB	YES	NO	NO	YES	LL	YES	YES	YES	YES	YES	YES
SB	YES	NO	NO	YES	LL	YES	YES	YES	YES	YES	YES

* ORIGINALLY Produced WITH BOLT LOCK SIMILAR TO M700

PLAINTIFF'S
EXHIBIT

3149

AL 0028132

A

PROCEDURE FOR REPLACEMENT OF TRIGGER HOUSING
ASSEMBLY ON MODEL SEVEN LIGHTWEIGHT

L

IMPORTANT NOTICE

E

Absolutely no alterations or adjustments are to be made to the replacement trigger assembly. If any of the conditions listed below are encountered during replacement of the Trigger Assembly, return the complete rifle to the factory.

- o Difficulty assembling Stock to receiver with guard screws.
- o Trigger projecting beyond side of trigger guard.
- o Binding of sear in housing.
- o Trigger binding on trigger guard plate.
- o Trigger binding on trigger guard.

S

I

C

H



124
AL 0028287

MAKE SURE FIREARM IS NOT LOADED AND THE MAGAZINE IS EMPTY

To Disassemble Firearm:

- o Put safety switch to "S" position.
- o Remove bolt assembly from action (See Page 5 of Model Seven Instruction Book).
- o Turn rifle upside down, Barrel pointing to your left.
- o Open floor plate by pushing front of latch. (See Picture 1).
- o Completely loosen front guard screw. (See Picture 2)
- o Completely loosen rear guard screw. (See Picture 2)
- o Lift Stock away from the barreled action. The floor plate base assembly, trigger guard front and rear guard screws will remain with the Stock.
- o Remove magazine from Receiver.
- o Turn firearm with left side up and Barrel pointing left. (See Picture 3)
- o With the Safety switch in the "S" position, tap out the front and rear sear pins from left to right and remove the trigger assembly from the Receiver. (See Picture 3)

To Reassemble Firearm:

- o Insert the new trigger assembly (with slave pins intact) into the Receiver. Align holes in housing with holes in Receiver and tap in sear pins from left to right (chamfered end first). (See Picture 3)

Note: Front sear pin must not protrude into the bolt stop slot.

CAUTION:

- o After assembling, push the bolt stop release. (See Picture 4 upward; bolt stop must pivot freely.

CAUTION: - Contd.

- o Put the safety switch in the "F" position, pull the trigger and hold. Depress the top rear of the safety cam to insure that the sear safety cam pivots freely and retracts without hesitation. (See Picture 5)
- o Push safety switch from "F" to "S" position several times to insure free movement with no binding and positive engagement of safety switch detents.
- o Restake both pins on the right side of the Receiver. Recheck to make sure bolt stop moves freely. (See Picture 6)
- o Reassemble the magazine into the Receiver. (See Picture 7)
- o Reassemble the Stock to the barreled action. This should include the floor plate base assembly trigger guard and front and rear guard screws if they were disassembled as a unit;
- o Be sure action is seated rearward in Stock.
- o Assemble front and rear guard screws to the Receiver. If any trouble is encountered in completing this step, return entire firearm to the factory.
- o Close floor plate.
- o Replace the bolt assembly.
- o After reassembling the rifle, check for clearance between the following parts; safety switch and stock, trigger and floor plate base.
- o Check for trigger projecting beyond side of trigger guard.
- o If any of these conditions are encountered, return the entire firearm to the factory.

SAFETY PERFORMANCE CHECK

The following checks for proper functioning of the safety must be made:

- o Close the bolt
- o Put the safety switch into the "S" position.

- o Pull the trigger (firing pin should not fall). Action of trigger pull must be smooth (no bind, drag, click, or catch).
- o Release the trigger (trigger must return forward to its original position).
- o Put the safety switch into the "F" position (firing pin must not fall).
- o Pull the trigger (firing pin must fall).
- o Repeat this test at least three time.
- o Push the safety switch from "F" to "S" position several times to insure free movement with no binding and positive engagement of safety switch detents.

CAUTION: IF "F" AND "S" POSITION ARE NOT POSITIVE, RETURN
COMPLETE RIFLE TO FACTORY FOR REPAIR

Check for "follow down" (firing pin moves to uncocked position as bolt is closed).

- o Put the safety switch into the "F" position.
- o Close the bolt smartly.
- o Firing pin must remain cocked. Pull the trigger to check. Firing pin must fall. Perform this operation several times.
- o If "follow down" occurs, RETURN THE RIFLE TO THE FACTORY.

JWB:js
Ilion Firearms Research Division

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

PETERS

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

Ilion, New York
January 26, 1979

R. L. HALL

MODEL XP-100 SEQUENCE OF EVENTS

Model XP-100 sequence of events in modifying customer return guns and insuring integrity of production Trigger Assemblies is listed chronologically below:

<u>Date</u>	<u>Event</u>
10-24-78	Remington announced recall of M/600 and XP-100 pistol.
11-78	Engineering and Production effort concentrated on M/600. Gunsmith write-up - assemblies for gunsmith - establishing process for Trigger Assemblies to be shipped.
11-17-78	Present process reviewed - trick test for XP-100 reviewed with assemblers - shim test added (check for clearance between Sear and Sear Block with shim Stock, with Safety in null position).
12-1-78	Initial work on defining situation for customer repair XP-100's started - process reviewed, additions and clarifications were made.
12-15-78	Process developed for customer repair pistols; Engineers tried sample run. Customer repair gunsmith trained.
12-18-78	Initial lot of 25 customer guns modified to repair process. Lot rejected, two guns failed test. Shim test and trick test.

PLAINTIFF'S
EXHIBIT

3151

AL 0028613

123

R. L. HALL

-2-

January 26, 1979

Date Event

12-18-78 Contd.

The trick test was re-evaluated and it was found that the engineer and gunsmith were using different techniques on standardized test. The shim test was also re-evaluated for consistent and easier operation.

It was also found that customers had made alterations to the Sear Housing Assemblies and they had to be readjusted to standards.

12-28-78 A second lot of 25 was modified to revised process. A large percent of pistols would not pass shim test and the new gaging technique was questioned - parts measured.

1-4-79 Engineering analysis showed second lot of pistols was using a new shipment of Safety Assemblies which had .006" less lift on Sear. R & D altered drawing to increase lift - parts were ordered with higher lift. Shim test results were ~~verified~~ ^{ANALYZED} by using dial gage which fits into back of Receiver. ~~ANALYZED~~ ^{ANALYZED} ~~REWORKED~~ ^{REWORKED}

1-10-79 New lot of 25 pistols started to process for modification - high lift Sear were used and pistols were audited - process verified.

1-12-79 Repair verified on customer pistols - pistols being returned to customers. ^{STARTED} Production using ~~new~~ ^{SAFETY} Safety levers; reject rate increased dramatically $\approx 50\%$.

1-19-79 New Safety levers delivered to Ilion - found to have too much Sear lift, .002" over max. model drawing.

1-22-79 New Safety levers in Assemblies - mechanism would lock up when put on Safe. Safety levers ground down to max. model drawing. Mechanism worked but rear of Sear interferes with Sear Housing Pin.

1-23-79 Safety levers ground to mean model drawing - still binding. Drawing change made to grind clearance on Sear - parts tried, mechanism worked.

223
AL 0028614

R. L. HALL

-3-

January 26, 1979

Date Event

1-24-79 Parts modified, Assemblies put together. Safety worked hard. Lubrication technique developed - parts delivered to Final Assembly - pistols put up.

1-25-79 Pistols tested satisfactorily. More parts were modified. Pistols which had been rejected were refitted with new Sear and lever.

1-26-79 More parts being modified - permanent process for part modification being developed.

1-29-79 Parts delivered to Customer Repair - to continue modifying guns - 147 shipped to date.

J. P. Linde, Superintendent
P E & C Section

JPL:eb

383
AL 0028615

TELEX

RD-41-1

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
OUTPORT

PETERS
OUTPORT

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

Ilion, New York
February 8, 1979

TO: B. K. DAUBENSPECK
BRIDGEPORT

XP-100

1. Changes to Sear

Sear redesigned to increase the lift clearance between the sear and the bolt stop cross pin to prevent hard "safety on" forces when the max. cam on the safety lever was used. This change was made to a non-critical area of the sear and does not adversely effect its operation or strength.

2. The front of the trigger was redesigned to eliminate possible interference with the trigger adjustment screw threads. Interference with the threads could cause the trigger to bind.

3. Redesign of the safety lever to better control tolerances is in progress. This is not yet complete.

C. B. Workman, Manager
Ilion Research Division

CBW:T

PLAINTIFF'S
EXHIBIT

3152

1081
AL 0028619

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

REPORT

c: D. M. Condon
C. A. Riley
W. H. Forson
W. J. Weeks
A. O. Library

Bridgeport, Connecticut
January 27, 1983

T. W. RAWSON
R. E. SCHRADER

CONSUMER CUES TO QUALITY - BOLT ACTION CENTER FIRE RIFLES - FINAL REPORT

Three consumer group sessions were conducted in November 1982 with recent and prospective center fire bolt action rifle buyers to determine the "cues" by which a prospective buyer assesses the quality of a rifle. An "expert" (custom gun maker) session was also conducted to help provide added insight into this issue.

"Cues" are the visible/external elements of a product (in this case a gun) which a consumer uses to come to some determination of the overall workmanship and performance of that product. A "cue" on a gun is usually a more subtle element than an obvious feature like a hinged floor plate and less noticeable than an attribute like "good wood-to-metal fit". However, these latter elements could be considered strong "cues" to quality for some consumers.

"Cues" are generally the numerous details on a product which convey to the consumer a concern for how it was manufactured. The addition of "cues" tends to have a cumulative effect to a point where the gun emits an "aura" of fineness.

Prospective center fire rifle buyers are greatly influenced by the cosmetics/appearance of a gun. To these buyers, an attractive/"pretty" gun conveys quality. Since a center fire rifle's stock is the largest part of the gun, it has more of an impact on generating an impression of "attractiveness" than any other component.

This research indicates that a "cue" to an attractive stock is tapered/slender lines. A stock designed and manufactured

PLAINTIFF'S
EXHIBIT

3153

AL 0028671

182

A with these kinds of lines conveys an attention to detail by making sure that the wood "flows" into the metal rather than looking like a "pipe stuck on a 2" x 4".

The research strongly suggests that a center fire rifle should have an "integrated appearance". An example of this is the way various metal parts are finished. While consumers prefer all machined parts, they grudgingly accept stamped parts in certain areas if they are finished "well", that is, if an aluminum stamping looks like (after bluing) the machined steel in the receiver or barrel. If this is done the metal parts all look the same.

The above discussion, hopefully, has clarified the notion of "cues" and how they apply to center fire rifles. The final report attached itemizes and elaborates them more fully.

In conclusion, this research suggests that we should avoid making unnecessary internal changes if they only marginally improve a new gun's performance. The benefit of these kinds of changes (improved consumer acceptance) would probably not justify the cost of implementation.

J. H. CHAMBERS

JHC/kam
Att.
0001M

AL 0028672 282

cc: J.G. Williams

FORM REV. 8-58

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

RECEIVED

FIREARMS RESEARCH DIVISION

June 1, 1982

P.H. HOLMBERG

NEW BOLT ACTION RIFLE

As a result of our recent meeting with R&D and Production, the following is my interpretation of our objective and, more importantly, the desirable features/model requirements.

OBJECTIVE

Replace current 700 BDL, Varmint, and Left-hand Specials with new bolt action rifles having demonstrable consumer-perceived value-in-use features and completely new styling at minimum cost and capital investment.

Specifically, the above objective can be broken down into four major categories. They are as follows:

1. Styling -

All-new look; i.e., stock, receiver, fore-end, barrel, trigger housing, etc.

2. Internal mechanical features -

Mechanical changes should only occur if needed to improve a current known deficiency or if providing demonstrably-perceived consumer advantage.

3. External Features -

Again, these features should represent consumer-perceived advantages such as scope mounts, external adjustable triggers, repositioning of safeties, etc.

4. Minimum Cost and Capital Investment -

In this area, we would hope to produce the new bolt action rifle at a cost equal to, or lower than, our current model; however, additional cost for a specific development may be incurred and

PLAINTIFF'S
EXHIBIT

3154

AL 0028726

185

June 1, 1982

accepted because they can be recovered in selling price. As for capital expenditures, if, in fact, we can develop this new gun in conjunction with the firearms modernization program, it would be most timely. Our basic goal is to introduce this new gun in the 1985 model year; however, if the situation requires, we could go as long as the 1986 model year.

Following are the desirable features/model requirements, along with some idea of what they mean, either to us in manufacturing or to the consumer.

Flat-bottom Octagonal Receiver

1. Easier to customize.
2. Reduce weight.
3. Narrower - allows narrower stock configuration.
4. Relates to trade likes - flat bottom.
5. Visually different.

Integral Recoil Lug

1. Consumer-perceived added strength.
2. Improved uniform appearance between barrel and receiver.

Integral and Standard Scope Mounts - (Integral preferably better than competition)

1. Flexibility in mounting systems.
2. Consumer-perceived value - windage and elevation adjustments.

Anti-bind Bolt

1. Consumer-perceived smoother action.
2. Reduced lateral motion of bolt through entire stroke.

Front Lock - (two-lug system (no change))

- *1. Possibly three-lug system.

* Low priority Add.

AL 0028727

225

June 1, 1982

Short and Long Actions

1. Provide actions for cartridge - although not necessary but common in the industry.

New Bolt Stop - Release

- *1. Improve quality - appear stronger.
2. Possibly relocate.

Block Trigger and Firing Pins

1. Dual safety switch.
2. Reposition.
3. May be 3 position.

Bolt Lock

1. Separate switch - not mandatory.

Cocking Indicator

1. Shows red when cocked.

Fire Control

- Adjust-ments
1. Pounds pull - external - fail safe - down to 3 lbs.
 2. Over travel - external - safety limits - if a factor??
 3. Change sear to wrought iron.
 4. New fire control - desirable.
 5. Standard trigger.

Barrel

- **1. High gloss - hammer marks - aesthetics - looks different.
2. Lt. weight contour - lighter weight - new contour.
3. Target crown - protects end of barrel - maybe accuracy improved.
4. Recoil reducing muzzle - & reduction in recoil.
- *5. Stainless steel - option.
6. Clean barrel - no sights or holes.

Low priority Adv.
Cost factor possible.

AL 0028728

385

June 1, 1982

Feed System

1. Unload with bolt open.
2. No-bind follower.
3. Rotary magazine - better feed - no angles - more rigid receiver.
4. Magazine - 3 shots versus 4; and 4 versus 5 shots.
5. Jeweled follower.

Bolt

1. Claw-type extractor - more guts, heavier looking, etc.
2. Restyled bolt handle - styling - looks. Distinctive but functional.
3. Two-lug system - possibly 3.
4. Easy lift - no more than present 700.
5. Jeweled - aesthetics.
6. Reduced locked time - would not sacrifice for easy lift.
7. Restyled bolt plug - aesthetics.

Stocks

1. Walnut - appearance.
2. Cut checkered - 20 lpi. - full - Schnable fore-end.
3. Recessed slug swivel studs - styling.
4. Cast off and toe out - similar to Hygrade custom stocks.
5. Skeletonized butt and grip cap.
6. Epoxy bedding - strength.
7. Emmons stock - slim down grip, etc.
8. Medium gloss.
9. No spacers.

During our session, we also discussed the need to conduct market research on potential new bolt action rifles. Following are a couple of areas where we discussed specific testing. I'm sure that as we proceed, others will become obvious.

June 1, 1982

A

Test Guns

1. Barrel - hammered high gloss versus no hammer high gloss.
2. Barrel contour - new versus straight or current.

Please feel free to update this list and the objective any way you see fit. We do need to expeditiously confirm in writing our discussion with R&D. In addition, we should include in this document our version of performance specifications, i.e. accuracy, weight, etc.

E

K

C.A. RILEY

CAR:jt

S

I

C

H

A

REMINGTON ARMS CO.
RECEIVED

MAR 16 1982

225 E. Edgewood Dr. Apt. 98
Lakeland, Florida 33803
Mar. 12, 1982

Mr. Clark Workman FIREARMS RESEARCH DIVISION
Remington Arms Co.
Ilion, N. Y.

Dear Clark:

Jim was here today and we went over the bolt actions from A to Z.

These are some of the things I propose:

1. Please don't bring out a new bolt action, without a fool proof safety which is capable of locking the bolt. Make it at least as good as the present M/70, better if possible.
2. Suggest you push for a complete line of bolt action rifles that cover the price gamut from lowest to highest. I feel the Carbine should be as simple and plain as you can make it with a price to match.
3. Forget pressed checkering!
4. I feel the idea of a hex cross section for a new receiver will increase cost. I also feel that indexing barrels and receivers will also increase cost. Since I feel that present volume is low because of price structure, increasing cost is a no no!
5. I didn't mention this to Jim, but we should make a large effort to capitalize on the fact that the benchrest shooters think our present 700 - 600 - XP100 - 40X actions are the most accurate production actions available and use them when they can get them for bench rest competition.
6. I am ~~personally~~ not in favor of the "as hammered" finish on barrels.
7. I do not think that Ruger is making more than 50000-77's per year. Anyone who says he is, is trying to mislead you.
8. The .243 has cost Win. and Sav. some fairly costly law suits due to its tendency to wear barrels quickly and cause high pressures due to excessive fouling. We have not had this problem because we use 6 MM barrel interiors for the .243, plus the fact that 700s do not come apart due to high pressure. To let the 6 MM die by taking it out of production in 700 is asinine. It's a better cartridge all the way than the .243 and we should make an effort to tell the customers. Letting the customers tell us in this instance, could get us into trouble.

PLAINTIFF'S
EXHIBIT

3155

AL 0028744 182

A 9. We obviously have some production or design problems with M/700 magazine feed. We need to get busy on this. Magazines too narrow or receiver openings too wide can cause the problem you are experiencing.

10. Jim mentioned that some one is pushing for a Mauser type extractor. Do they understand that the rifle will come apart same as the present competition with excessive pressure if we go to any extractor which breaks the bolt shroud?

11. Has anyone tried a floating wedge in the front of the present 700 trigger as an additional element to the safety? It would be operated and governed in position by a relatively long slot in the present safety arm on the exterior of the housing. The wedging action would hold it in position until the very last movement of the safety to the "off" position. It might be pushed to the "on" position by a light spring or by the final movement of the safety arm to the "on" position.

If I think of anything more I will call.

Sincerely,

M. H. Walker
M. H. Walker

G-48

DON'T SAY IT — WRITE IT

To A.A. HUGICKDate 1-5-79From C.I. SWEETM/700 CLASSIC PILOT LINE FIELD CYCLE TEST (243 CAL.)SUBJECT: BOLT LUBRICATIONWEATHER: 90° F - WINDY - LIGHT SNOW

Extremely hard bolt lift was experienced during Field Cycle Testing of the M/700 Classic Pilot Rifles. After one quarter of the test was shot (50 rds.), shooters found it difficult to lift the bolt handle to unlock the bolt. One gun was so severe, the bolt handle could not be lifted unless the gun was held between the legs, and the bolt handle was lifted by using both hands (One hand on the stock pulling down on the gun, and one hand on the bolt handle pulling up) Hard bolt lift was experienced after every fired round. A check was made by dry firing the guns. Hard bolt lift was evident, but not as severe as it was in live fire.

The bolts were then removed and inspected. The bolts had been lubricated with Molykote G-N Paste before testing. Small metal particles were noticed in the paste caused by the failure of the lubricant. The bolts were then cleaned and sprayed with WD-40 lubricant. The areas sprayed were the Cam Surface and the locking lugs. The bolts were then reassembled in the bolts and the test was completed (150 rds.). The bolts functioned well after lubrication with the WD-40.

The Molykote G-N Paste had hardened in the cold, which gummed up the bolt causing hard bolt lift.

THIS WAS APPLIED IN THE LAB JUST PRIOR
TO THE FIELD TESTS.

CJS:js

PLAINTIFF'S
EXHIBIT

3156

DON'T BE SORRY — BE SAFE

1/23
AL 0028926

REMINGTON ARMS COMPANY, INC.

INTERDEPARTMENTAL CORRESPONDENCE

Remington

REMINGTON

Pettis

PETTIS

Distribution: C.B. Workman
C.E. Ritchie

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

RESEARCH TEST and MEASUREMENT REPORT - Report No. 82 0331

Lubricant Evaluation: M700 Cock and Fire Simulation

Prepared by: Fred Supry

Date Prepared: 3-22-82

Proofread and Cleared By:

J.H. Hemmings, R.E. Nightingale,
Foreman-Test Lab/ Foreman-Measurement Lab

Signature

Date

C.E. Ritchie,
Sr. Supervisor - Testing,
Meas. & Mech. Analysis Lab

Signature

Date

2723
AL 0029379

A

TEST & MEASUREMENT LAB REPORT

REPORT NUMBER: 82 0331
REPORT TITLE: Lubricant Evaluation: M700 Cock and Fire Simulation
MODEL(S): 700
GAUGE OR CALIBER: 30.06
DATE: 3-22-82
WORK ORDER NO.: C-1803-000
PART NAME:
DESIGNER/ENGINEER:

TEST TYPE:

1. PHOTO LAB
2. STRENGTH TEST - NO. OF GUNS TESTED _____
3. FUNCTION TEST - NO. OF GUNS TESTED _____
4. ACCURACY TEST - NO. OF GUNS TESTED _____
5. MEASUREMENTS - TYPE: Static
6. ENVIRONMENTAL TEST
7. AMMUNITION TESTING & EVALUATION - TYPE: _____
8. VISUAL EVALUATION - _____ OUT OF _____ GUN SAMPLE
9. ENDURANCE - NO. OF GUNS TESTED: _____

NO. OF ROUNDS PER GUN: _____

TOTAL ROUNDS FIRED IN TEST: _____

AMMO TYPE: MACS _____ TARGET: _____

RIM FIRE _____ CENTER FIRE _____

10. DRY CYCLE - NO. OF SAMPLES TESTED 5 - each lubricant
MAX. NO. OF CYCLES 25000

3023
AL 0029380

REMINGTON ARMS COMPANY, INC.
Firearms Research Division

April 13, 1982

TO: J.H. Hennings
FROM: F.L. Supry
REPORT TITLE: Evaluation of Lubricants on Firearms M700 Cock and Fire Simulation

ABSTRACT

C.E. Ritchie requested that the Test Lab conduct a cock and fire evaluation on five spray lubricants.

1. Du Pont - Synthetic Diester
2. Krylon - Ten - 4
3. Sprayon - 711
4. CRC - 3-36
5. Houghton - HLP

These five lubricants were selected for evaluation from the results of a preliminary evaluation conducted by A.B. Hughes, Senior Consultant, ESD Maintenance Engineering Group, Du Pont. A copy of his evaluation for each of the five lubricants is located in Appendix "C".

Engineering Dept.

SCOPE OF TEST

To compare the five lubricants in a Model 700 cock and fire simulation test.

TEST RESULTS

In their order of finish, from the best performing lubricant to the poorest performing lubricant, the following results were obtained.

<u>LUBRICANT</u>	<u>AVERAGE CYCLE LIFE (5 Samples)</u>
1. Du Pont - Synthetic Diester	21,181 cys.
2. Sprayon - 711	17,646 cys.
3. CRC - 3-36	14,382 cys.
4. Houghton - HLP	8,333 cys.
5. Krylon - Ten-4	2,830 cys.

REPORT TEXT

A. Trigger pull, sear lift, sear engagement, safe on, safe off, and bolt lift measurements were taken on each test vehicle at the start of the test, and at 5000 cycle intervals. Remington specifications for the M700 components used are:

- | | |
|---------------------|-------------------|
| • Trigger Pull | 3½ lbs. - 6½ lbs. |
| • Sear Lift | .005" - .018" |
| • Sear Engagement | .015" - .020" |
| • Safe "On" - "Off" | None Established |
| • Bolt Lift | None Established |

Refer to Appendix "A", data sheets No. 1 through No. 5, for individual results.

The Rc hardness was measured, at the cocking cam area, on each M700 bolt. Remington specifications Rc 37-46.

Refer to Appendix "A", data sheet No. 6, for individual hardness, lubricant used, simulator used and cycles completed.

A graphical analysis comparing the lubricants tested to their cycle life, and their cycle life to the simulator used is found in Appendix "B".

2. Lubrication Procedure - continued

- c. All other lubrication points were lubricated by holding the aerosol can approximately six inches away from the area to be lubricated and covering the area until a thin layer of lubricant forms on the surface. Duration of spray; approximately 1 second.

C. Pictorial Presentation

1. Lubrication points and procedures.
2. Cocking cam, sear face, and ~~striker~~ radius and track areas were photographed at the start and completion of the test and are available on request.

ALEXIS CH

APPENDIX A
(Data Sheets)

7023

		TRIGGER	SEAR	SEAR	SAFE	SAFE	BOLT + LIFT	
		PULL	LIFT	ENGAGEMENT	ON	OFF	LOCKED	FIRE
REM - SPENS		34.6 ± 1.6	.005"-.008"	.015"-.020"	(165)	(165)	(165)	(165)
1 - DUPONT		(AVG. OF 3)			(AVG. OF 3)	(AVG. OF 3)	(AVG. OF 3)	(AVG. OF 3)
2 - 711								
3 - CRC								
4 - HLP								
5 - Ten 4								
0		6.25	.005	.020	7.5	6.50	3.00	7.00
cycles	2	6.50	.006	.015	6.75	4.25	2.00	6.50
	3	5.50	.005	.016	5.25	4.25	3.00	6.00
	4	6.00	.008	.017	7.00	5.75	3.00	6.50
	5	6.50	.008	.016	6.75	4.50	4.50	7.50
	1	6.00	.0055	.020	5.50	4.00	2.50	6.50
5000 cycles	2	6.00	.0065	.0175	6.00	5.50	2.50	6.50
	3	6.00	.006	.020	6.00	4.50	2.00	6.00
	4	5.75	.010	.017	7.50	5.00	3.00	7.25
	* 5	6.50	.010	.020	7.25	5.50	5.00	9.00
	1	5.75	.008	.020	5.75	4.0	2.25	7.00
10,000 cycles	* 2	5.75	.008	.018	5.25	3.75	2.50	10.50
	3	5.25	.008	.022	4.50	3.75	2.01	7.00
	4	6.25	.0095	.019	7.25	4.75	3.01	13.00
	5	—	—	—	—	—	—	—
	1	6.00	.009	.0205	6.00	4.00	2.00	8.50
15,000 cycles	2	—	—	—	—	—	—	—
	3	5.50	.009	.024	5.00	5.50	2.00	8.50
	* 4	6.00	.0105	.019	6.50	4.50	3.00	18.00
	5	—	—	—	—	—	—	—
	* 1	6.00	.0095	.021	6.00	4.00	2.00	8.00
20,000 cycles	2	—	—	—	—	—	—	—
	* 3	5.50	.0105	.027	4.50	4.00	2.00	9.00
	4	—	—	—	—	—	—	—
	5	—	—	—	—	—	—	—
	1	—	—	—	—	—	—	—
25,000 cycles	2	—	—	—	—	—	—	—
	3	—	—	—	—	—	—	—
	4	—	—	—	—	—	—	—
	5	—	—	—	—	—	—	—
	* 1	FAILED	15594	CYCLES				
* 2	FAILED	6226	cycles					
* 3	FAILED	18359	cycles					
* 4	FAILED	10400	cycles					
* 5	FAILED	1990	cycles					
								DATA SHEET 1

DATA SHEET 11

FLS

LUBRICANT EVALUATION

4-8-42

SECOND SAMPLE OF EACH LUBRICANT

		1	2	3	4	5	6
		TRIGGER	SEAR	SEAR	SAFE	SAFE	BOLT-LIFT
		PULL	LIFT	ENGAGEMENT	ON	OFF	CRACKED
							FILED
REMISAEZS		3 1/2 - 6 1/2 lbs	.005"-.018"	.015"-.020"	(1bs)	(1bs)	(1bs)
1	DUPONT	(AVG OF 3)			(AVG OF 3)	(AVG OF 3)	(AVG OF 3)
2	718						
3	188						
4	HLP						
5	TEN 4						
	1	6.00	.009	.0185	6.00	4.50	4.00
	2	5.00	.006	.018	7.50	4.75	3.00
cycles	3	6.00	.012	.012	7.00	4.50	3.00
	4	6.75	.0095	.016	7.50	6.75	2.50
	5	5.50	.008	.016	7.50	5.50	3.50
5000	1	5.25	.0095	.0215	6.00	4.50	3.50
cycles	2	5.00	.0065	.019	5.75	4.00	3.50
	3	5.75	.013	.020	5.00	4.00	3.00
	4	6.25	.0095	.020	6.75	6.25	2.50
	* 5	5.00	.009	.020	5.75	4.00	3.50
10,000	1	5.50	.011	.025	5.75	4.25	3.50
cycles	2	4.75	.0065	.019	5.25	4.00	2.50
	* 3	6.00	.013	.023	6.25	3.75	3.00
	* 4	6.00	.0095	.021	6.50	5.75	3.00
	5	-	-	-	-	-	-
15,000	1	5.50	.011	.026	5.50	4.25	4.00
cycles	2	4.75	.0075	.019	5.00	4.00	3.00
	3	-	-	-	-	-	-
	4	-	-	-	-	-	-
	5	-	-	-	-	-	-
20,000	1	5.50	.011	.0265	5.50	4.00	4.00
cycles	2	4.75	.009	.019	5.25	4.50	3.00
	3	-	-	-	-	-	-
	4	-	-	-	-	-	-
	5	-	-	-	-	-	-
25,000	* 1	5.25	.011	.0285	5.50	3.75	4.00
cycles	* 2	4.50	.0095	.021	5.25	4.00	2.50
	3	-	-	-	-	-	-
	4	-	-	-	-	-	-
	5	-	-	-	-	-	-
	* 1	COMPLETED	25,000	cycles			
	* 2	COMPLETED	25,000	cycles			
	* 3	FAILED	8317	cycles			
	* 4	FAILED	6115	cycles			
	* 5	FAILED	2788	cycles			

DATA SHEET 2

9823
AL 0029387

LUBRICANT EVALUATION

3-8-82

THIRD SAMPLE OF EACH LUBRICANT

		TRIGGER	SEAR	SEAR	SAFE	SAFE	BOLT - LIFT	
		PULL	LIFT	DISGAGEMENT	ON	OFF	CRACKED	FIRE
		25-60 lbs	.005"-.018"	.015"-.020"	(lbs)	(lbs)	(lbs)	(lbs)
1	DUPONT	(AVG. 0.023)			(AVG. 0.023)	(AVG. 0.023)	(AVG. 0.023)	(AVG. 0.023)
2	TII							
3	ORE							
4	HLP							
5	TEN 4							
6	1	5.75	.007	.015	7.25	4.50	2.50	6.50
7	2	6.00	.008	.015	7.50	7.50	2.50	8.25
8	cycles	3	.009	.017	6.75	5.50	3.00	7.00
9	4	5.75	.0125	.0195	8.00	5.50	3.00	7.00
10	5	5.50	.008	.015	8.00	5.00	2.50	6.00
11	5000	6.25	.009	.019	6.50	4.25	2.00	6.00
12	cycles	2	.009	.021	5.25	7.50	3.50	6.50
13	3	6.25	.0105	.0175	7.25	4.00	3.00	9.00
14	4	5.75	.0125	.021	7.00	5.00	3.00	10.00
15	* 5	5.50	.013	.021	6.00	3.75	2.50	18.00
16	10000	6.00	.010	.020	6.00	3.75	2.00	5.50
17	cycles	2	.009	.021	7.00	6.00	3.50	7.00
18	3	6.00	.015	.0195	6.75	4.75	3.00	10.00
19	* 4	5.75	.0135	.0225	6.50	4.50	3.50	51.00
20	5	—	—	—	—	—	—	—
21	15000	5.25	.0115	.020	5.75	4.00	2.00	6.50
22	cycles	* 2	.0095	.022	6.50	5.50	4.00	14.00
23	* 3	6.50	.015	.0195	6.75	4.00	3.00	15.00
24	4	—	—	—	—	—	—	—
25	5	—	—	—	—	—	—	—
26	20000	5.75	.0115	.020	6.00	4.00	2.00	6.00
27	cycles	2	—	—	—	—	—	—
28	3	—	—	—	—	—	—	—
29	4	—	—	—	—	—	—	—
30	5	—	—	—	—	—	—	—
31	25000	* 1	6.00	.0115	.021	6.35	3.75	2.00
32	cycles	2	—	—	—	—	—	—
33	3	—	—	—	—	—	—	—
34	4	—	—	—	—	—	—	—
35	5	—	—	—	—	—	—	—
36	* 1	COMPLETED	25,000	cycles				
37	* 2	FAILED	15,140	cycles				
38	* 3	FAILED	10,410	cycles				
39	* 4	FAILED	6,788	cycles				
40	* 5	FAILED	2,484	cycles				
DATA SHEET 3								

10723
AL 0029388

		TRIGGER	SEAR	SEAR	SAFE	SAFE	BOLT - LIFT	
		PULL	LIFT	ENGAGEMENT	ON	OFF	INCHES	FEET
		14 - 6 1/2 lbs	.005" - .018"	.015" - .020"	(lbs)	(lbs)	(lbs)	(lbs)
1	D. Pent	(AVG. OF 3)			(AVG. OF 3)	(AVG. OF 3)	(AVG. OF 3)	(AVG. OF 3)
2	Oil							
3	CRC							
4	HLP							
5	TEN 4							
6	1	6.50	.0095	.019	6.75	4.25	4.00	8.00
7	2	6.50	.0108	.019	8.50	5.25	3.50	7.00
8	cycles	3	5.50	.0088	.016	7.25	4.75	3.00
9	4	5.75	.009	.019	8.25	5.50	4.00	7.50
10	5	5.50	.005	.017	9.00	6.75	3.00	7.50
11	5000	1	6.25	.010	.023	6.25	3.25	3.00
12	cycles	2	6.00	.011	.020	7.50	4.25	3.50
13	3	5.50	.0085	.021	7.00	4.50	3.00	8.00
14	4	6.00	.010	.019	7.25	5.00	4.00	10.00
15	* 5	5.75	.010	.0185	7.00	4.75	3.00	16.00
16	10000	1	5.75	.010	.023	5.75	3.50	4.00
17	cycles	2	6.00	.012	.022	7.00	4.00	3.00
18	3	5.50	.0095	.021	6.50	4.25	3.00	8.00
19	* 4	6.00	.010	.021	7.00	5.25	4.00	29.00
20	5	—	—	—	—	—	—	—
21	15000	1	6.25	.0105	.024	5.25	3.00	3.50
22	cycles	2	6.25	.013	.0225	7.50	4.00	3.50
23	* 3	5.50	.0105	.0215	6.75	4.50	3.25	22.00
24	4	—	—	—	—	—	—	—
25	5	—	—	—	—	—	—	—
26	20000	* 1	5.75	.0115	.026	5.75	3.00	3.00
27	cycles	* 2	5.75	.0125	.024	6.50	4.00	4.00
28	3	—	—	—	—	—	—	—
29	4	—	—	—	—	—	—	—
30	5	—	—	—	—	—	—	—
31	25000	1	—	—	—	—	—	—
32	cycles	2	—	—	—	—	—	—
33	3	—	—	—	—	—	—	—
34	4	—	—	—	—	—	—	—
35	5	—	—	—	—	—	—	—
36	* 1	FAILED	19520 cycles					
37	* 2	FAILED	16865 cycles					
38	* 3	FAILED	11820 cycles					
39	* 4	FAILED	8576 cycles					
40	* 5	FAILED	3667 cycles					

DATA SHEET 4

11/23

AL 0029389

M700 COCK & FIRE SIMULATION

FLS

LUBRICANT EVALUATION


3-9-92

FIFTH SAMPLE OF EACH LUBRICANT

			1	2	3	4	5	6
			TRIGGER	SEAR	SEAR	SAFE	SAFE	BOLT - LIFT
			PULL	LIFT	ENGAGEMENT	ON	OFF	COCKED
			3 1/2 - 6 1/2 lbs	.005" - .018"	.015" - .020"	(lbs)	(lbs)	(lbs)
			(AVG OF 3)			(AVG OF 3)	(AVG OF 3)	(AVG OF 3)
1	1	D.Pant						
2	2	711						
3	3	CRC						
4	4	W.P.						
5	5	TEX 4						
6	1		6.00	.0095	.0117	7.00	4.75	2.00
7	2		5.75	.0085	.0155	6.75	5.00	3.50
8	3		5.75	.0105	.0215	6.50	5.00	3.00
9	4		6.25	.012	.016	7.00	4.50	3.00
10	5		6.25	.008	.016	7.25	5.50	3.00
11	1		5.50	.010	.0205	7.50	4.50	2.50
12	2		6.00	.0085	.016	5.75	4.00	4.00
13	3		5.75	.0105	.0215	5.50	4.25	3.00
14	4		6.25	.013	.019	6.50	4.25	4.00
15	*5		6.25	.010	.020	5.75	4.00	3.50
16	1		5.25	.010	.021	7.50	4.00	3.00
17	2		5.50	.010	.018	5.75	3.75	4.00
18	3		5.75	.0105	.0215	5.50	4.25	3.00
19	*4		6.25	.0135	.025	7.25	3.75	4.00
20	5		-	-	-	-	-	-
21	1		5.50	.0105	.021	6.50	4.00	3.00
22	2		5.75	.010	.018	5.75	4.00	3.50
23	3		6.00	.0105	.0215	5.50	4.50	3.00
24	4		-	-	-	-	-	-
25	5		-	-	-	-	-	-
26	1		5.50	.0105	.021	7.00	3.75	3.50
27	2		6.25	.010	.019	5.50	4.00	3.50
28	3		5.75	.0105	.022	5.50	4.25	3.00
29	4		-	-	-	-	-	-
30	5		-	-	-	-	-	-
31	*1		5.00	.0111	.022	7.00	4.00	3.00
32	*2		5.75	.011	.020	5.75	3.75	4.00
33	*3		6.25	.011	.023	5.25	4.00	4.00
34	4		-	-	-	-	-	-
35	5		-	-	-	-	-	-
36	*1	FAILED		20790	cycles			
37	*2	COMPLETED		25000	cycles			
38	*3	COMPLETED		25000	cycles			
39	*4	FAILED		9787	cycles			
40	*5	FAILED		3220	cycles			

DATA SHEET 5

12723
AL 0029390



W 700 ROCK & FIRE SIMULATION
LUBRICANT EVALUATION
1-10-82

RE HARDNESS: MICRO-BOLT COOKING ROOM AREA

REMARKS		HARDNESS		LUBRICANT		SIMULATOR		CYCLES	
REMARKS		HARDNESS		USED		USED		COMPLETED	
BOLT NO. 1									
C1		39		DUPONT		1		15,594	
C9		40		DUPONT		3		25,000	
C12		40		DUPONT		2		25,000	
C19		38		DUPONT		4		19,520	
C20		37		DUPONT		1		20,790	
C3		38		711		3		6,226	
C7		39		711		2		25,000	
C16		39		711		1		15,140	
C27		38		711		2		16,865	
C29		39		711		4		25,000	
C4		39		DUPONT		4		16,359	
C10		39		DUPONT		1		8,317	
C17		40		DUPONT		3		10,410	
C21		39		DUPONT		2		11,830	
C25		39		DUPONT		4		25,000	
C11		39		HLP		4		10,400	
C18		39		HLP		3		6,115	
C24		39		HLP		2		6,788	
C26		39		HLP		1		8,526	
C28		38		HLP		1		9,787	
C2		38		TEN-4		2		1,910	
C5		38		TEN-4		2		2,788	
C6		39		TEN-4		3		2,484	
C8		38		TEN-4		4		3,667	
C13		39		TEN-4		1		3,220	
C22		39		DRY				0	

DATA SHEET 6

13723
AL 0000391


A L E K S I C H

APPENDIX B
(Graphic Presentation)

14/23

AL 0029392

A



SPRAY LUBRICATION EVALUATION M700 COCK & FIRE SIMULATION


C

H

15223

A

SPRAY LUBRICATION EVALUATION - M700 COCK FIRE SIMULATION



H

A
L
E
K
S
I
C
H

APPENDIX C

(Previous Evaluation)

17823

AL 0029395

Test # 20

Product: Du Pont - Synthetic Diester - 20%

Function: Multipurpose, prevents rust
Displaces moisture, dirt and lubricates

Evaluation Notes

1. Odor: Synthetic chemical oily smell, not lasting
2. Feel: Light oily feel
3. Drying Rate: Slow drying
4. Penetration: Rapid penetration and spreading, clear color
5. Surface Wetting: Local wetting, removes oxidation, good cleanup
6. Grease Displacement: Rapid spreading, no dissolving, good cleanup
7. Type Container: 4 oz aerosol, nozzle with straw
8. Liquid Appearance: Watery, light tan
9. Wood-Open Pore: Damp look, no damage
10. Metal Surface: Wet look, no rust within 24 hours
11. Rust Removal: Most rust removed
12. Displace Moisture: Excellent
13. Displace Solids: Excellent
14. Gun Barrel: Excellent
15. Wood Stock: Excellent
16. Rust Prevention:

Test 1 - 7

Test 2 - 7

Avg - 7.0

17. Reason for Elimination: Continue testing

A

Test # 14

Product: Sprayon #711 Penetrant/Lube/Moisturize

Function: Multipurpose, prevents rust
Displaces moisture and lubricates

Evaluation Notes

1. Odor: Strong fly-spray, lasting
2. Feel: Very oily feel
3. Drying Rate: Medium drying rate
4. Penetration: Slow spreading, but continuous, clear color
5. Surface Wetting: Minimum spreading, removes oxidation, bright
6. Grease Displacement: Rapid spread, no dissolving, good cleanup
7. Type Container: 12 oz aerosol, nozzle with straw
8. Liquid Appearance: Very watery, light tan
9. Wood-Open Pore: Damp look, no damage
10. Metal Surface: Oily look, no rust within 24 hours
11. Rust Removal: Some rust removed
12. Displace Moisture: Excellent
13. Displace Solids: Good
14. Gun Barrel: Excellent
15. Wood Stock: Excellent
16. Rust Prevention:

Test 1 - 6

Test 2 - 5

Avg - 5.5

17. Reason for Elimination: Continue testing

H

19823

AL 0029397

Test # 15

Product: CRC - 3-36

Function: Multipurpose, prevents rust
Displaces moisture and lubricates

Evaluation Notes

1. Odor: Pleasant peppermint smell, lasting
2. Feel: Light oily feel
3. Drying Rate: Medium drying rate
4. Penetration: Medium penetrating and spreading, tan color
5. Surface Wetting: Slow spread, removes oxidation, good cleanup
6. Grease Displacement: Rapid spreading, some dissolving, easy cleanup
7. Type Container: 1 oz aerosol, nozzle
8. Liquid Appearance: Watery, light tan
9. Wood-Open Pore: Damp look, no damage
10. Metal Surface: Oily look, no rust within 24 hours
11. Rust Removal: Some rust removed
12. Displace Moisture: Excellent
13. Displace Solids: Good
14. Gun Barrel: Excellent
15. Wood Stock: Excellent
16. Rust Prevention:
 - Test 1 - 4
 - Test 2 - 5
 - Avg - 4.5
17. Reason for Elimination: Continue testing

Test # 11

Product: E. F. Houghton - ELP All Purpose

Function: Multipurpose, prevents rust
displaces moisture, dirt and lubricates

Evaluation Notes

1. Odor: Fly spray smell, not lasting
2. Feel: Oily feel
3. Drying Rate: Rapid drying
4. Penetration: Rapid spreading, med. spreading, tan stain
5. Surface Wetting: Slow spreading, rapid dry to oily film, hard to clean
6. Grease Displacement: Rapid spread, no dissolving, good cleanup
7. Type Container: 12 oz aerosol, nozzle with straw
8. Liquid Appearance: Waxy, dark tan
9. Wood-Open Pore: Damp look, no damage
10. Metal Surface: Oil look, no rust within 24 hours
11. Rust Removal: No rust removal
12. Displace Moisture: Poor
13. Displace Solids: Fair
14. Gun Barrel: Good
15. Wood Stock: Good
16. Rust Prevention:
 - Test 1 - 8
 - Test 2 - 5
 - Avg - 6.5
17. Reason for Elimination: Continue testing

Test # 13

Product: Krylon - Tan 4

Function: Multipurpose, prevents rust
Displaces moisture, gums, dirt and lubricates

Evaluation Notes

1. Odor: Strong fly spray, lasting
2. Feel: Light oily feel
3. Drying Rate: Medium drying rate
4. Penetration: Rapid absorption and spreading, dark tan stain
5. Surface Wetting: Slow spreading, oily appearance, good cleanup
6. Grease Displacement: Rapid spread, no dissolving, good cleanup
7. Type Container: 11 oz aerosol, nozzle with spray
8. Liquid Appearance: Dark tan, watery
9. Wood-Open Pore: Damp look, no damage
10. Metal Surface: Damp look, no rust within 24 hours
11. Rust Removal: Most rust removed
12. Displace Moisture: Good
13. Displace Solids: Good
14. Gun Barrel: Good
15. Wood Stock: Good
16. Rust Prevention:
 - Test 1 - 8
 - Test 2 - 5
 - Avg - 6.5
17. Reason for Elimination: Continue testing

22823

AL 0029400

APPENDIX D

(Pictorial Presentation)

1. Lubrication procedures.
2. Individual components at the start and completion of test.
(Available upon request.)

23023

AL 0029401

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
SUPPORT

DETROIT
MICH

Distribution: C.B. Werkman
C.E. Ritchie

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY" _____

RESEARCH TEST and MEASUREMENT REPORT - Report No. 82 0331

Lubricant Evaluation: M700 Cock and Fire Simulation

Prepared by: Fred Supry

Date Prepared: 3-22-82

Proofread and Cleared By:

J.H. Hemmings, / R.E. Nightingale,
Foreman-Test Lab / Foreman-Measurement Lab

James H. Hemmings 4-14-82
Signature Date

C.E. Ritchie,
Sr. Supervisor - Testing,
Mech. & Mech. Analysis Lab

C. E. Ritchie 4-14-82
Signature Date

PLAINTIFF'S
EXHIBIT

3157

1 of 22

AL 0029379

A

TEST & MEASUREMENT LAB REPORT

REPORT NUMBER: 82 0331
REPORT TITLE: Lubricant Evaluation: M700 Cock and Fire Simulation
MODEL(S): 700
GAUGE OR CALIBER: 30.06
DATE: 3-22-82
WORK ORDER NO.: C-1803-000
PART NAME:
DESIGNER/ENGINEER:

TEST TYPE:

1. PHOTO LAB
2. STRENGTH TEST - NO. OF GUNS TESTED _____
3. FUNCTION TEST - NO. OF GUNS TESTED _____
4. ACCURACY TEST - NO. OF GUNS TESTED _____
5. MEASUREMENTS - TYPE: Static _____
6. ENVIRONMENTAL TEST
7. AMMUNITION TESTING & EVALUATION - TYPE: _____
8. VISUAL EVALUATION - _____ OUT OF _____ GUN SAMPLE
9. ENDURANCE - NO. OF GUNS TESTED: _____
NO. OF ROUNDS PER GUN: _____
TOTAL ROUNDS FIRED IN TEST: _____
AMMO TYPE: MAGS _____ TARGET: _____
RIM FIRE _____ CENTER FIRE _____
10. DRY CYCLE - NO. OF SAMPLES TESTED 5 - each lubricant
MAX. NO. OF CYCLES 25000

2 of 22

AL 0029380

REMINGTON ARMS COMPANY, INC.
Firearms Research Division

April 13, 1982

TO: J.H. Hennings

FROM: F.L. Supry

REPORT TITLE: Evaluation of Lubricants on Firearms M700 Cock and Fire Simulation

ABSTRACT

C.E. Ritchie requested that the Test Lab conduct a cock and fire evaluation on five spray lubricants.

1. Du Pont - Synthetic Diester
2. Krylon - Ten - 4
3. Sprayon - 711
4. CRC - 3-36
5. Houghton - HLP

These five lubricants were selected for evaluation from the results of a preliminary evaluation conducted by A.B. Hughes, Senior Consultant, ESD Maintenance Engineering Group, Du Pont. A copy of his evaluation for each of the five lubricants is located in Appendix "C".

Engineering Dept.

SCOPE OF TEST

To compare the five lubricants in a Model 700 cock and fire simulation test.

TEST RESULTS

In their order of finish, from the best performing lubricant to the poorest performing lubricant, the following results were obtained.

LUBRICANT

AVERAGE CYCLE LIFE (5 Samples)

1. Du Pont - Synthetic Diester
2. Sprayon - 711
3. CRC - 3-36
4. Houghton - HLP
5. Krylon - Ten-4

21,181 cys.
17,646 cys.
14,382 cys.
8,333 cys.
2,830 cys.

H

3 of 22

REPORT TEXT

A. Trigger pull, sear lift, sear engagement, safe on, safe off, and bolt lift measurements were taken on each test vehicle at the start of the test, and at 5000 cycle intervals. Remington specifications for the M700 components used are:

- | | |
|---------------------|-------------------|
| • Trigger Pull | 3½ lbs. - 6½ lbs. |
| • Sear Lift | .005" - .018" |
| • Sear Engagement | .015" - .020" |
| • Safe "On" - "Off" | None Established |
| • Bolt Lift | None Established |

Refer to Appendix "A", data sheets No. 1 through No. 5, for individual results.

The Rc hardness was measured, at the cooking cam area, on each M700 bolt. Remington specifications Rc 37-46.

Refer to Appendix "A", data sheet No. 6 for individual hardness, lubricant used, simulator used and cycles completed.

A graphical analysis comparing the lubricants tested to their cycle life, and their cycle life to the simulator used is found in Appendix "B".

TEST PROCEDURE

A. Measurements

1. Trigger Pull
Trigger Pull measurements were conducted using a Chatillon Model IN-10 pull scale.
2. Sear Lift and Sear Engagement
Sear lift and sear engagement measurements were conducted using a Model FC-14 optical comparator and measuring machine.
3. Safe "ON" and "OFF" Forces.
Safe On and Off forces were taken using a Chatillon Model DPP-25, push-pull scale.
4. Bolt Lift
Bolt lift forces, both cocked and fired, were taken utilizing a Chatillon Model 80D pull scale mounted on a machine designed to be used for bolt lift measurements.
5. Rc Hardness
The Rc hardness measurements were taken by George Catta, a production inspector, utilizing a Wilson Rockwell Hardness Tester.

B. Lubrication -- (Pictorial presentation - Appendix "D")

1. Lubrication Points
 - a. Receiver: Locking lug area.
Track on receiver tang.
 - b. Bolt: Cocking cam
Locking lugs
 - c. Firing Pin: Threads
Striker radius and track.
 - d. Trigger Assembly: Sear safety cam face.
Interior of trigger assembly, through sear inspection hole.
2. Lubrication procedure
 - a. Components to be lubricated were completely degreased, using the solvent degreasing tanks located in our Heat Treat Department.
 - b. The interior of the trigger assembly was lubricated by holding the spray can to direct the spray into the sear inspection hole. Duration of spray approximately 1 second.

NOTE: The two position nozzle on Du Pont aerosol can was more difficult to control for pin point application, than the standard plastic tubes on the other samples. (Pictorial example included.)

ALEXISCH

APPENDIX A

(Data Sheets)

FIRST SAMPLE OF EACH LUBRICANT

		1	2	3	4	5	6
		TRIGGER	SEAR	SEAR	SAFE	SAFE	BOLT + LIFT
		DULL	LIFT	ENGAGEMENT	ON	OFF	RELEASED
							FIRE
REM - SPEEDS →		37.67 lbs	.005"-.008"	.015"-.020"	(lbs)	(lbs)	(lbs)
1	1 - DUPONT	(AVG OF 3)			(AVG OF 3)	(AVG OF 3)	(AVG OF 3)
2	2 - 711						
3	3 - CRC						
4	4 - HLP						
5	5 - Ten 4						
6	1	6.25	.005	.020	7.5	6.50	3.00
7	2	6.50	.006	.015	6.75	4.25	2.00
8	3	5.50	.005	.016	5.25	4.25	3.00
9	4	6.00	.008	.017	7.00	5.75	3.00
10	5	6.50	.008	.016	6.75	4.50	4.50
11	1	6.00	.0055	.020	5.50	4.00	2.50
12	2	6.00	.0065	.0175	6.00	5.50	2.50
13	3	6.00	.006	.020	6.00	4.50	2.00
14	4	5.75	.010	.017	7.50	5.00	3.00
15	* 5	6.50	.010	.020	7.25	5.50	5.00
16	1	5.75	.008	.020	5.75	4.0	2.25
17	* 2	5.75	.008	.018	5.25	3.75	2.50
18	3	5.25	.008	.022	4.50	3.75	2.0
19	4	6.25	.0095	.019	7.25	4.75	3.0
20	5	—	—	—	—	—	—
21	1	6.00	.009	.0205	6.00	4.00	2.00
22	2	—	—	—	—	—	—
23	3	5.50	.009	.024	5.00	5.50	2.00
24	* 4	6.00	.0105	.019	6.50	4.50	3.00
25	5	—	—	—	—	—	—
26	* 1	6.00	.0095	.021	6.00	4.00	2.00
27	2	—	—	—	—	—	—
28	* 3	5.50	.0105	.027	4.50	4.00	2.00
29	4	—	—	—	—	—	—
30	5	—	—	—	—	—	—
31	1	—	—	—	—	—	—
32	2	—	—	—	—	—	—
33	3	—	—	—	—	—	—
34	4	—	—	—	—	—	—
35	5	—	—	—	—	—	—
36	* 1	FAILED	15.594	cycles			
37	* 2	FAILED	6.226	cycles			
38	* 3	FAILED	16.359	cycles			
39	* 4	FAILED	10.400	cycles			
40	* 5	FAILED	1990	cycles			
DATA SHEET							

M700

COCK & FIRE SIMULATION

FLS

LUBRICANT EVALUATION

3-8-82

SECOND SAMPLE OF EACH LUBRICANT

		TRIGGER	SEAR	SEAR	SAFE	SAFE	BOLT-LIFT	
		PULL	LIFT	ENGAGEMENT	ON	OFF	COCKED	FIRE
	REMISAECS	3 1/2 - 6 1/2 lbs	.005"-.018"	.015"-.020"	(165)	(165)	(165)	(165)
1	1	DUPONT (AVG. OF 3)			(AVG. OF 3)	(AVG. OF 3)	(AVG. OF 3)	(AVG. OF 3)
2	2	711						
3	3	188						
4	4	HLP						
5	5	TEN 4						
6	1	6.00	.009	.0185	6.00	4.50	4.00	8.00
7	2	5.00	.006	.018	7.50	4.75	3.00	6.00
8	3	6.00	.012	.012	7.00	4.50	3.00	7.00
9	4	6.75	.0095	.016	7.50	6.75	2.50	7.00
10	5	5.50	.008	.016	7.50	5.50	3.50	7.00
11	5000	5.25	.0095	.0215	6.00	4.50	3.50	7.00
12	cycles	2	5.00	.0065	.019	5.75	4.00	3.50
13	3	5.75	.013	.020	5.00	4.00	3.00	8.00
14	4	6.25	.0095	.020	6.75	6.25	2.50	8.00
15	* 5	5.00	.009	.020	5.75	4.00	3.50	13.00
16	10,000	5.50	.011	.025	5.75	4.25	3.50	7.00
17	cycles	2	4.75	.0065	.019	5.25	4.00	2.50
18	* 3	6.00	.013	.023	6.25	3.75	3.00	15.00
19	* 4	6.00	.0095	.021	6.50	5.75	3.00	25.00
20	5	-	-	-	-	-	-	-
21	15,000	5.50	.011	.026	5.50	4.25	4.00	7.25
22	cycles	2	4.75	.0075	.019	5.00	4.00	3.00
23	3	-	-	-	-	-	-	-
24	4	-	-	-	-	-	-	-
25	5	-	-	-	-	-	-	-
26	20,000	5.50	.011	.0265	5.50	4.00	4.00	9.25
27	cycles	2	4.75	.009	.019	5.25	4.50	3.00
28	3	-	-	-	-	-	-	-
29	4	-	-	-	-	-	-	-
30	5	-	-	-	-	-	-	-
31	25,000	* 1	5.25	.011	.0285	5.50	3.75	4.00
32	cycles	* 2	4.50	.0095	.021	5.25	4.00	2.50
33	3	-	-	-	-	-	-	-
34	4	-	-	-	-	-	-	-
35	5	-	-	-	-	-	-	-
36	* 1	COMPLETED	25,000	cycles				
37	* 2	COMPLETED	25,000	cycles				
38	* 3	FAILED	8317	cycles				
39	* 4	FAILED	6115	cycles				
40	* 5	FAILED	2788	cycles				

DATA SHEET 2

M700 COCK & FIRE SIMULATION

F.L.S.

LUBRICANT EVALUATION

3-8-82

THIRD SAMPLE OF EACH LUBRICANT

		1		2		3		4		5		6	
		TRIGGER	SEAR	SEAR	SAFE	SAFE	SAFE	SAFE	SAFE	BOLT -	LIFT		
		PULL	LIFT	ENGAGEMENT	ON	OFF	COCKED	FIRED					
		25-65 lbs	.005-.018"	.015-.020"	(lbs)	(lbs)	(lbs)	(lbs)					
		(AVG OF 3)			(AVG OF 3)	(AVG OF 3)	(AVG OF 3)	(AVG OF 3)					
1	1	DUPONT											
2	2	TII											
3	3	ORC											
4	4	HLP											
5	5	TEN 4											
6	1		5.75	.007	.015	7.25	4.50	2.50	6.50				
7	2		6.00	.008	.015	7.50	7.50	2.50	8.25				
8	3		6.25	.008	.017	6.75	5.50	3.00	7.00				
9	4		5.75	.0125	.0195	8.00	5.50	3.00	7.00				
10	5		5.50	.008	.015	8.00	5.00	2.50	6.00				
11	1	5000	6.25	.009	.019	6.50	4.25	2.00	6.00				
12	2	cycles	5.25	.009	.021	5.25	7.50	3.50	6.50				
13	3		6.25	.0105	.0175	7.25	4.00	3.00	9.00				
14	4		5.75	.0125	.021	7.00	5.00	3.00	10.00				
15	*5		5.50	.013	.021	6.00	3.75	2.50	18.00				
16	1	10000	6.00	.010	.020	6.00	3.75	2.00	5.50				
17	2	cycles	5.25	.009	.021	7.00	6.00	3.50	7.00				
18	3		6.00	.015	.0195	6.75	4.75	3.00	10.00				
19	*4		5.75	.0125	.0225	6.50	4.50	3.50	51.00				
20	5		—	—	—	—	—	—	—				
21	1	15000	5.25	.0115	.020	5.75	4.00	2.00	6.50				
22	*2	cycles	5.50	.0095	.022	6.50	5.50	4.00	14.00				
23	*3		6.50	.015	.0195	6.75	4.00	3.00	15.00				
24	4		—	—	—	—	—	—	—				
25	5		—	—	—	—	—	—	—				
26	1	20000	5.75	.0115	.020	6.00	4.00	2.00	6.00				
27	2	cycles	—	—	—	—	—	—	—				
28	3		—	—	—	—	—	—	—				
29	4		—	—	—	—	—	—	—				
30	5		—	—	—	—	—	—	—				
31	*1	25000	6.00	.0115	.021	6.25	3.75	2.00	12.00				
32	2	cycles	—	—	—	—	—	—	—				
33	3		—	—	—	—	—	—	—				
34	4		—	—	—	—	—	—	—				
35	5		—	—	—	—	—	—	—				
36	*1	COMPLETED	25,000	cycles									
37	*2	FAILED	15,140	cycles									
38	*3	FAILED	10,410	cycles									
39	*4	FAILED	6788	cycles									
40	*5	FAILED	2484	cycles									

DATA SHEET 3

 9 of 22
 AL 0029388

M700 COCK & FIRE SIMULATION

FLS.

LUBRICANT EVALUATION

3-8-92

FOURTH SAMPLE OF EACH LUBRICANT

		TRIGGER	SEAR	SEAR	SAFE	SAFE	BOLT - LIFT	
							WHEEL	Fired
		PULL	LIFT	ENGAGEMENT	ON	OFF	(lbs)	(lbs)
		14.6 ± lbs	.005" - .018"	.015" - .020"	(lbs)	(lbs)	(lbs)	(lbs)
1	1	0.000	(AVG. OF 3)		(AVG. OF 3)	(AVG. OF 3)	(AVG. OF 3)	(AVG. OF 3)
2	2	0.000						
3	3	0.000						
4	4	0.000						
5	5	0.000						
6	1	6.50	.0095	.019	6.75	4.25	4.00	8.00
7	2	6.50	.008	.019	8.50	5.25	3.50	7.00
8	3	5.50	.008	.016	7.25	4.75	3.00	9.00
9	4	5.75	.009	.019	8.25	5.50	4.00	7.50
10	5	5.50	.005	.017	9.00	6.75	3.00	7.50
11	1	6.25	.010	.023	6.25	3.25	3.00	8.00
12	2	6.00	.011	.020	7.50	4.25	3.50	7.00
13	3	5.50	.0085	.021	7.00	4.50	3.00	8.00
14	4	6.00	.010	.019	7.25	5.00	4.00	10.00
15	* 5	5.75	.010	.0185	7.00	4.75	3.00	16.00
16	1	5.75	.010	.023	5.75	3.50	4.00	8.00
17	2	6.00	.012	.022	7.00	4.00	3.00	8.00
18	3	5.50	.0085	.021	6.50	4.25	3.00	8.00
19	* 4	6.00	.010	.021	7.00	5.25	4.00	29.00
20	5	—	—	—	—	—	—	—
21	1	6.25	.0105	.024	5.25	3.00	3.50	9.00
22	2	6.25	.013	.0225	7.50	4.00	3.50	9.00
23	* 3	5.50	.0105	.0215	6.75	4.50	3.25	22.00
24	4	—	—	—	—	—	—	—
25	5	—	—	—	—	—	—	—
26	* 1	5.75	.0115	.026	5.75	3.00	3.00	24.00
27	* 2	5.75	.0125	.024	6.50	4.00	4.00	24.00
28	3	—	—	—	—	—	—	—
29	4	—	—	—	—	—	—	—
30	5	—	—	—	—	—	—	—
31	1	—	—	—	—	—	—	—
32	2	—	—	—	—	—	—	—
33	3	—	—	—	—	—	—	—
34	4	—	—	—	—	—	—	—
35	5	—	—	—	—	—	—	—
36	* 1	FAILED	19520 cycles					
37	* 2	FAILED	16865 cycles					
38	* 3	FAILED	11820 cycles					
39	* 4	FAILED	8576 cycles					
40	* 5	FAILED	3667 cycles					

DATA SHEET 4

10 of 22

AL 0029389

FIFTH SAMPLE OF EACH LUBRICANT

		1	2	3	4	5	6
		TRIGGER	SEAR	SEAR	SAFE	SAFE	BOLT + LIFT
		PULL	LIFT	ENGAGEMENT	ON	OFF	COCKED FIRED
		21-64 lbs	.005"-.008"	.015"-.020"	(lbs)	(lbs)	(lbs) (lbs)
1	1 Dupont	(Average)			(Average)	(Average)	(Average)
2	2 711						
3	3 CRC						
4	4 W.P.						
5	5 TEN 4						
6	1	6.00	.0095	.0117	7.00	4.75	2.00 7.00
7	2	5.75	.0085	.0155	6.75	5.00	3.50 7.00
8	3 cycles	5.75	.0105	.0215	6.50	5.00	3.00 9.00
9	4	6.25	.012	.016	7.00	4.50	3.00 8.00
10	5	6.25	.008	.018	7.25	5.50	3.00 6.50
11	1000	5.50	.010	.0205	7.50	4.50	2.50 7.00
12	2 cycles	6.00	.0085	.016	5.75	4.00	4.00 8.00
13	3	5.75	.0125	.0215	5.50	4.25	3.00 8.00
14	4	6.25	.013	.019	6.50	4.25	4.00 7.50
15	*5	6.25	.010	.020	5.75	4.00	3.50 18.00
16	10000	5.25	.010	.021	7.50	4.00	3.00 8.00
17	2 cycles	5.50	.010	.018	5.75	3.75	4.00 7.50
18	3	5.75	.0105	.0215	6.50	4.25	3.00 7.50
19	*4	6.25	.0135	.025	7.25	3.75	4.00 27.00
20	5	—	—	—	—	—	—
21	15000	5.50	.0105	.021	6.50	4.00	3.00 8.00
22	2 cycles	5.75	.010	.018	5.75	4.00	3.50 7.50
23	3	6.00	.0105	.0215	5.50	4.50	3.00 7.00
24	4	—	—	—	—	—	—
25	5	—	—	—	—	—	—
26	20000	5.50	.0105	.021	7.00	3.75	3.50 14.00
27	2 cycles	6.25	.010	.019	5.50	4.00	3.50 9.00
28	3	5.75	.0105	.022	5.50	4.25	3.00 11.00
29	4	—	—	—	—	—	—
30	5	—	—	—	—	—	—
31	25000	*1	5.00	.011	.022	7.00	4.00 3.00 28.00
32	2 cycles	*2	5.75	.011	.020	5.75	3.75 4.00 12.00
33	*3	6.25	.011	.023	5.25	4.00	4.00 15.00
34	4	—	—	—	—	—	—
35	5	—	—	—	—	—	—
36	*1	FAILED	20790	cycles			
37	*2	COMPLETED	25000	cycles			
38	*3	COMPLETED	25000	cycles			
39	*4	FAILED	7787	cycles			
40	*5	FAILED	3220	cycles			

DATA SHEET 5

1000 INCHES
 M 700 COCK & FIRE SIMULATION
 LUBRICANT EVALUATION
 R_c HARDNESS: M700 BOLT COCKING CAM AREA
 3-10-82


REMARKS	R _c	HARDNESS	LUBRICANT		CYCLES
			USED	USED	
1					
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					

12 of 22
 AL 0029391

A
L
E
K
S
I
C
H

APPENDIX B
(Graphic Presentation)

A




SPRAY Lubrication EVALUATION: M700 COCK & FIRE SIMULATION

14 of 22

AL 0029393

A

SPRAY LUBRICATION EVALUATION - M700 LOCK FIRE SIMULATION



15822
AL 0029394

A L E K S I C H

APPENDIX C

(Previous Evaluation)

Test # 20

Product: Du Pont - Synthetic Diester - 20%

Function: Multipurpose, prevents rust
Displaces moisture, dirt and lubricates

Evaluation Notes

1. Odor: Synthetic chemical oily smell, not lasting
2. Feel: Light oily feel
3. Drying Rate: ~~slow drying~~
4. Penetration: Rapid penetration and spreading, clear color
5. Surface Wetting: Local wetting, removes oxidation, good cleanup
6. Grease Displacement: Rapid spreading, no dissolving, good cleanup
7. Type Container: 4 oz aerosol, nozzle with straw
8. Liquid Appearance: Watery, light tan
9. Wood-Open Pore: Damp look, no damage
10. Metal Surface: Wet look, no rust within 24 hours
11. Rust Removal: Most rust removed
12. Displace Moisture: Excellent
13. Displace Solids: Excellent
14. Gun Barrel: Excellent
15. Wood Stock: Excellent
16. Rust Prevention:

Test 1 - 7

Test 2 - 7

Avg - 7.0

17. Reason for Elimination: Continue testing

17 of 22

AL 0029396

Test # 14

Product: Sprayon 4711 Penetrant/Lube/Moisturize

Function: Multipurpose, prevents rust
Displaces moisture and lubricates

Evaluation Notes

1. Odor: Strong fly spray, lasting
2. Feel: Very oily feel
3. Drying Rate: Medium drying rate
4. Penetration: Slow spreading, but continuous, clear color
5. Surface Wetting: Minimum spreading, removes oxidation, bright
6. Grease Displacement: Rapid spread, no dissolving, good cleanup
7. Type Container: 12 oz aerosol, nozzle with straw
8. Liquid Appearance: Very watery, light tan
9. Wood-Open Pore: Damp look, no damage
10. Metal Surface: Oily look, no rust within 24 hours
11. Rust Removal: Some rust removed
12. Displace Moisture: Excellent
13. Displace Solids: Good
14. Gun Barrel: Excellent
15. Wood Stock: Excellent
16. Rust Prevention:

Test 1 - 6

Test 2 - 5

Avg - 5.5

17. Reason for Elimination: Continue testing

18 of 22

AL 0029397

A

Test # 15

Product: CRC - 2-36

Function: Multipurpose, prevents rust
Displaces moisture and lubricates

Evaluation Notes

1. Odor: Pleasant peppermint smell, lasting
2. Feel: Light oily feel
3. Drying Rate: Medium drying rate
4. Penetration: Medium penetrating and spreading, tan color
5. Surface Wetting: Slow spread, removes oxidation, good cleanup
6. Grease Displacement: Rapid spreading, some dissolving, easy cleanup
7. Type Container: 1 oz aerosol, nozzle
8. Liquid Appearance: Watery, light tan
9. Wood-Open Pore: Damp look, no damage
10. Metal Surface: Oily look, no rust within 24 hours
11. Rust Removal: Some rust removed
12. Displace Moisture: Excellent
13. Displace Solids: Good
14. Gun Barrel: Excellent
15. Wood Stock: Excellent
16. Rust Prevention:
 - Test 1 - 4
 - Test 2 - 5
 - Avg - 4.5
17. Reason for Elimination: Continue testing

19 of 22

AL 0029398

Test # 11

Product: E. P. Houghton - ELP All Purpose

Function: Multipurpose, prevents rust
Displaces moisture, dirt and lubricates

Evaluation Notes

1. Odor: Fly spray smell, not lasting
2. Feel: Oily feel
3. Drying Rate: Rapid drying
4. Penetration: Rapid spreading, med. spreading, tan stain
5. Surface Wetting: Slow spreading, rapid dry to oily film, hard to clean
6. Grease Displacement: Rapid spread, no dissolving, good cleanup
7. Type Container: 12 oz aerosol, nozzle with straw
8. Liquid Appearance: Waxy, dark tan
9. Wood-Open Pore: Damp look, no damage
10. Metal Surface: Oil look, no rust within 24 hours
11. Rust Removal: No rust removal
12. Displace Moisture: Poor
13. Displace Solids: Fair
14. Gun Barrel: Good
15. Wood Stock: Good
16. Rust Prevention:
 - Test 1 - 8
 - Test 2 - 5
 - Avg - 6.5
17. Reason for Elimination: Continue testing

20 of 22

AL 0029399

Test # 13

Product: Krylon - Tan 4

Function: Multipurpose, prevents rust
Displaces moisture, gums, dirt and lubricates

Evaluation Notes

1. Odor: Strong fly spray, lasting
2. Feel: Light oily feel
3. Drying Rate: Medium drying rate
4. Penetration: Rapid absorption and spreading, dark tan stain
5. Surface Wetting: Slow spreading, oily appearance, good cleanup
6. Grease Displacement: Rapid spread, no dissolving, good cleanup
7. Type Container: 11 oz aerosol, nozzle with spray
8. Liquid Appearance: Dark tan, watery
9. Wood-Open Pore: Damp look, no damage
10. Metal Surface: Damp look, no rust within 24 hours
11. Rust Removal: Most rust removed
12. Displace Moisture: Good
13. Displace Solids: Good
14. Gun Barrel: Good
15. Wood Stack: Good
16. Rust Prevention:
 - Test 1 - 8
 - Test 2 - 5
 - Avg - 6.5
17. Reason for Elimination: Continue testing

21 of 22

A
L
E
K
S
I
C
H

APPENDIX D
(Pictorial Presentation)

1. Lubrication procedures.
2. Individual components at the start and completion of test.
(Available upon request.)

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington



PETERS



"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

XC: L. R. Blackhurst	R. L. Joy
L. B. Mosquet	H. C. Munson
H. K. Boyle	C. O. Pardee
J. W. Brooks	D. I. Roark
J. J. Burns	D. J. Sanita
G. D. Campbell	J. R. Snedeker
J. H. Carter	W. C. VanSickle
W. W. Cook	W. A. Warren
G. E. Fletcher	E. G. Wilke
W. L. Ganey	<u>C. B. Workman</u>
M. C. Hardy	

March 5, 1982

J. P. LINDE

M/700 BOLT LOCK CHANGE
BOLT WILL OPEN WITH SAFE ON

Production change over has started as of February 26, 1982.
Guns are being marked as follows:

- All guns stamped with Final Inspection code AC or later.
- Approximate Serial Number changeover of guns was:
 - In Final Assembly - B6349XXX
 - Custom Shop - B630XXXX

by G. J. Hill 3/5/82
G. J. Hill, Supervisor
Process Engineering
Current Products

GJH/cac

PLAINTIFF'S
EXHIBIT

3158

101
AL 002404

20th April 1982

Dear Mark,

Many thanks for the bits for the Remington Mohawk 600. Now I can go ahead with my plans to make up an ultra-light deer rifle for mountain hunting. I have been worrying over whether or not to turn the barrel down to a slimmer contour as I am afraid that it will lose some of its fine accuracy. As it is, it is the most consistently accurate sporter on my rack. But I want the lightest outfit I can get. Chet Brown sent me one of his fibreglass stocks for it and I already had one of his handy bolt release catches (this is one that Remington should adopt if they release a new Model 600).

I am going to have to do something about the trigger too. While I was deer hunting last week I went to load the magazine and chamber a round. When I did chamber a round the bloody rifle discharged and blew a hole through the wall of my tent! Luckily, I had my gunsmith friend along and a toolkit. He pulled it apart and re-adjusted it so that it now seems to work all right again. But this is the fourth time that it has screwed up.

When I get this darn rifle completed and write a story about it I will send you a copy. My friend is making up a similar outfit on the Ruger M77 .308. What we want is a light rifle to carry on back packing trips where every ounce counts.

I think Remington could well bring out a similar rifle in .308 and .7mm/08 on a Mohawk 600 action.

By the way, is Remington still making the Mohawk 600 action? Hope to get over to the States again this year and if I see you we will have a couple of small beers and a chat.

I am trying to get a hundred things done so that I can get up to the NT and hunt buffalo along the Roper River next month. I have a friend coming out from Germany. He works for Dynamit Nobel.

Kindest Regards,

(Nick Harvey) Gun Editor
Sporting Shooter Magazine


PLAINTIFF'S
EXHIBIT

3159

AL 0029409

A

BY AIR MAIL PAR AVION
AEROGRAMME



AUSTRALIA 33c
NSW-AUST

TO MR Clark Workman,
2 Johnson Ave,
Mohawk,
New York 13407,
COUNTRY OF DESTINATION U.S.A

SENDER'S NAME AND ADDRESS

Nick Harvey,
Sporting-Shooter Magazine,
Hill End, Via Mudgee,
N.S.W 2850 Australia,
Postcode

FOLD SIDE FLAPS FIRST

FOLD SIDE FLAPS FIRST

Fold flaps before moistening gum, for maximum adhesion, press down for a few seconds. If another is enclosed, use the same instructions for this form.

SC

C

H

REMINGTON ARMS COMPANY, INC.
Firearms Research Division

August 19, 1981

c: T.L.Capeletti
J.R.Snedeker
J.P.Linde
J.W.Bower
C.E.Ritchie
K.R.Thondukolam

TO: C. B. WORKMAN

FROM: J. W. BROOKS

SUBJECT: MODEL 700 - Cleaning & Lubrication

Mr. Allan Hughes from the Du Pont Lubrication Lab will be here Wednesday, August 26th, at 9:00 AM to give us the information he has come up with during his investigation of a cleaner and lubricant for the Model 700 Fire Control.

If there are other people you feel would benefit from this discussion and presentation, please feel free to have them attend.

Place: Research Conference Room - 52-4

JWB:T

PLAINTIFF'S
EXHIBIT

3160

121
AL 0029472

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
SUPPORT

PETERS
SUPPORT

copy to

xc: J. P. Glas
J. E. Preiser
J. S. Martin
F. E. Martin

② workman

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

Ilion, New York
April 28, 1981

TO: C. B. WORKMAN

FROM: T. L. CAPELETTI

SUBJECT: MODEL 700 FEATURES FOR POSSIBLE USE IN ADVERTISING

*file - This
basis list can be used to
develop an advertising
campaign in conjunction with
our competitive evaluation now
in progress*
Clark

In response to Marketing's inquiry concerning strengths of the M/700 design which may be used in advertising campaigns, I asked Fred Martin to itemize areas he felt were significant. Fred provided me with the following information:

- | | | |
|--------------|---|--|
| * Strength | - | Action - Ability to withstand abuse of inexperienced handloaders. |
| | | Extractor - Comparison of competitive systems. |
| * Accuracy | - | Still the most accurate production center fire rifle made. Accurate enough to be used competitively "out of the box". |
| Fire Control | - | Adjustable and smooth still the best production trigger available - with planned modifications, will have another safety feature to advertise. |
| Calibers | - | A caliber and a loading available for anything from ground squirrels to Kodiak and Brown bear or elephant and rhino. |
| Adaptable | - | Several variations are available for military and police work. Gun/cartridge combination can be tailored to individual application. |

As indicated by the *, Fred feels that strength of the action and extraction systems and accuracy are prime selling points for these rifles.

TLC:ws
Firearms Research Division

PLAINTIFF'S
EXHIBIT

3161

AL 0029490

A

REMINGTON MODEL 700
FIELD SERVICE
GUNSMITH BULLETIN

INSTRUCTIONS FOR REMINGTON RECOMMENDED GUNSMITHS FOR REPLACEMENT OF
MODEL 700 TRIGGER ASSEMBLIES AND SELECTED TRIGGER ASSEMBLY PARTS

WARNING: TRIGGER ASSEMBLY PARTS NOT LISTED ARE NOT INTERCHANGEABLE.
REPLACE COMPLETE TRIGGER ASSEMBLY

BOLT STOP PIN
BOLT STOP
BOLT STOP SPRING

To Disassemble - Remove the bolt assembly, trigger guard or trigger guard assembly, magazine, magazine follower, spring and stock. Put the safety switch in "S" position. Tap out the bolt stop pin from left to right and remove the bolt stop and bolt stop spring.

To Reassemble - Place bolt stop spring into the recess in the bottom left side of the receiver with the long end of the spring facing forward and the bent end facing outward. The short, bent end of the spring sets in the receiver at the back of the trigger assembly. Place the bolt stop in slot with the contoured edge facing into the receiver and hole to the rear. Align the bolt stop, bolt stop spring and the trigger assembly holes with the bolt stop pin hole in the receiver. Insert the chamfered end of the bolt stop pin through bolt stop and bolt stop spring and tap pin into the receiver. Restake the bolt stop pin on the right side of the receiver.

CAUTION: After assembling the bolt stop - push bolt stop release upward, bolt stop must pivot freely. Push the safety switch to "F" position, pull the trigger and hold. Depress top rear of sear safety cam to insure that the cam pivots freely and retracts without hesitation.

Reassemble the magazine, magazine spring, follower, stock assembly, trigger guard and bolt assembly to the action. SEE SAFETY PERFORMANCE CHECK (PAGE 3).

SEAR PIN

To Disassemble - Remove the bolt assembly, trigger guard or trigger guard assembly, stock assembly, magazine, magazine follower, and spring. Put the safety switch in the "S" position. Tap out the bolt stop pin from left to right and remove the bolt stop and bolt stop spring. Tap out the sear pin from left to right.

To Reassemble - Align the sear safety cam and trigger assembly holes and tap in the sear pin from left to right (chamfered end first).

NOTE: Sear pin must not protrude into the bolt stop pin.

AL 0029503

PLAINTIFF'S
EXHIBIT

3162

Remington Arms Company, Inc.

183

Reassemble the bolt stop spring, bolt stop and bolt stop pin. Restake both pins on the right side of the receiver.

CAUTION: After reassembling, push bolt stop release upward; bolt stop must pivot freely. Put the safety switch in the "F" position, pull the trigger and hold. Depress top rear of sear safety cam to insure that the safety cam pivots freely and retracts without hesitation.

Reassemble the magazine, magazine follower, spring, stock assembly, trigger guard and the bolt assembly to the action. SEE SAFETY PERFORMANCE CHECK (PAGE 3).

TRIGGER ASSEMBLY COMPLETE

To Disassemble - Remove the bolt assembly, trigger guard or trigger guard assembly, magazine, magazine follower and spring. Put the safety switch in the "S" position. Tap out the bolt stop pin from left to right and remove the bolt stop and bolt stop spring. Tap out the sear pin from left to right and remove the trigger assembly.

To Reassemble - Insert trigger assembly (with slave pin intact) into receiver. Align holes and tap in sear pin from left to right (chamfered end first).

NOTE: Sear pin must not protrude into the bolt stop slot.

Reassemble the bolt stop spring, bolt stop and bolt stop pin. Restake both pins on the right side of the receiver.

CAUTION: After reassembling, push the bolt stop release upward; bolt stop must pivot freely. Put the safety switch in the "F" position, pull the trigger and hold. Depress top rear of sear safety cam to insure that the sear safety cam pivots freely and retracts without hesitation. Push safety switch from "F" to "S" position several times to insure free movement with no binding and positive engagement of safety switch detents.

Reassemble the magazine, magazine follower, spring stock assembly, trigger guard and bolt assembly to the action.

SEE SAFETY PERFORMANCE CHECK (PAGE 3)

SAFETY SWITCH SNAP WASHER
SAFETY SWITCH DETENT SPRING
SAFETY SWITCH DETENT BALL
SAFETY SWITCH PIVOT PIN
BOLT STOP RELEASE

To Disassemble - Remove the bolt assembly, trigger guard, stock assembly, magazine, magazine spring and follower. Remove the safety switch snap washer, safety switch detent spring and safety switch detent ball. Push safety switch pivot pin from right to left and remove the safety switch and bolt stop release.

AL 0029504

To Reassemble: Put the safety switch in the "S" position. Place the bolt stop release over the trigger pin on the left side of trigger assembly. Align holes in the bolt stop release, safety switch and trigger assembly. Push the safety switch pivot pin through the assembly from left to right. Set the safety switch detent ball into position in the safety switch. Place the safety switch detent spring over the safety switch. Make sure safety switch detent ball stays in position under the safety switch detent spring. Push the safety switch snap washer into position on the safety switch pivot pin on the right side of the trigger assembly.

CAUTION: After reassembly, push bolt stop release upward; bolt stop must pivot freely.

Put the safety switch in the "F" position, pull the trigger and hold. Depress top rear of sear safety cam to insure that the safety cam pivots freely and retracts without hesitation. Push the safety switch from "F" to "S" position several times to insure free movement with no binding and with positive engagement of safety switch detents.

Reassemble the magazine, magazine follower, spring stock assembly, trigger guard and bolt assembly into the action.

SAFETY PERFORMANCE CHECK

WARNING: CORRECT ALL MALFUNCTIONS 100% OR RETURN RIFLE TO FACTORY.

After reassembly, the following check for proper function of the safety must be made.

Close the bolt. Put the safety switch into the "S" position. Lift the bolt handle (bolt handle should not raise). Pull the trigger (firing pin should not fall). Action of the trigger pull must be smooth (no bind, drag, click or catch). Release the trigger (trigger must return to former position). Put the safety switch into the "F" position (firing pin must not fall). Pull the trigger (firing pin must fall). Repeat this test at least three (3) times. The safety switch must function in both of the two (2) positive positions: ON SAFE and FIRE. If the positions are not positive, check parts. Inspect the safety switch detent holes, safety switch snap washer, safety switch detent spring, safety switch detent ball and safety switch pivot pin for possible causes. Replace any worn or damaged parts.

CAUTION: IF STOP POSITIONS ARE NOT POSITIVE, REPLACE COMPLETE TRIGGER ASSEMBLY.

NOTE: Lubrication must not be used as a remedy for trigger assembly problems. The cause must be positively located and corrected.

After reassembling the stock assembly, check for clearance between the following parts: safety switch - stock; trigger - trigger guard; trigger - stock assembly.

Check for "Follow Down" (firing pin moves to uncocked position as bolt is closed). Put the safety switch into the "F" position. Close the bolt slowly. Firing pin must remain cocked (dry fire to check). If "Follow Down" occurs check for trigger being held back by interference between trigger and stock, trigger and trigger guard, or by the sear safety cam binding. Cause of "Follow Down" must be determined or the rifle should be returned to the factory.

WARNING: CORRECT ALL MALFUNCTIONS 100% OR RETURN RIFLE TO FACTORY.

AL 0029505

8/20/81
RLS:m

Remington Arms Company, Inc.

383

RULES FOR RECORDING EXPERIMENTS

1. Original records are to be in ink.
2. Each notebook page whereon there is recorded a completed experiment should be signed and dated by the experimenter in the space provided.
3. Each notebook page containing a completed experiment should be read and signed by a witness who will place his signature and the date in the space provided. The witness is to be one who understands the purpose of the experiment and the result obtained but who is not likely to be the inventor or a co-inventor. The witness should sign on the same day as the experimenter, or, if this is impossible, as soon thereafter as feasible.
4. Where entries on a single experiment do not completely fill a page, the remainder of the blank page should be ruled out. Where the record of the experiment extends over several pages which are not consecutive, proper cross-references should be inserted.
5. The bound notebook is to be preserved intact. In no case should any page or part of a page be removed.
6. No erasures are to occur in the record. Any corrections or changes should be made by cancellation, leaving the original entry legible.
7. The same rules as to signing, dating and witnessing are to be followed when the original data are recorded on loose sheets or forms other than the standard bound notebook.

PLAINTIFF'S
EXHIBIT

3163

181
AL 0029556

SUBJECT FOR INDEXING THIS BOOK
MUST BE GIVEN BELOW

A

M-700 Fire Control Design Page 1 -

M-700 Bolt Lock Page 3 - 6

M-700 - M-7 Scope Mounts Page 20

M-700 Rear Light - Page 10

E

K

S

I

C

H

PLAINTIFF'S
EXHIBIT

3164

1234
AL 0029557

DATE

SUBJECT OF EXPT.

14 JAN 1980

M-200 FIRE CONTROL DESIGN

1

As of this date the first model of the "new style" M-200 fire control has been assembled. The design requirements of this fire control to incorporate the following -
a trigger block $\neq$ sear block,
a bolt lock $\neq$ have an interceptor,
^{EXTERNAL} be adjustable $\neq$ operate in both
the fired and unfired condition -

have not all been met. Possibly in subsequent models.

This Model has a separate bolt lock and does not block the trigger in the on safe position.

The sear can be blocked in both positions by putting the safety on.

This is done by a finger of the safety engaging one of two notches in the side of the sear (See Next Page).

EXPERIMENTER


DATE

WITNESS

DATE

2034
AL 0029558

M 700 F. C. Design Gear



The sketch shows the gear in the fixed condition and the safety lever engaged as the belt is operated down rearward the gear spring forces the gear upward the safety lever springs outward and then returns to the lower notch. With this done the gear has been effectively blocked in two conditions.

EXPERIMENTER
WITNESS

F. E. Martin

Jack East

DATE

4-8-80

DATE

4/9/80

30334
AL 0029559

DATE

SUBJECT OF EXPT.

4-9-80 M-700 Bolt Lock

3

A method of allowing the shooter to open the bolt of his rifle, while in a safe condition has been developed. The mechanism consist of a bolt plug, a lever, a plunger and plunger spring. The bolt body is patterned to allow the lever to lock into it. The lever is actuated by the firing pin head.

- #1 - As the bolt is closed the spring loaded lever is urged to a locked position and engages a notch cut in the rear of the bolt body.
- #2 - To open this weapon the lever is pushed down with the thumb and the bolt handle shifted with the index finger.
- #3 - If the rifle is fired the firing pin head comes the lever upward automatically unlocks the gun.
- #4 - As the bolt is open and then closed the firing pin head is retracted and the lever allowed to re lock bolt.

The three photos shown on the next page will show the operation of the bolt lock and its location relative to the safety lever.

Photo #1 - The bolt is closed with the safety in the "On - Safe" position and the bolt is locked.

EXPERIMENTER

WITNESS

Arvid E. Martini
Jack Kast

DATE

DATE

4-10-80

4-11-80

40734
AL 0029560

4
 DATE 4-9-80
 SUBJECT OF EXPT. M-700 Bolt Lock




PHOTO #2 The gun is in the same condition as in the previous photo, safety lever in "On-Safe" position, the bolt lock lever has been depressed with the thumb and the bolt handle raised to illustrate the method of opening.

AL 0029561

EXPERIMENTER Fred E. Martin
 WITNESS Jack Kest

DATE 4-10-80
 DATE 4-11-80

5834

DATE

4-9-80

5

SUBJECT OF EXPT.

M-700 Bolt Lock

PHOTO # 2

FIRING PIN
HEAD

BOLT
LOCK

BOLT
HANDLE
RAISED

SAFETY LEVER





PHOTO # 3



EXPERIMENTER
WITNESS

AL 0029562

6234

2

6

DATE

S. ECT OF EXPT.

4-9-80

M-700 Bolt Lock

Photo #3

This photo shows the gun in the
fired condition, firing pin down
bolt unlocked bolt ready to be
opened.

Work on the development and production of
this subject continues both to improve
operation and appearance. Work is being
done to also reduce cost.

K

S

I

C

H

EXPERIMENTER

WITNESS

Fred E. Marti
Jack East

DATE

DATE

4-10-80

4-11-80

AL 0029563

7034

DATE

SUBJECT OF EXPT.

A

L

plank pages

from

7 - 20

E

K

S

I

C

H

EXPERIMENTER

WITNESS

DATE

DATE

AL 0029564

8

DATE

SUBJECT OF EXPT.

A

L

E

K

S

I

C

H

EXPERIMENTER

WITNESS

DATE

DATE

AL 0029565

9834

DATE
SUBJECT OF EXPT.

A
L
E
K
S
I
C
H

EXPERIMENTER
WITNESS

DATE
DATE

10234
AL 0029566

10

DATE

SUBJECT OF EXP'T

A

L

E

K

S

I

C

H

EXPERIMENTER

DATE


WITNESS

DATE

11234
AL 0029567

A

L



S

I

C

H

12234

AL 0029568

A
L
E



S
I
C
H

13234
AL 0029569

DATE
SUBJECT OF EXPT.

A
L
E
K
S
I
C
H

EXPERIMENTER
WITNESS

DATE
DATE

14734
AL 0029570

FILE

12

DATE

SUBJECT OF EXPT

A
L
E
K
S
I
C
H

EXPERIMENTER
WITNESS

DATE
DATE

15834
AL 0029571

DATE

SUBJECT OF EXPT.

ALEXANDER

EXPERIMENTER
WITNESSDATE
DATE16234
AL 0029572

14

DATE

SUF T OF EXPT

A
L
E
K
S
I
C
H

EXPERIMENTER
WITNESS

DATE
DATE

17234
AL 0029573

DATE

SUBJECT OF EXPT.

A

L

E

K

S

I

C

H

EXPERIMENTER

WITNESS

DATE

DATE

18234
AL 0029574

16

DATE

SUBJECT OF EXPT.

A
L
E
K
S
I
C
H

EXPERIMENTER

WITNESS

DATE

DATE

19234
AL 002975

DATE

SUBJECT OF EXPT.

A

L

E

K

S

I

C

H

EXPERIMENTER

WITNESS

DATE

DATE

20734

AL 0029576

18

DATE

SUE T OF EYPT

A

L

E

K

S

I

C

H

EXPERIMENTER

WITNESS

DATE

DATE

AL 0029577

21234

DATE
SUBJECT OF EXPT.

A
L
E
K
S
I
C
H

EXPERIMENTER
WITNESS

DATE
DATE

22734
AL 0029578

20

DATE

SUBJECT OF EXPT.

March 18, '81

Scope Mounts

Have been asked by F.S. Martin to look at
 designing scope mount for M-1 & M-100
 Bolt Action Rifles - Mount to be "UNIQUE"
 to Remington Rifle - May be of "Innovative"
 Concept - Cheap - Pleasant in appearance -
 Will look at previous attempts and whether
 Butler did some for Tinsle -
 Sango did some for Walker - (way back) -
 First layout has been done and signed
 by S.A. Forelle and A.R. Edley picture
 of mount is below.

See Top of Next Page
 For Photo

EXPERIMENTER

WITNESS

Fred E. Martin
 A.R. Edley

DATE

DATE

3-18-81

8/16/82

23034
AL 0029579


DATE

March 18, 81

SUBJECT OF EXPT.

Scope Mount

Prote type #1 used a dovetail cut in recess
to receive a mating cut in the scope ring.

Rear
BracketThump
Wheel

Rings were then locked in place by a jam-
screw that was activated by the thumb-wheels
that are visible.

Forward motion was stopped by the front
scope mount striking the rear of the rear
bracket.

Both rings functioned the same - rear ring
was higher by difference in rec. ring height.

Jam screw was keyed in lower half of ring
to keep it from turning when tightening.

No shooting done on this sample.

EXPERIMENTER

Fred E. Martin

WITNESS

O R Eddy

DATE

3-18-81

DATE

8/16/02

240734
AL 0029580

22

DATE


SUBJECT OF EXPT.

July 10, 81

Scope Mount

Sample #2 is in keeping with the request to be made - cheap ⁴²⁸ I mean "cost efficient". It has been designed as a stamping, to be attached to a dovetail as in Sample #1, it uses one screw to clamp and also hold the scope.

Screw



This sample, as sample #1 is of two different heights and would be stopped by the record bracket.

Parts are 1020 or 1095 Mat'l. spring tempered, to ensure a good grip. Large diameter that wraps around scope tube is slightly smaller than tube to ensure interference and a good grip.

No starting done with this sample.

EXPERIMENTER

WITNESS

Frederick J. Martin
A. L. Eddy

DATE

DATE

7-10-81

8/16/82

AL 0029581

25734


DATE

SUBJECT OF EXPT.

July 11, 81
Scope Mounts - again

Sample #3 is a variation of #2 hopefully
 it is a little easier to mount and assemble.
 This Mount was also designed as a stoppage
 to be fastened and mounted on a dove-
 tail cut in the receiver.

Picture to explain - One screw Mounting
 and clamping



As with other samples mounting was some

No shooting yet.

Maybe some day

EXPERIMENTER

WITNESS

Paul J. Martin
 G.R. Eber

DATE

DATE

7-10-81

8/16/82

26834
AL 0029582

24

DATE

SUBJECT OF EXPT.

July 31, 81

Scope Mounts - and again

This sample is a variation of a mount system that L. Butler developed for the M-16 Bolt Action Rifle.

It does not use a mounting block instead it ~~is~~^{is} directly to the receiver. In mounting like this ~~sample~~^{7.1981} complete disassembly is made when removing the mounts.

Mounting
Screws
3 each
ring



EXPERIMENTER

WITNESS

Fred L. Vinton
A. R. Easy

DATE

DATE

7-31-81

8/10/82

27034


AL 0029583

DATE

SUBJECT OF EXPT.

Aug 21, 81
Again Scope Mounts

The mount is similar to those marketed by
 Leica and Zeiss it uses a separate block
 to mount the ring and scope to the rifle.
 The scope mount does not have to be completely
 disassembled to remove from the rifle. It is
 shown as having two ring heights but
 could also be made for one ring height
 and two different block heights.
 Blocks are screw directly to receiver.

Lock
Screw
(5)Mounting
Block -
RearLock
Screw
(5)EXPERIMENTER
WITNESSFred S. Martin
C. R. EddyDATE
DATEMounting Block - Front
8-21-81
8/16/82

28834

AL 0029584

26


DATE

SUBJECT OF EXPT.

Aug 21, 81
Scope Mount (Continued)

A scope mount system that uses a mounting bushing instead of a mounting block was developed for use on the M-700 Bolt Action Rifle.

The bushing was formed with a tapered section with which the mount lock screw contacted.



Bushings was countersunk for mounting screw and could be mounted in any of the four scope screw holes on the receiver to facilitate the use of a variety of scopes.

EXPERIMENTER

WITNESS

Fred J. Martin
G.R. Eddy

DATE

DATE

8-21-81

8/16/81

29234

AL 0029585

26


DATE

SUBJECT OF EXPT.

Aug 21, 81
Scope Mount (Continued)

A scope mount system that uses a mounting bushing instead of a mounting block was developed for use on the M-700 Bolt Action Rifle.

The bushing was formed with a tapered section with which the mount lock screw contacted.



Bushing was countersunk for mounting screw and could be mounted in any of the four scope screw holes on the receiver to facilitate the use of a variety of scopes.

EXPERIMENTER

Fred S. Martin

DATE

8-31-81

30234

WITNESS

G.R. Eney

DATE

8/16/81

AL 0029586

DATE

SUBJECT OF EXPT.

Aug. 21, 1911 (Continued)

Position of the Scope Ring has been built
 and tested upon a ship set over the bushings.
 If the individual among the rifle wished he
 could remove the scope by loosening the lock.
 screws and still be able to use the same
 sight without inconvenience. Photo has the
 Scope mounted. Locked in to position.
 It is shown bushings can be moved for different
 scopes.

Lock
ScrewsLock
Screws
Insert
Screw
Mount

EXPERIMENTER

WITNESS

Fred S. Martin
O. R. Ewing

DATE

DATE

8-21-11

5/16/12

31734

AL 0029587

28

DATE

SUBJECT OF EXPT.

Jan 13, 1982
Integral Scope Mounts for M-7


This scope mount was intended and designed to be unique to Remington Bolt Action Rifle. By this I mean the mounting of a scope using these rings could only be done on a Remington Rifle.

There are normally three components necessary to mount a scope to a rifle; first the scope second the rings and thirdly the base. By making the base as part of the receiver we can eliminate the base and use a ring of our design.

This system that we have here is series of cuts on the top of the M-700 Receiver

Cuts in Top
of Receiver

Slot to take
Recoil



M-700 Receiver
cross-section

The scope ring designed for use with this system has to clamp to engage the angles recesses in the receiver and a lug to engage the slot.

EXPERIMENTER

Fred E. Martin

WITNESS

G. K. Eddy

DATE

1-13-82

DATE

5/16/82


32734
AL 002988

DATE
SUBJECT OF EXPT.

Jan 13, 1982

Integral Scope Mounts (Continued)

A




A variation of this system would be to have only one moveable clamp.

The picture shows the system mounted on a Remington Bolt Action Rifle.

An advantage of this system is that should the individual ~~with~~ wish to remove the scope he can and this replace no change necessary

can easily be, can it with in sight



EXPERIMENTER
WITNESS

Fred E. Martin
C.R. Eddy

DATE
DATE

1-13-82
5/10/82

33034
AL 002589

H

30

DATE

SUBJECT OF EXPT.

NOTEBOOK COMPLETE - NO FURTHER ENTRIES WILL BE MADE IN THIS BOOK.

JUL 23 1987

THIS BOOK MICROFILMED
AS COMPLETE
MAKE NO ADDITIONAL ENTRIES

EXPERIMENTER

WITNESS

DATE

DATE

34834
AL 0029590

RESEARCH NOTEBOOKS

<u>Book No.</u>	<u>Assigned To</u>	<u>Description</u>	<u>Date Issued</u>
1050	T.G. Bauman	Left Hand Model 870 and 1100 - 12 & 20 Ga.	7-22-69
1087	L.W. Baum	Powder Metals - General	1-18-68
1095	Bob Merhar	Powder Metal Research	
1178	Bob Merhar	Powder Metal Research	
1179	D.S. Findlay	7400-7600 Magazine Box	11-8-79
1180	D.S. Findlay	Magazine Box Design Testing 7400	11-28-79
1181	J.L. Kast	XSG Design	11-9-79
1182	G. Reinhardt	Powder Metallurgy	2-3-80
1183	R.J. Balaska	Stamped Gun Concept	3-26-76
2007	J.S. Martin	Powder Metallurgy	2-3-80
2008	A. R. Eddy	M/742-760 New Generation (7400-7600 Design)	9-20-76
2011	J.L. Kast	66 New Generation .22 Rimfire Semi Automatic	8-17-77
2031	W. A. Balcewicz	Programmable Manipulator Applications	10-3-78
2036	C. Lall	Powder Metallurgy	2-3-80
2038	J. R. Palmer	XSG Gas and Operating Systems	2-5-80
2039	A.A. Hugick	XSG Design Project	2-7-80
2040	F.E. Martin	Bolt Action Rifles - Misc. Design Projects	4-7-77
2041	D.S. Findlay	XSG	5-19-80
2042	K.C. Rowlands	New .22 Rimfire Autoloader	4-7-77
2043	W.A. Balcewicz	High Energy Beam Applications	10-3-78
2044	J. L. Kast	"XPG" Design (Experimental Slide Action Shotgun)	7-25-80
2045			

PLAINTIFF'S
EXHIBIT
3165

AL 0029592

RESEARCH DEPARTMENT

PROCEDURE

TECHNICAL NOTEBOOKS

Introduction

Employees of the Research Department are engaged in the conduct of experimental work which is of great importance to the Company. Its importance cannot always be adequately judged at the time the work is done. For this reason it is essential that all experimental work be recorded in bound notebooks, following procedures which will protect the Company's interests.

Purposes

There are two main purposes for Research notebooks:

1. To provide a clear record of the conception of ideas and experimental development of those ideas which will provide a sound basis for patent prosecution if the ideas are patentably novel.
2. To provide a clear and permanent record of the important details of experimental work so that Research employees in the future can determine what was done and the results obtained if they are interested in doing similar work. With a well-kept record, duplication of effort can be avoided in the future, even if the original experimenter is not available for questioning.

Procedures

Each exempt Research employee who conducts experiments, or directs non-exempt employees in conducting experiments, is expected to keep a notebook in which the details and results of his experiments are recorded. Enough narrative should be included in the record to enable anyone skilled in the art to find out what was done without having to question the experimenter.

Procedures for the use of Research notebooks are as follows:

Notebooks

Technical bound notebooks, 8-1/2" x 11" in size, shall be used, and may be procured from the designated custodian.

PLAINTIFF'S
EXHIBIT

3166

185
AL 0029594

RESEARCH DEPARTMENT

PROCEDURE

TECHNICAL NOTEBOOKS

Entries

Notebook entries shall be in strict accordance with the general Rules for entries appearing therein, and the following more-detailed instructions:

1. All entries shall be legibly written in waterproof ink. Standard, generally-accepted nomenclature should be employed.
2. All entries in a given notebook shall ordinarily pertain to a single general topic of research, and shall be made in chronological order from the first to the last page. However, it may sometimes prove desirable to divide a notebook into sections to record entries concerning several different and unrelated topics that are being worked on concurrently or intermittently by the experimenter. In that case, the title of each section and the page number on which it begins, should be entered on the index page concurrently with the establishment of the section. Each section is thereafter created as a separate notebook.
3. Blank spaces should be eliminated. When an entry does not fill a page, the next succeeding entry on the same subject matter may begin on the same page, with no space between the two. If it is preferred to start a new page for the next entry, any blank space on the preceding page should be ruled out, so that it would be virtually impossible to add anything to that entry at a later date.
4. The top of each notebook page should clearly state what subject matter the entries on the page relate to. It is not required to repeat the subject matter heading if it covers several consecutive pages. However, if it becomes necessary to continue a subject on a non-consecutive page, notations such as "continued on page ____" and "continued from page ____" should be made.
5. The author (and the experimenter, if he is not the author) should sign and date each notebook page after each independent entry is made. Each notebook page should also be read, signed, and dated

RESEARCH DEPARTMENTPROCEDURETECHNICAL NOTEBOOKS

A

by a witness who understands the subject matter recorded, but who is neither an inventor nor a co-inventor of any new concept that is discussed on that page. The witness should preferably sign on the same day as the author or, if this is not possible, as soon thereafter as may be feasible. In the case of multiple entries on a single page, the signatures and dates should appear immediately following each entry. There should be no writing below the last signatures and dates entered on a page.

Read and Understood By: _____ Date _____

6. The bound notebook is to be preserved intact. In no case should any page or part of a page be removed.
7. No erasures are to be made in the notebook. Any corrections or changes should be made by crossing out the incorrect entry, but leaving it legible.
8. The same rules as to signing, dating and witnessing are to be followed when the original notes are recorded on loose sheets, drawings, or forms other than a standard bound notebook.

Coding of Samples

Samples should be coded by marking them with the technical notebook number and page number on which the sample is first described. If more than one sample is referred to on one page, they may be distinguished by suffix letters, such as "250-16A", "250-16B". These would refer to notebook No. 250, page 16, samples A and B.

Inserts

The use of inserts should be kept to a minimum. However, any material which forms an important part of the record of the progress of experimental work should be permanently attached to the notebook by gluing or stapling directly to a notebook page. Materials left loose, put in with transparent tape, or inserted in an envelope in the notebook, are not considered part of the notebook and are therefore not a part of the legal record of the experiment described. If material is inserted in the notebook, adherence to the following instructions will simplify the microfilming of the records:

325

AL 0029596

RESEARCH DEPARTMENT

PROCEDURE

TECHNICAL NOTEBOOKS

1. It is preferable to attach and fold insert material so that it covers only the space on a single page between the subject and the signature. The page number and subject should not be obscured by the insert, nor should the space for signature and witnessing. The material should be fastened with staples or glued securely. To form a part of this permanent record, written inserts should be done in waterproof ink. Writing should appear on only one side of an insert.
2. If writing underneath the insert is desirable, the insert should be fastened only along the outside edge of the notebook. When the insert is unfolded, no part of the writing on the page should be obscured. If there is no writing under the insert, the statement "no writing underneath" should appear on the page below the insert.

Drawings and Sketches

All drawings and sketches should be initialed by the draftsman and signed and dated by the individual requesting the drawing.

Signatures

Except in extraordinary circumstances, notebook entries should be made by the experimenter and not by any other party. When necessary, another party may act as recorder for the experimenter, but the entry must so indicate and must be read, approved, and personally signed and dated by the actual experimenter.

"Active" versus "Complete" Notebooks

1. An "active" notebook is one in which further entries are to be made. Pages or portions of pages of an active notebook which are intended to be left blank should have a line drawn through them and should be signed and dated at the indicated place on the page.
2. A "complete" notebook is one in which no further entries are to be made, even if all the pages are not filled. Such notebooks should have a notation

RESEARCH DEPARTMENT

PROCEDURE

TECHNICAL NOTEBOOKS

on the last written page to the effect that no further entries will be made in the book. They should be turned over to the custodian as soon as possible after completion. Individuals should not retain notebooks in their possession which are not in everyday use. Under no condition should a notebook issued to one person be transferred to another. The person to whom a notebook is issued is held individually responsible for it.

Index

An index of notebooks will be maintained by the designated custodian.

Approved By:

N. Skovran 6/2/81
N. SKOVAN
Chief Patent Counsel

J.F. Glas 4/1/81
J.F. GLAS
Director of Research

RESEARCH DEPARTMENTPROCEDURETECHNICAL BOUND NOTEBOOKS

Technical notebooks, 8-1/2" x 11" in size, will be used, and may be procured from the designated custodian. (Barbara) 1000

Entries in such notebooks will be in strict accordance with the Rules for Recording Experiments appearing therein, in addition to which the following will be observed:

Entries

1. Entries in notebooks will ordinarily be in chronological order from the first to the last page. If it is found necessary to divide a notebook into sections, the subject of each section and the page number beginning such section will be entered on the index page concurrently with the establishment of the section; each section is thereafter treated as a separate notebook.
2. All entries will be legibly written in waterproof ink.
3. The subject at the top of each notebook page should clearly indicate what the data on the page concern. It is not necessary to repeat the subject notation if it covers several pages, provided that notations like "continued to page ____" and "continued from page ____" are made in appropriate places. There should be no writing below the signature or below the printing on the page.
4. Standard nomenclature should be employed.
5. No blank spaces will be left. When an entry does not fill a page, the next succeeding entry should begin on the same page, with no blank space between the two. If it is found desirable to start a new page for a particular entry, any blank space on the preceding page should be ruled out before the next entry is made, so that it will be virtually impossible to add anything to any entry at a later date.

10/11/68

PLAINTIFF'S
EXHIBIT

3167

1084
AL 0029599

A

Research Department
Procedure
Technical Bound Notebooks

Coding

1. Samples are coded by employing the technical notebook number and page number on which the sample is first described.
2. Variations on the basic code can be made by using letters, and these in turn can be subdivided by employing numbers. Thus, 250-16A1 would imply technical notebook No. 250; that the sample was first described on page 16; and that this particular sample was the number "1" modification of the "A" modification of sample 250-16.

Inserts

The use of inserts should be kept to a minimum. However, any material which forms an important part of the legal record of an experiment should be permanently attached to the notebook by gluing or stapling directly to a notebook page. Materials left loose, put in with transparent tape, or inserted in an envelope in the notebook, are not considered part of the notebook and are therefore not a part of the legal record of the experiment described. If material is inserted in the notebook, adherence to the following instructions will simplify the micro-filming of the records:

1. It is preferable to attach material so that it covers only the space on a single page between the subject and the signature. The page number and subject should not be obscured by the insert, nor should the space for signature and witnessing. The material should be fastened with staples or glued on all four sides. At the bottom of the insert, the statement, "no writing underneath," should be written. Inserts which form a part of the permanent record should be done in waterproof ink.
2. If writing under the insert is desirable, the insert should be fastened along the outside edge of the notebook so that the insert covers the page. When the insert is folded back, no part of the writing on the page should be obscured.
3. When it is absolutely necessary to insert material larger than the space for recording data on a single page, the material should be fastened and folded so that, when it is opened for inspection, it falls within the boundaries of the open notebook. None of the writing on the notebook pages should be obscured when the insert is folded back to reveal the pages underneath. Writing should appear on only one side of the inserted sheet.

10/11/68

224
AL 0029600

A

Research Department Procedure Technical Bound Notebooks

Drawings and Sketches

All drawings and sketches should be initialed by the draftsman and signed and dated by the individual requesting the drawing.

Signatures

Except in extraordinary circumstances, notebook entries should be made by the experimenter and not by any other party. When necessary, another party may act as recorder for the experimenter, but the entry must so indicate and must be read, approved, and personally signed and dated by the actual experimenter.

Witnessing

Each notebook page must be witnessed by a person who is neither a sole or joint inventor of the subject matter disclosed, and who is capable of understanding and does understand the entries on the page. The witness may be the experimenter's supervisor, a staff member in the same group, or some other qualified person. The witness must date his own signature.

Notebook entries witnessed some time after the date of writing, or by someone unfamiliar with the experiment, are not good legal evidence.

"Active" versus "Complete" Notebooks

1. A "complete" notebook is one in which no further entries are to be made even if all pages are not filled. Such notebooks should have a notation on the last written page to the effect that no further entries will be made in the book. They should be turned over to the custodian as soon as possible after completion. Individuals should not retain notebooks in their possession which are not in every-day use. Under no conditions should a notebook issued to one person be transferred to another. The person to whom a notebook is issued is held individually responsible for it.
2. An "active" notebook is one in which further entries are to be made. Pages or portions of pages which are to be left blank in an "active" notebook should have a line drawn through them and should be signed and dated at the indicated place on the page.

10/11/68

324
AL 0029601

Research Department
Procedure
Technical Bound Notebooks

Index

An index of notebooks will be maintained by the designated
custodian. (*Barbara - 1960*)

Approved by:

J. H. Lewis, Jr.
Patent Attorney

G. M. Calhoun
Director of Supporting Research

GMC:ND
10/11/68

424
AL 0029602

1003
AL 1003

PLAINTIFF'S
EXHIBIT
3168

RELATIVE STRENGTHS OF HIGH POWER CENTER FIRE RIFLES

MODEL NO.	RECEIVER AREA IN TENSION SQ. IN.	BOLT AREA IN SHEAR SQ. IN.	BOLT AREA IN COMPRESS. SQ. IN.	EXPECTED DEFLECTION OF BOLT IN RECEIVER BY YOUNG'S MODULUS P = 9000 E = 30x10 ¹⁰ INCHES	BOLT STEEL AISI OR NE NO	NOMINAL YIELD POINT 1000 #/SQ. IN.	LOAD W/OUT BOLT PERMANENT DEFORMATION LB.S.	BOLT		BARREL SIZE OR AT SHANK DIA. IN INCHES	STEEL AISI NO	BARREL	
								MEAN PRESSURE POSSIBLE IN 30-06 CASE = MAX. PRESS. ÷ 1.45 #/SQ. IN.	MEAN PRESSURE POSSIBLE IN .376 IN. CASE = MAX. PRESS. ÷ 1.45 #/SQ. IN.			MEAN PRESSURE POSSIBLE IN 30-06 CASE = MAX. PRESS. ÷ 1.45 #/SQ. IN.	MEAN PRESSURE POSSIBLE IN .376 IN. CASE = MAX. PRESS. ÷ 1.45 #/SQ. IN.
720	.443	.397	.109	.0015	2340	190	20,790	82,000	64,000	1.086	I-4130 120,000	58,000	54,000
721	.480	.429	.141	.0013	1335 2340	75 190	18,600 26,800	42,000 106,000	33,000 83,000	1.071	I-4130 120,000	57,000	53,000
IX-760*	.303	.206	.114	.0014	1335 2340	75 190	8,600 21,750	34,000 86,000	27,000 68,000	.897	I-4130 120,000	49,000	44,000
2X-760	.355		.071	.0150	1315 2340	75 190	5,350 13,500	21,000 53,000	17,000 42,000	.892	I-4130 120,000	48,000	43,000
W1903A3	.470	.329	.084	.0020	8620	190	10,900	43,000	34,000	1.011	1350 75,000	34,000	32,000
M-70-W	.537	.400	.086	.0020	Rock 48	190	16,400	65,000	51,000	.959	I-4130 120,000	52,000	48,000

(*) The Barrel Extension is the Receiver in the IX-760.

NOTE: The above Force and Pressure figures are theoretical and should be used for comparison only. According to experience actual figures would be higher.

M. H. W.
2-28-44

3083
AL 0029605

(*) The Barrel Extension is the Receiver in the II-760

NOTE: The above Force and Pressure figures are theoretical and should be used for comparison only. According to experience actual figures would be higher.

27, 1/10/1947
2-28-47

46

TITLE OF PROJ. _____

PROJ. NO. _____


SUBJECT _____

WORKS _____

COMPUTER _____

DATE _____

19 _____



$$\cos 22^\circ = \frac{0.32}{x} = 0.927$$

$$x = \frac{0.32}{0.927} = 0.346$$

$$\cos 23^\circ = \frac{1.323}{x} = 0.927$$

$$x = \frac{1.323}{0.927} = 1.427$$

$$\cos 27^\circ = \frac{x}{0.399} = 0.891$$

$$x = 0.399 \times 0.891 = 0.355$$

$$\sin 5^\circ = 0.087 = \frac{x}{1.322}$$

$$x = 1.322 \times 0.087 = 0.115$$

$$\frac{0.115}{0.413} = \frac{0.1148}{0.355}$$

$$d \text{ to top} = 1.563$$

$$1.504$$

C

H



TITLE OF PROJ. _____

PROJ. NO. _____

SUBJECT _____

WORKS _____

COMPUTER _____

DATE _____

19 _____

1561

182

3381

1502

178

3282

1504

3645

5749

3381

1768

1563

3645

5208

3282

1926

548

340

196

0066

2026

1703

0323

540

350

190

0022

1838

1864

0014

531

335

196

528

336

790

Asphy
life

338

190

148

335

1969

138

518

174

370

522

138

384

518

160

358

522

1570

372

4144
384
030

428
384
030

4144

384

030

428

384

030

5083

AL 0029607

$$\begin{aligned}
 &1.230 \pm .001 \\
 + &.062675 \pm .000175 \\
 &1.302675 \pm .001175 \\
 - &.06245 \pm .00005 \\
 = &1.240225 \pm .001225 \\
 + &.000225 \pm .000225 \\
 = &1.240450 \pm .001450 \\
 - &.972 \pm .01 \\
 = &.26845 \pm .00245 \\
 - &.075 \pm .001 \\
 = &.19345 \pm .00345
 \end{aligned}$$

$$\begin{aligned}
 &.000,01 \\
 &.000,000,306 \\
 &.000,000,025 \\
 &.000,001,506 \\
 &.000,01 \\
 &.000,01
 \end{aligned}$$

top of trigger from
fire control hole

diff. $.17835 \pm .00805$
 $= .1703 \text{ to } .1864$

$$\begin{aligned}
 &.650 \pm .001 \\
 - &.280 \pm .002 \\
 = &.370 \pm .003 \\
 + &.062675 \pm .000175 \\
 = &.432675 \pm .003175 \\
 - &.06245 \pm .00005 \\
 = &.370225 \pm .003225 \\
 + &.062675 \pm .000175 \\
 = &.432900 \pm .003400 \\
 - &.124 \pm .001 \\
 = &.3089 \pm .0034 \\
 + &.0629 \pm .0002 \\
 = &.3718 \pm .0036 \\
 - &.1845 \pm .0015 \\
 = &.1873 \pm .0061
 \end{aligned}$$

$$\begin{aligned}
 &.000,01 \\
 &.000,01 \\
 &.000,000,306 \\
 &.000,000,025 \\
 &.000,000,306 \\
 &.000,01 \\
 &.000,000,4 \\
 &.000,0225
 \end{aligned}$$

top of trigger from
fire control hole

$$\begin{aligned}
 &19345 \\
 &1873 \\
 &.00615 \pm .00850 \\
 &.0029 \pm .00615 \\
 &.00905 \pm .01470 \\
 &.00325 \pm .00240
 \end{aligned}$$

$$\begin{aligned}
 &.00850 \\
 &.01710 \\
 &.0148 \\
 &.0058 \\
 &.0287 \\
 &.01710 \\
 &.00360
 \end{aligned}$$

$$.000,084,374 - 2 = \pm .0029$$

700
698
2 1.002
1.001

4552
4408
2 0104
10052

1.004
1.005
1.007
1.001
1.000
430
432

2555
2800
2 1155
6075

2835
2811
2 002
001

2833
2800
2 0033
6061

435
0156
436

SEARCH

See

1518
178
3298
1969
1329
158
182
340
190
150

437
385
1044
642

414
3891
0263

521
1329
3891
518
150
368

4486
369
0766
64
0552

428
368
0

SEARCH

7783
AL 0029610

TITLE OF PROJ.

PROJ. NO.

SUBJECT


WORKS


COMPUTER

DATE

19

Star





$$\cos 22^\circ = \frac{1.220}{x} = .9272$$

$$x = 1.316$$

$$\sin 5^\circ = \frac{y}{1.316} = .08715$$


$$y = .1149$$

$$\begin{array}{r} .1149 \\ .0369 \\ \hline .1518 \checkmark \\ 178 \\ \hline .3298 \\ 19 \end{array}$$

$$\begin{array}{r} .1152 \\ .0478 \\ \hline .1530 \checkmark \\ 182 \\ \hline .3400 \end{array}$$

$$\begin{array}{r} .19345 \\ .00345 \\ \hline .190 \\ .19690 \end{array}$$

$$\begin{array}{r} 1.220 \\ \times 1.225 \\ \hline 1.270 \end{array}$$



$$\cos 5^\circ = \frac{z}{.043} = .9062$$

$$\begin{array}{r} .0426 \\ .0369 \end{array}$$

K

S

I

C

H

9883

AL 0029613

BOOK # 236

A
L
E

K

Issued to M. H. Walker
on m/721 (9/10/43)

To be returned on request.

236

S

I

C

H

10283
AL 0029615

A

THIS BOOK MICROFILMED
AS COMPLETE
MAKE NO ADDITIONAL ENTRIES

L

RULES FOR RECORDING
EXPERIMENTS

1. Original records are to be in ink.
 2. Each notebook page whereon there is recorded a completed experiment should be signed and dated by the experimenter in the space provided.
 3. Each notebook page containing a completed experiment should be read and signed by a witness who will place his signature and the date in the space provided. The witness is to be one who understands the purpose of the experiment and the result obtained but who is not likely to be the inventor or a co-inventor. Preferably the witness signs on the same day as the experimenter and in any event as soon thereafter as possible.
 4. Where entries on a single experiment do not completely fill a page, the remainder of the blank page should be ruled out. Where the record of the experiment extends over several pages which are not consecutive, proper cross-references should be inserted.
 5. The bound notebook is to be preserved intact. In no case should any page or part of a page be removed.
 6. No erasures are to occur in the record. Any corrections or changes should be made by cancellation, leaving the original entry legible.
 7. The same rules as to signing, dating and witnessing are to be followed when the original data are recorded on loose sheets or forms other than the standard bound notebook.
- S
- C
- H

SUBJECT FOR INDEXING THIS BOOK
MUST BE GIVEN BELOW

A

L

E

K

S

I

C

H

12/83
AL 0029617

DATE
SUBJ


EDGE
WITH

DATE

9-10-43

SUBJECT OF EXPT.

Blocked semi trigger



$$(10) .52 < 24 (33)$$



$$5.2 < 8$$

$$24 (33) = 10 (52) + x (85)$$

$$8 = 52 + x (85)$$

$$2.4 = x$$

$$x = 3.3$$



EXPERIMENTER

WITNESS

DATE

DATE

13783
AL 0029618


DATE

9-13-43

SUBJECT OF EXPT.


Dimensions - Resin

B.H.
Therms



.692
- 1.15 Center
- .577


OAL - 8.59



Length
52

OAL - 8.15

M 70



72 4.59

EXPERIMENTER

WITNESS

DATE

DATE

14/283
AL 0029619


DATE

9-15-43


SUBJECT OF EXPT.

3.0.6 Magazine


M720



RS03



M70



width of loading point

720 - 5.30"
 RS - 5.30"
 70 - 5.41"

EXPERIMENTER

DATE

WITNESS

DATE

15283

AL 0029620

A

DATE
SUBJECT OF EXP

9-15-43
Aluminum - Magnesium

Reveries Rase to bottom of Mg.
burn
17.4 1.52

17.70 1.75 1.58
17.20 1.72 1.54

R803

M 20

M 760

1.60

1.48

top width
7.14

Bottom view
9.10

Bottom Profile
8.12

K

S

C

E

EXPERIMENTER
WITNESS

DATE
DATE

1678
AL 0029621

EX
WT

9-16-43


SUBJECT OF EXP 1

43
721 ~~Revised~~ ~~Revised~~

EXPERIMENTER	
WITNESS	

DATE	DATE
------	------

AL 0029622



6

DATE

SUBJECT OF EXPT.

9-17-43

Receiver Calculations

Strength of Receiver Ring

$$\text{Min O.D.} = 1.370"$$

$$\text{Max I.D.} = 1.130"$$

$$\text{Area O.D.} = \left(\frac{1.370}{2} \right)^2 \pi = 1.475 \text{ sq in.}$$

$$\text{Area I.D.} = \left(\frac{1.130}{2} \right)^2 \pi = 1.004 \text{ sq in.}$$

$$\text{Cross Section Area} = .471 \text{ sq in.}$$

Yield strength of X1315 heat treated =

SIC

EXPERIMENTER

DATE

WITNESS

DATE

18B83
AL 0029623

DATE

9-28-43

SUBJECT OF EXPT.

Stock dimension 721

Depth at crown 1 $\frac{11}{16}$ "

Depth at heel 2 $\frac{5}{8}$ "







Length

13 $\frac{1}{2}$ "

Pitch with 24"

24"

not used



EXPERIMENTER

WITNESS

DATE

DATE

19483


AL 1029624

8

DATE

SUBJECT OF EXPT.

A 9-30-43
Bolt



EXPERIMENTER

WITNESS

DATE

DATE

120983






AL 0029625

DATE

10-1-43

SUBJECT OF EXPT.

Magneto



EXPERIMENTER

WITNESS

DATE

DATE

AL 0029626

21083

DATE _____
SCT OF EXP _____

11-16-43

DATE _____ CT OF EXP. _____

Magayona dimensions

475 / Mar 30

25/11/50

Quesada

Keep the Front to back

11

With love

With Good

Birth - never long

With back 2

North part of Sec. bridge

Stock thickness

Tryp. circum.

85

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

--	--

270

— — — — —

1. *Introduction*

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

1

[illegible]

11

100

1	2
3	4
5	6
7	8
9	10
11	12
13	14
15	16
17	18
19	20
21	22
23	24
25	26
27	28
29	30
31	32
33	34
35	36
37	38
39	40
41	42
43	44
45	46
47	48
49	50
51	52
53	54
55	56
57	58
59	60
61	62
63	64
65	66
67	68
69	70
71	72
73	74
75	76
77	78
79	80
81	82
83	84
85	86
87	88
89	90
91	92
93	94
95	96
97	98
99	100

EXPERIMENTER
WITNESS

DATE _____
DATE _____

10

AL 0029627

31



DATE 1-23-41
 SUBJECT OF EXPT. 7x1 tension Spring

FIBER LENGTH 3.375" *changed*

COCKED LENGTH 3.030"

d = .055"

$0 = 3.375 - 0.55 = 2.825$

n = 38 ACTIVE

19 # of 3.375" = 6.1" ENERGY

$$P = \frac{F \cdot d \cdot L}{8 \cdot D^3} = \frac{F \cdot \left(\frac{9.5 \times 10^{-6}}{8 \times 3.375 \times 0.055} \right)}{8 \cdot D^3}$$

Set from 78 to 64

$$P = 78 \cdot d \cdot L$$

$$P \cdot L (L - 3.375) = 78 \cdot d \cdot L$$

$$L = \frac{19}{8.8} \cdot 4.375 = 9.55"$$

$$L = 5.485" \rightarrow 5.55"$$

$$COCKED P = 19"$$

$$COCKED P = 8.8(5.50 - 3.03) = 21.2"$$

$$STOCKED P = 8.8(5.50 - 2.12) = 29.6"$$

$$S = \frac{8 \cdot P \cdot D}{\pi \cdot d^3} = \frac{8 \cdot \left(\frac{1 \times 10^{-6}}{\pi \cdot (0.055)^4} \right)}{S = 195700}$$

$$FIBER S = 19(5.50) = 98.800 PSI$$

$$COCKED S = 267(5.50) = 1468.500 PSI$$

$$STOCKED S = 2716(5.50) = 14942.000 PSI$$

12

DATE

SUBJECT OF EXPT

I - 23 - 44

Shot on 721, Main Spring

1" Shooter

FIRED LENGTH = 2.375

COCKED LENGTH = 2.030

 $d = .055$ $D = .395 - .055 = .340$

19# at 2.375 = 6" ENERGY

STACKED L = $.030 - .600 = 1.430$ = 25 Active Coils $P = 13.4 F$ $13.4 (L - 2.375) = 2.0$ $L = 3.66$

FIRED P = 48 #

COCKED P = $(3.66 - 2.030) 13.4 = 21.8$ STACKED P = $(3.66 - 1.43) 13.4 = 30.1$ $S = P(5200)$ FIRED S = $5200 \times 48 = 93,600$ COCKED S = $21.8 \times 5200 = 113,360$ STACKED S = $5200 \times 30 = 156,000$ $5200 \times 30 =$

EXPERIMENTER

DATE

WITNESS

DATE

24383
AL 0029629

DATE

3-29-44

SUBJECT OF EXPT.

FIRING PIN PROTRUSION

MAX BOLT LENGTH

MIN PIN LENGTH

.451
 .315
 .433
 .064
 1.263

1.810
 - .500
 1.310

MIN PROTRUSION = $1.310 - 1.263 = .047$

MIN BOLT LENGTH

MAX PIN LENGTH

.449
 .309
 .427
 .060
 1.245

1.813
 - .498
 1.315

MAX PROTRUSION = $1.315 - 1.245 = .070$

EXPERIMENTER

DATE

WITNESS

DATE

25883
 AL 0029630


14

DATE

SHEET OF EXPT



First cartridge Fired on 12/7/72




Head Space 1.937"

A standard 30.06 Rem. U.S. S.P. was fired after some trouble getting the indent up to .018. The case stretched in front of the solid head and ruptured enough to let out some gas. The primer was deformed to more than $\frac{1}{4}$ " diameter.

It is from evident that the leading plug took up on the body instead of the shoulder of the chamber causing severe head space.

Chamber after firing



Head Space 1.937"

No Swell is evident.

Ejector Spring

0.76 dia
1.37 od

EXPERIMENTER

WITNESS

DATE

DATE

26 283


AL 0029631

DATE

4-10-44

SUBJECT OF EXPT.

First Cartridge in 721 after reheading
Before Firing



Head Space
1.957

No change in use evident after 10 prop loads

E

K

S

I

C

H

EXPERIMENTER

WITNESS

DATE

DATE

27-283
AL 0029632

DATE

SUBJECT OF EXPT.

May 8, 1944
New born beech dimensions

$$S = \frac{P(r_1^2 + r_2^2)}{(r_1^2 - r_2^2)}$$

P = 540.37 1.067

P = 290 Win. PRESSURE = 84,000 PSI

$$r_1^2 = (474 - 2)^2 = 237^2 = 56169$$

$$r_2^2 = (1067 - 2)^2 = 534^2 = 285156$$

$$r_1^2 = 1.067 \quad r_2^2 = (1067 - 2)^2 = 534^2 = 285156$$

$$r_1^2 = 1.011 \quad r_2^2 = (1011 - 2)^2 = 509^2 = 259081$$

$$S = \frac{84000 (341.2)}{2788} = 105,200 \text{ PSI (270 Win)}$$

$$S = \frac{84000 (313.7)}{2021} = 130,000 \text{ PSI (270 Win)}$$

P = 284 Win. PRESSURE = 84,000 PSI

$$r_1^2 = (514 - 2)^2 = 257^2 = 66049$$

$$r_2^2 = (1067 - 2)^2 = 534^2 = 285156$$

$$r_1^2 = 1.018 \quad r_2^2 = (1018 - 2)^2 = 509^2 = 259081$$

$$S = \frac{84000 (351)}{219} = 135,000 \text{ PSI (284 Win)}$$

$$S = \frac{84000 (325)}{1193} = 144,000 \text{ PSI (284 Win)}$$

EXPERIMENTER

DATE

WITNESS

DATE

28083
AL 0029633

DATE June 5 1943
SUBJECT OF EXPT. 721 Lock Time

721 $\overline{G}^{\text{F}}$ Faring Range = 61.5 gms.

721 Spring = 12.8 gms.

722 Living Pine - S. 2. & 9 miles

722 Spring - 9.1.9 m

721 Lock time = $2 \times 67.9 \times 500 \times 800 = 333 \text{ ms}$
 $21 \times 500 \times 800$

~~$$\text{722 lock } \frac{1}{1142} = \frac{2 \times 50.9 \times 100 \times 100}{1142} = 3.01 \text{ kg}$$~~


13

$\frac{S_0}{S_1} = \frac{S_2}{S_3}$

29283
AL 0029634

EXPERIMENTER:	DATE
WITNESS	DATE

Barre, Bolt & Reeves Tolson, us



1.151
1.187
1.338
449
889

$$\begin{array}{r} 1.149 \\ + .185 \\ \hline 1.334 \\ + 4.511 \\ \hline 5.883 \end{array}$$
$$\begin{array}{r} 11334 \\ 600 \\ \hline 11934 \end{array}$$

890
892

~~334~~
~~683~~
790
110
P-5
A-334
883
449
449
449

$$\begin{array}{r} 680 \\ 370 \\ \hline 1050 \end{array}$$

~~315~~

4.73

34

DATE _____

30083
AL 0029635

$$\frac{7}{64} - \frac{18}{64}$$

DATE Jan 17, 1944
 SUBJECT OF EXP. Rev. Light
 17 720

Deflec = .192

H 721




Assume S of 150.00

$$F = \frac{252}{3.5} = 72$$

$$H = \frac{2(252,000)(2.67)}{3(3 \times 10^7)(.072)} = .044$$

$$P = \frac{S b h x}{6 I} = \frac{130,600(3.14)(.001)}{6(1.65)} = .92$$



EXPERIMENTER
 WITNESS

DATE

31883
 AL 0029636

20

DATE

SUBJECT OF EXPT

June 13, 1944

721 & 722 Calibers

M 721

.284 Rem Mag.

.30.06

.280 Rem

M 722

.224 Rem (.25-3000)

.220 Rem (.25-3059)

M 710 (Single Shot)

.220 Rem (.25-2055)

M 514 (Single Shot)

.22 L.R. Target Model

EXPERIMENTER

WITNESS

DATE


DATE

AL 002963

32883

DATE
SUBJECT OF EXPT.

6-19-44
CARRIAGE RAMP



$$\begin{array}{r} 1.355 \\ .6775 \\ \hline .3515 \\ .3760 \\ .070 \\ \hline .2560 \end{array}$$

$\tan 37^\circ = .7536$

$x = \frac{256}{.7536} = 340$

$x = \frac{270}{.7536} = 358$

$\text{MAX } y = 440 - 340 = 109$

$\text{MIN } y = 440 - 358 = 82$

$$\begin{array}{r} 1.360 \\ .680 \\ \hline .350 \\ .330 \\ .60 \\ \hline .270 \end{array}$$

$$\begin{array}{r} 4230 \\ 3716 \\ \hline 447 \end{array}$$

$$\begin{array}{r} 4230 \\ 3220 \\ \hline 410 \end{array}$$

$$\begin{array}{r} 340 \\ 440 \\ \hline 440 \end{array}$$

EXPERIMENTER
WITNESS

DATE
DATE

33283
AL 0029638

22


DATE

6-20-11

SUBJECT OF EXPT.

300 SAVAGE MAGAZINE

35 R.



EXPERIMENTER

DATE

WITNESS


DATE

34883
AL 0029639

24 24

DATE 6-22-33
SUBJECT OF EXPT. 300 SAVAGE FOLLOWER

A



.970
.088
.882

.835
.088
.747

2.930
.088
2.842

30
36


.517
.072
.599

.625
.072
.553




2.936
.088
2.848

1.742
2.600
2.442

1.590



Steel
.934-.034



EXPERIMENTER
WITNESS

DATE
DATE

36083
AL 0029641

DATE

6-27-44

SUBJECT OF EXPT.

M-722 MAIN SPRING

FIRED LENGTH = 2.475

LOCKED LENGTH = 2.155

 $d = .055$ $D = .395 - 407.7055 = .352 \text{ MAX.}$

STRAINED LENGTH = 1.540

24 TOTAL COILS 26 ACTIVE

 $P = 11.6 \text{ #/in}$

4" FREE LENGTH

$$\begin{array}{r} 2.475 \\ - 1.525 \\ \hline 0.950 \end{array}$$
FIRED $P = (1400 - 2475) / 11.6 = 17.7^*$ LOCKED $P = (1400 - 2180) / 11.6 = 21.1^*$

$$\begin{array}{r} 0.950 \\ - 0.208 \\ \hline 0.742 \end{array}$$

21" at 2050 - 230

SIC

EXPERIMENTER

DATE

WITNESS

DATE

37883


AL 0029642

26


DATE
SUBJECT OF EXPT.

7-12-44

Bolt Body and Log Intersection




MIN LUG & MAX BOLT



$$\sin \alpha = \frac{220}{.349} = .6304$$

$$\alpha = 39^\circ - 4' - 47''$$

MAX LUG & MIN BOLT



$$\sin \beta = \frac{223}{.347} = .6426$$

$$\beta = 39^\circ - 59' - 5''$$

$$\beta - \alpha = 54' - 18'' = 54.3'$$

$$\frac{54.3}{360 \times 60} \times .698 \times \pi = \text{Linear Movement Apex}$$

$$= .00552''$$


EXPERIMENTER
WITNESSDATE
DATE38883
AL 0029643

DATE

SUBJECT OF EXPT.

7-14-44

Bolt Head - Firing Pin



Find Min L


$$\frac{.132 - .077}{2} = L \tan 15^\circ$$

$$\frac{.132}{.555}$$

$$= .2679$$

$$L = \frac{.0275}{.2679} = .1027$$

$$\text{Min. } L = 2.00 - 1.02 = .99$$



Find Max & Min D

$$\frac{.132}{2} \div .990 = \tan 15^\circ = .0262$$

$$D_{\text{min}} = .132 - .990 \times .0262 \times 2 = .0518$$

$$D_{\text{max}} = .1838$$

$$D_{\text{min}} = .128 - .980 \times .0262 \times 2 = .0513$$

$$D_{\text{min}} = .1793$$

39883

EXPERIMENTER

DATE

WITNESS

DATE

AL 0029644


28

DATE

17-17-44

PROJECT OF EXP.

Placement of ejector pin hole



EXPERIMENTER

WITNESS

DATE

DATE

AL 0029645


404283

DATE:

7-18-44

SUBJECT OF EXPT.

300 H+H Follower



3.590
3.575

2726
812
3.590

S I C

W

EXPERIMENTER

WITNESS


DATE

DATE

41 983
AL 0029646

7-19-42

Calculations of Center centers for Line control



$$\begin{array}{r} 1860 \\ .515 \\ \hline 1345 - \\ 1700 + \\ \hline 355 \end{array}$$

$$\frac{h}{r} = \frac{355}{1700} = .2088$$

$$\frac{.025}{.013} \times .013 = .005$$

$$\frac{C}{r} = 1223$$

$$C = 2080$$

For 1.645 center

$$\frac{C}{r} = \frac{2080}{1.645} = 1265$$

$$\frac{.025}{.013} \times .005 = .005$$

$$\frac{h}{r} = .2254$$

$$h = .371$$

$$X = 1.645 - .371 + .515 = 1.789$$


EXPERIMENTER
WITNESSDATE
DATE42283
AL 0029647

DATE

7-19-44

SUBJECT OF EXPT.

Cutting centers



$$\frac{.680}{.220} = \frac{.900}{.450}$$

$$\frac{1860}{450} = \frac{1.410}{.370}$$

$$\frac{h}{r} = \frac{.370}{1.780} = .208$$

$$\frac{.001}{.005} \times .013 = \frac{.0013}{.025}$$

$$\frac{c}{r} = 1.221$$

$$c = 2.173$$

For 1.750 R cutter

$$\frac{c}{r} = \frac{2.173}{1.750} = 1.242$$

$$\frac{.011}{.014} \times .005 = \frac{.0055}{.0216}$$

$$\frac{h}{r} = .2112$$

$$h = .3786$$

$$X = 1.750 - .378 + .450 = 1.822$$

EXPERIMENTER

WITNESS

DATE

DATE


43 883
AL 0029648

DATE

7-20-44

SUBJECT OF EXP.

Extraction from Carbon Activated Carbon



$$1.865 + .915 =$$





$$1.585$$

$$= 1.265$$

1.15

1.20
1.15
1.05



EXPERIMENTER

DATE

4/4-883

AL 0029649

DATE

9-5-44

SUBJECT OF EXPT.

Assembly of m 721 & m 722

Two of the four models were assembled completely 9-5-44. The bolt heads were turned on and pinned to determine the actual strength requirements.

	M 721 300 H+H	M-722 300 Rev.
Headspace before	Max + .005"	Min
After spring tests	Max + .0035"	10 per bolt Min

The m-721 showed very high pressure on proofing.

The m-722 showed only ordinary pressure on proofing.

The m-722 bolt head had broken loose before firing. Only the pin was holding it. However it held quite satisfactorily for proofing.

A .45" charger was cut in the bolt body of the 722 and the bolt head broke out.

Considerable trouble was experienced with the softags. Carter checked one and found it would not meet the drawing. The safety surface all over .005" under min and .030" max placed.

EXPERIMENTER

WITNESS

DATE

DATE

45083

AL 0029650

9 - 11 - 46

M-722 bolt head & Socket

After approximately 40 seconds 300 lbs. was the M-722 bolt head broke loose a second time. Inspection of the joint showed that the brags was not sufficient. The head was joined a third time using a ring of 1000° F silver solder in a relief spot on the head. At the same time several test specimens were made up and checked on the tensile machine using different brazing compounds. The minimum joint strength obtained with a poor brazing compound was 7000⁺ force to separate head and body, the best joint gave 25000⁺. It was decided that the ring of brazing compound in a relief spot constituted the best joint.

The M-722 bolt handle bent during the process. Due to lead extraction (rough chamber). Opening the bolt by hitting with a stick of wood caused the bending. The handle was replaced and the chamber smoothed.

DATE

9-13-45

SUBJECT OF EXPT.

Fire control characteristics

$$\begin{array}{r} 1.046 \\ - .315 \\ \hline \end{array}$$

1.361 min diam end trip

$$\begin{array}{r} 1.241 \\ - .521 \\ \hline \end{array}$$

1.762 max diam trip hole to Rec E

$$\begin{array}{r} 1.762 \\ - 1.361 \\ \hline .401 \end{array}$$

#30

#01

1.029

min diam engagement

$$\begin{array}{r} 1.048 \\ - .335 \\ \hline 1.383 \end{array}$$

$$\begin{array}{r} 1.239 \\ - .519 \\ \hline 1.758 \end{array}$$

min diam trip hole to Rec E

$$\begin{array}{r} 1.758 \\ - 1.383 \\ \hline .375 \end{array}$$

#35

#75

.050

max diam engagement

$$\begin{array}{r} .521 \\ - .060 \\ \hline .581 \end{array}$$

$$\begin{array}{r} .435 \\ - .050 \\ \hline .385 \end{array}$$

$$\begin{array}{r} .585 \\ - .335 \\ \hline .250 \end{array}$$

$$\begin{array}{r} .720 \\ - .078 \\ \hline .642 \end{array}$$

$$\begin{array}{r} .798 \\ - .195 \\ \hline .603 \end{array}$$

.581 max diam Rec E to bottom of Bolt stop pin

.603 min diam Rec E to rear contact on bolt stop

Then .022 = min clearance

$$\begin{array}{r} .391 \\ - .195 \\ \hline .586 \end{array}$$

$$\begin{array}{r} .586 \\ - .600 \\ \hline .646 \end{array}$$

$$\begin{array}{r} .649 \\ - .646 \\ \hline .003 \end{array}$$

.003

min clearance between
Screw & Bolt stop pin with
safety on.47883
AL 0029652

EXPERIMENTER

DATE

WITNESS

DATE


36

DATE

SUBJECT OF EXPT.


9-13-44

Safety of Fire Control Characteristics (Cont.)



$$\frac{2980}{29} = \frac{143}{4}$$

dit



FOR 23°

$$\frac{13.1}{13.2} = \frac{x}{13.5}$$

x = 1.377

$$\frac{1.375}{1.383}$$

$$970 (1.383) = 1.373$$

$$\frac{1.375}{1.383}$$

how about the 23°

EXPERIMENTER

WITNESS

DATE

DATE

AL 0029653

DATE

9-13-44

SUBJECT OF EXPT.

Safety conditions

$$\begin{array}{r} 1.048 \\ 078 \\ \hline .970 \end{array}$$

$$\begin{array}{r} 1.241 \\ .651 \\ \hline .590 \\ .387 \\ \hline .977 \end{array}$$

$$\begin{array}{r} .977 \\ .970 \\ \hline \end{array}$$
Min. Safety interference = .007

$$\begin{array}{r} 1.046 \\ 82 \\ \hline .964 \end{array}$$

$$\begin{array}{r} 1.248 \\ 649 \\ \hline .597 \\ .391 \\ \hline .988 \\ .964 \end{array}$$
Max. Safety Int = .019

changed seal to make new oil and max. 026

EXPERIMENTER

WITNESS

DATE

DATE

49283
AL 0029654

38

DATE

EFFECT OF EXPT.

Thousand Spring design

Thick. OD - .170

Thin. OD - .164

ASSUME MEAN DIA .167

LEAD 1 .380 EXTENDED LOAD 4#

LEAD 1.340 COMPRESSION LOAD

$$d^3 = \frac{2.55 PD}{S} = \frac{2.55 (4) .147}{70,000} = .000025$$

$$d = .029" \text{ USE } .028$$

Schio HT. S.A. 270 = 9 COILS ACTIVE

$$\frac{P}{F} = 36.2$$

$$F = \frac{4}{36.2} = .11$$

$$.380 + .110 = .490 \text{ FREE LENGTH}$$

$$4^{\text{th}} \text{ LOAD } S = \frac{2.55 PD}{d^3} = \frac{2.55 (4) .139}{.0000219} = 48,700 \text{ PSI}$$

$$5^{\text{th}} \text{ LOAD } = 81,000 \text{ PSI}$$

$$6^{\text{th}} \text{ LOAD } = 97,000 \text{ PSI}$$

EXPERIMENTER

WITNESS

DATE

DATE

50283

AL 0029655

DATE
SUBJECT OF EXPT.

9-12-44
Star Spring (Cont)

$$\frac{P}{F} = \frac{G d^4}{8 D^3 N}$$

$$= \frac{11,500,000 (.000001615)}{4 \pi (.00268)} = 36.6 \pm 1/2$$

FREE LENGTH = .490

90% =

WT COCKED = $(.490 - .380) 36.6 = 4 \#$

WT FIRED = $(.490 - .340) 36.6 = 5.5 \#$

WT STACKED = $(.490 - .280) 36.6 = 7.7 \#$

$\frac{D}{d} = 5$ WAVE K = 1.31

$S = \frac{P 1755 (1.31)}{.0000319} K = P 16200 K$

COCKED S = $4 (16,200) 1.31 = 85,000 \text{ PSI}$

FIRED S = $5.5 = 117,000 \text{ PSI}$

80% S = $6.1 = 139,000 \text{ PSI}$

SOLIDS = $7.7 = 163,000 \text{ PSI}$

EXPERIMENTER
WITNESS


DATE
DATE

51283
AL 0029656

±U
DATE
SUBJECT OF EXPT.

A

9-10-55
Seal Spring (Second)



465
752
713

$$36(4) = 1.32 P$$

$$P = 1.1^{\#}$$

$$36(5.5) = 1.32 P$$

$$P = 1.5^{\#}$$

Second Spring

O.D. - 1.67

WIRE - 0.06

MEAN D - 1.41

0.06

0.06

$$29.5(X - 380) = 4^{\#}$$

$$X = \frac{38}{29.5} + 380 = 500 \text{ FREE LENGTH}$$

$$P = \frac{11,500,000 (0.0000047)}{64 (0.0078)} = 29.3 \text{ #/in}$$

505
234
266

$$\text{Index} + 5.4 = 1.78 \text{ WALL K}$$

COILED	(500 - 380) 29.3	= 3.5 #/in	
FIRE	(500 - 340)	= 4.7 #/in	S = P 7.5 #/in
STACKED	(500 - 240)	= 7.8 #/in	WITH K
80%	(215)	= 6.2 #/in	= P 20,400 K

COILS	3.5 (20,400) 1.78	= 92,000 PSI
FIRE	4.7	= 123,000
STACKED	7.8	= 204,000
80%	6.2	= 162,000

EXPERIMENTER

DATE

WITNESS

DATE

52,983

AL 0029657

DATE 9-18-44
SUBJECT OF EXPT. Live Loading (Flint)

$$\frac{P}{F} = \frac{G d^2}{8 D^3 N}$$

$$\begin{aligned} 0.8 &= d \\ 1.4 &= D \\ B &= N \end{aligned}$$

$$= \frac{11,500,000 (.000000615)}{64 (.00268)} = 41.2 \text{ #/in}$$

$$2.12 (X - 380) = 3.5$$

$$X = \frac{3.5}{41.2} + 380 = 380.085 = \text{FREE LENGTH}$$

$$\text{WT COCKED} = 380 (41.2) = 3.5$$

$$\text{FIRED} = 380 = 5.1$$

$$\text{STOPPED} = 752 = 8.8$$

$$\text{80\%} = 471 = 7.0$$

$$S = P \frac{F.55 (.159)}{1.0000719} R = P 16,700 K$$

$$\frac{P}{d} = 5 \quad R = 1.31$$

$$\text{COCKED } S = 3.5 (16,700) 1.31 = 74,000$$

$$\text{FIRED } S = 5.1 \quad " \quad " = 108,000$$

$$\text{STOPPED } S = 8.8 \quad " \quad " = 187,000$$

$$\text{80\% } S = 7.0 \quad " \quad " = 148,000$$

EXPERIMENTER
WITNESS

DATE
DATE

53083
AL 0029658

42

DATE

SUBJECT OF EXPT.

29-23-42

M-732 Preliminary Tests

A 360° preliminary sound check of the m-732 gave our patients to find out the carriage base locking under the post. The ball on the m-732 is noticeably hard on closing in the latter operation. A few of these 360° were fired at the target with very good results.

EXPERIMENTER

DATE

WITNESS

DATE

5/18/83

AL 0029659

9-21-44

DATE

SUBJECT OF EXPT.

M-721 Preliminary tests

After propogation in 721 dead .001°
 spec. dead spine (.274"). Max heading
 on assembly and poor contact on the edge
 condensation in this condition.

E K S I C H

EXPERIMENTER

WITNESS

DATE

DATE

58-283

AL 0029660

11

DATE

SUBJECT OF EXPT.

9-26-44 *Firing Pin Tolerance Check (Report)*FP
min 1.311

BOLT

.451

.315

.433

.064

1.263

1.311

.048 min protrusion

060
5.614
1.317
6.931
6.150

FP
max 1.317

.449

.309

.427

.060

1.245

1.317

.072

max protrusion

0.1800
450

225
5.3
720

min over all length

Rec & Sear

4819 4.871 Rec
1.365 min 1.389 Sear
6.180
47
6.137
6.148

tan 23° = 9.06 = 1.760

X = 1.309

Bolt

5.360
.492
4.863
.265
4.598 max

895
170
205

567
850
3.23

tan 23° = 4.285 = X

X = .0467

100
36
110

4.45
110

X = .064

Cocking Pin

565
450
1.010 max
4.598
5.400

Firing Pin from
to shoulder

6.184
6.1
6.120

6.180
6.1
6.128

EXPERIMENTER

DATE

WITNESS

DATE

56883

AL 0029661

DATE
SUBJECT OF EXPT.

9-26-44

Cocking Tolerances check (Repeat)

Some dimensions on 1st 5th 10th

$$10 \times \frac{1}{2} = 5$$

1000000

Rec Bolt min Dim - max
5.715 min 309 315
5.220 max 5.360

5.355

5.664

42.1

5.675

434

5.241 closed

less of bolt from
shoulder

5.239 closed

1.00

"

5.327 closed

35

Cocking Piece notch

5.292

400

553

150

400

5.692

437

6.129

560

45

15

5.781

434

6.165

6.137

812

5.325 notch to stop shoulder

5.125

300 mm stroke

497

315

815

145

444

589

5.604

5.025 notch to finger on shoulder

6145

796

5349 notch to stop shoulder

5008

0.341

max stroke

5608

600

3.002

EXPERIMENTER
WITNESS

DATE
DATE

57283
AL 0029662

46

DATE

SUBJECT OF EXPT.

9-27-44

Max solid height of main spring

1.000

.630

1.630

1.010

2.640

Bolt flange

4.50

.560

5.060 coiling piece

5.600

.200

5.363

2.840

2.513

max solid height 721

722

4.750

.200

4.503

2.840

1.663

max solid height 722

EXPERIMENTER

DATE

WITNESS

DATE

53883

AL 0029663

DATE
SUBJECT OF EXPT.

9-27-44
Main Springs 12-72
Drug # A-753-7

Load 24.4 - 26.8 at 2.00 283 deflection.

Length fired

985
365
620
330
950
742
1,692

430
62
492
250
742
5357
1,692

Strain 0.313
Prot 0.054

3,165
850
2,315

297
330
635
3,175

3,348
850
2,498

3,665 Length fired 19 #

3,348 Length cracked 21 #

5800
3,665
2,135

18.5 #
21.1 #

5700
3,348
2,452

21.1 #

24.4
26.8
51.2

25.4
663
32.23

2.97
2.20
77

3,348
3,628
290
145
3,493

19.8 # X 297 = 5,891 # Main Energy

$$S = \frac{8 \cdot P \cdot D}{\pi \cdot d^3} = \frac{8 \cdot (32.2) \cdot 345 \cdot 6.00}{\pi \cdot 3.1416 \cdot (0.016)^3} = 164,000$$

Max Working Stress = 121,000

mgat
69283

EXPERIMENTER
WITNESS

DATE
DATE

AL 0029664

48

DATE

SUBJECT OF EXPT.

Main Spring in 722

Screw in the Gun Hole

on 753" Pin

Free Length 1.600"

055 wire

400 outside

29 total coils

27 outside

$$\text{Spring Rate } \frac{F}{\Delta} = \frac{G d^4}{8 D^3 N} = \frac{11,500,000 (0.055)^4 (9.15)}{8 (27)^3 (24.12)} = 11.9$$

Coiled Length 2.498

Final Length 2.815

$$\begin{array}{r} 5.313 \\ 2.656 \\ 1.490 \\ \hline 4.246 \end{array}$$

S

Stress

313

Dist 0.54

5.7

3.20

1.84

2.00

1.54

5.2

23.6

26

49.6

24.8

24.8

6.6

31.4

$$\begin{array}{r} 2.498 \\ 2.815 \\ \hline 5.313 \end{array}$$

$$S(\text{stress}) = \frac{8 P D}{\pi d^3} = \frac{9(31.4)(34.5/100)}{3.14(0.055)^3} =$$

$$\text{Wt. Coiled} = 4.2 - 2.498 (11.8) = 20.1$$

$$\text{Wt. Fired} = 4.2 - 2.815 (11.8) = 16.5$$

$$18.5 \times 2.97 = 5.47 \text{ "H Energy}$$

$$\text{Max Working Stress} = 117,000 \text{ #}$$

EXPERIMENTER

WITNESS

DATE

DATE

AL 0029665

60283

SUBJECT OF EXPT


12-20-40

New Year's Society

Cont

Calc on old slar + Society

Ans: $L = \frac{8.5(1.5)}{1.29} = 9.9 \text{ ft}$



4.3/1 = ADVANTAGE

$$3.6(1.26) + 22.8(41) - 2(129) = 129.4$$

$$4.52 + 9.35 - 2.58 = 1.29 \text{ L}$$

Then $\frac{L}{r} = \frac{11.24}{1.48} = 7.8$

Actual Loss to prop. on = 6th off = 4th

Threats on = 1. ~~3~~ Neglecting safety features

Ca. ¹ million the Detroit

Return = $3\frac{1}{2}$

$$\frac{1}{8.8} = \cos \theta = .727$$

$$N = 62$$



$$X = \cos 45^\circ = 0.71$$

226

$$F_{\text{soil}} = \frac{196 \times 6.2}{97} = 12.2$$

By case $\frac{9.9}{4.3} = 2.3^{\#}$ to put sofa on

actual = $6^* - 3\frac{1}{2}^* = 2.5^*$

6283

EXPERIMENTER
WITNESS


DATE
DATE

AL 0029667

DATE

1-3-48

SUBJECT OF EXPT.

New location of Safety Detector Halon
Housing

$$\sin \alpha = \frac{301}{491} = .613 \quad \alpha = 37^\circ - 48'$$


Adding 5° to α

$$\alpha' = 42^\circ - 41'$$




$$\sin \alpha' = .6794 = \frac{x}{491}$$

$$x = 334 \quad \text{not satisfactory}$$



$$\sin \alpha = \frac{161}{491} = .3277$$

$$\alpha = 19^\circ - 8'$$



$$\sin \alpha' = \frac{.090}{.491} = .1831$$

$$\alpha' = 10^\circ - 33'$$

$$A = 21^\circ - 6'$$

$$10.45$$

$$21.36$$

$$10$$


$$5 = 48$$

$$\alpha + A = 40^\circ - 14'$$

$$37^\circ - 48'$$

$$\text{USE } 40^\circ - 48'$$

$$\sin 40^\circ - 48' = .6534 = \frac{x}{491} \quad x =$$



63883

EXPERIMENTER

WITNESS

DATE

DATE

AL 0029668

52

DATE

10-18-45

SUBJECT OF EXPT.

COCKING & TOL. CHECK.

Sear to Lug from Lug = 3.971 MAX
 " " to sear Point = 1.3036 MAX

LUG SEAT TO POINT OF SEAR 5.2946 MAX

MAX LUG TO BOLT HANDLE = 4.380.

MIN LUG TO COCKING POINT

30.9 BOLT HEAD

4.505 BOLT BODY

4.814

- .035 CAM SEAT

4.779

1.550 CAM POINT to shoulder

5.329

- .145 shoulder to notch

5.184

4.380

8.04

MIN BOLT HANDLE TO COCKING POINT

4.365 MIN LUG TO BOLT HANDLE SEAT

1.00 MIN PRIM EXT.

5.269 MIN LUG TO NOTCH BOLT ORIGIN

+ .030 for coming into notch in bolt

giving .025 MIN OVER TRAVEL

IF PRIMARY EXTRACTION CAM IS O.K.

Tan 27°: $\log 5 = \frac{x}{140}$

$x^{\text{max}} = .0714$

$x^{\text{min}} = .0765$

Cos 27°: $.891 = \frac{y}{x}$

$y^{\text{max}} = 1.375$

$y^{\text{min}} = 1.369$

1.375 - .0714 = 2

.0714

1.3036

1.369 - .0765 = 2

.0765


1.2925

1.3036

2.5961

2.98

.021



Tan 27°: $\frac{0.01}{x}$

2.5961

0.025

6.4283

EXPERIMENTER


WITNESS

DATE

DATE

AL 0029669

DATE 10-18-51
SUBJECT OF EXPT. PRIMARY EXTENSION CHECK



$$\sin x = \frac{100}{350} = .2855$$

$$x = 16^{\circ} 35'$$

$$\begin{array}{r} 45^{\circ} \\ 5^{\circ} \\ \hline 16^{\circ} 35' \\ \hline 66 \end{array}$$

$$3d = 5/4000$$

$$\begin{array}{rcl} \text{Seal Pin hole from Rec Lug} & = & 3.970 \pm 1 \\ \text{Seal Pin hole to seal notch} & = & 1.298 \pm 5.6 \\ \hline & & 5.268 \pm 6.6 \end{array}$$

$$\begin{array}{rcl} \text{Bolt Head} & = & .312 \pm 3 \\ \text{Bolt Body} & = & 4.5075 \pm 2.5 \end{array}$$

$$\begin{array}{rcl} \text{Cam Seat} & = & 4.8195 \pm 5.5 \\ & & - .0225 \pm 2.5 \end{array}$$

$$\begin{array}{rcl} \text{Cam point to shoulder} & = & 4.7870 \pm 8.0 \\ & & - .555 \pm 5.0 \end{array}$$

$$\begin{array}{rcl} \text{Shoulder to notch} & = & 5.3420 \pm 13.0 \\ & & - .1125 \pm 2.5 \end{array}$$

$$\begin{array}{rcl} \text{Lug to Bolt Head} & = & 5.1995 \pm 15.5 \\ \hline & & 4.3775 \pm 2.5 \end{array}$$

$$\begin{array}{rcl} \text{Rec shoulder to Ext cam} & = & 4.3675 \pm 2.5 \\ \text{Cam} & = & .1025 \pm 2.5 \\ \hline & & 4.4700 \pm 5 \end{array}$$

$$\begin{array}{rcl} 5.268 \pm 6.6 & 8.22 \pm 18 & 5.1995 \pm 15.5 \\ 4.470 \pm 5.0 & 2.98 \pm 11.6 & 4.3775 \pm 2.5 \\ 798 \pm 116 & .024 \pm 39.6 & 8.226 \pm 18 \end{array}$$

$$\sqrt{2.5} = \pm 10.2$$

65783

EXPERIMENTER
WITNESS

DATE
DATE

AL 0029670

54

DATE 10-22-45
SUBJECT OF EXPT.New section part & extraction curve center section
as per request of engineering.

$$\frac{5.572}{.613} = 9.09$$

$$\frac{1.317}{1.052} = 1.25$$

$$\frac{70}{9607}$$

$$76 = \frac{1361}{1.791} = 759.4$$

$$\alpha = 40^{\circ}32'$$

$$\tan \alpha = .855 = \frac{x}{1.361}$$

$$x = 1.165$$

$$\sin A = \frac{(1.93)2.97}{2.195(1.824)(1.05)(2.45)}$$

$$38^{\circ}11'$$

$$\frac{1.712}{x} = \cos 35^{\circ}11' = .805$$

$$A = 9^{\circ}13'$$

$$\frac{2.040}{1.351} = 1.503$$

$$\frac{2.175}{1.351} = 1.603$$

$$\frac{2.175}{1.351} = 1.603$$

$$\frac{300}{10.5} = 28.57$$

$$\sin 43.25^{\circ} = x = 4.82$$

$$1.328$$

$$\sin \alpha = \frac{1.67}{3.51}$$

$$\alpha =$$

$$27^{\circ}39'$$

$$27.65$$

$$3.37$$

EXPERIMENTER
WITNESSDATE
DATE660783
AL 0029671

DATE
SUBJECT OF EXPT.

$$h = .351(1 - .825)$$

$$= .351(1.175)$$

$$= .412$$

N.G.

Angle of chord on ext com on Rec = 13° 47' with H

$$\frac{.117}{.112}$$

$$\frac{1.93}{1.79}$$

$$1.14$$


$$\tan x = \frac{.1145}{.14} =$$

N.G.
 $\alpha = 39^{\circ} 16'$

$$9 + 355 = \frac{7}{.351}$$

$$\frac{1.71}{3.20}$$

$$1.39$$



$$\frac{21256}{.351}$$

$$21256$$


$$106280$$

$$63768$$

$$7460851$$

$$149216$$

$$\sin 20^{\circ} = .4647 = \frac{x}{.351}$$



$$\frac{1.165}{.143}$$

$$1.308$$

$$1.392$$

$$\sin 43.13^{\circ} = \frac{1.308}{x}$$

$$6847$$

$$x = \frac{1.910}{\text{outer Rectcom.}}$$

$$677.83$$

EXPERIMENTER
WITNESS

DATE
DATE

AL 0029672

56

DATE

SUBJECT OF EXPT.

A

$$\sin A = \frac{r}{b c} \sqrt{s(s-a)(s-b)(s-c)}$$

$$a = .499$$

$$b = 2.070$$

$$c = 1.900$$

$$4.469$$

$$2.2345$$

$$.400$$

$$1.7355$$

$$2.2345$$

$$2.070$$

$$.1645$$

$$2.2345$$

$$1.9$$

$$.3345$$

$$= .508$$

$$\sin A = .2348$$

$$A = 13^\circ - 35'$$

$$34^\circ = 12'$$

$$47^\circ - 47'$$

$$\sin 47^\circ = \frac{x}{1.900} = .7406$$

$$x = 1.407$$

$$1.165$$

$$\cos \alpha = \frac{.143}{.146}$$

$$\alpha = 11^\circ - 45' \text{ ept cam chord angle with horiz}$$

$$26791$$

$$351$$

$$20791$$

$$103955$$

$$62373$$

$$107297641$$

$$2$$

$$.14594$$

$$1910$$

$$179$$

$$1720$$

$$1185$$

$$120$$

$$99.6$$

$$A = 43^\circ 39' \text{ ept cam angle with Rec.}$$

EXPERIMENTER

WITNESS

DATE

DATE

68883

AL 0029673

DATE


SUBJECT OF EXPT.

$$\frac{1.165}{1.361} = \tan \alpha$$

$$\alpha =$$

$$\frac{1.172}{1.361} = \frac{35'}{13.61}$$

E





$$\frac{1.179}{1.361} = \frac{37'}{13.61}$$

$$\cos 49^{\circ} 28' = \frac{1.405}{X}$$

$$X = 2.161$$

$$\sec 49^{\circ} 28' = 1.5382$$

$$X = 1.5387 (1.405) = 2.161$$



$$\tan 43^{\circ} 30' = \frac{1.22}{X} = \frac{9.4996}{X}$$

6.9.83


EXPERIMENTER
WITNESS

DATE
DATE

AL 0029674

DATE / /
SUBJECT OF EXPT.

6-43
Clinton Hosiery



WITNESS

DATE _____

AL 0029675



0473


SUBJECT OF EXP'T.

3-13-46
EXPT. 2 putation down

五

5/9

1170
1168
1165


$$S_{\text{ST}} = 2.43$$

三

2000

38.9
- 9.25

29.65

$$3624 = 499 \cdot 480962$$
$$29 - 16 = 48$$

$2.5 \times 10^5 = 5.4 \times 10^5$

10

0	1	2	3	4	5	6	7	8	9
0	1	2	3	4	5	6	7	8	9

1.2025	1605
2.449	486
<u>1.4465</u>	1169

Chad = 1103

15

$$\Sigma + \beta = \frac{19965}{186} = 218$$

Q-517

$$S_{10} a - 10^2 = \frac{x}{100} = 169$$

155 = 2

Page 8 = 114665 = 1226

$\frac{1}{2} \times 0.8 = 0.4$

11

WITNESS

EXPERIMENTER

DATE _____

DATE

AL 0029677


$$\frac{x}{1.190} = 1.235 \quad 72.083$$

DATE _____

4-8-46

SUBJECT OF EXPT.

274 Rem.



9096

17247

1849

214314

2157

4314

292

21,1394

10697

242

1-46

37

1875

17272

17247

0030

4294

242

19117

1906

0021

77005

7245

0748

307

014

五八

1689

20542

100

506

7905
7575
0367

20479

1940

1079

EXPERIMENTER

WITNESS

DATE

DATE _____

73883

AL 0029678

62

DATE


SUBJECT OR EXPT.

5-29-46
SKETCH FOR SCIENTS

A

L

E



S

I

C

EXPERIMENTER

WITNESS

DATE

DATE

24-283

AL 0029679

DATE

SUBJECT OF EXPT.

L

E

K

S

I

C

H

EXPERIMENTER

WITNESS

DATE

DATE

76283

AL 0029680


64

DATE

8-25-47

SUBJECT OF EXPT.

Bolt + Bolt Class



93

95

1.149

1.183

1.332

0.728

0.604

0.600

0.004 down from

1.151

1.187

1.336

0.723

0.615

0.595

0.020 mark

.4485

1.151

1.187

1.338

.4485

.8895

1.149


1.183

1.332

.4515

.8805

S



345

345

345

345

0.604

0.600

0.004

0.020

0.004

0.020

0.004

0.020

0.004

0.020

0.004

0.020

EXPERIMENTER

WITNESS

DATE

DATE

76283

AL 0029681

DATE
SUBJECT OF EXPT.

10-1-48

New Calculations for Report in
Products Engineering Article

BARREL STRENGTH

FORMULAE Lame's

$$S = \frac{P(r_2^2 + r_1^2)}{r_2^2 - r_1^2}$$

S = stress tang.

P = Int press.

r₁ = inside r

r₂ = outside r

$$r_1 = .750 = .0625$$

$$r_2 = .575 = .331$$

$$S' = \frac{I \times P}{t} \quad t = \text{thickness}$$

$$P = 84,000 \text{ PSI}$$

$$= \frac{\frac{1}{2}(250)84,000}{.575}$$

$$S = \frac{84,000(.343)}{.269}$$

$$S' = 18,250 \text{ Longit.}$$

$$= 123,000 \text{ PSI}$$

$$\frac{17,300}{1.875} = 10,475$$

ORDNANCE

$$\theta = \frac{P}{\frac{3}{2} \left(\frac{r_2^2 - r_1^2}{r_2^2 + 2r_1^2} \right)}$$

θ = Elastic Limit
of material
used.

$$= \frac{84,000}{\frac{3}{2} \left(\frac{.264}{.724} \right)}$$

$$= \frac{84,000}{.572}$$

$$= 146,853$$

$$= 150,000$$

EXPERIMENTER
WITNESS

DATE
DATE

77883

AL 0029682

A

10-4-48

Cox's

$$y = \frac{2}{3} \left[\frac{P}{w^2 - 1} (2w^2 + 1) \right]$$

$$w = \frac{\text{outside dia}}{\text{inside dia}}$$

$$= \frac{1.15}{.5} = 2.3$$

$$w^2 = 5.19$$

P = Pressure unit

y = Stress

$$y = \frac{2}{3} \left[\frac{8400}{4.19} \right] 11.38$$

$$= 152000$$

AVERAGE S using LAMES $P_0 = 0$

$$S = \frac{P \left(r_1^2 + \frac{r_2^2 r_1^2}{r_2^2 - r_1^2} \right)}{r_2^2 - r_1^2}$$

Substituting

$$r = .750 \quad S_r = 123,000$$

$$r = .331 \quad S_r = 80,600$$

$$r = .412 \quad S_r = 57,200$$

$$r = .494 \quad S_r = 45,600$$

$$r = .576 \quad S_r = 38,800$$

$$203,600$$

$$132,800$$

$$102,400$$

$$84,400$$

782.83

DATE
SUBJECT OF EXPT.

10-4-48
CONT.

$$AREA = \frac{123,000 + 89,600}{2} (0.81) = 8230$$

$$\frac{80,600 + 57,200}{2} (0.81) = 5580$$

$$\frac{57,200 + 45,600}{2} (0.82) = 4160$$


$$\frac{45,600 + 38,800}{2} (0.81) = 3420$$

$$21390$$

$$- 300$$

$$\frac{21090}{375} = 64,900 \text{ p.s.i.} = \text{Avg stress}$$

64,900 p.s.i. = Avg stress



EXPERIMENTER
WITNESS

DATE
DATE

77883
AL 0029684

A

10-11-48
Cont. LOCK TIME

$$E = \frac{1}{2} MV^2$$

$$E = 15$$

$$V = \frac{V_1 - V_2}{2}$$

$$V_1 = 0$$

$$V = \frac{V_2}{2}$$

$$V = \frac{2.5}{T}$$

$$V = \sqrt{\frac{2E}{M}}$$

$$T = \frac{2.5}{\sqrt{\frac{2 \times 15}{M}}}$$

$$2 \left(\frac{.300}{12} \right)$$

S

$$2(0.25)$$

$$\frac{\sqrt{2(2) \frac{.500}{12}}}{67.9 \times .0022}$$

$$\sqrt{\frac{.005}{.00447}}$$

$$= \frac{.056}{\sqrt{2.46}}$$

$$= \frac{.056}{1.49}$$

$$= .00334$$

C

$$2 \left(\frac{.300}{12} \right) = \frac{1}{2} \frac{67.9(.0022)}{32} V^2$$

$$T^2 = \frac{4S^2}{2PSM}$$

$$T^2 = \frac{2SM}{P}$$

$$\frac{5.9 \times 10^{-4}}{3.4 \times 10^{-4}} = 1.7$$

80783

DATE

SUBJECT OF EXPT.

A

$$T = \frac{\sqrt{2MS}}{P}$$

$$E = \frac{1}{2}mv^2$$

$$E = PS$$

E

K

S

I

C

H

EXPERIMENTER

WITNESS

DATE

DATE

81 283

AL 0029686

70

DATE

SUBJECT OF EXPT.

THIS BOOK MICROFILMED
AS COMPLETE
MAKE NO ADDITIONAL ENTRIES

EXPERIMENTER

DATE

WITNESS

DATE

82283
AL 0029687

DATE
SUBJECT OF ENTRY

THIS BOOK MICROFILMED
AS COMPLETE
MAKE NO ADDITIONAL ENTRIES

K
S
I
C

EXPERIMENTER
WITNESS

DATE
DATE

83983
AL 0029688

RECEIVING and ESTIMATE REPORT

ORDER R **22286**

PROV DATE 11/14/76 RECEIVED 9176 ESTIMATED up VIA W33 CHARGES

FROM Peoria Police Dept

542 SW Adams St Peoria, ILL

MODEL and GRADE 700 BDL variant 223cm SERIAL NO. H6231124 DATE CODE X2

GRADE CODE 12/15

FOR COMPUTER REFER. ONLY Lights REPAIR CHG. 80.55

INS.

PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Quoted) TOTAL

CUSTOMER'S COMPLAINT safety moved from safe to fire

position & he was able to fire.

MAIN FAULT Trigger connector Broken

GALLERY REPORT 19461 - trigger connector

File - M/700 Customer Complaints

Done

PLAINTIFF'S EXHIBIT
3169

173
AL 0029689

RECEIVING and ESTIMATE REPORT

ORDER R 22285

FROM DATE 7-14-76 ESTIMATED 9-12-76 VIA up CHARGES

FROM Peoria Police Dept
 42 SW Adams St Peoria, ILL
 MODEL and GRADE 700BOL Year 223 Rem SERIAL NO AL36452 DATE CODE XZ

GRADE CODE
 FOR COMPUTER REFER. ONLY
 L1 Slight
 REPAIR CHG. 80.55
 INS
 PARCEL POST

GUN CONDITION (New) (Slightly worn) (Very worn) (Misused) (Ruined) TOTAL

CUSTOMER'S COMPLAINT Safety ~~not~~ safe to fire
 position & he was ~~not~~ firing
 MAIN FAULT

gun water Broken Trigger ADS
 Surveys not properly ADS outside factory

GALLERY REPORT

19461 - Trigger gun water

7-14-76
 Customer Complaints
 ADS Trigger (H)

(Clean) (Test) (Target)
 done

223
 AL 0029690

POLICE DEPARTMENT

CITY OF
PEORIA

Sept. 3, 1976

Remington Arms

Arms Service Division

Elion, N.Y. 13357

Gentlemen:

Enclosed please find two Remingtons, Model 700, Varmint Special, .223 Cal. rifles- Serial #'s A6237966 and A6236452. R 22285

These rifles were purchased by this department earlier this year from Varmes Guns Inc., Belle Fontaine, Ohio. Both of these weapons were found defective and when we contacted them, we were informed to send them back to the manufacture as they would be the only ones who would repair them.

Both these weapons are used by our Tactical Unit, and we are in need of them as soon as possible.

Both of these weapons were fired less than 100 rounds when it was found that they were unsafe. With a live round in the chamber and the bolt closed, the safety was moved from the "safe" to "fire" position the weapon would fire. This did not happen every time, but it did happen intermittently.

Sincerely,

Sgt. Russell
Sergeant Russell

5425th Admin
Rec'd: 11/15/1907
300/672-1521

AL 0029691
393

Handy Single

A action guns use this model, outside of excessive pressure ammunition, as firing or blowing into the firing pin sticking forward.

[m/200. In your gun forward -

This was a problem some time ago when the reassembly operation was performed by the first assembler. If too much cement was put on the same handle, in the process of turning the housing to seat the screws on the opposite side, the excess cement would go between the side plates in the area of the rear spring. The procedure now is for this operation to be done by a sub-assembler who leaves the housing in one position until the cement dries. Then the housing is turned over, and the opposite screws cemented.

gabauer
11/29/75

PLAINTIFF'S
EXHIBIT

3170

1071
AL 0029692

cc: E. R. Carr
J. P. Linde

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

DUPLICATE

PETERS

REPORT

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY" _____ March 10, 1975

C. B. WORKMAN

Re: M/700, 600 FIRE CONTROL MALFUNCTIONS

One M/700, and one M/600 were returned recently from Texas with complaints that the gun would not fire when the Trigger was pulled. On both of these guns, manipulating the Bolt Handle after the Trigger was pulled caused the gun to fire.

An investigation of both guns produced the same result. The Fire Control slots and Firing Pin Head slots in the Receivers were not properly lined up. As a consequence, when the Trigger was pulled the Firing Pin Head went forward until it hit the Fire Control Housing Side Plate which was protruding into the Firing Pin Head slot. Moving the Bolt Handle rotated the Firing Pin Head sufficiently to clear the Housing Side Plate and strike the Firing Pin.

Both guns were repaired by filing a lead on the Firing Pin Head and Fire Control Housing Side Plate.

These guns were able to pass our Gallery tests due to our lubrication practices. The M/700 was made in 1970. By the time this gun was used all of the lubrication that was on it when it left Ilion had dried up. The gun was made functionally acceptable again by oiling the Bolt without doing anything else to it.

JWB:jc

J. W. Bower
Sr. Process Engineer

PLAINTIFF'S
EXHIBIT

3171

121
AL 0029693

PURCHASE ORDER

Les Freer

GUN SHOP

FIREARMS DEALER
LICENSE NO. 74-6344

ORDER NO. 7476
THIS NO. MUST APPEAR ON
INVOICE, B/L, AND CASES.

DATE

Jan. 28, 1975

1928 SPRING BRANCH DRIVE
HOUSTON, TEXAS 77058
713/487-3016

ISSUED TO

Mr. George Martin
Remington Arms Co.
Ilion, New York # 13357

SHIPPING DATE

VIA

RECEIVED

For prompt payment mail invoice showing order number with bill of lading after shipment is made.
Acknowledge and advise promptly if unable to make immediate shipment.
Goods subject to our inspection, notwithstanding prior payment to obtain cash discount.

FEB 04 1975

QUANTITY

NUMBER

DESCRIPTION

G. W. MARTIN

Dear George:

Subject: Trigger malfunctions

Re our phone conversations, I am forwarding one Model 700BDL, 25/06, serial #6356761 just as we received it from GLOBE STORE #3, 6200 Bellaire Blvd., Houston.

We produced a malfunction in this trigger assembly as follows: cocked the bolt, put the safety on and pulled the trigger - the safety held as it should (did not fire) - then the safety was moved to "fire" position and the trigger pulled again but then the sear failed to trip (did not fire); however a few more pulls on the trigger and it suddenly fired.

Like most trigger malfunctions we have found, this one may be difficult to reproduce, may require several attempts to demonstrate but if you keep trying it will occur.

Although this particular malfunction is not the same as most recent ones it is closely related to the overall problem. Hope it is of some help to you.

SHIPPED UNDER SEPARATE COVER

Best regards,

Les
Les Freer

ON 1-31-75 VIA *Priority Post*
Please acknowledge receipt

PLAINTIFF'S
EXHIBIT

3172

AL 0029694

RECEIVED

FEB 4 1975

ARMS SERVICE

8928 SPRING BRANCH DRIVE
HOUSTON, TEXAS 77053
713/467-3016

PURCHASE ORDER

Les Freer

GUN SHOP

FIREARMS DEALER
LICENSE NO. 74-6344

ORDER No. 7477
THIS NO. MUST APPEAR ON
INVOICE, B/L, AND CASES

DATE

Jan. 29, 1975

ISSUED TO

Mr. George Martin
Remington Arms Co.
Ilion, New York 13357

SHIPPING DATE

VIA

For prompt payment mail invoice showing order number with bill of lading after shipment is made.
Acknowledge and advise promptly if unable to make immediate shipment.
Goods subject to our inspection, notwithstanding prior payment to obtain cash discount.

QUANTITY	NUMBER	DESCRIPTION
		Dear George: Subject: M/600 Trigger Malfunctionns Here is another Model 600 trigger problem, serial No.6651698, cal. 6mm, just as we received it from the owner - we have disturbed nothing on the gun, have not even removed it from its stock for inspection. Purchased last Saturday from Carter's Country, Houston, the owner fired half dozen rounds on the rifle range when he had a malfunction by simply failing to get a firing pin fall by pulling the trigger with the safety in normal "fire" position. He then removed his finger from the trigger and the gun discharged as he reached for the bolt handle. The owner assures us that no one has tinkered with any part of the rifle since he purchased it. We failed to produce the same malfunction after several attempts but we find the trigger pulls so creepy and rough we have to believe the owner. Here again we find performance of the trigger erratic and frustrating, but very dangerous for this reason. If we were to repair this one we probably would choose to replace the trigger assembly. Hope this helps to point up the problem. Owner: Raymond Osbon 11703 No. Petershan Houston 77071 Ph 498-8312

AL 0029695

PLAINTIFF'S
EXHIBIT

3173

But signed

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
CORPORATIONPETERS
CORPORATIONcc: C. B. Workman
J. P. Linde
C. F. Prosser

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

March 18, 1975

E. R. CARR

PROGRESS REPORT - M/600 - 700 FIRE CONTROL

All assemblers have been instructed in how to check for the gun firing when the Safety is released. Included in this instruction is the technique of attempting to hang the Safety up halfway between the on and off positions. The instructions will be included in the Process Records by 3/21.

An operation to swage the coming surface of the M/600 Safety is being done. This provides additional lift on the Sear.

Research is contemplating several design changes on the M/600. These include the following:

1. Heat treating the Housing stamping. This is currently soft and the Safety Detent Ball wears a groove in it which facilitates the Safety hanging up.
2. A change in the Safety to provide additional lift of the Sear.
3. A redesign of the countersink on the Housing to provide a minimum flat between the on and off position, which will mean a more positive Safety.
4. Eliminating the stamped Housing and going to side plates and spacers similar to the M/700. Costs are being developed on this proposal to determine if it is economically feasible.

JWB:jc

J. W. Bower
Sr. Process Engineer

Bob - Add to this list a positive method of measuring sear lift when the safety is in the "On" position to a "gage" tolerance range.

Clark

(note) Either optically or on dial indicators.

PLAINTIFF'S
EXHIBIT

3174

121
AL 0029703

A

L

E

K

S

L

C

H

2-10

Fred Milbauer

DON'T SAY IT—WRITE IT

To *M. Galt*

DATE December 21, 1973

FROM E. R. Carr

M/700 - CUSTOMER COMPLAINTS

Fires on Safe - Follows down

Over three years ago, all guns in the above category began to be referred to P.E. & C. for examination and diagnosis. It began to be readily apparent that these guns were all the result of minimal Connector-Sear engagement.

In June of 1972, an operation was initiated making the adjustment on a comparator which assured a minimum engagement of .015".

It is my opinion that review of these guns, except in the case of Damaged Actions or Personal Injury guns, is no longer justified and should be discontinued.

*Does this present any problem to you
like*

*Not at all. We
will stop sending
to P.E. & C. this type
of complaint as of 1/2/74
F. Plunkett*

TO BE SAFE, FIRST THINK YOU MIGHT NOT BE



AL 0029705

Cust. Complaint.

No GUN EXAMINATION REPORT NUMBER: MODEL: 700 ADL
 GENERAL CONDITION: GOOD R #: 002805
 OUTSIDE WORK: SWIVELS AND SCOPE MOUNT- DATE: 2-1-73
 ED. FROM: FULKS SPORTING
 FIRED AMMO TYPE: CLARKSBURG, W.VA.
 & CONDITION: GUN #: 6247427
 PROOP: R.E.P.-A INSP. 73 TEST: 87 CODE: KS = 5/69
 HEADING: O.K. GA./CAL.: 270 WIN.
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED:
 CHAMBER: O.K. APPROVED:
 TEST: NO APPROVED:
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. IS .020)

CONNECTOR CLEARANCE ON TRIGGER = .0069 (MODEL = 1.076 DRAINING = 1.079)

OF TRIGGER PIN HOLE TO TOP OF TRIGGER = .974 (.973 .971)

COMPLAINT: FIRES WHEN SAFETY IS MOVED TO FIRE POSITION.

INCIDENT: FOLLOW DOWN

COMMENTS: THE EXCESSIVE MOVEMENT BETWEEN TRIGGER &
 TRIGGER CONNECTOR WILL ALLOW INTERFERENCE
 BETWEEN THE SEAR AND CONNECTOR WHICH PREVENTS
 RETRACTION INTO COCKED POSITION. THE PRESENCE
 OF HARDENED LUBRICANT INCREASES THE POSSIBILITY
 OF A MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3176

AL 0029706

Carl Cuyler

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 003187
OUTSIDE WORK: NO DATE: 1-30-73
FROM: J. FOSTER
FIRED AMMO TYPE: - LYNCHBURG, VA.
& CONDITION: _____ GUN #: 6326074
PROOF: R.E.P. A INSP.: 9 TEST: 55 CODE: CT = 4/70
HEADING: O.K. GA./CAL.: 25-06
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
CONNECTOR-TRIGGER CLEARANCE = 1.084 (MODEL 1.080 DRAWING 1.083) TRIGGER-
CONNECTOR CLEARANCE = 1.072 (1.076 / 1.070) CENTER LINE OF PIN HOLE
TO TOP OF TRIGGER = .974 (.973 / .971) CENTER OF PIVOT HOLE
IN SAFETY TO TOP OF CAM = .291 (.292 / .286)

COMPLAINT: "FIRED WITH SAFETY ON"

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT
3177

COMMENTS: THE RIFLE WILL NOT FIRE WITH THE SAFETY ON.
THE CONDITIONS LISTED ABOVE: .005 TOO MUCH CLEAR-
ANCE BETWEEN CONNECTOR & TRIGGER, TOP OF TRIGGER
.001 OVER MAX. AND SAFETY .001 UNDER MIN., ALL
CONTRIBUTE TO AN INTERFERENCE BETWEEN THE
CONNECTOR AND SEAR WHICH WOULD PREVENT
RETRACTION INTO COCKED POSITION TO CAUSE FOLLOW

Cust Complaint

I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 002158
 OUTSIDE WORK: SCOPE MOUNTED DATE: 1-23-73
 FROM: SPORTSMAN'S HEADQUARTERS
 FIRED AMMO TYPE: _____ GRAND FORKS, N.D.
 & CONDITION: _____ GUN #: 6451849
 PROOP: R.E.P.-L INSP.: 9 TEST: 53 CODE: PU = 6/71
 HEADING: O.K. GUN./CAL.: 200G
 BREACH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

HOUSING: .069 AT TOP (MODEL DRAWING: 173) TRIGGER
.173 LOWER END (MODEL DRAWING: 170) METAL CHIPS
AROUND PIN HOLE ON TRIGGER SEAR-TRIGGER
CONNECTOR ENGAGEMENT .010 (MIN. .020)

COMPLAINT: "WILL FIRE WHILE REMOVING UNFIRED SHELL
FROM THE CHAMBER"

INCIDENT: FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3178

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED.
THE BINDING TRIGGER AND SEAR FAILING TO RETRACT
ALONG WITH UNDER MIN. ENGAGEMENT PROBABLY
CAUSED THE FOLLOW DOWN.

Custom Gun

1. NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: GOODR #: 001432OUTSIDE WORK: SCOPE MOUNTEDDATE: 1-16-73FROM: BEIRCH
AMMUNITION CORP.FIRED AMMO TYPE: TROCHESTER, N.Y.

& CONDITION: _____

GUN #: 375936PROOF: R.E.P. INSP.: U TEST: 87CODE: ER = 10/68HEADING: O.K.GA./CAL.: 3006BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

CONSIDERABLE DIRT INCLUDING METAL PARTICLES
INSIDE HOUSING. HARDENED LUBRICATION ON TRIGGER.
CONNECTOR = 1.083 (1.080 MODEL DRAWING) TRIGGER = 1.076
(1.076 MODEL DRAWING) SAFETY & TO CAM = .291 (1.292 MODEL
1.079 DRAWING)

COMPLAINT: "FIRES WITH SAFETY ON"INCIDENT: FOLLOW DOWN

COMMENTS: THE CONNECTOR CAN WORK UP TO INTERFERE
WITH THE SEAR AND PREVENT RETRACTION INTO
COCKED POSITION.

PLAINTIFF'S
EXHIBIT

3179

Curt Corp

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700

GENERAL CONDITION: FAIR R #: -

OUTSIDE WORK: RECEIVER RE-COLORED, DATE: 1-22-73

NEW BARREL FITTED, SPECIAL SLINGS, FROM: _____

FIRE AMMO TYPE: -

& CONDITION: DIATHALON GUN GUN #: 6403732

PROOF: NO MARKING TEST: - CODE: NO MARKING

HEADING: MAX. GA./CAL.: 22 P

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: EXCESSIVE RADIUS - REAR APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: 20 ROUNDS - AFTER FITTING NEW BOLT APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

OLD STYLE SAFETY - COCKING CAM DAMAGED
BY SAFETY. HEADING MAX DUE TO BEARING ON
EXCESSIVE RADIUS AT REAR OF RECOIL SHOULDERS.

COMPLAINT: _____

INCIDENT: _____

PLAINTIFF'S
EXHIBIT

3180

COMMENTS: THE BEARING ON THE RADIUS AT REAR OF RECOIL
SHOULDERS CAUSED HEAVY BOLT LIFT, FURTHER
INTERFERENCE BY CLOSING AND LOCKING THE
BOLT WITH THE SAFETY "ON" COULD CAUSE A
JAM AND DAMAGE TO THE COCKING CAM.

I. NO GUN EXAMINATION REPORT NUMBER: _____GENERAL CONDITION: GOODOUTSIDE WORK: SCOPE MOUNTEDFIRED AMMO TYPE: -

& CONDITION: _____

PROOF: R.E.P. INSP. U TEST: ?HEADING: O.K.BRECH OPENING: -RECOIL SHOULDERS: O.K.CHAMBER: O.K.

TEST: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

*Cast. Compl.*MODEL: 700ADLR #: 000972DATE: 1-5-73FROM: COOPER'S
SPORTING GROUPSMANFIELD, PA.GUN #: 300043CODE: NP = 8/67GA./CAL.: 270WIN.CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

BOLT HANDLE BROKEN OFF. TRIGGER BINDING -
HEAVY LUBRICANT - CONNECTOR STUCK TO
TRIGGER. CORNER OF SEAR BROKEN DOWN.

COMPLAINT: FIRES WHEN SAFETY IS TAKEN OFF.INCIDENT: FOLLOW DOWNPLAINTIFF'S
EXHIBIT3181

COMMENTS: THE TRIGGER BINDING AS A RESULT OF THE
DRIED OUT LUBRICANT FAILED TO RETRACT,
REMAINING IN FIRED POSITION, CAUSED THE
FOLLOW DOWN.

Curt Campbell

I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660
 GENERAL CONDITION: GOOD R #: 000918
 OUTSIDE WORK: NO DATE: 1-12-73
 FIRED AMMO TYPE: _____ FROM: C.H. DANA JR.
 & CONDITION: _____ ST. JOHNSBURY, VT.
 PROOF: R.E.P. INSP. U TEST: 49 GUN #: 104573
 HEADING: _____ CODE: BR-1/68
 BREACH OPENING: _____ G.K./CAL.: 222
 RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
 CHAMBER: O.K. APPROVED: _____
 TEST: NO. APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR BIND - HEAVY LUBRICANT + BURRS AROUND PIN
HOLES IN HOUSING. FIRING PIN HEAD MARKS IN THE
HOUSING LEFT, REAR.

COMPLAINT: GUN GOES OFF BY ITSELF.

INCIDENT: FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3182

COMMENTS: CUSTOMER'S MALFUNCTION NOT DUPLICATED.

THE SEAR, BINDING FROM BURRS AT THE PIN HOLES
AND HEAVY LUBRICANT, PROBABLY REMAINED IN FIRED
POSITION ALLOWING THE FIRING PIN TO FOLLOW DOWN.

.1. NO GUN EXAMINATION REPORT NUMBER: _____GENERAL CONDITION: GOODOUTSIDE WORK: SCOPE MOUNTED, BUTT PADFITTED.

FIRED AMMO TYPE: _____

& CONDITION: _____

PROOF: R.E.P. INSP.: D TEST: B7HEADING: -BREECH OPENING: -RECOIL SHOULDERS: O.K.CHAMBER: O.K.TEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

Curt GoughMODEL: 700 ADLR #: 000130DATE: 1-11-73FROM: ESTELL CURRYGATESVILLE, TEXASGUN #: 165224CODE: WM = 8/65GK./CAL.: 20.3 W.M.CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

STEEL CHIPS BETWEEN TRIGGER AND CONNECTOR.HARDENED LUBRICANT AROUND SEAR. EVIDENCE OF
FIRING PIN HEAD CATCHING ON REAR-LEFT CORNER
OF HOUSING.COMPLAINT: FIRED AS BOLT WAS UNLOCKEDINCIDENT: FOLLOW DOWNPLAINTIFF'S
EXHIBIT3183COMMENTS: THE CHIPS BETWEEN TRIGGER AND CONNECTOR
CAUSE SEAR-CONNECTOR ENGAGEMENT TO VARY
LEADING TO FOLLOW-DOWN. THE HARDENED
LUBRICANT AND FIRING PIN HEAD-HOUSING INTER-
FERENCE ALSO CONTRIBUTE TO FOLLOW-DOWN
MALFUNCTIONS.

Cust Conyht

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 000394
OUTSIDE WORK: NO DATE: 1-9-73
FROM: JOHN'S SPORTS CENTER
FIRED AMMO TYPE: - PITTSBURGH, KAN.
& CONDITION: _____ GUN #: 6432940
PROOF: R.E.P.-4 INSP.: 73 TEST: B4 CODE: CU-4/71
HEADING: - GA./CAL.: 243 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

BOLT CAM MARRED BY SAFETY. GROOVE CUT INTO
LEFT REAR OF HOUSING BY FIRING PIN HEAD. SEAR-
TRIGGER CONNECTOR ENGAGEMENT .015 (MIN. IS .020)
CONNECTOR BINDING ON TRIGGER.

COMPLAINT: "WENT OFF WHEN THE BOLT WAS CLOSED"

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT

3184

COMMENTS: THE TRIGGER CONNECTOR PROBABLY FAILED TO
RETRACT INTO POSITION UNDER THE SEAR, ALLOWING
THE FIRING PIN TO FOLLOW DOWN.

NO GUN EXAMINATION REPORT NUMBER: _____

GENERAL CONDITION: FAIR

OUTSIDE WORK: SCOPE MOUNTED, BUTT PAD
FITTED, SEALS REMOVED - TRIGGER

FIRE AMMO TYPE: _____

& CONDITION: _____

PROOF: R.E.P. INSP.: 5 TEST: 13

HEADING: ?

BREECH OPENING: -

RECOIL SHOULDERS: O.K.

CHAMBER: -

TEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

EXCESSIVE LUBRICANT, TRIGGER BIND ON TRIGGER
GUARD POSSIBLE.

COMPLAINT: "WILL FIRE ACCIDENTALLY ON PUSHING OFF THE
SAFETY"

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED.
IT PROBABLY IS ASSOCIATED WITH TRIGGER BIND
AND TYPE OF LUBRICATION USED.

Cash Comp.

MODEL: 700 BDL

R #: 000014

DATE: 1-4-73

FROM: W.K. FRAYSUR

HOUSTON, TEXAS

GUN #: 69329

CODE: PK-5/63

GR./CAL.: 270

CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

PLAINTIFF'S
EXHIBIT

3185

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: GOOD R #: 027716
OUTSIDE WORK: SCOPE MOUNTED, ALL SEALS DATE: 1-4-73
BROKEN ON TRIGGER ASSEMBLY FROM: DUNHAM'S
FIRED AMMO TYPE: _____ MEDFORD, OREGON
& CONDITION: _____ GUN #: 369419
PROOF: R.E.P. INSP.: ASSEMBLER 13 TEST: ? CODE: DR = 9/68
HEADING: O.K. EX./CAL.: 3006
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

HARDENED LUBRICANT CAUSING TRIGGER BIND. TRIGGER
STOP SCREW OUT OF POSITION BINDING IN CONNECTOR.

COMPLAINT: FIRES ON RELEASING SAFETY

INCIDENT: FOLLOW DOWN

COMMENTS: THE OUT OF POSITION STOP SCREW HOLDS THE
TRIGGER CONNECTOR IN FIRED POSITION CAUSING
FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3186

141
AL 0029716

Cust. Compl.

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 027329
OUTSIDE WORK: NO DATE: 1-2-73
FIRE AMMO TYPE: ✓ FROM: OSHMAN'S
& CONDITION: ASSEMBLER 56 BEAUMONT, TEXAS.
PROOF: R.E.P.-M INSP. 73 TEST: 13 GUN #: 6521466
HEADING: O.K. CODE: AW = 3/72
BREECH OPENING: - GR./CAL.: 3006
RECOIL SHOULDERS: O.K. CHECKED BY: CIPROSSER
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: GUN FIRED WHEN SAFETY WAS REMOVEDINCIDENT: FOLLOW DOWNCOMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED. THE PRESENCE OF EXCESSIVE LUBRICANT
POSSIBLY CONTRIBUTED TO POOR TRIGGER RETRACT-
ION AND CAUSED FOLLOW DOWN.PLAINTIFF'S
EXHIBIT

3187

AL 0029717

No GUN EXAMINATION REPORT NUMBER: _____

GENERAL CONDITION: NEW

OUTSIDE WORK: SCOPE MOUNTED

FIRED AMMO TYPE: _____

& CONDITION: _____

PROOF: REP-D INSP. 74 TEST: 55

HEADING: _____

BREECH OPENING: _____

RECOIL SHOULDERS: O.K.

CHAMBER: O.K.

TEST: No

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDL

R #: 027443

DATE: 12-22-72

FROM: KAYTON MFG. CO.

ALLENTOWN, PA.

GUN #: 6241978

CODE: KS = 5/69

GA./CAL.: 243

CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

SEAR - TRIGGER CONNECTOR ENGAGEMENT OK. TRIGGER
BINDING IN HOUSING. LUBRICATION LIKE GREASE ON
SEAR

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE LUBRICANT USED PROBABLY CAUSED
SLUGGISH TRIGGER-CONNECTOR-SEAR RETRACTION
INTO COCKED POSITION, RESULTING IN FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3188

AL 0029718

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 027515
 OUTSIDE WORK: NO DATE: 12-22-72
 FROM: MORLEY BRO.
 FIRED AMMO TYPE: _____ SAGINAW, MICH.
 & CONDITION: _____ GUN #: 6241128
 PROOF: R.E.P.-K INSP. 73 TEST: 13 CODE: KU=5/71
 HEADING: - OK./CAL.: 25-06
 BRESC OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: EXCESSIVE RADIUS-REAR APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: _____ APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .025
BURRS ON TRIGGER. TRIGGER TOO CLOSE TO
GUARD ON RIGHT SIDE. THERE ARE INDICATIONS
OF PRIMER PIERCING ON FIRING PIN ASSEMBLY.

COMPLAINT: "WILL FIRE DURING FEEDING OPERATION."

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED. TRIGGER BIND MAY HAVE PREVENTED
PROPER RETRACTION.

PLAINTIFF'S
EXHIBIT

3189

AL 0029719

Cust Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 027088
 OUTSIDE WORK: NO DATE: 12-18-72
 FIRED AMMO TYPE: - FROM: VALLEY HOME SUPPLY CO.
 & CONDITION: ASSEMBLER - P MILES BURG, PA.
 PROOF: R.E.P.-D INSP.: 9 TEST: 13 GUN #: 6261266
 HEADING: O.I.C. CODE: OS = 7/69
 BREECH OPENING: - GA./CAL.: 308 WIN.
 RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

EVIDENCE OF TRIGGER BURRS BINDING. TRIGGER 1.074
 (MODEL DRAWING 1.076) EXCESSIVE LUBRICANT - TOO HEAVY.
 TRIGGER CONNECTOR - SEAR ENGAGEMENT .015 (MIN. 13.020)

COMPLAINT: "FIRED WHEN SAFETY WAS RELEASED"

INCIDENT: FOLLOW-DOWN.

COMMENTS: THE TRIGGER BIND, HEAVY LUBRICANT COMBINATION
PROBABLY CAUSED THE FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3190

AL 0029720

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 026555
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-18-72
 FIRED AMMO TYPE: _____ FROM: Sgt. WIS. SPT. CENT.
 & CONDITION: _____ BELOIT, WIS.
 PROOF: R.E.P.-B INSP.: 73 TEST: 97 GUN #: 6580387
 HEADING: O.K. CODE: OW = 7/72
 BREACH OPENING: - AL./CAL.: 3006
 RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

HEAVY LUBRICANT AROUND SEAR BURR AT REAR OF
HOUSING FROM FIRING PIN HEAD.

COMPLAINT: "FIRES SOMETIMES WITH SAFETY ON"

INCIDENT: PROBABLY FOLLOW-DOWN.

COMMENTS: THE HEAVY LUBRICANT COMBINED WITH SEAR-
BIND PROBABLY HELD THE SEAR IN FIRED POSITION
AND CAUSED FOLLOW-DOWN.

PLAINTIFF'S
EXHIBIT

3191

AL 0029721

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 027181
OUTSIDE WORK: SCOPE MOUNTED DATE: 12-18-72
FROM: BRUCE WIGGINS
SPORTS SHOP
FIRED AMMO TYPE: — BEAUMONT, TEXAS
& CONDITION: ASSEMBLER P GUN #: 6418163
PROOF: R.E.P. INSP.: 73 TEST: 55 CODE: AU = 3/71
HEADING: O.K. GR./CAL.: 17 REM.
BREECH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. IS .020)

BURRS ON TRIGGER, SMALL BURR ON SEAR.

COMPLAINT: FIRES WHEN SAFETY IS RELEASED.

INCIDENT: FOLLOW DOWN.

COMMENTS: CUSTOMER'S MALFUNCTION NOT DUPLICATED.
APPARENTLY THE TRIGGER-SEAR BIND WAS ENOUGH
TO PREVENT RETRACTION INTO COCKED POSITION.

PLAINTIFF'S
EXHIBIT

3192

AL 0029722

I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 026826
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-18-72
 FROM: DICK'S SPT. SHOP
 FIRED AMMO TYPE: _____ STAHLSTONN, PA.
 & CONDITION: _____ GUN #: 6223531
 PROOF: R.E.P. INSP. ? TEST: 87 CODE: AS = 3/69
 HEADING: O.K. GRA./CAL.: 3006
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .015 (MIN.
15.020) BURRS ON SEAR AND TRIGGER. TRIGGER
1.074 (MODEL DRAWING = 1.076) CONNECTOR 1.081 (1.080)
1.079) 1.083)
SAFETY CENTER OF PIVOT TO TOP OF CAM .290 (.292)
.296)

COMPLAINT: "MISFIRES WHEN HE PUSHES THE SAFE OFF"

INCIDENT: FOLLOW DOWN

COMMENTS: FOLLOW DOWN COULD HAVE BEEN DUE TO
BURRS BINDING AND PREVENTING RETRACTION OR
EXCESSIVE CONNECTOR-TRIGGER CLEARANCE
ALLOWING THE CONNECTOR TO WORK UP TO INTERFERE
WITH THE SEAR WHICH THE SAFETY DID NOT LIFT
ENOUGH TO CLEAR.

PLAINTIFF'S
EXHIBIT

3193

AL 0029723

700 Custom. Springfield

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 026289
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-15-72
 FIRED AMMO TYPE: _____ FROM: GALLINGHAM & JONES INC. CHENALIS, WASH.
 & CONDITION: _____ GUN #: 6295844
 PROOF: R.E.P.-E INSP. 9 TEST: 18 CODE: X5 = 12/69
 HEADING: _____ GA./CAL.: 300 WIN. MAG.
 BREECH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .015 (MIN. .020)
CONNECTOR 1.085 (MODEL DRAWING 1.080) SAFETY 2.91 (MODEL DRAWING 2.92)
TRIGGER BINDING IN HOUSING.

COMPLAINT: FIRED WHEN CLOSING ACTION.INCIDENT: FOLLOW DOWN.

COMMENTS: THE BINDING TRIGGER PROBABLY FAILED TO
RETRACT CAUSING THE ACTION TO FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3194

AL 0029724

700 Cust. Comp

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 025940
 OUTSIDE WORK: BATT PAD ADDED, TRIGGER DATE: 12-15-72
PULL RE-ADJUSTED. FROM: BEST PRODUCTS
 FIRED AMMO TYPE: _____ HAMPTON, VA.
 & CONDITION: _____ GUN #: 6517902
 PROOF: R.E.P.-8 INSP. 58 TEST: 97 CODE: BW = 1/72
 HEADING: O.K. ON INSPECTION MAX. GA./CAL.: 3006
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER BINDING ON GUARD, TRIGGER PULL ADJUSTED
DOWN TO 2-2 1/2 LBS. BY CUSTOMER. EXCESSIVE LUBRICANT.

COMPLAINT: GUN FIRES WHEN SAFETY IS RELEASED.

INCIDENT: FOLLOW DOWN.

COMMENTS: CUSTOMER'S MALFUNCTION NOT DUPLICATED,

HOWEVER WITH TRIGGER PULL REDUCED BELOW
SPECIFICATIONS (3 TO 5 LBS.) THE BINDING TRIGGER
PROBABLY DID NOT RETRACT SUFFICIENTLY TO LOCK THE
FIRING PIN.

PLAINTIFF'S
EXHIBIT

3195

AL 0029725

710 *Cust. Complaint*

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 025800
 OUTSIDE WORK: NO DATE: 12-14-72
 FROM: BILL'S SPORTS & HOBBY SHOP,
 ONEONTA, N.Y.
 FIRED AMMO TYPE: _____ GUN #: 6365666
 & CONDITION: _____ CODE: WT = 8/70
 PROOF: R.F.P.-C INSP. BB TEST: 29
 HEADING: O.K. GA./CAL.: 3006
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .015 (MIN. IS .020)
 CONNECTOR CLEARANCE ON TRIGGER = 1.073 (MODEL DRAWING = 1.079/1.076)
 BURRS ON TOP SIDES OF TRIGGER.

COMPLAINT: GUN FIRED WHEN SAFETY WAS PUSHED OFF.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE TRIGGER BIND COULD CAUSE FAILURE TO
 RETRACT AND FOLLOW DOWN, THE UNDER MIN. ENGAG-
 EMENT CONTRIBUTING TO THE MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3136

AL 0029726

Just Complaint

A 44-61

IN EXAMINATION REPORT NUMBER: _____ MODEL: 70C

WORK: NEW R #: 025981

DATE: 12-7-72

FROM: GRAF & SONS INC.

FIRED N/A TYPE: _____ MEXICO, MO.

& CONDITION: _____ GUN #: 6439493

PROOF: R.E.P.-L INSP.: 73 TEST: 53 CODE: KU=5/71

HEADING: O.K. GA./CAL.: 25-06

BREACH OPENING: _____ CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

FEAR-TRIGGER CONNECTOR ENGAGEMENT, 0.10 (MIN. 15.020)
BURRS ON SIDE OF TRIGGER.

COMPLAINT: 'GUN GOES OFF WHEN BOLT IS CLOSED.'

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED,
HOWEVER THE TRIGGER BIND COMBINED WITH UNDER
MIN. ENGAGEMENT MAY HAVE CAUSED A FOLLOW
DOWN.

**PLAINTIFF'S
EXHIBIT**
3197

10/1
AL 0029727

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: GOOD R #: 025024
 OUTSIDE WORK: SCOPE MOUNTED, ALL DATE: 12-5-72
 TRIGGER ADJUSTMENTS CHANGED. FROM: COMMUNITY HDW. CO.
 FIRED AMMO TYPE: _____ THOMASVILLE, N.C.
 & CONDITION: _____ GUN #: 6338169
 PROOF: R.E.P. INSP.: 9 TEST: 87 CODE: KT=5/70
 HEADING: O.K. GA./CAL.: 25-06
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: 15 ROUNDS - NO PIERCING APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN, SEAR DAMAGED. PRIMER
 PIERCING IS INDICATED.

COMPLAINT: "BOLT FIRES WHEN YOU PUSH IT DOWN."

INCIDENT: FOLLOW DOWN.

COMMENTS: WITH THE TRIGGER CONNECTOR BROKEN THERE IS NO WAY
 THE ACTION CAN BE COCKED. THE BREAK DOWN EVIDENTLY
 STARTED WITH PRIMER PIERCING.

PLAINTIFF'S
EXHIBIT

3198

AL 0029728

NO GUN EXAMINATION REPORT NUMBER: MODEL: 700
 GENERAL CONDITION: NEW R #: 026064
 OUTSIDE WORK: SCOPE MOUNTED DATE: 12-5-72
 FROM: HERTER'S INC.
 FIRED AMMO TYPE: OLYMPIA, WASH.
 & CONDITION: GUN #: 6524373
 PROOF: R.E.P.-B INSP. 74 TEST: 97 CODE: CW = 4/72
 HEADING: O.K. GR./CAL.: 300G
 BRESCHE OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED:
 CHAMBER: O.K. APPROVED:
 TEST: NO APPROVED:
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

SEAR-TRIGGER CONNECTOR ENGAGEMENT .025 (MIN. IS
 .020) CONNECTOR = 1.088 MODEL DRAWING = 1.088, TRIGGER
 MEASURES 1.074, MODEL DRAWING = 1.076

COMPLAINT: "FIRES WHEN SAFETY IS PUSHED OFF"

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
 DUPLICATED, HOWEVER, THE .007 OVER MAX. CLEARANCE
 BETWEEN THE TRIGGER AND CONNECTOR WILL ALLOW
 THE CONNECTOR TO INTERFERE WITH THE SEAR AND
 FAILING TO RETRACT INTO COCKED POSITION, CAUSE
 A FOLLOW-DOWN.

PLAINTIFF'S
EXHIBIT

3199

AL 0029729

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700BOL
 GENERAL CONDITION: NEW R #: 024573
 OUTSIDE WORK: SCOPE & RECOIL PAD FITTED. DATE: 11-27-72
 FROM: FRONTIERSMAN SPORTS INC.
 MINNEAPOLIS, MINN.
 FIRED AMMO TYPE: _____
 GUN #: 6365254
 & CONDITION: ASSEMBLER 72
 PROOF: R.E.P. INSP. 74 TEST: 49 CODE: DT = 9/70
 HEADING: O.K. OK./CAL.: 3006
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .005 (MIN. = .020)

TRIGGER CONNECTOR CLEARANCE ON TRIGGER = 1.075,

M/D = 1.076, 1.079; TRIGGER CLEARANCE ON CONNECTOR = 1.086,

M/D = 1.080, 1.083, FIRING PIN CAN CATCH ON REAR CORNER OF HOUSING. LAPPING ON CONNECTOR CROOKED.

COMPLAINT: RIFLE DISCHARGED WHEN LOADING CARTRIDGE.

INCIDENT: FOLLOW DOWN

COMMENTS: THERE IS EVIDENCE OF TRIGGER BIND. THIS COMBINED WITH UNDER MIN. ENGAGEMENT AND EXCESSIVE TRIGGER CONNECTOR CLEARANCE, CAUSES FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3200

AL 0029730

Cust. Cr.
 1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: GOOD R #: 024437
 OUTSIDE WORK: SCOPE MOUNTED, RECOIL PAD DATE: 11-22-72

ADDED FROM: DONALDSON'S GUN SHOP
 FIRED AMMO TYPE: _____ MINNEAPOLIS, MINN.
 & CONDITION: _____ GUN #: 309624
 PROOF: R.E.P. ASSEMBLER 63 INSP.: 96 TEST: 87 CODE: EP = 10/67
 HEADING: O.K. GA./CAL.: 3006
 BREACH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR CLEARANCE ON TRIGGER .003 UNDER MIN.
BURRS ON SIDES OF TRIGGER HOUSING PROTRUDES
INTO FIRING PIN HEAD SLOT, SEAR-TRIGGER CONNECTOR
ENGAGEMENT .025

COMPLAINT: FIRE UPON LOCKING THE BOLT.

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION CAN NOT BE
DUPLICATED AND THERE IS NO EVIDENCE OF SUCH
MALFUNCTION. HOWEVER, THE TRIGGER BURRS,
EXCESSIVE TRIGGER-TRIGGER CONNECTOR CLEARANCE,
AND HOUSING PROTRUDING COULD CONTRIBUTE -
SUCH A MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3201

AL 0029731

Cust. Complaint

No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 BDL

GENERAL CONDITION: NEW

R #: 000219

OUTSIDE WORK: No

DATE: 1-4-72

FIRED AMMO TYPE: _____

FROM: BAY CITY HOW. CO.

BAY CITY, MICH.

& CONDITION: _____

GUN #: 6425267

PROOF: R.F.D.-K

INSP.: _____

72

TEST: 87

CODE: CU = 4/71

HEADING: O.K.

GR./CAL.: 300 W.M.M.S.

BREECH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

No Broken or Damaged Components.

TRIGGER PULL 5 POUNDS, HORIZONTAL ENGAGEMENT .020

(MIN. IS .020) VERTICAL ENGAGEMENT .035 (MIN. IS .015)

TRIGGER DOES NOT RUB ON TRIGGER GUARD.

COMPLAINT: "WHEN SAFETY IS PULLED BACK GUN FIRES WITHOUT
PULLING TRIGGER."

INCIDENT: FOLLOW DOWN.

COMMENTS: CAN FIND NO DEFECT WHICH MIGHT LEAD TO

THE CUSTOMER'S MALFUNCTION. HIS MALFUNCTION
NOT DUPLICATED.PLAINTIFF'S
EXHIBIT

3202

AL 0029732

c.i. NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: GOODR #: 023941OUTSIDE WORK: ALL TRIGGER ADJUSTINGDATE: 11-16-72SCREWS WITHOUT SEAL.FROM: CHARLES W. FISHERFIRED AMMO TYPE: REMINGTONCOLUMBUS, OHIO

& CONDITION: _____

GUN #: 6418265PROOF: R.E.P.-1 INSP.: 9 TEST: 13CODE: AV = 3/71HEADING: O.K.GA./CAL.: 17 REM.BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: 20 ROUNDS NO PRIMER PIERCING

APPROVED: _____

AFTER SWAGING FIRING PIN HOLE,

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

TRIGGER STOP AND ENGAGEMENT SCREWS OUT OF ADJUST-
MENT. FIRING PIN HOLE NOT SWAGED. SEAR AND TRIG-
GER CONNECTOR DAMAGED.

COMPLAINT: PIERCES PRIMERS, FIRES CLOSING BOLT.INCIDENT: FOLLOW DOWN

COMMENTS: PRIMER PIERCING CAUSED DAMAGE TO THE
CORNERS OF THE SEAR AND TRIGGER CONNECTOR,
RESULTING IN FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3203

AL 0029733

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

GENERAL CONDITION: NEW

OUTSIDE WORK: NO

FIRE AMMO TYPE: _____

& CONDITION: _____

PROOF: R.E.P.-L INSP.: 72 TEST: 53

HEADING: O.K.

BRECH OPENING: -

RECOIL SHOULDERS: O.K.

CHAMBER: O.K.

TEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDL

R #: 023622

DATE: 11-15-72

FROM: MONTGOMERY WARD

RICHMOND, CAL.

GUN #: 647155B

CODE: WU: 8/71

GA./CAL.: 3006

CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .025

TRIGGER HOUSING PROTRUDING INTO FIRING PIN

HEAD CLEARANCE SO FIRING PIN HEAD CAN BE

PREVENTED FROM ASSUMING ITS POSITION AGAINST

THE SEAR.

COMPLAINT: FIRE WHEN SAFETY IS PUSHED OFF.

INCIDENT: FOLLOW DOWN

COMMENTS: THE INTERFERENCE BETWEEN FIRING PIN

HEAD AND HOUSING CREATES A BUMP WHICH

CAUSES SEAR BIND. SEAR STICKS DOWN IN

POSITION RESULTING IN FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3204

AL 0029734

Cost Complaint

No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 BDLGENERAL CONDITION: NEWR #: 023451OUTSIDE WORK: NODATE: 11-13-72FROM: RON SHIRKS
SHOOTERS SUPPLIES.FIRED AMMO TYPE: ASSEMBLER 84LEBANON, PA.

& CONDITION: _____

GUN #: 6494579PROOF: R.E.P.-M INSP.: U TEST: 84CODE: RU=11/71HEADING: O.K.GA./CAL.: 270 WIL.BREACH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

TRIGGER ASSEMBLY COMPONENTS STUCK TOGETHER
MAKING IT INOPERABLE.COMPLAINT: WONT COCKINCIDENT: FOLLOWS DOWN.COMMENTS: TRIGGER ASSEMBLY WAS RENDERED INOPERABLE
BY SOME HARDENED SUBSTANCE.PLAINTIFF'S
EXHIBIT

3205

AL 0029735

Curt Camp?

No GUN EXAMINATION REPORT NUMBER: MODEL: 700

GENERAL CONDITION: GOOD R #: 023332

OUTSIDE WORK: No DATE: 11-13-72

FIRED AMMO TYPE: - FROM: GRANTS' FOR GUN INC. COSTA MESA, CAL.

& CONDITION: GUN #: 6449597

PROOF: REP-N INSP. 89 TEST: 53 CODE: WV = 8/71

HEADING: O.K. PR./CAL.: 3006

BREACH OPENING: CHECKED BY: C PROSSER

RECOIL SHOULDERS: O.K. APPROVED:

CHAMBER: O.K. APPROVED:

TEST: No APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

SEAR-TRIGGER CONNECTOR ENGAGEMENT = 0.010
(MIN. IS .020) BURRS ON SIDES OF TRIGGER

COMPLAINT: GUN FIRES WHEN SAFETY IS TAKEN OFF.

INCIDENT: FOLLOW DOWN

COMMENTS: IT APPEARS THAT TRIGGER BIND MAY HAVE
PREVENTED FULL RETRACTION OF CONNECTOR UNDER
THE SEAR REDUCING THE UNDER MIN. ENGAGEMENT
TO ZERO.PLAINTIFF'S
EXHIBIT

3206

AL 0029736

Crest Arms.

1 No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDLGENERAL CONDITION: GOOD R# : 022218OUTSIDE WORK: SCOPE MOUNTED. TRIGGER DATE: 11-10-72PULL WEIGHT CHANGED. FROM: JOHN PAYNEFIRED AMMO TYPE: _____ MT. VIEW, ARK.& CONDITION: _____ GUN # : 6504815PROOF: R.E.P.-M INSP.: U TEST: 13 CODE: XU = 12/71HEADING: -O.K. GUN/CAL.: 222BRESCH OPENING: - CHECKED BY: C. PROSSERRECOIL SHOULDERS: EXCESSIVE RADIUS REAR-LUGS. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .025 (ADJUST-
MENT UNDISTURBED) TRIGGER STOP & ADJUSTING SCREWS
SEALS BROKEN. TRIGGER CONNECTOR WARPED.

COMPLAINT: RIFLE FIRED WHEN SAFETY WAS PUSHED OFF.INCIDENT: FOLLOW DOWN.PLAINTIFF'S
EXHIBIT

3207

COMMENTS: WITH THE TRIGGER PULL REDUCED TO TWO POUNDS
TRIGGER CONNECTOR RETRACTION WOULD BE ERRATIC.
THE WARPED CONNECTOR ALSO WOULD CAUSE ERRATIC
ENGAGEMENT AND COULD RESULT IN FOLLOW DOWN.

REMINO CUSTOMER REMINGTON DOES NOT
RECOMMEND UNDER THREE POUND TRIGGER PULL.

*Antony
Complaint*

I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: GOOD R #: 022245

OUTSIDE WORK: SCOPE MOUNTED DATE: 10-30-72

FIRED AMMO TYPE: _____ FROM: LOAR JEWELRY CO.

& CONDITION: _____ GRAFTON, W. VA.

PROOF: R.E.P.-D INSP. 74 TEST: 49 GUN #: 6246723

HEADING: O.K. CODE: PS = 6/69

BREECH OPENING: - GR./CAL.: 7MM REM. MAG.

RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

RECEIVER AND BOLT RUSTED. SEAR-TRIGGER
CONNECTOR ENGAGEMENT .085 (MIN. .15, .020) BURRS
ON SIDES OF TRIGGER, TRIGGER CLEARANCE ON
CONNECTOR 1.085 MODEL DRAWING = 1.080
CLEARANCE ON TRIGGER = 1.070 MODEL DWG. = 1.076
1.083 CONNECTOR 1.079

COMPLAINT: FIRES WHEN SAFETY IS MOVED TO OFF POSITION.

INCIDENT: FOLLOW DOWN

COMMENTS: THE EXCESSIVE CLEARANCE BETWEEN THE
TRIGGER AND CONNECTOR ALLOWS THE CONNECTOR
TO INTERFERE WITH THE SEAR, FAILING TO RETRACT
INTO COCKED POSITION.

PLAINTIFF'S
EXHIBIT

3208

AL 0029738

No GUN EXAMINATION REPORT NUMBER: _____

GENERAL CONDITION: GOODOUTSIDE WORK: NoFIRED AMMO TYPE: F& CONDITION: LPROOF: P.P.C INSP. 59, 97 TEST: 98HEADING: OKBRESCH OPENING: -RECOIL SHOULDERS: O.K.CHAMBER: O.K.TEST: No

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDLR #: 021210DATE: 10-20-72FROM: HA-STEADSUMMERVILLE, VA.GUN #: 6381222CODE: ET = 10/10 P.M.GA./CAL.: 200 WADSWORTHCHECKED BY: C. PROCTOR

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

TRIGGER ASSEMBLY CORRECTLY SCREWED BUT ADJUSTED
NEVER TO HAVE BEEN ADJUSTED.

COMPLAINT: DISCHARGED THREE TIMES WITHOUT FINGER ON
TRIGGER.

INCIDENT: FOLLOW DOWN.COMMENTS: THE EXISTING TRIGGER MECHANISMTO BE REPAIRED TO CORRECT THE ABOVE COMPLAINTTO BE REPAIRED TO CORRECT THE ABOVE COMPLAINTPLAINTIFF'S
EXHIBIT

3209

AL 0029739

Curb Comp

GUN EXAMINATION REPORT NUMBER: 117 MODEL: 700 A.D.L.

GENERAL CONDITION: GOOD R #: 020432

OUTSIDE WORK: BY ARDEN SPORTS UNLIMITED DATE: 10/8/72

SACRAMENTO, CAL. FROM: DENNY'S HOME

FIRE AMMO TYPE: - ARBUCKLE, CAL.

& CONDITION: - GUN #: 6422450

PROOF: R.E.P. INSP.: 9 TEST: ST CODE: AU = 3/2

HEADING: O.K. GA./CAL.: 3006

BRECH OPENING: - CHECKED BY: C.F. ROSS

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEMI-TRIGGER CONNECTOR ENGAGEMENT D10

(MIN. 18,000) TRIGGER PULL SET TOO LIGHT

COMPLAINT: SAFETY DOES NOT WORK

INCIDENT: FOLLOW DOWN

COMMENTS: CONF. WITH AT LIGHT TRIGGER SET, D

MIN. ENGAGEMENT SET TO 18,000 BARS

TESTED TO 18,000 IN FIELD POSITION

18,000 BARS

PLAINTIFF'S
EXHIBIT

3210

AL 0029940

Crab-Camp.

No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700

GENERAL CONDITION: NEW

R #: 020090

OUTSIDE WORK: SCOPE MOUNTED

DATE: 10-10-72

FROM: SOUTHERN GUN ^{INC.} DKT

FIRED AMMO TYPE: W-W SUPER

MIAMI, FLORIDA

& CONDITION: _____

GUN #: 6562968

PROOF: R.E.P.-M INSP.: 73 TEST: 59

CODE: KH = 5/72

HEADING: _____

GA./CAL.: 7MM REM. MAG.

BREACH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT, 020, STEEL
SHAVINGS BETWEEN SEAR AND HOUSING AT SEAR PIN
HOLE.

COMPLAINT: FIRES WHEN CLOSING BOLT

INCIDENT: FOLLOW DOWN.

COMMENTS: THE STEEL SHAVINGS PROBABLY CAUSED THE
SEAR TO BIND AND FAIL TO RETRACT TO COCKED
POSITION THUS, FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3211

AL 0029741

RD-6542-1 Rev. 2-15-61

P.I. No GUN EXAMINATION REPORT NUMBER: _____

GENERAL CONDITION: NEW

OUTSIDE WORK: No

FIRE AMMO TYPE: _____

& CONDITION: _____

PROOF: R.E.P.-A INSP. 58 TEST: 49

HEADING: O.K.

BREECH OPENING: -

RECOIL SHOULDERS: O.K.

CHAMBER: O.K.

TEST: No

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700

R # : 019718

DATE: 10-5-72

FROM: K MART ENTERPRISE

ROYAL OAK, MICH.

GUN # : 6258285

CODE: OS = 7/69

GA./CAL.: 3006

CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

SEAR - CONNECTOR ENGAGEMENT 010 (MIN. 15.020)

SOLIDIFIED LUBRICANT ON SIDE OF SEAR.

COMPLAINT: 'FIRES WHEN EJECTING SHELLS'

INCIDENT: FOLLOW DOWN

COMMENTS: THE SOLIDIFIED LUBRICANT CAUSED THE SEAR
TO STAY DOWN IN FIRED POSITION. WHEN THE REC-
WAS ROTATED TO LOCK-UP, FOLLOW DOWN OCCURRED.

PLAINTIFF'S
EXHIBIT

3212

AL 0029742

Cast. Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: GOOD R #: 019853
OUTSIDE WORK: SCOPE MOUNTED DATE: 10-4-72
FIRE AMMO TYPE: _____ FROM: DESA IND.
& CONDITION: _____ PARK FOREST, ILL.
PROOF: R.E.P. INSP. U TEST: 13 GUN #: 6401425
HEADING: _____ CODE: LU = 2/71
BREECH OPENING: _____ GA./CAL.: 6MM
RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .005 (MIN. IS .020) BURRS ON SIDES OF TRIGGER.

COMPLAINT: FIRES ON CLOSING.

INCIDENT: FOLLOW DOWN.

COMMENTS: POOR RETRACTION COMBINED WITH UNDER MIN. ENGAGEMENT ALLOWED THE SEAR TO SLIP BY THE CONNECTOR AND THE FIRING PIN TO FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3213

AL 0029743

RD-6542-1 Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

GENERAL CONDITION: GOOD

OUTSIDE WORK: NO

FIRE AMMO TYPE: _____

& CONDITION: _____

PROOF: R.E.P. INSP.: 58 TEST: 49

HEADING: -

BREECH OPENING: -

RECOIL SHOULDERS: EXCESSIVE RADIUS REAR LUGS,

CHAMBER: O.K.

TEST: 20 ROUNDS

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDL

R #: 016530

DATE: 8-24-72

FROM: KLINEDINST & HOPPER

LOGANVILLE, PA.

GUN #: 6401603

CODE: BU=1/71

GR./CAL.: 6MM REM.

CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

ENGAGEMENTS O.K., TRIGGER PULL O.K. EXCESSIVE
RADIUS REAR OF LOCKING LUGS ON BOLT CAUSING
CLOSE HARD.

COMPLAINT: "SHELLS DON'T CHAMBER, FIRES WHEN YOU CLOSE
IT."

INCIDENT: CLOSE HARD & FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3214

COMMENTS: THE CLOSE HARD WAS CAUSED BY BEARING
ON A RADIUS BACK OF LOCKING LUGS INSTEAD OF
ON THE FLAT SURFACES. THE FOLLOW DOWN
PROBABLY WAS CAUSED BY RUBBER BLOTTING
TOP OF THE TRIGGER CATCHING ON THE INSIDE OF
THE HOUSING AND FAILING TO RETRACT.

AL 0029744

N/700 Custom. Config.

GUN EXAMINATION REPORT NUMBER: MODEL: 700 ADLGENERAL CONDITION: NEW R #: 016319OUTSIDE WORK: FIRING PIN HEAD GROUNDS DATE: 8-23-72ON BOTTOMFROM: SENCELLKOFF CO.FIRED AMMO TYPE: DALLAS, TEXAS& CONDITION: GUN #: 6481075PROOF: R.E.P.-M INSP.: 9 TEST: 53 CODE: EV = 10/71HEADING: - GRA./CAL.: 7MM K.BREECH OPENING: CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: CHAMBER: O.K. APPROVED: TEST: No APPROVED: COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

ENGAGEMENT (HORIZONTAL) BETWEEN SEPS AND TRIGGER
CONNECTOR .025 (VERTICAL ENGAGEMENT ZERO BEHIND
OF THE GROUND FIRING PIN HEAD)

COMPLAINT: "WITH STOCK OFF GUN FOLLOWS DOWN."INCIDENT: FOLLOW DOWN

COMMENTS: IT APPEARS THAT THE CUSTOMER GAVE THE
FIRING PIN HEAD REDUCING THE FIRING P. HEAD-SEP
ENGAGEMENT TO ZERO, CAUSING THE FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3215

AL 0029145

M/700 Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: MODEL: 700
 GENERAL CONDITION: NEW R #: 016257
 OUTSIDE WORK: NO DATE: 8-16-72
 FIRED AMMO TYPE: FROM: HENRY L. FRAME
 & CONDITION: W. BARRINGTON, R.I.
 PROOF: R.E.P. INSP.: 1A TEST: 49 GUN #: 297377
 HEADING: CODE: WR = 8/68
 BREACH OPENING: GK./CAL.: 270 WIN.
 RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
 CHAMBER: O.K. APPROVED:
 TEST: NO APPROVED:
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

TRIGGER PULL 3 1/2 LBS. SEAR-TRIGGER CONNECTOR
 ENGAGEMENT .005 (MIN. IS .020) STICKY LUBRICANT
 INSIDE HOUSING, CORNER OF TRIGGER CONNECTOR
 WORN ROUND.

COMPLAINT: "IT DISCHARGES PREMATURELY"

INCIDENT: FOLLOW DOWN

COMMENTS: WITH INSUFFICIENT ENGAGEMENT BETWEEN
 SEAR & CONNECTOR THE CONNECTOR BROKE DOWN
 ON THE CORNER ALLOWING THE FOLLOW DOWN
 MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3216

AL 0029746

GUN EXAMINATION REPORT NUMBER: GENERAL CONDITION: NEWOUTSIDE WORK: NOFIRED AMMO TYPE: FACTORY LOADS& CONDITION: PROOF: R.E.P.E INSP.: 74 TEST: 49HEADING: MAX. WITH ASSEMBLY MAX.BREACH OPENING: -RECOIL SHOULDERS: EXCESSIVE RADIUS BACK OFCHAMBER: O.K.TEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDLR # : 015571DATE: 8-14-72FROM: HIGHSPIRE SPTG.
GROUPS INC.HIGHSPIRE, PA.GUN # : 6312165CODE: LT-2/70GA./CAL.: 3006CHECKED BY: C. PROSSERAPPROVED: APPROVED: APPROVED: APPROVED:

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. IS .030)
BURRS ON SIDES OF UPPER PART OF TRIGGER SHOW FRICTION
MARKS. POOR COLOR ON BARREL AT REAR SIGHT.

COMPLAINT: "FIRES JUST AS BOLT IS CLOSED."INCIDENT: FOLLOW DOWN

COMMENTS: THE TRIGGER BIND WITH UNDER MIN. ENGAGEMENT
CAUSED ERRATIC TRIGGER RETRACTION AND FOLLOW
DOWN.

PLAINTIFF'S
EXHIBIT

3217

AL 0029747

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

CC: E. R. Carr
H. K. Boyle

Remington

PETERS

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

N/700 Custom Complaint

Ilion, New York
August 14, 1972

L. J. BOYLE
S. M. ALVIS

The attached trip report by Harvey Boyle is relative to a complaint that difficulty was being experienced in fitting telescopes to Model 700 rifles. In addition to the scope complaints, 11 rifles were returned to Ilion and Bridgeport with a list of visual complaints. In our analysis of the returned guns, some complaints were justified but many were not. Because of the problem in determining the magnitude of the complaints and the fact that we were able to sight scopes on each of the returned rifles, Harvey Boyle, Denny Anderson and W. B. Cockman visited Jerry's Sport Center and E. L. Blair.

As a result of the trip (report attached), both Jerry's Sport Center and E. L. Blair are satisfied that corrective action has been taken. The Plant is investigating the scope sight hole process to initiate improvements.

It is further suggested that Research contact Leupold and remind them that their 3x-9x variable power scope has only 1/3 the windage adjustment of competitive scopes making adjustments difficult if used with bases without windage adjustments.

LF
L. Fox, Supt.
P E & C Section

LF:I
Attach.

PLAINTIFF'S
EXHIBIT

3218

183
AL 0029748

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington
SUPPORT

PETERS
SPORT

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY" _____

July 28, 1972

TO: L. FOX

FROM: H. K. BOYLE/D. J. ANDERSON

TRIP REPORT

Places visited: Jerry's Sport Center, Olyphant, Pa. 7/24/72
E. L. Blair & Son Sporting Goods,
Williamsport, Pa. 7/25/72

Reference: M/700 Quality Complaint

1. Scope holes in Receiver out of alignment--
can't bore sight rifles with a collimator.
2. Visual defects.

D. J. Anderson, Process Engineer; W. B. Cockman, Field Representative;
and the writer visited the following establishments and reviewed the
referenced M/700 Quality Complaints:

Jerry's Sport Center, Olyphant, Pa. - Jerry Warsky, Distributor-Jobber.

Mr. Warsky stated that M/700 rifles were unable to be collimated
when equipped with a Leupold 3x-9x variable power scope mounted
with fixed Weaver rings and mounts. Two (2) M/700 RDL, 30-06 Cal.
rifles and one (1) Leupold 3x-9x scope were selected from Mr.
Warsky's inventory and collimated satisfactorily. One (1) of the
original complaint guns was selected and collimated satisfactorily
with the Leupold scope. All three (3) guns were successfully targeted
with live ammunition for point of impact; however, one (1) had very
little additional windage or elevation adjustment remaining.

The visual items observed on the returned guns were reviewed and
the program for corrective action discussed.

283

E. L. Blair & Son, Williamsport, Pa. - Sporting Goods Dealer (retailer)

Mr. Blair verified that the Leupold 3x-9x variable power scope and Weaver fixed rings and mounts were the primary problem although the Redfield 3x-9x variable power and the Redfield 4x have also been incapable of sighting in at times. He estimated that about 40% of the M/700-Leupold-Weaver combination could not be collimated as assembled and that shim stock was necessary for proper targeting. When shimming was necessary it was always applied to the left side of the rear base. Of the five (5) guns originally returned to Ilion by Mr. Blair and hand carried to his gunshop by this writer, two (2) could not be collimated with a Leupold 3x-9x scope selected from his inventory.

Comments and Observations:

The Leupold 3x-9x variable power scope has only 28 inches total windage and elevation adjustment (± 14 inches). This is only about 1/3 of the adjustment available in other hunting scopes. Because adjustment appears to be limited in one direction only, the Leupold Company should be contacted on this matter.

Mr. Warsky and Mr. Blair are both good friends of Remington, and they appeared glad that such attention was being given to M/700 quality. They pointed out that Remington has the major portion of the centerfire rifle market and practically all of the shotgun market.

HKB/DJA/bd

343
AL 0029750

M/76 Customer Complaint

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700GENERAL CONDITION: Good R #: 014720OUTSIDE WORK: SCOPE MOUNTED, BUTT PLATE DATE: 7-24-72CHANGED TO RECOIL PAD. FROM: S.R. MAYMOULFIRED AMMO TYPE: - MELBOURN, FLA.& CONDITION: _____ GUN #: 357864PROOF: R.E.P. INSP.: 0 TEST: A7 CODE: RP = 11/67HEADING: O.K. G.K./CAL.: 300GBREECH OPENING: - CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER ADJUSTING SCREWS NOT SEALED (NO INDICATION
THE EVER WERE). ENGAGEMENT SEAR TO TRIGGER CONNECTOR
.020, TRIGGER PULL ALBS, TRIGGER RUBS ON GUARD.
GREASE LIKE LUBRICANT ON TRIGGER INSIDE HOUSING.

COMPLAINT: FIRES WHEN THE SAFETY IS THROWN OFF.INCIDENT: FOLLOW DOWN

COMMENTS: THE HEAVY LUBRICANT COMBINED WITH FRICTION
OF THE TRIGGER AGAINST THE TRIGGER GUARD
CAUSED TRIGGER RETRACTION TO BE ERRATIC
RESULTING IN FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3219

AL 0029751

Ni/700 Customer Complaint

... N/A GUN REGISTRATION REPORT NUMBER: _____ MODEL: 700 YARMINT

GENERAL CONDITION: NEW R # : 014704

OUTSIDE WORK: SCORE MOUNTED. DATE: 7-21-72

FIRED 8000 TYPE: - FROM: BILLINGS P.D.

& CONDITION: _____ BILLINGS, MONT.

PROOF: R.E.P. IMP. : 7.8 TEST: 55 GUN # : 318117

WEADING: _____ CODE: RP = 1/62

BATCH OPENING: - GR./DALY: 22-250

RECOIL SHOULDERING: O.K. CHECKED BY: C. PROSSER

CHAMBER: O.K. APPROVED: _____

TEST: _____ APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.

COMPLAINT: "GUN FIRES ON LOSING THE BOLT." ALSO REPORTED IN KEYHOLE.

INCIDENT: FELLON DOWN

COMMENTS: THE FELLON DOWN WAS A RESULT OF THE BROKEN TRIGGER CONNECTOR FAILING TO RETRACT.

PLAINTIFF'S
EXHIBIT

3220

10/1
AL 0029752

N/710 Cust. Complaint

... No GUN REGISTRATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: Good R #: 014609
 OUTSIDE WORK: SCREWS MONITOR DATE: 7-21-72
 FROM: LEO D. JONES
 FIRED AMMO TYPE: 150 GR. SUPER X HARREN, OHIO
 & CONDITION: _____ GUN #: 6282457
 PROOF: R.E.P.-D TRIP: 79 TEST: Q7 CODE: ES-10/69
 READING: O.K. ME./OAL: 7MM REM MAG
 BREACH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDER: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: _____ APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SCREW-TRIGGER CONNECTOR ENGAGEMENT .005 (MIN. IS .020)
STEP IN FACE OF BOLT. TRIGGER NOT DB-BURNED.

COMPLAINT: "UPON OPENING THE BOLT THE GUN DISCHARGED.
"SHOULDS HARD TO CHAMBER"

INCIDENT: FOLLOW DOWN, CLOSERS HARD

COMMENTS: FOLLOW DOWN WAS CAUSED BY .005 ENGAGEMENT
AND SLIGHT TRIGGER BIND. THE CLOSERS HARD WAS DUE
TO THE STEP IN THE BOLT FACE WHICH CREATED A MIN.
HEADER CONDITION NOT PICKED UP BY THE HEADING
DUMMY.

PLAINTIFF'S
EXHIBIT

3221

AL 0029753

RD-6542-1 Rev. 2-15-61

NO GUN EXAMINATION REPORT NUMBER: MODEL: 700

GENERAL CONDITION: GOOD R #: 014102

OUTSIDE WORK: SCOPE MOUNTED DATE: 7-14-72

FROM: GUSTAVE GUNDERSON

FIRE AMMO TYPE: CONRAD, MONTANA

& CONDITION: GUN #: 6226860

PROOF: R.E.P. ASSEMBLER 79 INSP.: 73 TEST: 87 CODE: AS- 3/69

HEADING: - GA./CAL.: 22-250

BREACH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED:

CHAMBER: O.K. APPROVED:

TEST: No APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

CONNECTOR - SEAR ENGAGEMENT .010 (MIN. IS .020) TRIGGER
PULL $2\frac{1}{2}$ LBS. (3 LBS. IS MIN.) RE-ADJUSTED BY CUSTOMER.
SEAR BEARING OF CONNECTOR CROOKED. TRIGGER MEASURED -
.008 UNDER MIN. ON CONNECTOR CLEARANCE, .002 OVER MAX. ON
& IF PIN HOLE TO TOP.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF TRIGGER PULL
TOO HEAVY.

INCIDENT: FOLLOW DOWN

COMMENTS: LIGHT TRIGGER PULL RESULTS IN ERRATIC RETRACTION,
THE TRIGGER HOLDING THE CONNECTOR TOO HIGH AND
ALLOWING IT TO WORK UP .008 TO INTERFERE WITH THE
SEAR COULD MAKE RETRACTION IMPOSSIBLE, FOLLOW
DOWN WOULD RESULT.

PLAINTIFF'S
EXHIBIT

3222

AL 0029754

V1700 Custom Comp. 1/1

I. NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 VARMINTGENERAL CONDITION: NEWR #: 014137OUTSIDE WORK: FRONT TRIGGER ADJUSTINGDATE: 7-13-72SCREWS ADJUSTED.FROM: H.L. PETERS INC.

FIRED AMMO TYPE: _____

BUFFALO, N.Y.

& CONDITION: _____

GUN #: 6519891PROOF: R.E.P.-M INSP.: 48 TEST: 44LW = 2/72
CODE: PW = 6/72HEADING: -GA./CAL.: 25-06 REM.BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

CONNECTOR - SEAR ENGAGEMENT .010 (MIN. = .020) TRIGGER
ADJUSTING SCREW BACKED OUT ELIMINATING SPRING TENSION
REQUIRED TO RETRACT TRIGGER & TRIGGER CONNECTOR.

COMPLAINT: FIRES WHEN CLOSING BOLTINCIDENT: FOLLOW DOWNCOMMENTS: APPARENTLY THE CUSTOMER ATTEMPTING TO

ADJUST THE TRIGGER PULL, BACKED THE ADJUSTING
SCREW OUT TOO FAR WHICH ELIMINATED ALL SPRING
TENSION. WITHOUT THIS, THE TRIGGER AND CONNECTOR
FAILED TO RETRACT RESULTING IN FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3223

AL 0029755

M/700 Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 013812
 OUTSIDE WORK: SCOPE MOUNTED DATE: 7-12-72
 FROM: CHRISTMAN'S INC.
 FIRED AMMO TYPE: REMINGTON DARIEN, CT.
 & CONDITION: _____ GUN #: 6394467
 PROOF: R.E.P. ASSEMBLER 97 INSPECTION: 7A TEST: _____ CODE: XT = 12/70
 HEADING: O.K. GRA./CAL.: 222
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: 10 ROUNDS - O.K. APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR - SEAR ENGAGEMENT .010 (MIN.) .020 TRIGGER
PULL = 2 LBS. (MIN. 15 LBS.) NECK MEASURES .460 (MIN. .4518)
THROAT IS SHALLOW.

COMPLAINT: "CHAMBER NECK IS TOO SHORT, CHECK TRIGGER AT LIGHT SETTING"

INCIDENT: POTENTIAL FOLLOW DOWN.

COMMENTS: THIS RIFLE WAS RETURNED QUESTIONING THE FRONT
OF THE CARTRIDGE CASE BEING MARKED, WHICH IS
THE MARK OF THE CASE WIDING ACROSS THE RECHAMBER
IN BEING EJECTED. THE LIGHT TRIGGER PULL AND UNDER
MIN. ENGAGEMENT COULD HAVE LED TO A MORE SERIOUS
COMPLAINT LATER.

PLAINTIFF'S
EXHIBIT

3224

AL 0029756

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 013324
 OUTSIDE WORK: NO DATE: 7-6-72
 FIRED AMMO TYPE: _____ FROM: MEYER HOWER ^{INC.} SPAS,
 & CONDITION: _____ GOLDEN, COLO.
 PROOF: R.E.P. ASSEMBLER R10 GUN #: 6230255
 INSP.: 73 TEST: 87 CODE: AS = 3/69
 HEADING: _____ GA./CAL.: 6MM REM.
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR CLEARANCE ON TRIGGER .004 UNDER MIN. DUE
PIN TO TOP OF TRIGGER ON MAY. TRIGGER HITS TRIGGER
HOUSING. HEAVY LUBRICANT USED INSIDE HOUSING.
SAFETY R. .001 UNDER MIN. CONNECTOR CLEARANCE .005 D.
WITH SAFETY ON.

COMPLAINT: "HAMMER FALLS"

INCIDENT: FOLLOW DOWN

COMMENTS: THE COMBINATION OF LOW SAFETY, HIGH TRIGGER
AND TRIGGER BIND CAUSES FAILURE TO RETRACT WHEN
TRIGGER IS PULLED WITH SAFETY ON, THEN FOLLOW
DOWN WHEN SAFETY IS PUSHED OFF.



AL 0029757

No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 *Curt*GENERAL CONDITION: NEWR #: 013117OUTSIDE WORK: SCOPE MOUNTEDDATE: 6-19-72FIRED AMMO TYPE: -FROM: SPORTSMEN'S DENMT. SHASTA, CAL.& CONDITION: ASSEMBLER 65GUN #: 6249832PROOF: R.F.P.-D INSP.: 7ATEST: B7CODE: P5=6/69, CH3=4/72HEADING: O.K.GA./CAL.: 7MMBREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN=.020)BOTH SEAR AND CONNECTOR DAMAGED ON ENGAGEMENT CORNERS. CONDITION OF FIRING PIN HOLE & FIRING PIN POINT INDICATE PRIMER PIERCING HAS BEEN EXPERIENCED.COMPLAINT: WILL NOT FIREINCIDENT: FOLLOW DOWNCOMMENTS: THE CUSTOMER PROBABLY EXPERIENCED A PERCEDPRIMER WHICH WITH THE .010 ENGAGEMENT, CAUSED THE SEAR-CONNECTOR DAMAGE RESULTING IN FOLLOW DOWN.PLAINTIFF'S
EXHIBIT

3226

AL 0029758

M/115 Custom

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700

GENERAL CONDITION: NEW R #: 012925

OUTSIDE WORK: NO DATE: 6-14-72

FROM: LEO'S CUSTOM STOKES

FIRE AMMO TYPE: _____ BETHEL PARK, PENN.

& CONDITION: _____ GUN #: 6445877

PROOF: R.E.P.N INSP.: 73 TEST: 13 CODE: PU-6/71

HEADING: O.K. GRA./CAL.: 17REM.

BRECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: NO - 20 ROUNDS WITH NO BLOWN PRIMERS APPROVED: _____

AFTER NEW BOLT, APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR'S SEAR ENGAGEMENT .010, BOTH
CORNERS BROKEN OFF, FIRING PIN ASSEMBLY RUSTED,
BOLT BODY STAINED & FIRING PIN HOLE AT HEADING SHARP.

COMPLAINT: WHEN HE CLOSED THE BOLT ON THE FOURTH ROUND
IT WENT OFF.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE CORNER BREAKAGE ON THE SEAR AND
TRIGGER CONNECTOR, WHICH RESULTED IN FOLLOW-DOWN,
IS THE RESULT OF INSUFFICIENT ENGAGEMENT AND PRIMER
PIERCING.

PLAINTIFF'S
EXHIBIT

3227

AL 0029759

M/700 Customer Complaint.

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 012758
 OUTSIDE WORK: FRONT ADJUSTING SCREWS DATE: 6-12-72
 UNSEALED FROM: J.V. ELIOT JR.
 FIRED AMMO TYPE: _____ SAN MEOTO, CALIF.
 & CONDITION: _____ GUN #: 6446926
 PROOF: R.E.P.-L INSP. ASSEM. 30 TEST: 84 CODE: DU= 9/71
 HEADING: O.K. GR./CAL.: 17 REM.
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: EXCESSIVE RADIUS APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CORNER OF SEAR CHIPPED OFF. FIRING PIN HOLE NOT
 ROUNDED. FIRING PIN HOLE, REAR, NOT CLEANED - FIRING
 PIN ASSEMBLY RUSTY. ENGAGEMENT UNDER MIN. - SEAR TO
 CONNECTOR.

COMPLAINT: FOLLOWS DOWN

INCIDENT: FOLLOW DOWN

COMMENTS: EVIDENTLY THE CUSTOMER EXPERIENCED A PIECED
 PRIMER, WHICH WITH UNDER MIN ENGAGEMENT CAUSED
 THE CORNER OF THE SEAR TO CHIP OFF.

PLAINTIFF'S
EXHIBIT

3228

AL 0029760

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDLGENERAL CONDITION: GOOD R #: 12354OUTSIDE WORK: SCOPE MOUNTED, TRIGGER DATE: 6-16-71ASSEMBLY ADJUSTED (FRONT SCREWS) FROM: RON MCKINNEYFIRED AMMO TYPE: - THOMASTON, TEXAS& CONDITION: _____ GUN #: 6324285PROOF: R.E.P.-G ASSEMBLER AI INSP: 73 TEST: 87 CODE: AT-3/70HEADING: CLOSES ON MAY. HEADING DUMMY GA./CAL.: 25-06BREACH OPENING: - CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

FIRING PIN POINT FLAT ON SIDES, TRIGGER CONNECTOR
BROKEN, GRIP CAP OFF, RADINS AT REAR OF RECOIL
SHOULDERS ON BOLT.

COMPLAINT: "CANNOT GET THE TRIGGER TO STAY IN ADJUSTMENT,"
"WHEN I SHOOT THE RIFLE, THE FIRING PIN KNOCKS HOLES IN THE PRIMER,"
 INCIDENT: FOLLOW-DOWN & PIERCED PRIMER.

COMMENTS: THE BROKEN TRIGGER CONNECTOR FAILING TO RETRACT
CAUSED THE FOLLOW-DOWN. PRIMER PIERCING MAY
HAVE BEEN CAUSED BY THE DEFORMED FIRING PIN POINT.
REPLACED TRIGGER CONNECTOR.
REPLACED BOLT ASSEMBLY & FIRING PIN - SEE ABOVE.

PLAINTIFF'S
EXHIBIT

3229

101
AL 0029761

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: NEW R #: 010030

OUTSIDE WORK: NO DATE: 5-1-72

FIRED AMMO TYPE: _____ FROM: ODELL HOWE, CO.

& CONDITION: _____ GREENSBORO, N.C.

PROOF: R.F.E.-H INSP.: 51 TEST: 13 GUN #: 6429469

HEADING: O.K. CODE: EU-10/71

BREECH OPENING: - GA./CAL.: 3006

RECOIL SHOULDERS: O.K. CHECKED BY: C. PEDDER

CHAMBER: O.K. APPROVED: _____

TEST: NO. APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTS. CONNECTOR, SEAR ENGAGEMENT = .008 MIN. IS .020 ALSO FOUND METAL CHIP BETWEEN TRIGGER & CONNECTOR.

COMPLAINT: WILL NOT FIRE.

INCIDENT: FOLLOWS DOWN.

COMMENTS: THE METAL CHIP BETWEEN THE TRIGGER AND CONNECTOR REDUCED THE CONNECTOR-SEAR ENGAGEMENT TO ZERO CAUSING THE FOLLOWS DOWN.

PLAINTIFF'S
EXHIBIT

3230

AL 0029762

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: NEW R #: 010133
 OUTSIDE WORK: NO DATE: 5-1-72
 FIRED AMMO TYPE: _____ FROM: RUDY'S GUN EYCH.
 & CONDITION: _____ WYNDMERE, N.D.A.C.
 PROOF: R.E.P. - L INSP.: 55 TEST: - GUN #: 6450564
 HEADING: O.K. CODE: PU = 6/71
 BREECH OPENING: - GA./CAL.: 3006
 RECOIL SHOULDERS: O.K. CHECKED BY: CIPROSSER
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
TRIGGER CONNECTOR BROKEN.

COMPLAINT: "TRIGGER DOES NOT WORK PROPERLY AND GUN
WONT COCK"

INCIDENT: FOLLOWS DOWN

COMMENTS: THE BROKEN TRIGGER CONNECTOR FAILS TO RETRACT,
SO THAT THE SEAR, BEING UNSUPPORTED DOES NOT
STOP THE FIRING PIN WHICH FOLLOWS DOWN,

PLAINTIFF'S
EXHIBIT

3231

AL 0029763

*Custom Complaint*P.I. NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: GOODR #: 23021OUTSIDE WORK: SCOPE MOUNTED TRIGGERDATE: 11-15-71ADJUSTMENTS CHANGEDFROM: WILLIAM H. ULERYFIRED AMMO TYPE: -OBERLIN, KANSAS& CONDITION: ASSEMBLER 73GUN #: 6456668PROOF: R.E.P. - D INSP. 73 TEST: 66CODE: OU = 7/91HEADING: CLOSES OVER MAX. BELT GAGE.GR./CAL.: 7MMBREACH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: EXCESSIVE RADIUS AT REAR.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED COMPONENTS.COMPLAINT: WENT OFF ACCIDENTALLY WHILE UNLOADING, AGAIN LATER WHILE LOADING.INCIDENT: FOLLOW DOWN.

COMMENTS: CUSTOMER'S MALFUNCTION NOT VERIFIED BY WRITER,
HOWEVER HIS READJUSTING HAS MADE IT IMPOSSIBLE TO
DETERMINE WHETHER THE RIFLE WAS CORRECTLY
ADJUSTED ON FINAL ASSEMBLY.

PLAINTIFF'S
EXHIBIT

3232

AL 0029764 10/10

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: GOOD R #: 22791
 OUTSIDE WORK: NO DATE: 11-12-71
 FROM: CHRISTY GUN WORKS
 FIRED AMMO TYPE: - SACRAMENTO, CAL.
 & CONDITION: ASSEMBLER 12 GUN #: 6372120
 PROOF: R.E.P.-A INSP.: NONE TEST: 13 CODE: NO COD
 HEADING: BOLT CLOSSES ON ASSEMBLY MAX. GA./CAL.: 3006
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED COMPONENTS.

COMPLAINT: GUN FIRES WHEN SAFETY IS RELEASED.

INCIDENT: FOLLOW DOWN.

COMMENTS: MALFUNCTION NOT VERIFIED BY WRITER.
HOWEVER, EXAMINATION OF THE TRIGGER REVEALS
SEVERAL SMALL METAL SHAVINGS WHICH MAY HAVE,
IF CONCENTRATED IN ONE POSITION, REDUCED THE
ENGAGEMENT TO A DANGEROUS LEVEL.
TRIGGER PULL WAS FOUR POUNDS, SEAR-CONNECTOR
ENGAGEMENT WAS .020.

PLAINTIFF'S
EXHIBIT

3233

AL 0029765

181
0

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: GOOD R #: 19457
OUTSIDE WORK: SCOPE MOUNTED. DATE: 10-4-71

FROM: GEN. SPT. SUPPLY CO.FIRED AMMO TYPE: _____ SYRACUSE, N.Y.& CONDITION: _____ GUN #: 6279663PROOF: R.E.R.-E INSP.: 74 TEST: 87 CODE: E5 = 10/69HEADING: O.K. GR./CAL.: 3006BREECH OPENING: - CHECKED BY: G. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED OR BROKEN COMPONENTS.COMPLAINT: FIRES WHEN SAFE IS PUSHED OFF.

INCIDENT: _____

PLAINTIFF'S
EXHIBIT

3234

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BE
DUPLICATED ANY WAY. IT WAS NOTED AND VERIFIED
BY K. CHADWICK THAT THE CUSTOMER HAD ADDED
A LUBRICANT WHICH IS TOO HEAVY (THICK) TO THE
TRIGGER ASSEMBLY. THIS, IN COLD CLIMATES WOULD
CAUSE A MALFUNCTION SUCH AS THAT CLAIMED BY
THE CUSTOMER.

AL 0029766

Customer Complaint... NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700VAR.GENERAL CONDITION: GOOD R #: 010987OUTSIDE WORK: NO DATE: 5-9-72FIRED AMMO TYPE: - FROM: ALVIN A. SMITH

& CONDITION: _____ CORYDON, IND.

PROOF: R.F.P.-C INSP. 9 TEST: 41 GUN #: 6342627HEADING: O.K. CODE: KT. 5/70BREACH OPENING: _____ SK./CAL.: 222RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSERCHAMBER: O.K. APPROVED: [Signature]TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN. NO STOCK ETC.COMPLAINT: REPAIRINCIDENT: FOLLOW DOWNCOMMENTS: THE BROKEN TRIGGER CONNECTOR COULD NOT PERFORM ITS FUNCTION OF SUPPORTING THE SEAR AGAINST THE THRUST OF THE FIRING PIN HEAD.PLAINTIFF'S
EXHIBIT

3235

AL 0029767

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 EPL
 GENERAL CONDITION: NEW R #: 006000
 OUTSIDE WORK: SAFETY WORK DATE: 3-13-72
 FIRED AMMO TYPE: _____ FROM: BRASS, HORN CO.
 & CONDITION: _____ BREWER, DODGE, PR.
 PROOF: R.E.P. INSP.: 79 TEST: 87 GUN #: 6245354
 HEADING: _____ CODE: 05-2/68
 BREACH OPENING: _____ GR./CAL.: 308
 RECOIL SHOULDERS: O.K. CHECKED BY: C.P. 4/4/72
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEALING INJECT. ENTIRELY NEW (STYLING)

CONDUCTOR OF WORKING PARTS THE NO 69 (P12-1038) TRIGGER
 CLEARANCE ON CONNECTOR = 1.090 (P12-1038) THIS ADDS UP TO
 .014 MORE CLEARANCE BETWEEN CONNECTOR AND TRIGGER THAN
 SPECIFICATIONS.

COMPLAINT: FIRING WHEN SAFETY IS RELEASED

INCIDENT: FOLLOW DOWN

COMMENTS: THE EXCESSIVE CLEARANCE
AND CONNECTOR ALLOWED THE
TRIGGER TO FALL BACK AND
CAUSING FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3236

AL 0029768

P. 140 GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: USED R #: 006153
 OUTSIDE WORK: TRIGGER ADJUSTING SCREWS RE- DATE: 3-10-72
ADJUSTED, SCOPE MOUNTED, & SIGHTS REMOVED. FROM: GIBSON PRODUCTS CO.
 FIRED AMMO TYPE: _____ MISSOULA, MONTANA
 & CONDITION: _____ GUN #: 6325677
 PROOF: P.F.D.-D INSP.: 9 TEST: 41 CODE: CT = 4/70
 HEADING: _____ GA./CAL.: 2506
 BREECH OPENING: _____ CHECKED BY: PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN-DAMAGED COMPONENTS. CONNECTOR CLEARANCE
ON TRIGGER 1.070 ($\frac{1412}{1.070}$) TRIGGER CLEARANCE IN CONNECTOR
1.091 ($\frac{1412}{1.091}$) ADJUSTMENTS HAVING BEEN ALTERED MAKE IT
IMPOSSIBLE TO DETERMIN CONDITION AFTER FINAL ASSEMBLY.
AS RECEIVED, SEAR CONNECTOR ENGAGEMENT = .005 MIN. IS .030.
 COMPLAINT: "SAFETY DEFECTIVE"

INCIDENT: MAY HAVE BEEN FOLLOW DOWN

PLAINTIFF'S
EXHIBIT

3237

COMMENTS: THE GUN OWNER'S MALFUNCTION COULD HAVE BEEN THE
RESULT OF LIGHT TRIGGER HILL, 3235, AND 11005 MIN.
SEAR CONNECTOR ENGAGEMENT THIS WOULD PERMIT JAM
UP. IT COULD ALSO HAVE BEEN THE RESULT OF THE
1/4 EXCESS CLEARANCE BETWEEN TRIGGER & CONNECTOR
WHICH PERMITS CONNECTOR-SEAR INTERFERENCE PREVENT-
ING PROPER TRIGGER-CONNECTOR RETRACTION.

P NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660GENERAL CONDITION: NEW R #: 006930OUTSIDE WORK: SCOPE MOUNTED, SWIVELS ADDED DATE: 3-13-72CEMENT REMOVED - REAR ADJUSTING SCREW FROM: ACKERMAN'S FIRST
AND SUPPLIESFIRED AMMO TYPE: - GROVE CITY, PA.& CONDITION: _____ GUN #: 111373PROOF: R.I.D. ASPECTS INSP.: 73 TEST: 79 CODE: KR = 5/68HEADING: - GA./CAL.: 223 W.M.BREACH OPENING: - CHECKED BY: PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR AND TOP INSIDE OF HOUSING COATED WITH DRIED
LUBRICANT OR OTHER MATERIAL.COMPLAINT: "GOES OFF WITHOUT WARNING."INCIDENT: FOLLOW DOWNCOMMENTS: THE LUBRICANT OR WHATEVER, SHOULD INFLUENCE
RESPONSE OF TRIGGER ASSEMBLY - TRIGGER FULLY TO
RESET - SEAR FALLS TO RESET TO COCKED POSITION.PLAINTIFF'S
EXHIBIT

3238

- 1 of 1
AL 0029770

P. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: FAIR R #: 006152
 OUTSIDE WORK: SCOPE MOUNTED, SIGHTS DATE: 3-8-72
REMOVED. FROM: GIBSON PRODUCTS CO.
 FIRED AMMO TYPE: _____ MISSOULA, MONTANA
 & CONDITION: _____ GUN #: 6222426
 PROOF: R.E.P. INSP.: ASSEMBLER 30 TEST: 49 CODE: P5-6/69
 HEADING: — GUN/CAL.: 3006
 BREECH OPENING: _____ CHECKED BY: PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN, DAMAGED COMPONENTS. SEAR CONNECTOR
ENGAGEMENT .06 (MIN. IS .020) TRIGGER CLEARANCE IN
CONNECTOR = 1.091 (M/D = 1.083, 1.080); CONNECTOR CLEARANCE ON
TRIGGER = 1.071 (M/D = 1.079) CONNECTOR IS WARPED AND
TRIGGER HAS EXCESSIVE RADIUS UNDER CONNECTOR ON TOP.

COMPLAINT: DEFECTIVE SAFETY

INCIDENT: FOLLOW DOWN IS POSSIBLE

PLAINTIFF'S
EXHIBIT

3239

COMMENTS: THE EXCESS CLEARANCE BETWEEN THE CONNECTOR
AND TRIGGER (.013 EXCESS) COULD ALLOW THE CONNECTOR
TO WORK UP TO INTERFERE WITH THE SEAR PREVENTING
RETRACTION WITH THE SAFETY ON. PUSHING THE
SAFETY OFF THEN WOULD RESULT IN A FOLLOW DOWN.

P NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: GOOD R #: 005856
 OUTSIDE WORK: NO DATE: 3-7-72
 FIRED AMMO TYPE: _____ FROM: CONRAD SGT. ADS.
 & CONDITION: _____ MOBERLY, MO.
 PROOF: R.E.P.-E INSP.: 9 TEST: 13 GUN #: 6243-00
 HEADING: _____ CODE: 05-6/69
 BREECH OPENING: _____ GA./CAL.: 309
 RECOIL SHOULDERS: OK CHECKED BY: C. PROSSER
 CHAMBER: OK APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED, BROKEN COMPONENTS. TRIGGER PULL 8 LBS.

NO TRIGGER-TRIGGER GUARD INTERFERENCE. REAR-LOCK-
 ECTOR ENGAGEMENT = .020 (MIN. IS .020) SPRING 14-22T.
 HEAVILY OILED.

COMPLAINT: "GUN SOMEHOWS WILL FIRE AT 300 YD. BOW IS
 ENGAGED WITH TRIGGER GUARD"

INCIDENT: FOLLOW DOWN

COMMENTS: IT APPEARS DEFECTS BEING FOUND TO THE

OIL USED PROBABLY CAUSED THE TRIGGER TO
 REMAIN IN FIRED POSITION BY PRESSING THE FOLLOWING
 DOWN MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3240

1 of 1

AL 0029772

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: GOOD R #: 005424
 OUTSIDE WORK: TRIGGER STOP SCREEN SEAL DATE: 2-25-72
 FROM: DONALD GABNON
 FIRED AMMO TYPE: _____ CHICAGO, ILLINOIS
 & CONDITION: _____ GUN #: 6362419
 ASSEMBLER V
 PROOF: R.E.P.-A INSP.: 58 TEST: 13 CODE: DT-9/70
 HEADING: _____ GR./CAL.: 300 G SPR.
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: _____ APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED COMPONENTS. HORIZONTAL ENGAGEMENT

.030 MIN. = .020 CONNECTOR CLEARANCE ON TRIGGER =

1.072 MID = ^{1.079} 1.076 TRIGGER CLEARANCE ON CONNECTOR =

1.089 MID = ^{1.083} 1.080. TRIGGER STOP SCREEN SEAL BROKEN.

TRIGGER BIND DETECTABLE, LUBRICANT TOO HEAVY.

COMPLAINT: FIRES WHEN SAFETY IS RELEASED.

INCIDENT: TRIGGER FAILS TO RETRACT.

COMMENTS: THE FIT OF THE TRIGGER TO THE HOUSING, TOO
 HEAVY LUBRICANT & EXCESS CLEARANCE BETWEEN
 CONNECTOR AND TRIGGER (.010) COULD LEAD TO THE
 CUSTOMER'S MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3241

1 of 1
AL 0029773

I. NA GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: GOOD R #: 22234
 OUTSIDE WORK: TRIGGER SCREWS READJUSTED DATE: 12/7/67
 FIRED AMMO TYPE: UNKNOWN FROM: WESLER WEITER
 & CONDITION: _____ ARMS ETC
 _____ 205 SECOND ST
 _____ SAN FRANCISCO CAL
 GUN #: 300523
 PROOF: REP INSP.: 14 TEST: 58 8-67
 HEADING: OK 20 WIN
 BREACH OPENING: _____ CHECKED BY: MT
 RECOIL SHOULDERS: NORMAL APPROVED: [Signature]
 CHAMBER: _____ APPROVED: [Signature] 1/3/68
 TEST: _____ APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

STOCK CRACKED, BUTT PLATE MISSING, MAGAZINE
BOX DEFORMED

GUN FIRED WHEN SAFE WAS MOVED TO
POSITION (PER CUSTOMER)

INCIDENT: GUN APPARENTLY FIRED WHEN SAFE WAS RELEASED AND
TRIGGER INADVERTENTLY PULLED AT SAME TIME OR GUN WAS
HIT CAUSING JAR OFF DUE TO IMPROPER SETTING.

COMMENTS: SEAL WAS REMOVED FROM TRIG. ADJUSTING SCREW AND EN-
GAGEMENT SET LESS THAN RECOMMENDED. 620 MIN. ENGAGEMENT
SCREW ALSO SHOWS EVIDENCE OF HAVING BEEN MOVED
TRIGGER PULL WAS CHANGED SO THAT [REDACTED] APPROXIMATE
1 1/2 LBS. EVEN SO WAS NOT ABLE TO [REDACTED] FOLLOW -
DOWN AT PRESENT SETTING AS CUSTOMER MAINTAINS.

PLAINTIFF'S
 EXHIBIT

3242

AL 0029774

1 of 1

NOT A BLOW-UP

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 1514
 OUTSIDE WORK: TRIGGER PULL ADJUSTED. DATE: 1-22-70
 FIRED AMMO TYPE: — FROM: DENVER,
— COLORADO
 & CONDITION: _____ GUN #: 6227025
 PROOP: R.E.F. INSP.: 73 TEST: _____ = 3/69
 HEADING: — _____ 250
 BREACH OPENING: — CHECKED BY: E. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: DRY FIRED - MALFUNCTION VERIFIED. APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

FIRES WHEN RELEASING SAFETY TO OFF POSITION.

INCIDENT: SAFETY DOES NOT LIFT SEAR CLEAR OF TRIGGER CONNECTOR.

COMMENTS: SAFETY, HOUSING, TRIGGER CONNECTOR & TRIGGER
WERE MEASURED. ONLY THE TRIGGER WAS FOUND TO
BE NOT TO SPECIFICATIONS. DIMENSIONS FROM 4 OF 5
HOLE TO TOP BEING .9782 (MODE - DRAWING = .971)

PLAINTIFF'S
EXHIBIT

3243

AL 0029775

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 22570
 OUTSIDE WORK: NO DATE: 11-2-70
 FROM: LIMA, OHIO
 FIRED AMMO TYPE: _____
 & CONDITION: _____ GUN #: 6233914
 PROOF: _____ INSP.: _____ TEST: _____ CODE: CS = 4/69
 HEADING: _____ GA./CAL.: 222
 BREECH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: _____ APPROVED: _____
 CHAMBER: _____ APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
O.K.

COMPLAINT: FIRES WHEN SAFE IS RELEASED.

INCIDENT: TRIGGER CONNECTOR MOVES UP WHEN TRIGGER IS PULLED WITH THE SAFETY ON.

COMMENTS: TRIGGER CONNECTOR IS .007 OVERSIZE ON TRIGGER CLEARANCE. TRIGGER IS .006 UNDERSIZE ON CONNECTOR CLEARANCE. THIS EXCESSIVE CLEARANCE ALLOWS THE CONNECTOR TO WORK UP, INTERFERES WITH THE SEAR AND FAIL TO RETRACT UNDER THE SEAR RESULTING IN FOLLOW DOWN WHEN THE SAFETY IS PUSHED OFF.

PLAINTIFF'S
EXHIBIT

3244

10 of 1
AL 0029776

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: LIKE NEW R #: _____
OUTSIDE WORK: NO DATE: 11-3-70
FIRED AMMO TYPE: _____ FROM: EAU CLAIRE,
_____ WISCONSIN.
& CONDITION: _____ GUN #: 6258555
PROOF: _____ INSP.: _____ TEST: _____ CODE: 03-7/69
HEADING: _____ GA./CAL.: 3006
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: _____ APPROVED: _____
CHAMBER: _____ APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
O.K.

PLAINTIFF'S
EXHIBIT

3245

COMPLAINT: GUN FIRES WHEN SAFETY IS PUSHED ON FIRE.INCIDENT: NOT VERIFIED.

COMMENTS: HEAVY LUBRICANT PRESENT. PARTS MEASURED
INDICATE EXCESSIVE CLEARANCE (.013) BETWEEN
TRIGGER & CONNECTOR, WHICH WOULD ALLOW THE CONNECTOR
TO MOVE UP & INTERFERE WITH THE FRONT
OF THE SEAR AND PREVENT RETRACTION.
SEAR-CONNECTOR ENGAGEMENT .010.

1 of 1

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 02095
 OUTSIDE WORK: SCOPE MOUNTED DATE: 1-24-71
 FROM: NAGEL'S GUN SHOP
 FIRED AMMO TYPE: _____ SAN ANTONIO, TEXAS.
 & CONDITION: _____ GUN #: 6206774
 PROOF: R.E.P. INSP.: 9 TEST: 13 CODE: B5-1/69
 HEADING: O.K. GA./CAL.: 270 WIN.
 BREACH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: "FIRES WHEN YOU RELEASE SAFETY"INCIDENT: FOLLOWS DOWN
 PLAINTIFF'S
 EXHIBIT
 3246

COMMENTS: TRIGGER CLEARANCE ON TRIGGER CONNECTOR = 1.091
MODEL DRAWING = 1.080
1.063 OVERSIZE .008; CONNECTOR
CLEARANCE ON TRIGGER = 1.068 MODEL DRAWING = 1.076
UNDERSIZE .008. ALTHOUGH THE MALFUNCTION COULD
NOT BE DUPLICATED, THE EXCESSIVE CLEARANCE BETWEEN
CONNECTOR & TRIGGER WOULD ALLOW INTERFER-
ENCE BETWEEN CONNECTOR & SEAR AND RESULT
IN FOLLOW DOWN.

Customer Complaint

F... NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADLGENERAL CONDITION: NEW R #: 06640OUTSIDE WORK: NO DATE: 3-9-71FIRED AMMO TYPE: _____ FROM: JOE W. HARRISVICTORIA, TEXAS.& CONDITION: _____ GUN #: 6364870PROOF: R.E.P.-A INSP.: D TEST: 13 CODE: WT = 11/70HEADING: O.K. GR./CAL.: 270 WIN.BREACH OPENING: _____ CHECKED BY: C. PROUDERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN OR DAMAGED COMPONENTSCOMPLAINT: FIRE WHEN SAFETY WAS PUSHED OFF.PLAINTIFF'S
EXHIBIT

3247

INCIDENT: FOLLOWED DOWNCOMMENTS: CONNECTOR-SEAR ENGAGEMENT .010, MIN. IS .015THIS COUPLED WITH A TOO HEAVY LUBRICANT AND SLIGHTLY
ROUNDED SEAR, PROBABLY LED TO THE MALFUNCTION.THE MALFUNCTION COULD NOT, HOWEVER, BE
DUPLICATED HERE.ENGAGEMENT RE-ADJUSTED TO .015.

AL 0029779

1 NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 ADLGENERAL CONDITION: FAIRR #: 11954OUTSIDE WORK: SCOPE MOUNTEDDATE: 6-2-71

FIRED AMMO TYPE: _____

FROM: NATIONAL PK. SYS.
KAHULUI, MAUI, HAWAII

& CONDITION: _____

GUN #: 6258351PROOF: R.E.P.-E. INSP.: U TEST: 87CODE: OS = 7/69HEADING: O.K.GA./CAL.: 3006BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO BROKEN ETC. COMPONENTS.CONNECTOR CLEARANCE ON TRIGGER = 1.069 M/D = 1.079 - 1.007TRIGGER CLEARANCE ON CONNECTOR = 1.089 M/D = 1.088 - 1.006CONNECTOR - SEAR ENGAGEMENT = 0.015 (0.005 UNDER MIN.)TRIGGER PULL FIVE POUNDS. EXCESSIVE LUBRICANTS?COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.PLAINTIFF'S
EXHIBIT

3248

INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACTCOMMENTS: CAN NOT DUPLICATE CUSTOMER'S MALFUNCTION.THE TRIGGER-CONNECTOR & TRIGGER NOT TO MODELDRAWING PERMIT SEAR, CONNECTOR INTERFERENCEFAILURE TO RETRACT.

NO GUN EXAMINATION REPORT NUMBER: MODEL: 700 ADL

GENERAL CONDITION: FAIR R #: 12986

OUTSIDE WORK: SCOPE MOUNTED DATE: 6-28-71

FIRE AMMO TYPE: KAULU, MAUI, HAWAII

& CONDITION: GUN #: 6258726

PROOF: R.E.D.-F INSP. TEST: 37 CODE: 05 = 7/69

HEADING: O.K. GA./CAL.: 300G

BREECH OPENING: CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED:

CHAMBER: O.K. APPROVED:

TEST: NO APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

NO COMPONENT BROKEN.

CONNECTOR CLEARANCE ON TRIGGER = 1.090 M/D = 1.074 - 0.006

TRIGGER CLEARANCE ON CONNECTOR = 1.000 M/D = 1.083 - 0.010

CONNECTOR - SEAR ENGAGEMENT O.K.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACT.

COMMENTS: CAN NOT DUPLICATE CUSTOMER'S MALFUNCTION.

THE TRIGGER CONNECTOR-SEAR NIP TO MODEL DRAWING, PERMIT SEAR, CONNECTOR INTERFERENCE - FAILURE TO RETRACT.

PLAINTIFF'S
EXHIBIT

3249

AL 0029781

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: FAIR R #: 12933
 OUTSIDE WORK: SCOPE MOUNTED DATE: 6-23-71
 FIRED AMMO TYPE: _____ FROM: NAT. PARK SERV.
 & CONDITION: _____ KAHULUI, MAUI, HAWAII
 PROOF: R.E.P.-E INSP.: 11 TEST: 87 GUN #: 6258663
 HEADING: O.K. CODE: 05-7/69
 BREACH OPENING: - G.K./CAL.: 3006
 RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTS

CONNECTOR CLEARANCE ON TRIGGER 1.062 M/D = ^{1.079}_{1.072} ±.014
 TRIGGER CLEARANCE ON CONNECTOR 1.087 M/D = ^{1.033}_{1.020} ±.004
 CONNECTOR-SEAR ENGAGEMENT .025-O.K.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACT.

COMMENTS: CAN NOT DUPLICATE THE CUSTOMER'S MALFUNCTION.
THE TRIGGER CONNECTOR & TRIGGER NOT TO MODEL
DRAWING PERMIT SEAR, CONNECTOR INTERFERENCE,
FAILURE TO RETRACT.

PLAINTIFF'S
EXHIBIT

3250

1 of 1

AL 0029782

M/700 Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: MODEL: 700

GENERAL CONDITION: GOOD R #: 19055

OUTSIDE WORK: SEAL MISSING ON TRIGGER ADJ. DATE: 9-26-71

ADJUSTING SCREW. FROM: ALLEN L. WOOD

FIRED AMMO TYPE: + CLINTON, MO.

& CONDITION: GUN #: 6291404

PROOF: R.E.P.-E INSP.: D TEST: 13 CODE: RS-"/69

HEADING: O.K. GA./CAL.: 3006

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED:

CHAMBER: O.K. APPROVED:

TEST: NO APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

NO BROKEN OR DAMAGED COMPONENTS. STOCK MISSING.

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF

INCIDENT: FOLLOW DOWN

COMMENTS: ENGAGEMENT O.K., TRIGGER PULL 5 1/2 LBS. SEAL

MISSING AND ADJUSTING SCREW, FRONT, BACKED OUT 50

NO TENSION REMAINED TO RETRACT THE TRIGGER.

PLAINTIFF'S
EXHIBIT

3251

AL 0029783

Customer Complaint

NO GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 ADL

GENERAL CONDITION: USED

R #: 22448

OUTSIDE WORK: SCOPE MOUNTED

DATE: 11-8-71

FIRED AMMO TYPE: _____

FROM: THE SPORTSMAN

HARLINGEN, TEXAS

& CONDITION: _____

GUN #: 276664

PROOF: R.E.P. INSP.: 9 TEST: 87

CODE: RP. 5/67, OTS: 7/70

HEADINGS: _____

CHK./OAL: _____

BREECH OPENING: _____

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED, OR BROKEN COMPONENTS

TRIGGER BINDS ON GUARD. TRIGGER PULL $2\frac{1}{2}$ POUNDS.

COMPLAINT: "FIRES WHEN SAFETY IS PUT IN FIRE POSITION"

INCIDENT: FOLLOWS DOWN

COMMENTS: WITH THE TRIGGER PULL LIGHT ($2\frac{1}{2}$ POUNDS) AND THE TRIGGER BINDING ON THE GUARD, IT IS POSSIBLE THAT TRIGGER COMPRESSOR RETRACTION WOULD BE SUFFICIENT. THIS COULD CAUSE FOLLOW ON DOWN WHEN THE TRIGGER IS PULLED WITH THE SAFETY ON.

PLAINTIFF'S
EXHIBIT

3252

AL 0029784

1 of 1

Customer Complaint

P NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 ADLGENERAL CONDITION: NEWR #: 24698OUTSIDE WORK: NODATE: 12-14-71

FIRED AMMO TYPE: _____

FROM: BIG BEAR STEEL INC.BILLINGS, MONT.

& CONDITION: _____

GUN #: 6360196PROOF: R.E.P.-E INSP.: U TEST: 29CODE: WT: 8/70HEADING: O.K.GR./CAL.: 270 WIN.BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED, BROKEN COMPONENTS.TRIGGER PULL 7 POUNDS, SEAR-TRIGGER CONNECTORENGAGEMENT O.K. TRIGGER BINDS ON TRIGGER GUARD.COMPLAINT: FIRES WHEN SAFETY IS RELEASED.INCIDENT: FOLLOW DOWNPLAINTIFF'S
EXHIBIT

3253

COMMENTS: THE CUSTOMER'S MALFUNCTION NOT DUPLICATED.HOWEVER, AN INTERFERENCE BETWEEN THE TRIGGER AND
TRIGGER GUARD WAS NOTED WHICH LIKELY CAUSED
THE TRIGGER TO FAIL TO RETRACT INTO COCKED
POSITION.

1 of 1

F NO GUN EXAMINATION REPORT NUMBER: _____GENERAL CONDITION: GOODOUTSIDE WORK: NO

FIRED AMMO TYPE: _____

& CONDITION: _____

PROOF: R.E.A.-A INSP.: J TEST: E7HEADING: OKBREECH OPENING: -RECOIL SHOULDERS: OKCHAMBER: OKTEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

NO BROKEN OR DAMAGED COMPONENTS.TRIGGER CONNECTED 1.00 (MID-1935) TRIGGER 1.065 (MID-1935)CONNECTED - SEAR ENGAGEMENT 0.30 MID 1915, TRIGGERPULL: 4 TO 4 1/2 LBS. LUBRICANT USED APPLIED TO 35 TUBHEAVY.COMPLAINT: WHEN PUSHING SAFETY OFF THE GUN FIRES OFF.INCIDENT: FALLING DOWN.Carat ComplaintMODEL: 700 AGLR # : 23155DATE: 11-18-71FROM: BIGGS SGT. GUN.PENSACOLA, FLA.GUN # : 6344022CODE: KT-5/10GA./CAL.: 22-250CHECKED BY: G.F. GUN.

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

PLAINTIFF'S
EXHIBIT

3254

COMMENTS: WITH THE EXCESSIVE GREASE BETWEEN THETRIGGER AND SEAR AND THE TRIGGER WAS PUSHED UPTHE TRIGGER CONNECTED TO SEAR AND FIRED UPIT FIRED IN THE EAR, FAILING TO RETRACTIN THE EAR AND FIRED IN THE EAR AND FIRED IN THEREAR. THE FINGER WAS PUSHED TO THE EAR AND

10 of 1

R 342-1 Rev. 2-15-61

F.I. NO GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 ADL

GENERAL CONDITION: GOOD

R #: 27191

OUTSIDE WORK: SCOPE MOUNTED

DATE: 12-27-71

FIRE AMMO TYPE: _____

FROM: PESCO SPT GOS.

& CONDITION: _____

PESCO, TEXAS

PROOF: PESCO INSP.: 72 TEST: 27

GUN #: 6323773

CODE: RT = 11/7-

HEADING: OK

GA./CAL.: 250650W

BREECH OPENING: -

CHECKED BY: C. P. [unclear]

RECOIL SHOULDERS: OK

APPROVED: _____

CHAMBER: OK

APPROVED: _____

TEST: 1/0

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SEARCH COMPARTMENT ENGAGEMENT 1030. TRIGGER PULL 14
POUNDS. STOCK ETC. NOT INCLUDED. MARK ON TRIGGER
SIDE INDICATES POSSIBLE BUD ON TRIGGER GUARD.
NO STOCK, MAGAZINE OR MAGAZINE FEEDER OR
SPRING.

COMPLAINT: DISCHARGED WHEN SAFETY WAS MOVED FROM SAFE
TO FIRE POSITION.

INCIDENT: FOLLOW DOWN.

**PLAINTIFF'S
EXHIBIT**

3255

COMMENTS: THE CUSTOMER'S MALFUNCTION WAS NOT DUPLICATED
HOWEVER IT MAY HAVE BEEN CAUSED BY TRIGGER PULL
IN THE TRIGGER GUARD.

1 of 1

AL 0029787

F. 110 GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL

GENERAL CONDITION: NEW R # : 002686

OUTSIDE WORK: N/O DATE: 2-1-72

FROM: Dunn's Shooter

FIRE AMMO TYPE: _____ ADDITION: N/A

& CONDITION: _____ GUN # : 6310545

PROOF: P.P.F. - N INSP.: 71 TEST: 49 CODE: LT = 2/70

HEADING: O.K. GA./CAL.: 300% S

BREECH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: O.K. APPROVED: _____

TEST: N/O APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER PULL 4 LBS., ENGAGEMENT 0.12 (MIN. 0.020)

MARKS TO BE MADE ON SIDE OF TRIGGER PULL
ON TOP SIDE EDGES (RUE MARKS LOWER RIGHT SIDE)

COMPLAINT: RIFLE DISCHARGED BY ITSELF TWO OF SIX TIMES
FIRE.

INCIDENT: FOLLOW DOWN.

COMMENTS: MARKS ON THE TRIGGER INDICATE FRICTION, THE
COMBINATION OF FRICTION, HEAVY LUBRICATION AND UNDER
MIN. ENGAGEMENT PROBABLY PREVENTED TRIGGER
CONNECTOR RETRACTION CAUSING FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3256

AL 0029788

1 of 1

F No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDLGENERAL CONDITION: NEW R #: 002678OUTSIDE WORK: No DATE: 2-2-72FIRED AMMO TYPE: _____ FROM: BILL DOTSON'S INC.& CONDITION: _____ DECATUR, ILL.PROOF: R.E.P.-A INSP.: 9 TEST: 13 GUN #: 6294075HEADING: O.K. CODE: X5-12/69BREACH OPENING: - GA./CAL.: 270 WIN.RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSERCHAMBER: O.K. APPROVED: _____TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER PULL 6 LBS., ENGAGEMENT 0.20. TRIGGER
BIND IS NOTICEABLE. IN DIS-ASSEMBLING THE TRIGGER
HAS WHAT APPEARS TO BE DRIED STEEL GUARD ON
THE SIDES CAUSING IT TO BIND.

COMPLAINT: "WHEN BOLT IS PUT IN ALL THE WAY THE GUN WILL
GO OFF"

INCIDENT: FOLLOW DOWN

COMMENTS: THE SLUGGISH TRIGGER PROBABLY FAILED TO
RETRACT RESULTING IN A FOLLOW DOWN MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3257

1 of 1
AL 0029789

P 1/2 GUN EXAMINATION REPORT NUMBER: _____ MODEL: 6801GENERAL CONDITION: GOOD R # : 0010-3OUTSIDE WORK: SCOTT MOUNTED DATE: 1-31-72FIRED AMMO TYPE: _____ FROM: ROUNDS B222 LK.& CONDITION: _____ GUN # : 127052PROOF: R.F.P. INSP.: U TEST: 13 CODE: ER= 10/62LOADING: _____ GK./CAL.: 6.5MMBREACH OPENING: _____ CHECKED BY: C. FOSTERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

RUST AROUND TRIGGER AND BETWEEN BOLT &
FIRING PIN & BOLT ASSEMBLY. TRIGGER FULL 3/4"
(SPEC. 4 TO 6) ENGAGEMENT .010 (SPEC. .020 MIN.)

COMPLAINT: FIRED THREE WHEN SAFETY WAS PUT IN OFF POSITIONINCIDENT: FOLLOW DOWNPLAINTIFF'S
EXHIBIT

3259

COMMENTS: AS RECEIVED, RUST IN FIRING PIN ASSEMBLY MADE IT

DIFFICULT TO CLOSE AND LOCK BOLT. FIRING PIN
WOULD NOT FALL. IT IS PROBABLE THAT THE RUST
AROUND THE TRIGGER CONNECTOR WHEN UNDER MINIMUM
USE & UNDER MAINTENANCE RUL. CAUSED THE TRIGGER
CONNECTOR TO FAIL TO EXTRACT WHEN PULLED IN
THE SAFETY OFF POSITION. THE SAFETY RELEASED
THE FIRE & BOLT TO FALL.

GUN EXAMINATION REPORT NUMBER: MODEL: 700 BDLGENERAL CONDITION: NEW (SOME RUST) R #: 001869OUTSIDE WORK: NO DATE: 1-28-72FIRED AMMO TYPE: FROM: MAC & RD, SHTG. CO.& CONDITION: GUN #: 6290291PROOP: R.E.P.-F INST.: 9 TEST: 55 CODE: RS=11/69HEADING: O.K. GRA./CAL.: 3006 SEC.BREACH OPENING: - CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: CHAMBER: O.K. APPROVED: TEST: NO APPROVED: COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

NO BROKEN COMPONENTS. EXTRACTOR PISTON, BOLT
BODY ALSO. SUBSTANCE RESEMBLING DIED SCUM
ON TRIGGER & SEAR. TRIGGER PULL 2 1/2 LBS. ENGAGE-
MENT .010. LUMP ON BOLT

COMPLAINT: "FIRST SHELL HE TRIED TO CHARGE DISCHARGED"INCIDENT: FOLLOW DOWNPLAINTIFF'S
EXHIBIT

3260

COMMENTS: THE MATERIAL ON THE SEAR & TRIGGER CAUSED
THE TRIGGER TO STICK IN FIRED POSITION, WHEN THE
ACTION WAS CLOSED THE FIRING PIN FOLLOWED DOWN
FIRING THE ROUND

1 of 1

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 002023
 OUTSIDE WORK: NO DATE: 1-27-72
 FIRED AMMO TYPE: _____ FROM: BAY CITY HDQ. CO.
 & CONDITION: _____ BAY CITY, MICH.
 GUN #: 6500965
 PROOF: R.E.P.-M INSP.: _____ TEST: 13 CODE: NONE
 HEADING: O.K. GA./CAL.: 243 WIN.
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

MILINE STOCK, TRIGGER PULL 4 1/2 LBS. - O.K. ENGAGEMENT
.008 (.020 MIN.) NEW RIVETED HOUSING CONNECTOR
1.093 M/D = 1.080 TRIGGER 1.076 M/D = 1.076 BURS ON
CONNECTOR SIDES.

PLAINTIFF'S
EXHIBIT

3261

COMPLAINT: "FIRES ON SAFE"

INCIDENT: MAY HAVE FOLLOWED DOWN WHEN SAFE WAS
RELEASED.

COMMENTS: ENGAGEMENT IS SET TOO CLOSE, WITH THE
BURS ON THE CONNECTOR AND CLOSE ENGAGEMENT,
IT IS POSSIBLE THAT THE CONNECTOR FAILED TO
RETRACT WHILE THE SAFETY WAS ON THEN FOLLOW
DOWN OCCURRED WHEN THE SAFETY WAS RELEASED.

1 of 1

Customer Complaint

P No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADLGENERAL CONDITION: NEW R #: 001648OUTSIDE WORK: SCOPE MOUNTED, SWIVELS DATE: 1-26-72RECOIL PAD FITTED.FROM: DUNN'S F&B, GDS, INC.

FIRED AMMO TYPE: _____

PEVELY, MISSOURI

& CONDITION: _____

GUN #: 332321PROOF: R.E.P. INSP.: D TEST: 49CODE: BL = 1/64HEADING: O.K.GA./CAL.: 3006BREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED, BROKEN COMPONENTS. SEAR-CONNECTORENGAGEMENT .010 (MIN. .020) TRIGGER FULL = 3 1/2 (MIN. = 3 1/2)TRIGGER CLEARANCE ON CONNECTOR 1.087 M/D = 1.080CONNECTOR CLEARANCE ON TRIGGER 1.073 M/D = 1.074(.014 CLEARANCE WHERE .007 IS MAX.)COMPLAINT: FIRES WHEN SAFE IS RELEASEDINCIDENT: CONNECTOR FAILS TO RETRACT.PLAINTIFF'S
EXHIBIT

3262

COMMENTS: THE EXCESSIVE CLEARANCE BETWEEN CONNECTOR
AND TRIGGER ALLOWS THE CONNECTOR TO CREEP UP INTO
AN INTERFERENCE POSITION WHERE IT FAILS TO RETRACT
WITH THE SAFETY ON, WHEN THE SAFETY IS
RELEASED THE FIRING PIN FOLLOWS DOWN.

1 of 1

P... NO GUN EXAMINATION REPORT NUMBER: _____GENERAL CONDITION: GOODOUTSIDE WORK: NO

FIRED AMMO TYPE: _____

& CONDITION: _____

PROOP: R.E.P.

INSP.: _____

TEST: 79HEADING: O.K.BREECH OPENING: -RECOIL SHOULDERS: O.K.CHAMBER: O.K.TEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDLR # : 000999DATE: 1-12-72FROM: CADDIE LABAR'S

DISTR. CO.

DALLAS, PENN.GUN # : 232943CODE: WN = 8/66GA./CAL.: 280 REM.CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

NO DAMAGED OR BROKEN COMPONENTS. TRIGGER PULL FOUR
POUNDS, ENGAGEMENT .015, TRIGGER BINDING ON GUARD
SLIGHTLY. GREASE-DIRT COATING ON HIDDEN PARTS
INCLUDING INSIDE & OUTSIDE OF TRIGGER ASSEMBLY.

COMPLAINT: SOMETIMES IT WILL FIRE, OTHER TIMES IT WON'T, SOMETIMES
IT WILL BE A DELAYED FIRING.

INCIDENT: SEAR DOES NOT RELEASE FIRING PIN.

**PLAINTIFF'S
EXHIBIT**

3263

COMMENTS: THE CUSTOMER'S MALFUNCTION WAS DUPLICATED WITH
STOCK IN PLACE BUT WORKED O.K. WITH S-S&S OFF.
APPARENTLY THE TRIGGER-THROTTLE GUARD BIND
COMBINED WITH THE TOO HEAVY LUBRICATION WAS
THE CAUSE OF HIS TROUBLE.

P. NO GUN EXAMINATION REPORT NUMBER: _____GENERAL CONDITION: NEWOUTSIDE WORK: SCOPE MOUNTED, REGULARSIGHTS REMOVED.FIRED AMMO TYPE: R.P.& CONDITION: ONE PERCED PRIMERPROOF: R.E.P.-B INSP.: 71 TEST: 49HEADING: O.K.BRESCH OPENING: -RECOIL SHOULDERS: O.K.CHAMBER: O.K.TEST: TEP ROUNDS OF 120 GR. 44S PERCED PRIMERS.

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 ADL.R # : 26180DATE: 12-21-71FROM: H.A.H. S&A, GDS, INC.AMARILLO, TEXAS.GUN # : 6332550CODE: CT-4/70GA./CAL.: 25-06 TCHECKED BY: C. PROBER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

FIRING PIN POINT TOO FLAT. TRIGGER CONNECTORDAMAGED. SEAR-TRIGGER CONNECTOR ENGAGEMENT
.005COMPLAINT: RIFLE WILL NOT COCK.INCIDENT: FOLLOWS DOWN.PLAINTIFF'S
EXHIBIT

3264

COMMENTS: THE .010 UNDER MIN. ENGAGEMENT COMPLAINED WITH
BACKLASH FROM PERCED PRIMERS FORCE DOWN
THE CORNER OF THE TRIGGER CONNECTOR RESULTING
IN THE FOLLOW DOWN MALFUNCTION.

1 of 1

GUN EXAMINATION REPORT NUMBER: _____

MODEL: 400 RDLGENERAL CONDITION: NEWR # : 24301OUTSIDE WORK: NODATE: 12-13-71FIRED AMMO TYPE: -FROM: JENSEN BYRD CO.SPokane, WASH.

& CONDITION: _____

GUN # : 6411367PROOF: R.I.P.-1

INSP.: _____

55TEST: 49CODE: AU-3/71HEADING: O.K.GA./CAL.: 300GBREECH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED BROKEN COMPONENTS. TRIGGER FULL SENS-
ITRIGGER CONNECTOR ENGAGEMENT AND SENS-FRAME PIN
HEAD ENGAGEMENT WITHIN SPECIFICATIONS. TRIGGER CLEAR
TRIGGER GUARD.

COMPLAINT: FIRES WHEN BOLT IS CLOSEDINCIDENT: FOLLOW DOWNPLAINTIFF'S
EXHIBIT

3265

COMMENTS: THE CUSTOMER'S MALFUNCTION CANNOT BE DUPLICAT-
ED. SOME FOREIGN MATERIAL IS NOTED ON THE TRIGGER
CONNECTOR WHICH MAY HAVE CAUSED IT TO STICK IN
FIRED POSITION, RESULTING IN A FOLLOW DOWN.

RD-542-1 Rev. 2-15-61

Custom Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: Good R #: 25226
OUTSIDE WORK: No DATE: 12-8-71
FIRED AMMO TYPE: _____ FROM: QUEEN CITY DIST. CO.
& CONDITION: _____ ALBUQUERQUE, NM.
PROOF: REP-M INSP.: 9 TEST: 87 GUN #: 6448107
HEADING: O.K. CODE: PU- 6/71
BREECH OPENING: - G&C/CAL.: 3006 S&C.
RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSER
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CORNER OF TRIGGER CONNECTOR DAMAGED. CONNECTOR-SEAR ENGAGEMENT .005.

COMPLAINT: "FIRES UPON CLOSING ACTION"

INCIDENT: FOLLOWS DOWN.

PLAINTIFF'S
EXHIBIT

3266

COMMENTS: TRIGGER CONNECTOR-SEAR ENGAGEMENT SET TOO CLOSE. THE CONNECTOR CORNER BROKE DOWN SO THAT IT BECAME IMPOSSIBLE FOR THE ACTION TO STAY COCKED.

1 of 1

AL 0029798

1-87/10-1 Nov. 2-15-61

Customer Complaint

GUN EXAMINATION REPORT NUMBER: _____ MODEL: 750 S-TL

GENERAL CONDITION: NEW R # : 229700

OUTSIDE WORK: ✓ DATE: 12-9-71

FIRE ARM TYPE: _____ FROM: SAFETY, 1000, 1000

& CONDITION: _____ GUN # : 6810000

PROOF: 1000-5 INSP.: 0 TEST: SM CODE: PT-1/10

HEADING: OK GA./CAL.: 3000

BREACH OPENING: 1 CHECKED BY: 2-10000

RECOIL SHOULDERS: OK APPROVED: _____

CHAMBER: OK APPROVED: _____

TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGE-BROKEN COMPONENTS.

TRIGGER CONNECTOR CLEARANCE 1.092 (1.075) - 1.075

CLEARANCE 1.092 (1.075) - 1.075; ENGAGEMENT, 0.000

TRIGGER PULL OK. SLIGHT COILER BEHIND

SEAR & TRIGGER CONNECTOR CONTACT

COMPLAINT: FIRE WHEN SAFE IS RELEASED.

INCIDENT: FOLLOWS DOWN

COMMENTS: CUSTOMER'S MALFUNCTION NOT CONFIRMED. IT IS

POSSIBLE WITH COMPONENTS SUBSTITUTED. THE

TRIGGER CONNECTOR TO WIDE UP ON THE TRIGGER (CLEAR-

ANCE, 0.070 OVER MAX). ALSO TRIGGER MAY HAVE BEEN

STUCK DUE TO BIND IN THE TRIGGER GUARD CAUSED BY

OUT OF POSITION SCREW HOLES IN THE GUARD.

1 of 1

PLAINTIFF'S
EXHIBIT
3267

GUN EXAMINATION REPORT NUMBER: 700 MODEL: 700
 GENERAL CONDITION: NEW R #: 24195
 OUTSIDE WORK: SEAR ANGLE ON FIRING PIN DATE: 11-30-71
HEAD MAY HAVE BEEN COLORED BY HEAT FROM: BOES GUN SHOP
 FIRED AMMO TYPE: LANING, MICH.
 & CONDITION: ASSEMBLER 30 GUN #: 6361958
 PROOF: R.E.P.-E INSP.: 9 TEST: 29 CODE: W.T. = 8/70
 HEADING: O.K. GA./CAL.: 7MM REM. MAG.
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: No APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED, OR BROKEN COMPONENTS. SOME FRICTION
MARKS ON TRIGGER AND INSIDE HOUSING. CONNECTOR-
SEAR ENGAGEMENT .005 MIN. F.O.I.S. TRIGGER PULL:
FOUR POUNDS.

COMPLAINT: "GUN DISCHARGES WHEN BOLT IS BEING OPENED"

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT

3268

COMMENTS: CUSTOMER'S MALFUNCTION NOT DUPLICATED.

IT IS POSSIBLE THAT A SLIGHT TRIGGER PINN CAUSED
FAILURE TO RETRACT, REDUCING THE CONNECTOR-SEAR
ENGAGEMENT SO THAT A MOVEMENT OF THE BOLT
HANDLE RELEASED THE FIRING PIN TO FIRE THE
ROUND IN THE CHAMBER.

1 of 1

P. 119 GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL

GENERAL CONDITION: Good R# : 22615OUTSIDE WORK: NO DATE: 11-8-71PIRED AMMO TYPE: _____ FROM: BOWLING, INC.WHITE SULPHUR SPRINGS,
WEST VIRGINIA, E.A CONDITION: _____ GUN # : 6320472PROOF: R.E.P.E INSP.: 75 TEST: 27 CODE: ATC 3/10, HTB: 8/10LOADING: _____ CAL/DAL: 300.00.100BREECH OPENING: _____ CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED OR BROKEN COMPONENTSCOMPLAINT: "COULD GET IT - WOULD NOT - THE TRIGGER"INCIDENT: FELL OFF DOWN (VERIFIED BY WITNESS)**PLAINTIFF'S
EXHIBIT**
3269COMMENTS: TRIGGER FULL 22 REMINGTON-UMC .38 S&WWENT OFF (MAYBE 1015) NO INDICATION OF GUN PARTS
ALLOTTING.APPROXIMATELY 1/2 INCHES OF GEAR AND CONSOLEWENT OFF IN CONJUNCTION WITH THE LIGHT TRIGGER FULLSTAYED THE AT - 2000.

1 of 1

Customer Complaint

P.I. NA GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 15003
OUTSIDE WORK: TRIGGER PULL REDUCED TO DATE: 7-30-71
ONE POUND. FROM: UNITED DIST.
FIRED AMMO TYPE: _____ GALVESTON, TEXAS
& CONDITION: _____ GUN #: 6408400
PROOF: R.E.P. INSP.: 74 TEST: 98 CODE: LO = 2/71
HEADING: O.K. EX./CAL.: 270 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: No APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

ADJUSTING SCREW FOR TRIGGER PULL UNSEALED
AND ADJUSTMENT ALTERED.

COMPLAINT: FIRING PIN ENGAGES & FIRES WHEN BOLT IS
PUSHED FORWARD.

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT
3270

COMMENTS: WHEN TRIGGER PULL WAS CORRECTED ENGAGE-
MENT OF SEAR AND TRIGGER CONNECTOR WAS .025-
MIN. IS .015 WITH TRIGGER PULL REDUCED THE
SPRING WILL NOT RETRACT THE TRIGGER CONNECTOR
CORRECTLY AND FOLLOW DOWN MAY RESULT.

1 of 1

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

GENERAL CONDITION: NEW

OUTSIDE WORK: NO

FIRE AMMO TYPE: +

& CONDITION: +

PROOF: R.E.P.-C INSP.: 9 TEST: 49

HEADING: O.K.

BRECH OPENING: -

RECOIL SHOULDERS: O.K.

CHAMBER: O.K.

TEST: 40 ROUNDS REMINGTON

COMPONENT CONDITION: (Damaged, Broken, Old Style)

MODEL: 700 BDL VAR.

R #: 12943

DATE: 6-29-71

FROM: H.P. Cox

MEER HIGH SCHOOL
ARLEY, ALABAMA

GUN #: 6408250

CODE: LU 2/71

GR./CAL.: 223

CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

SEAR AND TRIGGER CONNECTOR CORNER BROKEN OFF,
ENGAGEMENT P.015 (.005 UNDER MIN.) FIRING PIN P.015 -
RADIUS TOO LARGE.

COMPLAINT: FIRE ON CLOSING, FIRE WHEN SAFE WAS PUSHED
OFF, PIERCED PRIMERS.

INCIDENT: FOLLOWED DOWN.

COMMENTS: THE PRIMER PIERCING WAS NOT DUPLICATED IN TEST.
ING. IT MAY HAVE SPEEDED UP THE CONNECTOR - SEAR
BREAK-DOWN

PLAINTIFF'S
EXHIBIT

3271

1 of 1

P. No GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: NEWR # : 13298OUTSIDE WORK: NoDATE: 6-29-71FROM: J.C. PENNEYFIRED AMMO TYPE: TKING OF PRUSSIA, PA.

& CONDITION: _____

GUN # : 6274124PROOP: R.E.P.-EINSP: 58TEST: 13CODE: DS-9/69HEADING: O.K.GA./CAL.: 270

BRESCCH OPENING: _____

CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: No

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

No Broken or Damaged Components.TRIGGER CONNECTED - SEAR ENGAGEMENT .012 (.020 - MIN.)TRIGGER DULL 4 1/2 LBS. - A SMALL METAL CRIP - CAUSE -
BETWEEN TRIGGER CONNECTOR & STRIKER.COMPLAINT: "FIRES DURING SHELL EXTRACTION"INCIDENT: FOLLOWING DOWNPLAINTIFF'S
EXHIBIT

3272

COMMENTS: THE CUSTOMER'S MALFUNCTION COULD NOT BEDIAGNOSED. THE UNDER MAIN ENGAGEMENT WAS CAUSED
BY THE METAL CRIP (HELD IN PLACE BY A PROTECTIVE
CORATING APPLIED BY THE CUSTOMER) PROBABLY CAUSE
E MALFUNCTION.

1 of 1

Cust. Complaint ✓1... No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700GENERAL CONDITION: FAIR R #: 11955OUTSIDE WORK: SCOPE MOUNTED DATE: 6-3-71FROM: NATIONAL PARK SERVICEFIRED AMMO TYPE: - KANULUI MAIL, HAWAII& CONDITION: _____ GUN #: 6258362PROOF: R.E.P.-E INSP.: 11 TEST: 27 CODE: 05 = 7/69HEADING: O.K. GA./CAL.: 3006BRECH OPENING: - CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

10 BROKEN, ETC. COMPONENTS.CONNECTOR CLEARANCE ON TRIGGER = 1.070 MID = 1.079 - .006TRIGGER CLEARANCE ON CONNECTOR = 1.089 MID = 1.083 + .006CONNECTOR-SEAR ENGAGEMENT = .020 EXCESSIVELUBRICANT OIL DIRTY, TRIGGER PULL FOUR POUNDS.COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.INCIDENT: TRIGGER CONNECTOR FAILED TO RETRACT.COMMENTS: CAN NOT DUPLICATE CUSTOMER'S MALFUNCTION.THE TRIGGER & TRIGGER CONNECTOR NOT TO MODELDRAWING PERMIT SEAR-TRIGGER CONNECTOR INTERFERENCEFAILURE TO RETRACT.PLAINTIFF'S
EXHIBIT

3273

1 of 1

AL 0029805

P NO GUN EXAMINATION REPORT NUMBER: _____MODEL: 700 BDLGENERAL CONDITION: GOODR # : 10002OUTSIDE WORK: TRIGGER PULL WEIGHT AND STOPDATE: 4-28-71SCREWS RE-ADJUSTED, SCOPE MOUNTED.FROM: MAX MERHELSTEIN DIST. CO.

FIRED AMMO TYPE: _____

CARBONDALE, PENNA.

& CONDITION: _____

GUN # : 6333602PROOF: R.E.P. - G INSP. INCOMPLETE TEST: 55CODE: CT-4/70HEADING: MAX.GA./CAL.: 25-06BREACH OPENING: -CHECKED BY: C. PROSSERRECOIL SHOULDERS: EXCESSIVE RADIUS REAR CORNER.

APPROVED: _____

CHAMBER: _____

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

NO DAMAGED, BROKEN COMPONENTS.PLAINTIFF'S
EXHIBIT

3274

COMPLAINT: "BOLT LOCKS SHUT, GUN HAS FIRED WITH SAFETY ON""FACTORY BULLETS SEAT IN RIFLING."

INCIDENT: _____

COMMENTS: CAN NOT DUPLICATE CUSTOMER'S "FIRED WITH SAFETY ON."SEAR-CONNECTOR ENGAGEMENT, 020 - SPECIFICATIONS MIN. 020.

THERE IS EVIDENCE OF CUSTOMER'S RE-ADJUSTING OF TRIGGER
STOP & PULL WEIGHT SCREWS. DECREASING TRIGGER PULL
WENT BUT REDUCES SEAR-CONNECTOR ENGAGEMENT MAKING
A FOLLOW UP DOWN LIKELY.

P Ma GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL

GENERAL CONDITION: Good R# : 07215

OUTSIDE WORK: SCOPE MOUNTED DATE: 4-23-71

FIRED AMMO TYPE: - ORD. NEBRASKA

CONDITION: _____ GUN #: 6320412

PROOF: R.E.P.B INSP.: 9 TEST: 49 CODE: AT-3/70

HEADING: O.K. GA./CAL.: 270

BREACH OPENING: - CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O. K. APPROVED: _____

CHAMBER: O.K. [] [] [] APPROVED: _____

TEST: TEN ROUNDS APPROVED:

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN OR DAMAGED COMPONENTS. SLIGHT BURR

ROUND EJECTOR HOLE.

COMPLAINT: LOADING SHELL INTO BARREL IT WENT OFF ALSO

UNABLE TO EXTRACT SHELL.

INCIDENT:	EXHIBIT
-----------	---------

COMMENTS: UNABLE TO DUPLICATE FIRES ON CLOSING. IN TEST

EJECTOR STUCK BACK CAUSING FAILURE TO EJECT.

EJECTOR WAS FREED UP AND BURR REMOVED AFTER

WHICH RIFLE FUNCTIONED O.K.

**PLAINTIFF'S
EXHIBIT**

3275

P. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: Good R #: 07367
 OUTSIDE WORK: No DATE: 4-26-71
 FROM: MONTGOMERY WARD
 FIRED AMMO TYPE: _____
 & CONDITION: _____ GUN #: 6204725
 PROOF: REP. INSP.: 9 TEST: 41 CODE: XR = 12/68
 HEADING: O.K. GR./CAL.: 270 WIN.
 BREACH OPENING: _____ CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: No. APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED OR BROKEN COMPONENTS.

COMPLAINT: "FIRED WHEN BOLT WAS CLOSED."

INCIDENT: _____

PLAINTIFF'S
EXHIBIT

3276

COMMENTS: COULD NOT DUPLICATE CUSTOMER'S MALFUNCTION.
HOWEVER, TRIGGER-CONNECTOR CLEARANCE BEING EXCESS-
IVE & TOO HEAVY LUBRICANT MAY HAVE CONTRIBUTED TO
SUCH A FAILURE IN COLD TEMPERATURES.

CONNECTOR .006 OVERSIZE (1.089)

TRIGGER .009 UNDERSIZE (1.067)

REPLACED TRIGGER & CONNECTOR ENGAGEMENT O.K.

1 of 1

P. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700GENERAL CONDITION: GOOD R #: 09523OUTSIDE WORK: REPAIRED LOCALLY ONE TIME DATE: 4-22-71FIRED AMMO TYPE: _____ FROM: TEMPE ARIZONA

& CONDITION: _____ POLICE DEPT. _____

PROOF: R.E.P. INSP.: POOR STAMP TEST: 49 GUN #: 386831HEADING: O.K. CODE: RS-11/69BREECH OPENING: - GA./CAL.: 223 REM.RECOIL SHOULDERS: O.K. CHECKED BY: C. PROSSERCHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKENCOMPLAINT: FIRES CLOSING

INCIDENT: _____

PLAINTIFF'S
EXHIBIT3277

COMMENTS: THE BROKEN TRIGGER CONNECTOR FAILS TO RETRACT
UNDER THE SEAR SO WHEN THE SAFETY IS PUSHED OFF,
FIRING PIN FALLS AND FIRES ROUND.

No GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 ADL

GENERAL CONDITION: NEW

R #: 07070

OUTSIDE WORK: TRIGGER ENGAGEMENT SCREW

DATE: 4-23-71

SEAL REMOVED.

FROM: LLOYD CO.

FIRED AMMO TYPE: -

LITTLE ROCK, ARK.

& CONDITION:

GUN #: 6266361

PROOF: R.I.P.-E INSP.: 73 TEST: 87

CODE: WS = 8/69

HEADING: O.K.

GA./CAL.: 22-250

BREACH OPENING: -

CHECKED BY: C. PROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

TRIGGER CONNECTOR BROKEN. TRIGGER SPRING MISSING.

TRIGGER ENGAGEMENT SCREW OUT OF ADJUSTMENT.

COMPLAINT: "LEVER IN TRIGGER HOUSING BROKEN"

INCIDENT: -

COMMENTS: APPARENTLY A DEFECTIVE TRIGGER CONNECTOR WAS USED.

PLAINTIFF'S
EXHIBIT

3278

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 06681
 OUTSIDE WORK: NO DATE: 3-15-71
 FIRED AMMO TYPE: _____ FROM: KENNETH JOHNSON
 & CONDITION: _____ STURTEVANT, WISC.
 PROOF: R.E.P. B INSP: 73 TEST: 87 GUN #: 6312955
 HEADING: O.K. CODE: L.T. = 2/70
 BREECH OPENING: _____ GA./CAL.: 7MM
 RECOIL SHOULDERS: EXCESSIVE RADIUS AT REAR CHECKED BY: C. PROSSER
 CHAMBER: O.K. BODY. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: CLOSES HARD OVER SHELL. FIRED WHILE TRYING TO
CLOSE.

INCIDENT: CLOSE HARD

PLAINTIFF'S
EXHIBIT

3279

COMMENTS: THE EXCESSIVE RADIUS AT REAR OF RECOIL SHOULDER
CAUSES THE BOLT TO CAM HARD WITH A ROUND IN THE
CHAMBER. THERE APPEARS TO BE NOTHING WRONG WITH
THE TRIGGER ASSEMBLY. THE CUSTOMER LIKELY, (NADVERT-
ENTLY TOUCHED THE TRIGGER WHILE TRYING TO FORCE
THE BOLT HANDLE DOWN.

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: GOOD R #: 04 04
 OUTSIDE WORK: NO DATE: 3-1-71
 FIRED AMMO TYPE: — FROM: GLOBE #10
 & CONDITION: _____ TUCSON, ARIZONA
 GUN #: 6319824
 PROOF: R.E.P.-E INSP.: 58 TEST: NO STAMP CODE: AT-3/70
 HEADING: O.K. GA./CAL.: 270 WIN.
 BREECH OPENING: — CHECKED BY: C. R. Rauer
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO COMPONENT DAMAGED OR BROKEN. TRIGGER-CONNECTOR
SEAR ENGAGEMENT 0.005 (MIN. IS 0.015)

COMPLAINT: FIRES ON CLOSING BOLT

INCIDENT: FOLLOW DOWN

COMMENTS: THE TRIGGER CONNECTOR-SEAR ENGAGEMENT IS
NOT ENOUGH FOR PROPER SUPPORT, ALLOWS THE
FIRING PIN TO FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3280

AL 0029812

1 of 1

P.I. ND GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: Good R #: 03978
 OUTSIDE WORK: NO DATE: 3-1-71
 FROM: ERBACHERS SPORTS CENTER
 FIRED AMMO TYPE: - MARLSON, OHIO.
 & CONDITION: _____ GUN #: 278328
 PROOF: R.E.P. INSP.: D TEST: 87 CODE: CP-4/37
 HEADING: O.K. GA./CAL.: 7MM MAG.
 BREECH OPENING: - CHECKED BY: C.P.
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO COMPONENT DAMAGE OR BREAKAGE.

COMPLAINT: "FIRED TWOTIMES WHEN CLOSING BOLT."

INCIDENT: FOLLOW DOWN

PLAINTIFF'S
EXHIBIT

3281

COMMENTS: TRIGGER CONNECTOR-SEAR ENGAGEMENT .025. THE
TRIGGER ETC. WAS FOUND TO BE COATED WITH A HEAVY-
GREASE-LIKE LUBRICANT WHICH WOULD CAUSE TRIGGER
RETRACTION TO BE ERRATIC. THIS APPARENTLY HAPPENED
TO THE CUSTOMER - TRIGGER DID NOT RETRACT AND
WHEN THE BOLT WAS CLOSED THE FIRING PIN
FOLLOWED DOWN.

1 of 1

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDLGENERAL CONDITION: GOOD R #: 01780OUTSIDE WORK: SCOPS MOUNTED, REAR SIGHT DATE: 1-26-71LEAF REMOVED. FROM: GREEN BROOK, N.J.FIRED AMMO TYPE: _____ GREEN BROOK, N.J.& CONDITION: _____ GUN #: 6362025PROOF: R.E.P.-E INSP.: 74 TEST: 87 CODE: WT = 8/70HEADING: O.K. GUN/CAL.: 7MM MAG.BREACH OPENING: _____ CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPONENTS O.K.COMPLAINT: "UPON RELEASING THE SAFETY MAY FIRE"INCIDENT: FELL-W DOWNPLAINTIFF'S
EXHIBIT

3282

COMMENTS: THE MALFUNCTION CAN NOT BE DUPLICATED.

HOWEVER, THE SEAR-CONNECTOR ENGAGEMENT IS NOT
TO SPECIFICATION (.008 SHOULD BE .015 MIN.) THIS COUPLED
WITH ANY TRIGGER BIND, SUCH AS TOO HEAVY LUBRICANT,
MIGHT CAUSE A MALFUNCTION. ENGAGEMENT
CORRECTED.

1 of 1

AL 0029814

1. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: NEW R #: 29996
 OUTSIDE WORK: FRONT TRIGGER ADJUSTING DATE: 1-4-71
SEAR WITH RE-ADJUSTED. FROM: LEFAYETTE SKI S.
 FIRED AMMO TYPE: - WINCHESTER 12 GA.
 & CONDITION: ASSEMBLY IS GUN #: 6339151
 PROCP: RE-ONE INSR: 0 TEST: 98 CODE: DT-9170
 HEADING: O.K. SK/OIL: 3006
 BREECH OPENING: - CHECKED BY: C. PROVER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: N.O. APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO DAMAGED OR BROKEN PARTS.

COMPLAINT: "SEVERAL TIMES GUN WENT OFF WHEN CLOSING BOLT."

INCIDENT: FOLLOWS DOWN

COMMENTS: SEAR-TRIGGER CONNECTOR ENGAGEMENT .005,
MINIMUM IS .015. THIS LETS THE SEAR SLIP OFF THE
CONNECTOR UNDER PRESSURE AND FELL ON DOWN
RESULTS.

PLAINTIFF'S
EXHIBIT

3283

1 of 1

Customer Complaint

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: USED-GOOD R #: 00931
 OUTSIDE WORK: SCOPE MOUNTED DATE: 1-12-71
 FROM: JOHN M. ANGELO
 FIRED AMMO TYPE: - LANSING, MICH.
 & CONDITION: ASSEMBLER C GUN #: 247248
 PROOP: R.E.P. INSP.: B TEST: 87 CODE: EN-10/66
 HEADING: O.K. GA./CAL.: 3006.5PR.
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
NO BROKEN COMPONENTS.

COMPLAINT: FIRED AS BOLT WAS PULLED HALF WAY UP.INCIDENT: APPARENTLY TRIGGER FAILED TO RETRACT.PLAINTIFF'S
EXHIBIT

3284

COMMENTS: TRIGGER-CONNECTOR-SEAR ENGAGEMENT .020.
NO INTERFERENCE INDICATED AND MALFUNCTION NOT
DUPLICATED. SOME EVIDENCE OF TOO HEAVY A
LUBRICANT BEING USED. SUGGEST CLEANING AND
INFORMING CUSTOMER HE SHOULD USE VERY LIGHT
OR NO LUBRICANT.

REMINGTON ARMS COMPANY, INC.

INTERDEPARTMENTAL CORRESPONDENCE

Remington

PETERS

CC: J. E. Dickey - Bdpt.
F. E. Morgan - "
A. D. Kerr

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

Ilion, New York
December 10, 1969

D. LEE BRAUN

CORRESPONDENCE REGARDING MODEL 700
TO HUGH WILSON, NOVEMBER 3, 1969

Pete Morgan has asked us to comment on a series of letters dating back to October 10, 1969 concerning problems encountered by Hugh Wilson on Model 700, 7mm magnum rifles. These problems include burrs on bolts, feeding from the magazine and undersized chambers.

We have audited our warehouse, gallery and assembly line, and reviewed our quality control reports for 1969, looking for similar deficiencies at the factory.

- . Burrs on bolts - We have had minor but persistent problems this year in fitting extractors to the Model 700 bolt. Both gallery and final inspection reports include "hard close" defects because of this extractor problem. We are now changing our process and expect immediate relief.
- . Feeding from magazine - We have had isolated cases of feeding problems. Usually the follower spring is upside down or the spring detent in the follower is improperly formed.
- . Undersized chamber - Our center fire rifles have head space and chamber dimensions measured 3 separate times during the manufacturing process. However, to recheck, we have measured warehouse rifles. We also checked Winchester, Federal and Remington factory ammunition and can find no dimensions out of specification. Without having the rifles here at Ilion, we cannot establish the cause.

PLAINTIFF'S
EXHIBIT

3285

AL 0029817

1 of 2

A
D. LEE BRAUN

-2-

December 10, 1969

Lee, the following comments are pure conjecture and may not be related to the Model 700, 7mm magnum chamber problems reported by Hugh Wilson. The appearance of an undersized chamber in magnum calibers can be caused by defective extractors, rusty chambers (even in stainless steel), oversized cartridge cases, reloads, burrs in the chamber or damaged heading shoulders. We do have some instances of the magnum heading shoulder being damaged by poor technique in measuring head space.

Polishing the chamber almost always improves feeding and chambering. However, polishing can lead to reload problems, max. head space or oversized chambers. The hazard of max. headers or oversized chambers is over-rated, but can lead to poor performance and unhappy customers. If a customer has doubts about magnum rifle chamber dimensions, I suggest the rifle be returned to us.

As you can see, I have not really answered any of your questions other than try to relate to current production problems. If you can return some of the rifles to us, then we can be more specific.

R. A. Williamson
Plant Manager

by

L. Fox, Supt.
P E & C Section

LF:I

2 of 2
AL 0029818

Customer Complaint

MODEL: 700 PCL
R # : 20000
DATE: 12-10-90
FROM: FLYNN, J. D.
FIRING ARM TYPE: 1000
GUN # : 6884951
CODE: CTR-460
GAT/CAL.: 25-01
CHECKED BY: C. F. R. 10
APPROVED: _____
APPROVED: _____
APPROVED: _____
APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style)

COMPLAINT: "BULLET STICKS IN CHAMBER ALSO BOLT IS
IMMOVABLE FOR SOME REASON."

INCIDENT: _____

COMMENTS: THE CUSTOMER PULLED THE BULLET OUT OF THE
CASE LEAVING IT IN THE THROAT. THIS APPARENTLY
IS AN AMMUNITION PROBLEM (PER M. WALKER).
THE BOLT CATCHING IS CAUSED BY PUSHING THE
SAFETY ON BEFORE LOCKING THE BOLT THUS CATCH-
ING THE SAFETY PIN IN THE LOCKING CAM.

PLAINTIFF'S
EXHIBIT

3286

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 23406
OUTSIDE WORK: NO DATE: 11-2-70
FROM: OCONTO, WIS.
FIRED AMMO TYPE: _____
& CONDITION: _____ GUN #: 6248578
PROOF: _____ INSP.: _____ TEST: _____ CODE: PS-6/69
HEADING: _____ GA/CAL.: 7MM
BREECH OPENING: _____ CHECKED BY: C. PROSSER
RECOIL SHOULDERS: _____ APPROVED: _____
CHAMBER: _____ APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.

COMPLAINT: FIRES WHEN SAFE IS REMOVED & WONT COCK
AT TIMES.

INCIDENT: _____

COMMENTS: MALEFUNCTION WAS CAUSED BY THE BROKEN
TRIGGER CONNECTOR.

PLAINTIFF'S
EXHIBIT

3287

1 of 1

AL 1129820

Custom Complaint

P.I. 17 GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700

GENERAL CONDITION: NEW R # : 24907

OUTSIDE WORK: NO DATE: 11-9-70

FIRED AMMO TYPE: _____ FROM: SHARPS HORN

& CONDITION: _____ GUN # : 5211334

PROOF: R.S.P. INSP.: 2 TEST: _____ CODE: BT-1/70

HEADING: O.K. GA./CAL.: 3006

BREECH OPENING: _____ CHECKED BY: C. ROOSTER

RECOIL SHOULDERS: O.K. APPROVED: _____

CHAMBER: _____ APPROVED: _____

TEST: in APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

R.P. - O.K.

COMPLAINT: "EVERY TIME YOU PUSH THE FOOT HARD THE
RIFLE FIRES"

INCIDENT: FOLLOWS DOWN

COMMENTS: THE ENGAGEMENT OF THE SEAR, TRIGGER CON-
NECTOR SET TOO CLOSE AT FINAL ASSEMBLY (0052)

PLAINTIFF'S
EXHIBIT
3288

AL 0029821

Custom Complaints

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 26143
OUTSIDE WORK: NO DATE: 11-12-70
FROM: DAKIN SALES CORP. CO.
FIRED AMMO TYPE: - BANGOR, MAINE
& CONDITION: _____ GUN #: 6219140
PROOF: R.E.P. INSP.: _____ TEST: ASSEMBLER 41 CODE: LS-2/69
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: - APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.

COMPLAINT: "WILL NOT STAY COCKED"

INCIDENT: FOLLOWS DOWN

COMMENTS: THE BROKEN CONNECTOR MAKES RETRACTION
UNDER SEAR UNCONTROLLABLE. THE CONNECTOR
FAILING TO RETRACT CAUSES FOLLOW DOWN.

PLAINTIFF'S
EXHIBIT

3289

1 of 1

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 26910
OUTSIDE WORK: NO DATE: 11-17-70
FROM: GOLD BUSH SALES
FIRED AMMO TYPE: - BROOKLYN, N.Y.
& CONDITION: _____ GUN #: 6288540
PROOF: R.E.P. INSP.: ASSEMBLER #30 TEST: 79 CODE: CS-4/69
HEADING: O.K. 74 79 GAT/CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
COMPONENTS O.K.

COMPLAINT: FIRE UPON CLOSING BOLT.INCIDENT: APPARENTLY FOLLOWED DOWN.COMMENTS: ENGAGEMENT O.K. NO REASON FOR MALEFUNCTION COULD BE FOUND. THE MALEFUNCTION COULD NOT BE REPRODUCED.PLAINTIFF'S
EXHIBIT

3290

1 of 1
AL 0029823

Customer Complaint

A
NAME: _____
ADDRESS: _____
CITY: _____
STATE: _____
ZIP: _____
PHONE: _____
FIREARM TYPE: _____
& CONDITION: _____
PROOF: _____ INSP.: _____ TEST: ST
HEADING: 30.06
BREECH OPENING: _____
RECOIL SHOULDERS: _____
CHAMBER: _____
TEST: NO
COMPONENT CONDITION: (Damaged, Broken, Old Style)
NO BROKEN OR DAMAGED COMPONENTS.

MODEL: _____
R.F.: _____
DATE: _____
FROM: _____
GUN # : _____
CODE: _____
GAT./CAL.: 30.06
CHECKED BY: C.F. 100
APPROVED: _____
APPROVED: _____
APPROVED: _____
APPROVED: _____

COMPLAINT: GUN FIRES WHEN BOLT IS CLOSED.

INCIDENT: FOLLOWS DOWN

COMMENTS: THE SEAR-CONNECTOR ENGAGEMENT WAS SET TOO CLOSE BY FINAL ASSEMBLY.

PLAINTIFF'S
EXHIBIT

3291

AL 0029824

*Customer Complaint.*P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDLGENERAL CONDITION: GOOD R #: 27632OUTSIDE WORK: STOCK BEDDING ALTERED. DATE: 12-3-70SCOPE MOUNTED. FROM: R. ROYSEFIRED AMMO TYPE: - PORTLAND, OREGON.& CONDITION: _____ GUN #: 6275235PROOF: R.E.P. INSP.: 9 ASSEMBLER 90 TEST: 55 CODE: ES-10/69HEADING: O.K. GA./CAL.: 7MM R-U.V.A.BREACH OPENING: - CHECKED BY: C. PROSSERRECOIL SHOULDERS: O.K. APPROVED: _____CHAMBER: O.K. APPROVED: _____TEST: No APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: POOR GROUPS, FIRED WHEN SAFETY WAS PUSHED TO FIRE POSITION.INCIDENT: BARREL BORE ROUGH, FOLLOWED DOWN.COMMENTS: THE FOLLOW DOWN CAN NOT BE DUPLICATED.BARREL BORE EXCESSIVELY ROUGH - SHOULD BE REPLACED.PLAINTIFF'S
EXHIBIT

3292

1 of 1
AL 0029825

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
 GENERAL CONDITION: NEW R #: 27287
 OUTSIDE WORK: NO DATE: 11-23-70
 FIRED AMMO TYPE: _____ FROM: SARGLE ELECT. CO.
 & CONDITION: _____ VERNAL, UTAH
 PROOF: R.E.P. 2 INSP: 74 TEST: 55 GUN #: 6296977
 HEADING: _____ CODE: LT = 2/70
 BREACH OPENING: _____ GAT/CAL.: 300G
 RECOIL SHOULDERS: _____ CHECKED BY: C. PROSSER
 CHAMBER: _____ APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER / CONNECTOR CLEARANCE .003 OUTSIDE MODEL
 DRAWING. CONNECTOR / TRIGGER CLEARANCE .005 OUTSIDE
 MODEL DRAWING. THIS ADDS UP TO .008 MORE MOVE-
 MENT UP, OF CONNECTOR THAN THERE SHOULD BE TO
 POSSIBLE INTERFERENCE WITH THE SEAR.

COMPLAINT: "TRIGGER FIRES SOMETIMES WHEN TAKEN OFF
 SAFE" (EXTRACTOR FAULTY)

INCIDENT: FOLLOWS DOWN WHEN SAFE IS PUSHED OFF.

COMMENTS: THE FALLING DOWN MALFUNCTION COULD NOT
 BE VERIFIED ALTHOUGH EXCESSIVE CONNECTOR
 MOVEMENT IS PRESENT.

EXTRACTOR CHAIN DAMAGED.

PLAINTIFF'S
 EXHIBIT
 3293

1 of 1

*Customer Complaint*P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700GENERAL CONDITION: NEW R #: 27774OUTSIDE WORK: NO DATE: 12-10-70FIRED AMMO TYPE: - FROM: KROGER'S FOOD

& CONDITION: _____ SUPPLY

PROOF: R.E.P.A. INSPECTION: 33 TEST: 13 GUN #: 6367225HEADING: - CODE: DT-9/70BREECH OPENING: - G.K./CAL.: 3006RECOIL SHOULDERS: - CHECKED BY: C. PROSSERCHAMBER: - APPROVED: _____TEST: NO APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPONENTS O.K.COMPLAINT: "HAMMER IN BOLT WILL NOT STAY COCKED."INCIDENT: FOLLOWS DOWN.COMMENTS: SEAR, TRIGGER CONNECTOR, ENGAGEMENTADJUSTED TOO CLOSE (.005) MINIMUM IS .015, THIS
LETS THE SEAR SLID OFF THE CONNECTOR UNDER
PRESSURE & FIRING PIN FOLLOWS DOWN.RE-ADJUSTED ENGAGEMENT.PLAINTIFF'S
EXHIBIT

3294

1 of 1
AL 0029827

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BCL
 GENERAL CONDITION: GOOD R #: 29327
 OUTSIDE WORK: EXTRACTOR PISTON - BRASS DEF. DATE: 12-15-70
TRIGGER ADJUSTED - ENGAGEMENT SCREEN FROM: HARPER ST. CO.
APPEARS UNTOUCHED. WILLIAMSBURG, PA.
 FIRED AMMO TYPE: _____ GUN #: 6262972
 & CONDITION: _____ CODE: W5-9/10
 PROOF: R.E.P.E INSP.: 47 TEST: 55 SA./OAL: _____
 HEADLINE: _____ CHECKED BY: C. HARPER
 BREACH OPENING: _____ APPROVED: _____
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: No APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DEFECTIVE OR BROKEN COMPONENTS.

COMPLAINT: "FIRED UPON CLOSING"

INCIDENT: FOLLOWED DOWN

COMMENTS: SEAR-CONNECTOR ENGAGEMENT .003, MINIMUM IS .015,
THIS LETS THE SEAR SLIP OFF THE CONNECTOR UNDER
PRESSURE AND FOLLOW DOWN RESULTS.

PLAINTIFF'S
EXHIBIT

3296

AL 0029828

1 of 1

P.I. NO GUN EXAMINATION REPORT NUMBER: _____

MODEL: 700 S&W

GENERAL CONDITION: NEW

R # : 29277

OUTSIDE WORK: NO

DATE: 12-21-70

FROM: LEONARD

FIRED AMMO TYPE: _____

ED - 410 - 100

& CONDITION: _____

GUN # : 333-470

PROOF: BAF INSP.: 0 TEST: 49

CODE: WT = 8/70

HEADING: O.K.

GA./CAL.: 270 W&M

BREECH OPENING: -

CHECKED BY: C. FROSSER

RECOIL SHOULDERS: O.K.

APPROVED: _____

CHAMBER: O.K.

APPROVED: _____

TEST: NO

APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style)

APPROVED: _____

SAFETY CAN BE KEPT OFF OF SEAR.

COMPLAINT: 'SAFETY DOES NOT WORK'

INCIDENT: FIRE IN THE SAFE

COMMENTS: SAFETY CAN NOT FUNCTION WITHOUT THE GUN ON THE SEAR - SAFETY CAN.

PLAINTIFF'S
EXHIBIT

3296

1 of 1

AL 0029829

P.I. 100 GUN IDENTIFICATION REPORT NUMBER: MODEL: 700 BCL
 GENERAL CONDITION: Good R #: 38794
 OUTSIDE WORK: No DATE: 10-21-70
 FROM: TL. R. H. Co.
 FIRED AND TYPE: ESTIM. 1000 YDS.
 & CONDITION: GUN #: 38794
 PROOF: R.F.P. DISP.: TEST: ✓ CODE: 2.2 = 410
 HEADING: S.L. GA./CAL.: 300 MIN. R.L.
 BREACH OPENING: CHECKED BY: E. PROSE
 RECOIL SHOULDERS: APPROVED:
 CHAMBER: O.K. APPROVED:
 TEST: No APPROVED:
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED:

COMPLAINT: "GUN FIRED WHEN PICKED UP"

INCIDENT: FOLLOWING DATA

COMMENTS: TRIGGER CONNECTOR - SEEN ENGAGEMENT @ 10
MIN. ENGAGEMENT = 015. MALFUNCTION NOT DUPLICATED.
ENGAGEMENT RE-ADJUSTED.

PLAINTIFF'S
EXHIBIT

3297

10 of 1

AL 0029830

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 00285
OUTSIDE WORK: NO DATE: 1-6-71
FIRE: NO FROM: KMART SPTG. DEL
FIRED AMMO TYPE: - ST. CLAIR SHORES, MICH
& CONDITION: ASSEMBLER 12 GUN #: 6248840
PROOF: R.E.P. INSP: _____ TEST: _____ CODE: P.S. = 6/69
HEADING: O.K. GUN/CAL.: 7MM REM.
BREACH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

BROKEN TRIGGER CONNECTORCOMPLAINT: DEFECTIVEINCIDENT: FOLLOWS DOWN

COMMENTS: THE BROKEN TRIGGER CONNECTOR FAILS TO
RETRACT TO SUPPORT THE SEAR IN CORRECT POSIT-
ION. WITHOUT SUPPORT, THE SEAR FOLLOWS DOWN.

PLAINTIFF'S
EXHIBIT

3298

AL 0029831

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
 GENERAL CONDITION: USED R #: 00598
 OUTSIDE WORK: NO DATE: 1-11-71
 FROM: REM. ARMS OF CAN.
 FIRED AMMO TYPE: _____ TORONTO, ONT., CANADA
 & CONDITION: _____ GUN #: 6216023
 PROOF: R.E.P. ASSEMBLER: GA INSP.: U TEST: 55 CODE: LS-2/69
 HEADING: _____ GR./CAL.: 350 REM. MAG.
 BREACH OPENING: _____ CHECKED BY: _____
 RECOIL SHOULDERS: _____ APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTS.COMPLAINT: SEAR WILL NOT HOLD.INCIDENT: FOLLOW DOWN.

COMMENTS: SEAR-TRIGGER CONNECTOR ENGAGEMENT O.K.; MAL-
FUNCTION COULD NOT BE DUPLICATED. HOWEVER BRIGHT
EDGE ON TRIGGER (TOP) INDICATES A SLIGHT INTERFER-
ENCE WHICH MAY HAVE CAUSED THE MALFUNCTION.

PLAINTIFF'S
EXHIBIT

3299

1 of 1
AL 0029832

MODEL 700 CUSTOMER GUNS RETURNED BY COMPLAINT-MONTH RECEIVED AND YEARLY TOTAL

1963

1962

	Total	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Total
Total Guns Returned:	355	81	86	71	55	62	34	42	54	70	83	87	87	812
Total Complaints:	397	83	89	72	61	62	34	42	54	70	83	87	87	824
Total Functional Complaints	130	29	28	24	19	21	8	13	23	24	30	29	27	275
Ejection	6	1	1		1	3	1	1	1		1	2	2	14
Firing	8	1		1	2	1			3	1	1			9
Extraction	10	1	7	5	1	3	1	2	1	3	2		4	28
Feeding	31	4	6	1	5	4	1	1	4	5	6	5	2	44
Closing	12	5	5	10	4	2			2	1	1	4	1	35
Bolt Binds	8	1	1				2		1	1	3	1	3	13
Trigger Pull	5	2	3	1		1		2	3	6	3	6	6	33
Safe	6	2		1	1								3	8
Damaged or Blown Cases or Primers	18	3	2	5	5	7	2	7	5	4	4	7	5	56
Ejector Binds or Stuck in Bolt	6	1	1						2	2		1	3	7
Jr., Repair Etc.	5	2												8
Up to Standard (Functional)	4	6	2				1		2	3	8	3		26
S														
Total Intermediate Complaints	206	47	48	44	32	40	24	25	31	40	46	49	53	457
Stock Broken, Cracked	70	21	16	17	12	14	6	6	11	14	16	20	35	189
Stock Finish or Checkering	83	12	14	17	6	11	9	5	6	11	14	12	7	124
Stock Cracked at Barrel Groove														
Accuracy (Point of Impact)	2		2	1	3	3	4	5		2	2	5	3	29
Accuracy (Group Size)	11	4	5	2	3	6	6	5	8	5	2	3	2	46
Belt Handle Broken-Loose	13	2	1				1	1		2	4	2	7	20
Sights Crooked-Tipped Etc.	5	1		2		2		1		1		1	1	9
Sights Out of Line			1							1				2
Rings Mounting Trouble	6	1						2	4	1				8
Sights Broken		1	3							1				5
Bolt Pulls Out	1				1									2
Up to Standard (Intermediate)	15	3	1	1	2	1	3			3	7	6		37
Broken Steel Parts	11	2	5	4	6	3			2		1			23
Total Visual Etc.-Complaints	61	7	13	4	10	1	2	4		6	7	9	5	68
Misc. Visual Complaints	52	7	11	4	10		2	4		5	7	7		57
Misc. Non-Functional	8					1				1		2	5	9
Up to Standard (Non Functional)	1		3											4

**PLAINTIFF'S
EXHIBIT**
3300

Model 700 Total Complaints (except up to Btd.)

Date Prepared
per Month

Year	Month	1962												1963												Total
		J	F	M	A	M	J	J	A	S	O	N	D	J	F	M	A	M	J	J	A	S	O	N	D	
1961																										
Jan.																										
Feb.																										
Mar.																										
Apr.																										
May																										
June																										
July																										
Aug.																										
Sept.																										
Oct.																										
Nov.																										
Dec.																										
Jan.																										
Feb.																										
Mar.																										
Apr.																										
May																										
June																										
July																										
Aug.																										
Sept.																										
Oct.																										
Nov.																										
Dec.																										
Jan.																										
Feb.																										
Mar.																										
Apr.																										
May																										
June																										
July																										
Aug.																										
Sept.																										
Oct.																										
Nov.																										
Dec.																										

PLAINTIFF'S
EXHIBIT
3301

RE 10 X 10 TO THE WINCH 359-110
KODAK SAFETY FILM CO. MADE IN U.S.A.

Model 700 - Functional


PERGAD-Bayonne, N. J.
PLAINTIFF'S
EXHIBIT
3302

835

104

K-E 10 X 10 TO THE INCH 359-119
STUFFY & SONS, CO. NEW YORK

Model 700 Stock Broker/Stock Finish & Clearing



PENGAD-RODINA, M. J.
PLAINTIFF'S
EXHIBIT
3303

AL 0029836

1061

PROJECT NO. M1700 TRIAL USE OF LPS INSTEAD OF MOLYCOTE FOR CONTROL OF TRIGGER PULL

COMPUTER

DATE 5-18

1974

REPORTED BY LOADS OF TWENTY RIFLES.

REJECTED
FOR CREP

PASSED

lay,

11

8

2

15

4

15

13

7

5

15

6

14

3

17

9

11

12

8

5

15

4

16

4

16

7

13

4

16

4

16

This is a report on using LPS Lubricant instead of Moly-cote. It doesn't look very good. This is about the reject rate we get with no luber.

Jim

EXHIBIT

PLAINTIFF'S
EXHIBIT
3304

AL 0029838

M/700 Fire Control

NE GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 PDL
 GENERAL CONDITION: GOOD R #: 22760
 OUTSIDE WORK: ACT TRIGGER ADJUSTING DATE: 10-16-79

SCREWS UNSEATED, ADJUSTMENTS CHANGED FROM: GENERAL
 FIRED AMMO TYPE: _____ 12.1 INCH

& CONDITION: _____ GUN #: 123512
 PROOF: R.E.P. INSP.: 9 TEST: _____ CODE: WTS = 5/15
LN = 2/15

READING: _____ GA/CAL.: 222

BREECH OPENING: _____ CHECKED BY: GENERAL

RECOIL SHOULDERS: _____ APPROVED: _____

CHAMBER: _____ APPROVED: _____

TEST: _____ APPROVED: _____

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

OLD STYLE SEAR-SAFETY SPRING HEAVY OIL USED
TRIGGER CONNECTOR BROKEN

COMPLAINT: FOLLOWS DOWN

INCIDENT: _____

COMMENTS: FOLLOW DOWN WAS CAUSED BY FIVE BROKEN CONNECTORS

PLAINTIFF'S
 EXHIBIT
 3306

181
 AL 0029841

NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 22775
OUTSIDE WORK: NO DATE: 10-15-70
FROM: MARKLEYSBURG, PA.
FIRED AMMO TYPE: _____
& CONDITION: _____
PROOF: R.E.P. INSP.: 9 TEST: _____
HEADING: O.K. GA./CAL.: 22-250
BREECH OPENING: — CHECKED BY: C. PROSSER
RECOIL SHOULDERS: — APPROVED: _____
CHAMBER: — APPROVED: _____
TEST: FUNCTION ONLY APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: FOLLOWS DOWN WHEN SAFETY IS PUSHED OFF.

INCIDENT: _____

COMMENTS: THE DIMENSION FROM THE TOP OF THE TRIGGER TO CENTER OF TRIGGER PIN HOLE BEING .011 OVERSIZE ELIMINATES MOST OF THE CLEARANCE NEEDED FOR THE TRIGGER-CONNECTOR TO RETRACT WITH THE SAFETY ON.

PLAINTIFF'S
EXHIBIT
3307

10/

AL 0029842

P NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 22730
OUTSIDE WORK: NO DATE: 10-16-70
FIRED AMMO TYPE: _____ FROM: LIVONIA,
& CONDITION: _____ MICH.
PROOF: -R.E.P. INSP.: _____ TEST: _____ GUN #: 6278113
HEADING: _____ CODE: _____
BREACH OPENING: _____ GR./CAL.: 3006
RECOIL SHOULDERS: _____ CHECKED BY: C. PROSSER
CHAMBER: _____ APPROVED: _____
TEST: FUNCTION ONLY APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR IS .005 UNDERSIZE ON 1.080
CLEARANCE) ON 1.083 DIMENSION (TRIGGER

COMPLAINT: FOLLOWS DOWN

INCIDENT: _____

COMMENTS: CONNECTOR BEING TIGHT ON TRIGGER DID NOT RETRACT,
ACTION WOULD NOT COCK. AS LONG AS THE CONNECTOR
STAYED IN POSITION ON THE TRIGGER THE RIFLE WOULD
WORK O.K.



181
AL 0029843

P.T. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: GOOD R #: 21196
OUTSIDE WORK: SCOPE MOUNTED DATE: 10-2-70
FIRED AMMO TYPE: - FROM: DAVISON
& CONDITION: _____ MICHIGAN
PROOF: R.E.P. INSP: 9 TEST: 87 GUN #: 6216922
HEADING: O.K. CODE: LS-2/69
BREECH OPENING: - GA./CAL.: 243 WIN.
RECOIL SHOULDERS: - CHECKED BY: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN.

COMPLAINT: FIRING PIN FOLLOWS DOWN

INCIDENT: _____

COMMENTS: THE CONNECTOR BEING BROKEN, ENGAGEMENT
BETWEEN IT AND THE SEAR WAS UNLIKELY THEREFORE
THE FIRING PIN WAS FREE TO FOLLOW DOWN.



REMINGTON ARMS COMPANY, INC.

INTERDEPARTMENTAL CORRESPONDENCE

Remington

SUPER

PETERS

SUPER

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

XC: K. W. Augustine R. L. Joy
 S. D. Bennett M. J. Kantor
 L. R. Blackhurst H. C. Munson
 L. B. Bosquet C. O. Pardee
 H. K. Boyle D. F. Polley
 J. W. Brooks D. D. Ricci
 J. J. Burns D. I. Roark
 G. D. Campbell D. J. Sanita
 W. L. Ganey D. S. Valent
 B. H. Gilbert W. C. VanSickle
 M. C. Hardy L. G. Wilke
 P. G. Johnson

February 8, 1982

J. H. CARTER, G. E. FLETCHER, J. P. LINDE

M/700 FIRE CONTROL - REMOVE BOLT LOCK

MEETING HELD 2/8/82 TO REVIEW IMPLEMENTATION

BELOW IS AGREED UPON SCHEDULE

START DATE - FEBRUARY 26, 1982

A. Items needing completion to meet above date:

1. Process Record needed, new Part Numbers for components - Issue by 2/12/82.
2. Push new safe arms thru production:
 - 9,700 in Stores, 3,000 of these issued 2/5/82.
 - 10,000 more to be sent to Vendor for clipping.
 - Additional sent to Vendor for clipping as needed to meet schedule.
3. New instruction folders available.
4. A quantity of 5,000 old style safe arms to be sent to Arms Service for use on customer guns.
5. Old Instruction Folders - Gather up and dispose of.

S. Bennett
J. Brooks

M. Kantor

S. Bennett
D. Ricci

M. Kantor

J. Carter

D. Roark
J. CarterD. Roark
W. Ganey

PENDING - 1/1/82

PLAINTIFF'S
EXHIBIT
3310

182 AL 0029845

M/700 FIRE CONTROL - REMOVE BOLT LOCK - Contd.

B. On starting date, Final Assembly area will do the following:

1. All assembled guns, repairs included, will be torn down and a new Safe Arm will be assembled to the Fire Control.
2. All guns packed on February 26, 1982 and thru March, will be stamped AL (March 82). This includes guns and packing labels.
3. Mark gun labels "S".
4. Guns must have modified Safe Arm and new instruction folder.
5. Custom Gun Shop to use new Safe Arms in Fire Controls in guns from February 26th forward. New instruction folders must also be used.

by

Still 2/9/82
G. J. Hill, Supervisor
Process Engineering
Current Products

GJH/cac

272
AL 0029846