RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R91-24221

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
11/21/91	11/25/91	KT 5-70	6337799		700 25-06	ADL

ACCESSORIES W/STUDS L/SIGHTS

FROM:
LAHEY, CHRIS M
501 SOUTH WASHINGTON
ALTAMONT KS 67330
USA

SHIP TO:
LAHEY, CHRIS M
501 SOUTH WASHINGTON
ALTAMONT KS
USA 67330

CUST NO:053607 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.					E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"In the safe will now sometimes fire upon releasing the safety".

MAIN FAULT Cannot duplicate complaint. However, inside of trigger area has accumulation of dried lubricant and trigger has been improperly adjusted outside factory as evidenced by missing sealant on front adjusting screws. 1) Insufficient over travel 2) trigger pull heavier than max. spec — measured at 6 pounds.

Sear-lift - .008"

PARTS

COMMENTS Offer new trigger assembly at [illegible] normal cost, as gesture of good-w[illegible]

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV