RECEIVING AND ESTIMATING REPORT

COMMENTS: F. Supply / Product Service

ORDER: R 94-11470

INITIAL	CUSTOMER ORDER NO.
FJB	5136

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
03/30/94	03/31/94	PI 6-88	C6260904		700 270 FS/CAMO

ACCESSORIES: SLING STRAP W/STUDS W/SWIVELS L/SIGHTS

FROM:
SOUTHLAND GUN WORKS INC
1134 HARTSVILLE HWY
DARLINGTON SC 29532

SHIP TO:
SOUTHLAND GUN WORKS INC
1134 HARTSVILLE HWY
DARLINGTON SC 29532

CUST NO:006042 ILIONL

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
063103		☐		5-14-94	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☑ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	20.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	Rifle fired when safety was pushed on fire				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Mfgr. 6-88 Could not duplicate customer concern as required. Trigger Assy. was rusted and some rust on bottom of receiver. Trigger was also adjusted outside of the factory. We do not recommend that the trigger be adjusted outside of the factory and All metal parts should be maintained with a light film of light oil. Exchange trigger assy. at a special price as a gesture of good will.

PARTS	COMMENTS
Trigger Assy. Complete	Trigger pull measured 4½ TO 7 LBS As Rec'd. Sear lift was .014 Sling on Car.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RB		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94