RECEIVING AND ESTIMATING REPORT

COMMENTS: GEKL

ORDER: R92-20751

INITIAL	CUSTOMER ORDER NO.
FPS	V474637693

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
10/01/92	10/08/92	KQ 5-78	A6604933		700 6MM REM BDL

ACCESSORIES: W/STUDS

L/REAR SIGHT

FROM:
WANSTREET, FRED
P O BOX 307
ELLENBORO WV 26346

SHIP TO:
WANSTREET, FRED
P O BOX 307
ELLENBORO WV 26346

CUST NO:067888 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER NC	WRITE	PROM. DATE	ESTIMATED	VIA
		CLEAN/TEST			UPS

GUN CONDITION
- [ ] NEW
- [ ] LIGHTLY WORN
- [x] WORN
- [ ] VERY WORN
- [ ] UNREPAIRABLE
- [ ] MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

sometimes fires on closing

MAIN FAULT: Trigger assembly improperly installed as received — assembly is contaminated with a gummy substance that is inhibiting movement of internal trigger parts. Sear-Safety cam is stuck to trigger assembly side plates. Trigger assembly has also been improperly adjusted outside factory — sear engagement and over-travel are excessive

PARTS

COMMENTS: Offer new trigger assembly at ½ normal cost, as a gesture of good will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PPS 05341