RECEIVING AND ESTIMATING REPORT

COMMENTS: Stekl

ORDER: R 92-00037

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/20/91	01/02/92	WU 8-71	6468599		700 30-06 ADL

ACCESSORIES: W/STUDS SCOPE BASE

FROM:
T.V.'S RELOADING SHOP
119 MAXEY ROAD
HOUSTON TX 77013
USA

SHIP TO:
T.V.'S RELOADING SHOP
119 MAXEY ROAD
HOUSTON TX
USA 77013

CUST NO:022477 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		1-16-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Gun shoot off when Bolt was closed

MAIN FAULT: Rifle cannot be made to malfunction, however, inside of trigger assembly is contaminated with a gummy substance that is affecting movement of trigger. The same material appears to be on the bolt stop causing sluggish movement.

Trigger pull 3 3/4 pounds; sear-lift .012"

PARTS

COMMENTS: Offer to clean present trigger assembly if possible — if not, we can install a new trigger assembly at ± normal cost as a gesture of good-will.

This rifle is 20+ years old.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RBL					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

PS06275