RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN JIM STEKL

ORDER: R91-24360

INITIAL	CUSTOMER ORDER NO.
LCS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/22/91	11/26/91	AO 3-77	A6430942		700 308 BDL

ACCESSORIES: W/STUDS SCOPE BASE

FROM:
VINKEMULDER, SCOTT
9900 IVANREST
BYRON CENTER MI 49315
USA

SHIP TO:
VINKEMULDER, SCOTT
9900 IVANREST
BYRON CENTER MI
USA 49315

CUST NO:053695 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Rifle discharged when the safety was moved to the "fire" position

MAIN FAULT: Rifle could be made to malfunction as described by customer. Subsequent disassembly of rifle revealed rust on bottom of hand, release, outside and inside of trigger assembly. Examination of the trigger assembly revealed that because of depletion rust the internal parts were not moving freely nor properly. Trigger was not moving freely between trigger assembly side plates and on pivot pin. Removal of firing pin from bolt revealed rust on interior of bolt body and firing pin assembly. Apparently rifle became wet at some time and was not properly cleaned and maintained afterward.

PARTS:

COMMENTS:
1) Send quotation for thorough cleaning and oiling
2) Quote for new trigger assembly at ½ normal cost, as a gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91