Remington Arms Co., Inc.
Product Service
Legal Case #:5014

## Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|-----|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 213373 | 12/8/2010 | 11/8/2010 | 12/9/2010 | | | | |

## Customer Information

| Type | Business | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|------|----------|------------|-----------|--------|------|-------|-----|-----|---------|
| Incident | | Joe | Lineberger | 3029 Preston Mill Rd | Huddleston | VA | 24104 | | H 540-297-7114 |

## Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|-------|-------------|-------------------|----------------|
| PI | | | | |
| PD | Cause:4038 | Could Not Duplicate Concern | | |
| S  Fired when he worked the bolt to unload | Concern:1020 Fired on Bolt Opening | | Unknown | |
| C | | | | |

11/8/10 Per call from Lineberger, he has a 700 that is about 25 yrs old and a couple of years ago he was coming out of the woods and he worked the bolt to unload the round out of the chamber and it fired. Hasn't happened since. Wants a new trigger even if he has to pay for it.cm

## Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl. | DOM |
|------|------|-----------|-----|--------|------|-----|
| Remington | CF/BA | 700/30-06 SPR | n/a | B6228267 | KA | 5/27/1980 |

| Date Purchased | Where Purchased | Accessories | Original Owner |
|----------------|-----------------|-------------|----------------|
| | SANDY DIST CHARLESTON WV | TWO PIECE SCOPE BASE | Y |

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|------------|-------------------|--------------|---------------|-----------------|----------------|---------------|
| Replace TPA, clean at BLSM program price | | | | | | |

| Repair/Replacement Cost | Repair/Replacement Date |
|-------------------------|-------------------------|
| 40.23 | 12/12/2010 |

11/8/10 Mailing ARS and letter.cm 12/12/10 Per Ilion, could not duplicate concern. Trig assm set screws altered. Replace TPA, clean and test fire under BLSM program price of $20 + shipping. Emailed Linberger inspection info and quote.cm 12/13/10 Lineberger called and approved repair.cm 12/14/10 Per call from Lineberger, 8:45 am, he has read on the internet that no one likes the XMark trigger. He wants me to get them to stop the repair and send him his rifle and original trigger back. I've sent the request to the repairman and will send a waiver if they can stop repairs.cm 12/14/10 Lineberger called back, changed his mind, wants us to install the trigger. Nagle retrieved the rifle from Packing and will get back to repairman.cm

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|---|---|---|---|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 12/9/2010 |
| | Product Type | | RF |
| | Action Type | | A |
| | Assigned To | | T.NAGLE |
| Cause | 4038 | Could Not Duplicate Concern | |
| Barrel | Description | | 22" 30-06 SPR |
| | Date Code | | KA |
| | Bore Plugged | False | |
| | Bulged | False | |
| | Fired | False | |
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| Bolt | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |
| | Face | Slightly Worn; Functioning | |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Functioning | |
| Extractor | Condition | Slightly Worn; Functioning | |
| | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | ---Select--- | |
| | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | ---Select--- | |
| Overall | Exterior Condition | Slightly Worn; Functioning | |
| | Stock Condition | Slightly Worn; Functioning | |
| | Fore End Condition | ---Select--- | |
| Receiver | Condition | Slightly Worn; Functioning | |
| | Bulged | False | |
| Safety | Description | | STANDARD M/700 BOLT LOCK SAFETY |
| | Function | Like new; Functioning | |
| | Sub-Assembly | Non-ISS | |
| Sear | Lift | ---Select--- | .011 |
| | Notch | Slightly Worn; Functioning | |
| Feeding Test | Tests | Test Fired | False |
| | | False | |
| Trigger | Condition | Slightly Worn; Functioning | |
| | Pull | ---Select--- | 2.5# |
| | Altered | True | SET SCREWS ALTERED |
| | Sub-Assembly | M/700 Bolt Lock | |

**BARBER - Kinzer PPS GAL RE 0011322**

| Non-Remington Components | Description | | TWO PIECE SCOPE BASE |
|---|---|---|---|

BARBER - Kinzer PPS GAL RE 0011322

PS 13210