RECEIVING AND ESTIMATING REPORT

COMMENTS: BOTTOM HALF OF SEE THRU MTS ONLY

ORDER: R91-23431

STEKO

INITIAL	CUSTOMER ORDER NO.	DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
JJM		11/12/91	11/18/91	00 7-77	A6480720		700 30-06 ADL

ACCESSORIES: W/STUDS

FROM:
CARNEYS SHOOTERS SUPPLY
ROUTE 1 BROWNING RD
MASSENA NY 13662
USA

SHIP TO:
CARNEYS SHOOTERS SUPPLY
ROUTE 1 BROWNING RD
MASSENA NY
USA 13662

CUST NO:008354 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		11/21/91	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"... It discharged when the bolt was being closed".

MAIN FAULT: Cannot duplicate complaint. Rifle operates properly, however disassembly & adj. revealed the trigger assembly has been adjusted outside factory specs. Evident missing from adjusting screws — 1) trigger pull reduced over our Max Spec (at 6 oz #) 2) insufficient over-travel

Sear lift — .011"

PARTS

COMMENTS: Offer to re-adjust and re-seal specific trigger assembly, or, if owner desires, we can install a new trigger assembly at ½ normal cost as a gesture of good-will, if it will help restore confidence in the rifle.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
NRR					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 8/91