RECEIVING AND ESTIMATING REPORT

COMMENTS: W/1 SPENT CASE

ORDER: R 92-02568

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
01/14/92	01/21/92	DQ 9-77	A6659392		700 6MM ADL

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:
MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

SHIP TO:
MCCLELLANDS GUN SHOP
DIVISION OF REMCO
1533 CENTERVILLE ROAD
DALLAS TX 75228

CUST NO:006612 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		2-4-92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		fires when safety disengaged			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Cannot duplicate reported malfunction – Trigger assembly and safety operate properly. However, the trigger assembly has been improperly altered outside factory (as evidenced by red sealant on all operating screws) outside Remington specifications: 1) trigger pull 2 3/4 pounds 2) insufficient sear engagement, 3) insufficient over-travel.

Sear-lift .008"

PARTS

COMMENTS: Offer new trigger assembly at ½ normal cost, as a gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

REV. 8/91

PPS 03303