Full Safety

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 94-12159

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/06/94	04/07/94	DV 9-79	A6817421		700 7MM EXP ADL

ACCESSORIES: W/STUDS L/SIGHTS

FROM:
SHAFER, ARTHUR R.
5710 WEST "A" ST.
WEST LINN OR 97068

SHIP TO:
SHAFER, ARTHUR R.
5710 WEST "A" ST.
WEST LINN OR 97068

CUST NO. 095494 GLO.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
063103		☐			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☑ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☑ MARRED

Product Service

REPAIR CHARGE	20.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1					
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Gun fired by itself upon release of safety. Bullet went thru roof of house and letter box.

MAIN FAULT: After 9-79 Ghostly to duplicate problem anyone as well. Parts pull and overtravel screws have been adjusted outside of the factory. We do not recommend that the trigger be adjusted outside of the factory. Exchange Trigger only at a special price as a gesture of good will.

PARTS

COMMENTS: Trigger pull measured 2 1/2 to 3 lbs as rec'd. sear lift was .013

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
CJC		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY REV. 1/94

To H/S
5/21/94