ECEIVING AND ESTIMATING REPORT

COMMENTS ATTN: JACK KAST
L/FRONT SIGHT
RECOIL PAD NOT OF OUR MFG.

R ORDER 94-14821

AL	CUSTOMER ORDER NO.
FPS	

RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
05/02/94	05/03/94	BW 1-72	6516093		700 30-06 ADL

ESSORIES

L/STUDS Set up file

M:

LEE AIKINS SPORT SHOP
245 N MAIN
POCATELLO ID 83204

SHIP TO:

LEE AIKINS SPORT SHOP
245 N MAIN
POCATELLO ID 83204

CUST NO:001144 C.O.D

OUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
163103		☐			UPS

CONDITION		REPAIR CHARGE
NEW		EXCISE
LIGHTLY WORN		TAX
WORN		INSURANCE
VERY WORN		UPS
UNREPAIRABLE		PARCEL POST
MARRED		TOTAL

STOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
LE	A1	B1				
GGER GROUP		B2			E1	F1
T ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
. ASSY.		B5		D2	E4	F4
OD			C1	D3	E5	F5
AL			C2			

Gun goes off when disengaging the safety

FAULT Mfgr. 1-72 Unable to duplicate customer concern as received. Trigger has been adjusted outside of the factory and inside of Housing is loaded with excessive amber colored grease. Trigger should not be altered outside of the factory and only light film of light oil. 'Like Rem oil' is required for maintainence and storage. Exchange Trigger Assy. at a special price as a gesture of good will and to restore customer confidence.

TS

COMMENTS Trigger pull measured 4 to 4 1/2 LB as received and sear lift measured .009

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS00403