RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER R 92-11529

INITIAL	CUSTOMER ORDER NO.
JJM	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE	
05/06/92	05/18/92	WW B-72 W/STUDS	6590847		700 .17MMMAG	ADL

ACCESSORIES

FROM:
BURNETT, TRAVIS
BURNETT PAINT & WALLPAPER CO
702-C E ROBINSON
SPRINGDALE AR 72764

SHIP TO:
BURNETT, TRAVIS
BURNETT PAINT & WALLPAPER CO
702-C E ROBINSON
SPRINGDALE AR 72764

CUST NO:061946 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		5-20	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE		FIRES B1 ON SAFETY RELEASE				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT
As received, complaint could be duplicated. Determined the specific trigger assembly had been completely maladjusted outside factory. Cedant missing from all adjusting screws — 1) excessive over-travel 2) excessive sear engagement 3) trigger pull only 2½ pounds — trigger had no return action — many times allowing bolt, firing pin easily followed down when closing bolt. Trigger pull 2½ pounds; sear-lift .0065"

PARTS

COMMENTS
Quote new trigger assembly at ½ normal cost, as a gesture of good-will. Warn customer about adjusting trigger assembly!

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
FB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

PS00974