RECEIVING AND ESTIMATING REPORT

COMMENTS: ATTN JIM STEKL
CUT OFF BBL

ORDER R91-23272

INITIAL	CUSTOMER ORDER NO.
LCS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/11/91	11/14/91	ER 10-68	367847		700 6MM ADL

ACCESSORIES: W/STUDS SCOPE BASE L/SIGHTS

FROM:
DUVON, ROBERT
224 SHELBYVILLE ST
CENTER TX 75935
USA

SHIP TO:
DUVON, ROBERT
224 SHELBYVILLE ST
CENTER TX
USA 75935

CUST NO:052969 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

"...will fire when you switch off the safety without pulling the trigger."

MAIN FAULT: As received, rifle would not cock when closing bolt. Disassembly of rifle revealed 1) trigger assembly has been adjusted outside factory 2) insufficient sear-engagement 3) trigger assembly is contaminated with gummy residue — trigger is not moving freely (sticking to side plates of housing) 4) bolt stop is gunned-up and not working properly — Improper maintenance.

PARTS	COMMENTS
	Per attached letter, install new trigger assembly — call without. Customer wants expedited and wants to use MasterCard (409) 598-5621

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE

GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.

PS02128