RECEIVING AND ESTIMATING REPORT

COMMENTS: Set up file
W/LEUPOLD 2 X 7 SCOPE
W/SOFT CASE

ORDER R 94-12420

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
04/07/94	04/08/94		371659		700 7MM MAG BDL

ACCESSORIES: SLING STRAP W/STUDS W/SWIVELS SCOPE MNTS SCOPE BASE L/SIGHTS

FROM:
EARLY, THOMAS D.
P O BOX 296
12376 GREEN RD.
GOODRICH MI 48438

SHIP TO:
EARLY, THOMAS D.
P O BOX 296
12376 GREEN RD.
GOODRICH MI 48438

CUST NO:095580 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
063103		☐			UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☑ VERY WORN
- ☐ UNREPAIRABLE
- ☑ MARRED

COD

REPAIR CHARGE	20.00
EXCISE	
TAX	
INSURANCE	
UPS	8.00
PARCEL POST	
TOTAL	28.00

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP						
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Rifle went off when it touched the safety
Bolt on the safety

MAIN FAULT: Mfgr 1968 Gun follows down as rec'd, erratic trigger pull. Removed stock, action glass bedded, bottom of receiver rusted and pitted, all three trigger adjusting screws have been altered outside of factory. Sear had glue like substance on both sides. Exchange trigger assy. at special price as gesture of good will. We do not recommend that the trigger be adjusted outside of the factory.

PARTS

COMMENTS: Trigger pull measured 4 to 4 1/2 lbs as rec'd.

Safety lever catches in bolt cam spot at times

Bolt release sticks due to gummy type lubrication

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
HB					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/94

PS02281