[illegible]

[illegible] PA 14411

[illegible]

THIS IS AN ESTIMATE TO REPAIR OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW.
RETURN THE FIRST COPY TO REMINGTON ARMS CO., INC., ILION, NY. 13357. KEEP THE SECOND COPY AS YOUR RECEIPT.

REPAIR TO TAKE ABOUT 5 WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN THIRTY DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED.

700 0030-06 BDL SERIAL NUMBER: 6798517
M/STUDI

☐ NEW ATTN JIM STEKL ☐ ☑

CUSTOMER REQUESTS
THIS WEAPON DISCHARGED TWICE WHEN SAFETY WAS RELEASED

MAIN FAULT FOUND:
NO FAULT FOUND - COULD NOT DUPLICATE COMPLAINT. TRIGGER & SAFETY ASSY. OPERATE PROPERLY. HOWEVER, TRIGGER ASSY. HAS BEEN ADJUSTED OUTSIDE OF FACTORY-(FOREIGN SEALANT).TRIG.PULL BELOW OUR MIN.SPEC.& 2 3/4# OVERTRAVEL INSUFFICIENT. SEAR LIFT OK @ .0085= REAR SCREW HAS BEEN ADJUSTED. 10-74 MFG.

1	D026345	TRIGGER ASSEM RH SPECIAL 1/2 PRICE TRIGGER ASSY. NEW STYLE SAFE (WILL OPEN ON SAFE) POLISH CHAMBER FIT & ADJUST TEST NOTE: TRIGGER PLATE MARKED LEH:JZ	23.60

TOTAL REPAIR CHARGE	23.60
TAXES	1.42
INSURANCE PARCEL POST	5.00
TOTAL CHARGES ▶	30.02

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

FEB 13 1991

W/Ord. ORDER AND SHIPPING COPY

PRINTED BY THE STANDARD REGISTER COMPANY, U.S.A.

PS05538