RECEIVING AND ESTIMATING REPORT

CO RE0000393

ORDER R92-20041

INITIAL	CUSTOMER ORDER NO.
FPS	

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
09/23/92	10/02/92	CL 4-91	7675320		7 308 WIN

ACCESSORIES W/STUDS

FROM:

BBJ'S
448 HWY 46
DICKSON TN 37055

SHIP TO:

BBJ'S
448 HWY 46
DICKSON TN 37055

CUST NO:058517 C.O.D

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE-UP	PROM. DATE	ESTIMATED	VIA
		☐ CLEAN/TEST		10/9/92	UPS

GUN CONDITION
- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE	
EXCISE	
TAX	
INSURANCE	
UPS	
PARCEL POST	
TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2				F1
BOLT ASSY.		B3				F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT "Safety would release trigger & when it finally did the gun fired when bolt was manually pushed forward".

Disassembly of rifle revealed dirt and rust on bottom of barrel, receiver and on and in trigger assembly. Rust inside of trigger assembly is causing internal trigger parts to bind and not move freely. Screwed, bolt would not cock — rifle was inoperative.

Appears rifle became wet and dirty during use and was not cleaned after. Lack of maintenance.

PARTS

COMMENTS

Charge to clean rifle and replace trigger assembly.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
T.163					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE